

December 4, 2020

To: Gianna Petito, District Manager, Winooski
Natural Resources Conservation District

From: Meghan Arpino, Gabe Bolin, PE, Stone
Environmental, Inc.

MEMO

Stone Project No. 20-007
Subject: Hands Mill Dam Removal – BCA Analysis Memo

Stone Environmental, Inc. (Stone) has completed a Benefit-Cost Analysis (BCA) as part of the Hands Mill Dam Removal 30% design effort. This memo provides a summary of the analysis, along with a BCA report and supporting documentation, that can be used as part of a larger grant application submission by the Winooski Natural Resources Conservation District (District) to the US Federal Emergency Management Agency (FEMA) for funding to support future project phases.

The BCA is a method developed by FEMA that compares risk reduction benefits of a hazard mitigation project to its costs. The result is a Benefit-Cost Ratio (BCR), where a project is considered cost-effective when the BCR is at or greater than 1.0. To establish cost-effectiveness of a project, those that are applying to FEMA for project funding are required to use FEMA methodologies and tools. Stone used the FEMA BCA Toolkit, Version 6.0 (<https://www.fema.gov/grants/guidance-tools/benefit-cost-analysis>) for this analysis. The following sections provide an explanation of details and assumptions of the analysis. Relevant supporting documents are provided as attachments to this memo.

1. Analysis Methodology and Assumptions

The overall analysis includes two mitigation actions, 1) mitigation at the dam property itself, including dam removal and 2) mitigation of impacts to the residential property at 16 Woodchuck Hollow Road, which is located at the intersection of West Corinth Road and Woodchuck Hollow Road, immediately adjacent to the dam property. Analysis of the dam property and dam removal is based on professional expected damages due the limited availability of historical damages data. Analysis of impacts to the residential property included a comparison of existing and proposed HEC-RAS model conditions and results. The following provides a summary of details, information and assumptions that were made to complete the analysis using the BCA Toolkit Version 6.0. The information is presented in the order it was input into the toolkit, for ease of understanding by FEMA reviewers. A printout of the completed BCA Toolkit Form is provided in Attachment 1.

1.1 Mitigation Actions

Mitigation Action 1 – Dam Removal at Dam Property

- Property Structure – Set to ‘Other’ since the dam did not fall into any of the listed categories.
- Hazard Type – ‘Riverine Flood’ was selected since it was most applicable to the project and provided a means to account for the ‘ecosystem benefits’ of the floodplain bench and open space components of the proposed project.
- Initial Project Costs – A value of \$437,269 was used which is the construction opinion of probable cost (OPC) for the selected alternative and includes the construction costs, mobilization/demobilization and construction contingency, currently set at 20% for this 30% design project. The OPC table is provided as Attachment 2 to this memo.
- Annual Maintenance Costs – A value of \$1,500 was used to account for monitoring of planted grasses, shrubs, and/or trees for 2 to 3 years following construction, with replanting and reseeding occurring as needed throughout the project life. The Dam Removal General O&M document (<http://winooskinrcd.org/wp-content/uploads/Dam-Removal-OM-General-Comments-1-1.pdf>) was referred to for this item and is provided as Attachment 3 to this memo.
- Professional Expected Damages Before Mitigation
 - Flood Recurrence Interval – The dam breach analysis performed by the VTDEC Dam Safety Program (Attachment 4) to support this analysis simulated a breach of the highest dam structure capable of impounding water, which currently is a concrete training wall along river right with a top elevation of 1280’. This elevation defined the max pool elevation in the analysis and corresponded to the 200-year recurrence interval flood event in Stone’s project hydrologic and hydraulic model, simulated using the Army Corps of Engineers HEC-RAS model (<https://www.hec.usace.army.mil/software/hec-ras/>). Note that the model includes a ‘levee’ set to elevation 1280’ at two cross sections that intersect the dam; levees do not exist anywhere else in the model. Starting at the 100-year recurrence interval flood event, flow from upstream of the training wall is conveyed around the levee/training wall along river right resulting in shallow flooding in a town yard located north of the concrete training wall, and along Woodchuck Hollow Road.
 - Damages – The Town of Washington Local Hazard Mitigation Plan (2014; Attachment 5) indicated that if the dam were to fail, impacts would be severe resulting in approximately ‘\$2,000,000+’ as the cost of impact. A value of \$2,000,000 was used in the BCA as the cost for dam failure based on this estimation. Damage costs for the residential structure located immediately adjacent to the dam at 16 Woodchuck Hollow Road using damage curves developed under Mitigation Action 2 of this BCA were also included. A 6-foot flood depth was assumed based on model data from the VTDEC Dam Breach Report (Attachment 4)

and a finished floor elevation (FFE) of 1269.40'. The FFE was based on a topographic survey shot located at an exterior corner of the structure. One foot was added to the elevation to obtain the best approximation of FFE based on the location of an adjacent window and other observations of the structure made in the field during the survey. A photo of the survey shot location and structure is provided as Attachment 6.

- Total Damages = \$2,000,000 + \$68,701.60 (building) + \$40,343.20 (building contents) + \$38,880.00 (displacement) = \$2,147,924.80
 - Loss of Life and Injury – Applicable values from Appendix C – FEMA Standard Values – Casualties and Injuries Section were summed to provide an estimate of this metric. The VTDEC Dam Breach Report indicated probable loss of life at 16 Woodchuck Hollow Road and potential for injuries downstream.
 - Economic Costs – This metric was estimated for interruptions to normal traffic patterns in the area. Based on the Dam Breach Report, several roads downstream of the dam, including the road accessing the local school, may be flooded in the event of a dam breach. These calculations were made using the daytime and nighttime Population at Risk (PAR) provided in the Dam Breach Report.
 - Total Cost = (Daytime PAR + Nighttime PAR)*38.15(vehicle delay time, per vehicle per hour)*24(assume 1 day, 24 hrs. of delays) =
 - Total Cost = (94+40)*38.15*24=\$112,690.40
- Professional Expected Damages After Mitigation
 - Post Mitigation Costs – Stone considered including a cost for damage to an adjacent road (i.e. West Corinth Road or Woodchuck Hollow Road), assuming that after dam removal the pilot channel could migrate/adjust during a large storm event and negatively impact adjacent infrastructure. However, a cost was ultimately not included, as the existing channel would be lowered significantly (i.e. ~10') away from the roads as part of the dam removal construction, and the potential for impacts to roads or road embankments are further reduced.
- Standard Benefits – Ecosystem Services
 - These include benefits to the ecosystem related to floodplain, riparian, wetland and open space areas created by the project. The proposed work includes 17,330 SF of riparian area via a floodplain bench along river left and 18,670 SF of open space, defined as the area from the floodplain bench limits to the proposed grading up to existing grade. A map showing these areas is provided as Attachment 7.

Mitigation Action 2 – Lowering of Flood Water Surface Elevations at 16 Woodchuck Hollow Road Following Dam Removal

- Project Useful Life – A project useful life (PUL) of 30 years was used for the stream and floodplain restoration project associated with dam removal.
- Initial Project Costs – This value was set to \$0 since the dam removal costs are already captured in Mitigation Action 1.
- Annual Maintenance Costs – A value of \$500 was used to cover annual activities similar to the annual maintenance costs for Mitigation Action 1, but covers a smaller area associated with this property.
- Lowest Floor Elevation – As stated above, a FFE of 1269.40' was used for the building.
- Streambed Elevation at the Property Location – Thalweg elevation at the property was obtained from survey data and the hydraulic model. Before and after mitigation water surface elevations were obtained from cross sections at the upstream extent of property, within the limits of disturbance of the proposed dam removal and restoration project. Differences in water surface elevations between existing and proposed conditions reduce moving from upstream to downstream. A series of graphic cross sections from the HEC-RAS model are included in Attachment 8.
- Building Size – The building square foot area is based on the building outer dimensions and assumes two levels of living space.
- Standard Benefits – Ecosystem Services were captured at the residential property, similar to the Ecosystem Services discussed for Mitigation Action 1 above.

2. Results

The BCR generated for the proposed removal of Hands Mill Dam using the BCA Toolkit, and based on the assumptions as stated in this memo is 2.32. This is a composite score that includes the costs and benefits for Mitigation Actions 1 and 2.

Attachment 1: BCA Report

Project Summary				
Mitigation Title	Hazard	Benefits (B)	Costs (C)	BCR (B/C)
Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"	IFA - Riverine Floo	\$813,658	\$455,883	1.78
Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675	Riverine Flood	\$259,600	\$6,205	41.84
	Total	\$1,073,258	\$462,088	2.32

Property Configuration	
Property Title:	Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"
Property Location:	05675, Orange, Vermont
Property Coordinates:	44.1055750, -72.4298000
Hazard Type:	Riverine Flood
Mitigation Action Type:	Floodplain and Stream Restoration
Property Type:	Other
Analysis Method Type:	Professional Expected Damages

Cost Estimation		Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"
Project Useful Life (years):	30	
Project Cost:	\$437,269	
Number of Maintenance Years:	30 Use Default: Yes	
Annual Maintenance Cost:	\$1,500	

Comments	
Mitigation Project Cost:	See construction opinion of probable cost developed using 2-year and 5-year average unit cost data maintained by Vermont Agency of Transportation (VTrans) Estimated based on typical post-construction and restoration monitoring. Assumed monitoring of newly planted grasses, shrubs, and/or trees for 2 to 3 years, with replanting and reseeding occurring as needed.
Annual Maintenance Cost:	

Damage Analysis Parameters - Damage Frequency Assessment		Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"
Year of Analysis Conducted:	2020	
Year Property was Built:	1860	
Analysis Duration:	161 Use Default: Yes	

Comments	
Year Built:	See Dam Beach Report, Hands Mill Inspection Report, Local Hazard Mitigation Plan (LHMP)

Professional Expected Damages Before Mitigation		Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"					
Recurrence Interval (years)	Other	Optional Damages			Volunteer Costs		Total
	Damages (\$)	Loss of Life and Injury (\$)	Economic (\$)	Displacement (\$)	Number of Volunteers	Number of Days	Damages (\$)
200	2,147,924.80	6,990,000	122,690.40	0	5	2	9,262,543

Comments	
Damages Before Mitigation:	Damages equal estimated damages in Town of Washington Local Hazard Mitigation Plan (LHMP) plus damages to 16 Woodchuck Hollow Road from damage curves in that property's mitigation task (based on depth of water from the Dam Breach Report). Loss of Life and Injury calculated from FEMA Standard Rates (Appendix C, BCA Reference Guide), economic costs calculated based on daytime and nighttime PAR and FEMA Standard Rates for road closure. Volunteers to help clean debris from channel and floodplain.

Annualized Damages Before Mitigation			Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"
Annualized Recurrence Interval (years)	Damages and Losses (\$)	Annualized Damages and Losses (\$)	
200	9,262,543	46,312	

Professional Expected Damages After Mitigation								Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"
Recurrence Interval (years)	Other Damages (\$)	Loss of Life and Injury (\$)	Optional Damages Economic (\$)	Displacement (\$)	Number of Volunteers	Number of Days	Total Damages (\$)	
0	0	0	0	0	0	0	0	

Annualized Damages After Mitigation			Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"
Annualized Recurrence Interval (years)	Damages and Losses (\$)	Annualized Damages and Losses (\$)	

Standard Benefits - Ecosystem Services		Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"
Total Project Area (sq.ft):	36,000	
Percentage of Green Open Space:	52.00%	
Percentage of Riparian:	48.00%	
Percentage of Wetlands:	0.00%	
Percentage of Forests:	0.00%	
Percentage of Marine Estuary:	0.00%	
Expected Annual Ecosystem Services Benefits:	\$19,257.78	

Comments	
Total Project Area:	Entered in square feet. Sum of riparian and green open space identified on Hands_Mill_FEMA_Ecosystem_Benefits.pdf.

Benefits-Costs Summary		Floodplain and Stream Restoration @ 44° 6' 20.07"; -72° -25' -47.28"
Total Standard Mitigation Benefits:	\$813,658	
Total Social Benefits:	\$0	
Total Mitigation Project Benefits:	\$813,658	
Total Mitigation Project Cost:	\$455,883	
Benefit Cost Ratio - Standard:	1.78	
Benefit Cost Ratio - Standard + Social:	1.78	

Property Configuration		
Property Title:	Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675	
Property Location:	05675, Orange, Vermont	
Property Coordinates:	44.10567, -72.43038	
Hazard Type:	Riverine Flood	
Mitigation Action Type:	Floodplain and Stream Restoration	
Property Type:	Residential Building	
Analysis Method Type:	Modeled Damages	

Cost Estimation		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675
Project Useful Life (years):	30	
Project Cost:	\$0	
Number of Maintenance Years:	30 Use Default: Yes	
Annual Maintenance Cost:	\$500	

Comments	
Mitigation Project Cost:	Total initial project costs are captured in the mitigation task for
Annual Maintenance Cost:	Assumes project will require 2 to 3 years of monitoring following construction of the pilot channel. Newly planted riparian vegetation will be monitored to ensure that an 80% survival rate is establish for newly planted grasses, shrubs and/or trees. Reseeding and/or re-planting will occur as necessary.

Hazard Probabilities Parameters - Flood		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675
Lowest Floor Elevation of the Property (ft):	1269.4	
Streambed Elevation at the Property Location (ft):	1259.94 Use Default Recurrence Intervals:	
Use Default:	Yes	

Comments	
Lowest Floor Elevation:	Surveyed building corner plus 1 ft to account for foundation. Streambed elevation at property pulled from survey data and hydraulic model. Before and After mitigation WSEs pulled from cross section at upstream extent of property, within the limits of disturbance of the proposed dam removal and restoration project. Differences in WSE between existing and proposed conditions reduce moving from upstream to downstream. See Model Cross Sections pdf.
Streambed Elevation:	

Discharge			Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675
Before Mitigation			
Recurrence Interval (years)	Surface Elevation (ft)	Discharge (cfs)	
10	1264.68	433	
50	1265.16	701	
100	1265.48	836	
500	1266.29	1232	
After Mitigation			
Recurrence Interval (years)	Surface Elevation (ft)	Discharge (cfs)	
10	1262.82	433	
50	1263.8	701	
100	1264.24	839	
500	1265.33	1232	

Building Information		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675
Building Type:	Two or More Stories	
Foundation Type:		
Building Has Basement:	No	
NFIP:	No	

Comments	
Building Type:	See Hands Mill House SR Form pdf
Building has basement:	Unfinished, based on examples no basement.

Standard Benefits - Building		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675
Depth Damage Curve:	USACE Generic Use Default: Yes	
Building Size (sq.ft):	1,688	
Building Replacement Value (\$/sq.ft):	\$100 Use Default: Yes	
Demolition Threshold (%):	50.00% Use Default: Yes	
Expected Annual Losses due to Building Damages before Mitigation:	\$0.00	
Expected Annual Losses due to Building Damages after Mitigation :	\$1.00	
Expected Annual Benefits - Building :	(\$1.00)	

Comments	
Building Size:	Calculated based on approximate dimensions of house. See Hands Mill House SR Form pdf.

Depth Damage Curve - Building		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675						
Flood Depth (ft)	Percent (%)	Before Mitigation Damage Value (\$)	NFIP (\$)	ICC Fees (\$)	Percent (%)	After Mitigation Damage Value (\$)	NFIP (\$)	ICC Fees (\$)
-2	0	0	0	0	0	0	0	0
-1	3	5,064	0	0	3	5,064	0	0
0	9.3	15,698.40	0	0	9.3	15,698.40	0	0
1	15.2	25,657.60	0	0	15.2	25,657.60	0	0
2	20.9	35,279.20	0	0	20.9	35,279.20	0	0
3	26.3	44,394.40	0	0	26.3	44,394.40	0	0
4	31.4	53,003.20	0	0	31.4	53,003.20	0	0
5	36.2	61,105.60	0	0	36.2	61,105.60	0	0
6	40.7	68,701.60	0	0	40.7	68,701.60	0	0
7	44.9	75,791.20	0	0	44.9	75,791.20	0	0
8	48.8	82,374.40	0	0	48.8	82,374.40	0	0
9	52.4	168,800	0	0	52.4	168,800	0	0
10	55.7	168,800	0	0	55.7	168,800	0	0
11	58.7	168,800	0	0	58.7	168,800	0	0
12	61.4	168,800	0	0	61.4	168,800	0	0
13	63.8	168,800	0	0	63.8	168,800	0	0
14	65.9	168,800	0	0	65.9	168,800	0	0
15	67.7	168,800	0	0	67.7	168,800	0	0
16	69.2	168,800	0	0	69.2	168,800	0	0

Standard Benefits - Contents		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675	
Contents Value in Dollars:	\$0	Use Default:	Yes
Utilities Elevated:	No		
Expected Annual Losses due to Content Damages before Mitigation:	\$0.00		
Expected Annual Losses due to Content Damages after Mitigation:	\$1.00		
Expected Annual Benefits - Content:	(\$1.00)		

Depth Damage Curve - Contents		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675		
Flood Depth (ft)	Before Mitigation		After Mitigation	
	Percent (%)	Damage Value (\$)	Percent (%)	Damage Value (\$)
-2	0	0	0	0
-1	1	1,688	1	1,688
0	5	8,440	5	8,440
1	8.7	14,685.59	8.7	14,685.59
2	12.2	20,593.60	12.2	20,593.60
3	15.5	26,164	15.5	26,164
4	18.5	31,228	18.5	31,228
5	21.3	35,954.40	21.3	35,954.40
6	23.9	40,343.20	23.9	40,343.20
7	26.3	44,394.40	26.3	44,394.40
8	28.4	47,939.20	28.4	47,939.20
9	30.3	51,146.40	30.3	51,146.40
10	32	54,016	32	54,016
11	33.4	56,379.20	33.4	56,379.20
12	34.7	58,573.60	34.7	58,573.60
13	35.6	60,092.80	35.6	60,092.80
14	36.4	61,443.20	36.4	61,443.20
15	36.9	62,287.20	36.9	62,287.20
16	37.2	62,793.60	37.2	62,793.60

Standard Benefits - Displacement		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675	
Lodging Per Diem:	\$96	Use Default:	Yes
Meals Per Diem:	\$55	Use Default:	Yes
Population Affected: Total Residential	1		
Displacement Cost:	\$144		
Expected Annual Losses due to Displacement Damages before mitigation:	\$0.00		
Expected Annual Losses due to Displacement Damages after Mitigation:	\$0.00		
Expected Annual Losses - Displacement:	\$0.00		

Depth Damage Curve - Displacement		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675			
Flood Depth (ft)	Before Mitigation		After Mitigation		
	Days	Damage Value (\$)	Days	Damage Value (\$)	
-2	0	0	0	0	
-1	0	0	0	0	
0	0	0	0	0	
1	45	6,480	45	6,480	
2	90	12,960	90	12,960	
3	135	19,440	135	19,440	
4	180	25,920	180	25,920	
5	225	32,400	225	32,400	
6	270	38,880	270	38,880	
7	315	45,360	315	45,360	
8	360	51,840	360	51,840	
9	405	58,320	405	58,320	
10	450	64,800	450	64,800	
11	495	71,280	495	71,280	
12	540	77,760	540	77,760	
13	585	84,240	585	84,240	
14	630	90,720	630	90,720	
15	675	97,200	675	97,200	
16	720	103,680	720	103,680	

Additional Benefits - Street Maintenance		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675			
Total Annual Street Maintenance Budget:	\$0				
Total Number of Street Miles Maintained:	0				
Street Miles that will not require future maintenance:	0				
Expected Annual Benefits - Street Maintenance:	\$0.00				

Standard Benefits - Volunteer Costs		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675			
Number of Volunteers (volunteers/event):	5				
Number of Days of Lodging: Expected Annual Volunteer	1				
Benefits:	\$1,467.60				

Comments	
Number of volunteers Required:	Large amount of debris on property, assume volunteer hours will be used to help remove debris transported from property downstream during flood events.

Standard Benefits - Ecosystem Services		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675
Total Project Area (sq.ft):	36,000	
Percentage of Green Open Space:	52.00%	
Percentage of Riparian:	48.00%	
Percentage of Wetlands:	0.00%	
Percentage of Forests:	0.00%	
Percentage of Marine Estuary:	0.00%	
Expected Annual Ecosystem Services Benefits:	\$19,257.78	

Comments	
Total Project Area:	See Hands Mill FEMA Ecosystem Benefits pdf

Additional Benefits - Social		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675
Number of Workers:	0	
Expected Annual Social Benefits:	\$2,443	

Benefits-Costs Summary		Floodplain and Stream Restoration @ 16 Woodchuck Hollow Rd, Washington, Vermont, 05675
Total Standard Mitigation Benefits:	\$257,157	
Total Social Benefits:	\$2,443	
Total Mitigation Project Benefits:	\$259,600	
Total Mitigation Project Cost:	\$6,205	
Benefit Cost Ratio - Standard:	41.44	
Benefit Cost Ratio - Standard + Social:	41.84	

Attachment 2: 30% Design Opinion of Probable Cost

Hands Mill Dam Removal
Alternative A4 - 30% Design OPC
Stone Environmental, 11/2020

ITEM #	ITEM	AMOUNT	UNIT	UNIT COST	TOTAL
General					
1	SURVEY LAYOUT	1	LS	\$4,000.00	\$4,000.00
2	CONSTRUCT ACCESS	1	LS	\$10,000.00	\$10,000.00
3	EPSC MEASURES	1	LS	\$7,500.00	\$7,500.00
4	FLOW BYPASS AND DEWATER SITE	1	LS	\$10,000.00	\$10,000.00
Dam Removal					
5	DEMO DAM AND HAUL OUT STONE	403	CY	\$220.00	\$88,578.52
Channel Restoration					
6	COMMON EXCAVATION (CHANNEL AND FLOODPLAIN BENCHES)	13940	CY	\$7.00	\$97,580.00
7	SEDIMENT HAUL	13386	CY	\$7.00	\$93,702.00
8	CHANNEL REALIGNMENT	1	LS	\$5,000.00	\$5,000.00
9	INSTALL STONE STEPS, POOLS AND ROOTWADS	1	LS	\$10,000.00	\$10,000.00
10	PLACE SEED, MULCH AND FASCINES	1	LS	\$10,000.00	\$10,000.00
CONSTRUCTION TOTAL					\$336,361
MOBILIZATION / DEMOBILIZATION (10%)					\$33,636
CONSTRUCTION CONTINGENCY (20%)					\$67,272
FINAL DESIGN & PERMITTING (10%)					\$33,636
BID AND CONSTRUCTION PHASE SERVICES (6%)					\$20,182
TOTAL (ROUNDED TO NEAREST \$100)					\$491,100

Attachment 3: Dam Removal General O&M

Dam Removal General O&M

May 20, 2019

DESIGN REVIEW

The design plans include an erosion prevention and sediment control (EPSC) plan that is different from an Operations and Maintenance (O&M) description.

1. All relevant text in plans, reports and documents should label and/or refer to the “pilot channel” in the future excavated sediments and not referenced as a “new stream channel”. This use of the “pilot channel” term is intended to manage the public expectations that the newly created channel will meander over time and to establish that an underlying project goal is to manage the reach towards dynamic stream equilibrium conditions as the underlying design objective.
2. The Operations and Maintenance (O&M) component of the design plans to be implemented after project completion shall address three issues that are typical for dam removal projects:
 - A. The completed project is intended to restore *dynamic stream equilibrium* to the channel as an underlying design concept and minimal channel stabilization is required and to be evaluated at this design review phase. The O & M plan shall discuss restoring *dynamic stream equilibrium* as a goal and objective for clarity for the public relative to the next two items.
 - B. The completed project will likely require 2 to 3-years of monitoring of the newly planted riparian vegetation to successfully establish an 80% survival rate of the newly planted grasses, shrubs and trees and report to the US Army Corps of Engineers, VDF&W and the State Rivers Program on the status and a plan for any required re-seeding and/or re-planting of the project site.
 - C. The US Army Corps of Engineers, VDF&W, State Rivers Program and Project Manager will review and approve the monitoring status and any plan for re-seeding and/or re-planting of the project site.
3. There may be various riparian buffer species encountered during the dam removal that can be discussed in the plans to be set aside for possible replanting by the selected contractor after completion of the work and at the common direction of VDF&W, state and federal staff.

Attachment 4: VTDEC Dam Breach Report

Vermont Department of Environmental Conservation

Water Investment Division
1 National Life Drive, Davis 3
Montpelier, VT 05620
Phone: 802-622-4093

Agency of Natural Resources

MEMORANDUM

TO: Town of Washington, Care of Carol Davis, Town Clerk, Dam Owner
FROM: Benjamin Green, PE, Dam Safety Program (DSP), Engineer
Katherine King, DSP, Assistant
DATE: November 18, 2020
SUBJECT: DSS-Wise Lite Dam Failure Analysis and Flood Inundation Maps
Hands Mill Dam, Washington, Vermont
State ID No: 225.01 | National ID No: VT00308

This memorandum summarizes the methods, assumptions, and results of dam failure and downstream flood inundation analysis using the Decision System for Water Infrastructural Security (DSS-Wise Lite) model for the Hands Mill Dam. Hands Mill Dam and its floodway are in the Town of Washington. The following attachments are included:

- **Attachment A:** Dam Failure Flood Inundation Map
- **Attachment B:** DSS-Wise Lite Simulation Results Final Report
- **Attachment C:** DSS-Wise Lite Human Consequences Final Report

It should be noted that **Attachments B** and **C** are automatically generated reports by the DSS-Wise Lite Program.

Purpose:

The analysis was performed to investigate the hazard potential classification of the dam and potential downstream consequences in the event of a dam failure.

Dam Overview:

Hands Mill Dam is a partially breached concrete and stone rubble gravity dam with a principal spillway and outlet works founded on bedrock and/or earth. It is our understanding that dam removal is being considered and a feasibility study is currently underway.

The dam is currently classified as a SIGNIFICANT hazard potential dam. According to our files, the dam has a total length of approximately 325 feet and a structural height of 20 feet. The principal spillway consists of an eroding concrete and stone rubble weir with a total length of about 20 feet. To the left of the principal spillway is an approximately 40-foot long training wall and an old mill foundation comprised of concrete and stone rubble with an abandoned intake and concrete sluiceway. There is no auxiliary spillway. The low-level outlet (LLO) to the right of the principal spillway is an approximately 2-foot by 2-foot square opening on the downstream face that is reportedly inoperable/plugged and abandoned. To the right of the principal spillway is an approximately 300-foot-long non-overflow concrete wall that extends to the right abutment at the valley wall.

Our records dating back to 1950 indicate that the dam was built circa 1860 and was repaired after the 1927 flood. No records exist of repairs as of the 1947 ownership transfer for use as a sawmill. The dam impounds a pond with a surface area of about 2 acres at normal pool elevation that is substantially filled with sediment. It is our understanding the dam and pond currently serve no current social or economic purpose. The upstream drainage area is approximately 4,128 acres. The normal and maximum storage of the dam were estimated as 11.2 and 18.1 acre-feet in 2020 by Stone Environmental, Inc. (STI) an engineering consultant working on the dam removal feasibility study. These storage estimates compare well with historic estimates.

Downstream Conditions:

The Hands Mill Dam flows into the Jail Branch River which flows through the Town of Washington to the East Barre Dam and northerly into the City of Barre. East Barre Dam is a large, State owned and operated flood control dam that would safely contain dam failure flood waters, preventing damage further downstream. It appears that a dam failure could potentially impact several road crossings, several homes and businesses, and a school downstream.

Methods:

The DEC DSP prepared a DSS-Wise Lite model of the Hands Mill Dam and the downstream area. DSS-Wise Lite is a publicly available flood modeling and consequence analysis tool developed by The National Center for Computational Hydroscience and Engineering at the University of Mississippi. DSS-Wise Lite is a web-based program that allows the user to setup an automated two-dimensional dam breach model with minimal inputs and provides results including inundation maps, flood arrival times, hydrographs, and other life consequence information. As noted in program literature, DSS-Wise Lite is a simplified analysis producing rough, approximate results that are not intended to replace more detailed modeling processes/programs. The following limitations of DSS-Wise Lite should be considered:

- While a flood hydrograph can be manually input into DSS-Wise Lite to simulate a storm day dam failure, the program does run most reliably under sunny day failure scenarios. For this reason, a sunny dam failure during maximum pool conditions (water level at the dam crest) was modeled. This scenario is possible assuming that the principal spillway was clogged, and the water level were to rise to the dam crest. This approach also assumes normal, base flow in the downstream channel, allowing for a more easily understood incremental impact of dam breach flooding than would be present during a storm event. The failure is assumed to occur rapidly and completely to model a worst-case scenario.
- The model defaults to the use of publicly available digital elevation models (DEMs). For the area of this project, the resolution of the DEMs used in the model is 1 meter (3.281 feet).
- The program does not allow for the modeling of culverts at downstream road crossings. Accordingly, culverts are not included in the model. This does depict a somewhat worst case but observed scenario where downstream culverts become plugged with debris during a flood flow and are ineffective. Large bridges can be input in the model but are modeled as an opening with no deck.

Model Inputs:

The model inputs are summarized in **Attachment B**. Based on the DEMs, the following elevation and storage data was used (all elevations reference the North American Datum of 1988, NAVD88, in feet):

- | | |
|--------------------------|----------------|
| • Normal Pool Elevation | El. 1,287 |
| • Normal Pool Storage | 11.2 acre-feet |
| • Maximum Pool Elevation | El. 1,292.5 |
| • Maximum Pool Storage | 18.1 acre-feet |
| • Dam height | 20 feet |

Several challenges are present when performing dam breach and flood inundation analyses/mapping at Hands Mill Dam. As noted above, the normal and maximum storage inputs are based on preliminary estimates by STI. STI also estimated the volume of impounded sediment behind the dam at 14,300 cubic yards. This estimated sediment volume is equivalent to about 386,100 cubic feet, or 8.9 acre-feet. With estimated normal and maximum storage volumes of the dam of 11.2 and 18.1 acre-feet, respectively, the impounded sediment makes up approximately 80% of the impounded volume at normal pool and 50% of the impounded volume at maximum pool. It is anticipated that in the event of a dam failure, a portion of this sediment would be mobilized downstream. It is generally recognized that saturated sediment or mud flows can result in a dam failure wave that would move slower, maintain its height and shape further downstream, but perhaps travel less distance overall when compared to its clear water equivalent. This analysis was performed assuming that all impounded liquids would perform as clear water. Accordingly, it is anticipated that in the event of a dam failure, it is possible that flood depths near the dam may be greater than predicted, but the flood wave may also dissipate more quickly.

Model Results:

The DSS-Wise Lite model results are summarized in *Attachments A* through *C*. The estimated inundation limits were overlain on a ANR Atlas satellite image map. The following results are provided at select locations downstream of the dam.

Location	Max. Estimated Flood Depth (ft)	Max. Estimated Flood Flow Velocity (ft/s)	Estimated Arrival Time of Peak Flood (hours)
At Dam	NA ¹	NC ²	NA
16 Woodchuck Hollow Road	3 to 6	3 to 6	Immediate
Woodchuck Hollow Road crossing	3 to 12	6 to 15	Immediate
39 Woodchuck Hollow Road	0 to 2	3 to 10	<0.25
64 West Corinth Road	<1	<1	
29 Woodchuck Hollow Road	<1	0 to 3	
31 Woodchuck Hollow Road	<1	0 to 3	
33 Woodchuck Hollow Road	<1	<1	
57 Fairgrounds Road	<1	0 to 3	
56 Fairgrounds Road	1 to 2	3 to 6	
73 Fairgrounds Road	<1	1 to 6	
2985 VT Route 110	1 to 2	1 to 3	
2973 VT Route 110 (Baptist Church)	1 to 2	1 to 3	
40 School Lane	1 to 3	3 to 6	
72 School Lane (School)	<1	0 to 3	
School Lane crossing	3 to 6	10 to 15	
Creamery Road crossing	3 to 6	10 to 15	0.25 to 0.5
Tucker Road crossing	2 to 3	3 to 6	1 to 1.5

(1) Not applicable

(2) Not calculated

Hazard Potential Classification:

As noted above, this dam is currently as a SIGNIFICANT hazard. The current hazard potential classification definitions from the Vermont Dam Safety Rule are provided below:

Classification	General Definition
HIGH	Dams where failure or mis-operation will probably cause loss of human life.
SIGNIFICANT	Dams where failure or mis-operation results in no probable loss of human life but can cause economic loss, environment damage, disruption of lifeline facilities, or impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.
LOW	Dams where failure or mis-operation results in no probable loss of human life and low economic and environmental losses.
MINIMAL	A dam that meets the LOW hazard definition, above, but is only capable of impounding less than 500,000 cubic feet.

The Hazard Consequence Model (HCom) estimated the Population at Risk (PAR) resulting from the simulated dam failure of the Hands Mill Dam. The PAR is the estimated number of people within an inundation limits of a simulated dam failure. The HCom estimated a Nighttime PAR of 40 and a Daytime PAR of 94. The daytime and nighttime PAR vary based on the number of homes where people are typically at night, versus business, churches, or schools, where people are typically during the day.

Based on the results, the primary risk driver is the 16 Woodchuck Hollow Road property immediately downstream of the dam. While the occupancy of this property is not clear, it is noted that there was both a house and a mobile home recently observed on the lot. In the event of dam failure, the estimated depths and velocities at these structures would approach to slightly exceed accepted, survivable limits at the house and would exceed survivable limits at the mobile home. In either case, given the proximity to the dam, there would be little to no warning/evacuation time. Accordingly, there appears to be a potential for probable loss of life at the property during a dam failure.

In addition, approximately 10 buildings, including homes, a farm, and a church, would experience minor flooding that does not appear to rise to the level of probable loss of human life, but is indicative of economic loss. Also, four roadways would be overtopped, but the anticipated low daily traffic and low travel speeds suggest it is not likely this damage would result in probable loss of human life but does infer economic loss. One of the downstream roadways, School Lane, is the primary entry and exit to the Washington Village School, the failure of which could strand or limit access. According to the model results, some minor, low velocity flooding is anticipated up to and around portions of the school. This flooding is not anticipated to cause probable loss of human life but should be given extra consideration given the vulnerable population involved.

Given the results of this study, a hazard classification of HIGH or SIGNIFICANT hazard potential should be considered. A determination of the occupancy status of the 16 Woodchuck Hollow Road property is necessary to classify the dam based on this work. Also, given the close proximity of the school, a more detailed analysis may be warranted to better understand risks associated with this vulnerable population, particularly if dam removal is not pursued in the near future or if either no action or dam rehabilitation alternatives instead considered.

As the feasibility study for the dam removal project is currently underway, a prudent risk reduction measure to undertake until dam removal can be implemented would be the development of an Emergency Action Plan (EAP). The DSP would be happy to assist in the development of an EAP, which would include the flood inundation map attached here-in, pre-planned actions in the case of a dam incident or failure, and identification of key emergency personnel as well as potential evacuees.

Y:\WID_DamSafety\Dams\H\HandsMill\Hazard Classification\Hands Mill Dam (No. 225.01) – DSS Wise Lite Dam Flood Mapping

Attachment A:



LEGEND

- Buildings (E911)
- Roads
 - Interstate
 - US Highway; 1
 - State Highway
 - Town Highway (Class 1)
 - Town Highway (Class 2,3)
 - Town Highway (Class 4)
 - State Forest Trail
 - National Forest Trail
 - Legal Trail
 - Private Road/Driveway
 - Proposed Roads
- Stream/River
 - Stream
 - Intermittent Stream
- Town Boundary
- Flow Direction

Approximate Limits of Possible Shallow Flooding, <1 ft.

73 Fairgrounds Rd.
57 Fairgrounds Rd.
56 Fairgrounds Rd.

33 Woodchuck Hollow Rd.
31 Woodchuck Hollow Rd.
29 Woodchuck Hollow Rd.
39 Woodchuck Hollow Rd. (Farm)

Hands Mill Dam

Estimated Dam Failure Flood Inundation Limits

64 W Corinth Rd.

16 Woodchuck Hollow Rd.

2985 VT Route 110

2973 VT Route 110 (Baptist Church)

40 School Ln.

72 School Ln. (School)

Flooding north of this point largely remains in the channel and no inundated habitable structures were identified. Possible flooding/damages at the Creamery Road Crossing (0.6 miles downstream) and Tucker Road Crossing (1.7 miles downstream)

Note: The dam breach flooding information and inundation areas shown on this map are approximate and should be used only as a guideline for establishing evacuation zones. Actual flooding conditions may differ from those depicted on the map. The results of the maximum pool (water level at dam crest), rapid failure breach scenario is shown.

NOTES

Prepared by VTDEC Dam Safety Program using DSS-Wise Lite, November 2020. Represents maximum pool, rapid failure estimated flood inundation map.

346.0 0 173.00 346.0 Feet

WGS_1984_Web_Mercator_Auxiliary_Sphere
© Vermont Agency of Natural Resources

1" = 173 Ft. 1cm = 21 Meters
THIS MAP IS NOT TO BE USED FOR NAVIGATION

DISCLAIMER: This map is for general reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable. ANR and the State of Vermont make no representations of any kind, including but not limited to, the warranties of merchantability, or fitness for a particular use, nor are any such warranties to be implied with respect to the data on this map.



Attachment B:



DSS-WISE™ Lite Flood Simulation Report

Run #2

Hands Mill Dam

NAXXXXX

November 16, 2020

Contact Information:

DSS-WISE™ Lite modeling questions: admin@dsswiseweb.ncche.olemiss.edu

Table of Contents

1.0 Overview	1
2.0 Modeling Parameters and Conditions	3
2.1 Project Information	3
2.2 Simulation Parameters	3
2.3 Impounding Structure(s) Characteristics	3
2.4 Bridge(s) to be Removed	3
2.5 Reservoir Characteristics	3
2.6 Failure Conditions	4
3.0 Automated Data Preparation and Job Flow Summary	5
3.1 Job Flow Summary	5
3.2 Reservoir Bathymetry and Filling	6
3.3 Data Sources	7
3.4 Digital Elevation Model	8
3.5 Reservoir Boundary and Breaching Structure	9
3.6 Reservoir Initial Depth Profile	10
3.7 Land Use/Land Cover	11
4.0 Simulation Results	12
4.1 Simulation Summary	12
4.2 Land Use and Manning's Roughness Coefficient for Inundated Area	13
4.3 Coverage and Sources of DEM Raster Datasets	14
4.4 Maximum Flood Depth	16
4.5 Flood Arrival Time	17
4.6 Computed Breach Hydrograph through the Breaching Structure	18
4.7 Observation Line Hydrograph(s)	19
4.8 Reservoir Time History	19
4.9 Downloading Simulation Results	21

1.0 Overview

The Decision Support System for Water Infrastructure Security (DSS-WISE™) is an integrated software package combining 2D numerical flood modeling capabilities with a series of GIS-based decision support tools. It was developed by the National Center for Computational Hydroscience and Engineering (NCCHE) at the University of Mississippi and was initiated by the US Department of Homeland Security (DHS) Science and Technology Directorate through the Southeast Region Research Initiative (SERRI) Program.

A simplified, and fully automated, version of the DSS-WISE™ software suite (DSS-WISE™ Lite Ver 1.0) was developed on behalf of the US Army Corps of Engineers (USACE) Critical Infrastructure Protection and Resilience (CIPR) Program and the DHS Office of Infrastructure Protection. This simplified dam break flood modeling capability was available to interested parties through the Dams Sector Analysis Tool (DSAT) secure web portal until November 2014. An updated version with more features was developed on behalf of Federal Emergency Management (FEMA) and is available at dsswiseweb.ncche.olemiss.edu.

The DSS-WISE™ Lite software suite, running on NCCHE servers, automatically processes input files for dam-break modeling scenarios submitted by an user. DSS-WISE™ Lite further simplifies simulations by making several general overarching assumptions in an effort to streamline data preparation and computations.

The results produced by this simplified dam-break flood simulation tool represent a rough approximation. They are not intended to replace more detailed flood inundation modeling and mapping products or capabilities developed by hydraulic and hydrologic engineers and GIS professionals.

The user is, therefore, warned that professional engineering judgment should be used in the interpolation of the results generated by this simplified and automated dam-break flood analysis.

To learn more about DSS-WISE™ and DSS-WISE™ Lite visit us at:
<https://dsswiseweb.ncche.olemiss.edu>

Disclaimer

The National Center for Computational Hydroscience and Engineering (NCCHE), The University of Mississippi, makes no representations pertaining to the suitability of the results provided herein for any purpose whatsoever. All content contained herein is provided "as is" and is not presented with any warranty of any form. NCCHE hereby disclaims all conditions and warranties in regard to the content, including but not limited to any and all conditions of merchantability and implied warranties, suitability for a particular purpose or purposes, non-infringement and title. In no event shall NCCHE be liable for any indirect, special, consequential or exemplary damages or any damages whatsoever, including but not limited to the loss of data, use or profits, without regard to the form of any action, including but not limited to negligence or other tortious actions that arise out of or in connection with the copying, display or use of the content provided herein.

Elevation Datum

All reported elevations use the North American Vertical Datum of 1988 (NAVD 88).

2.0 Modeling Parameters and Conditions

2.1 Project Information

Project Name:	Hands Mill Dam
Scenario Name:	Run #2
NIDID:	NAXXXXX
Scenario Description:	Sudden Failure at maximum pool with 5.5 feet between normal and max pools.
User e-mail:	katherine.king@partner.vermont.gov

2.2 Simulation Parameters

Simulation distance requested (miles):	5
Simulation cell size requested (ft):	15.0
Simulation duration requested (days):	2

2.3 Impounding Structure(s) Characteristics

Number of Structures: 1

Structure Name:	Structure 1
Structure Type:	Embankment
Hydraulic Height (ft):	20.0
Crest Elevation (ft):	1292.5
Length (ft):	495.0

2.4 Bridge(s) to be Removed

Number of Bridges: 0

2.5 Reservoir Characteristics

Selected Reservoir Point (Latitude/Longitude):	44.1054194801/-72.4297714233
--	------------------------------

Pool Elevation @ Max Storage (ft):	1292.5
Maximum Storage Volume (ac-ft):	18.1
Pool Elevation @ Normal Storage (ft):	1287.0
Normal Storage Volume (ac-ft):	11.2

2.6 Failure Conditions

Structure Name:	Structure 1
Structure Type:	Embankment
Failure Mode:	Total Dam Breach
Breach Type:	Embankment
Pool Elevation @ Failure (ft):	1292.5
Storage Volume @ Failure (ac-ft):	18.1
Breach Location (Latitude/Longitude):	44.105464754/-72.4298403157

3.0 Automated Data Preparation and Job Flow Summary

3.1 Job Flow Summary

1. Prepare Digital Elevation Model (DEM) and Land Use/Land Cover (LULC) tiles for the Area of Interest (AOI) based on requested cellsize and maximum downstream distance.
2. Burn U.S. Army Corps of Engineers (USACE) levee lines into DEM for the AOI.
3. Assign Manning's coefficients based on LULC classifications.
4. Validate user provided simulation input parameters.
5. Remove user identified bridges from the DEM.
6. Estimate reservoir bathymetry.
7. Extend impounding structures if the specified reservoir level cannot be contained.
8. Fill reservoir to specified failure elevation.
9. Prepare boundary condition and all input data for simulation.

3.2 Reservoir Bathymetry and Filling




Figure 1. Stage-Volume Curve for Reservoir

Prototype: Theoretical cubic Hermite spline curve generated from user-provided reservoir elevation and volume information.

Imposed: Measured from reservoir bathymetry after filling to the failure elevation.

The reservoir water surface was detected to be in the DEM, so bathymetry estimation was performed using the prototype stage-volume curve shown above.

User-given Storage Volume at Failure (ac-ft): 18.1

Imposed Storage Volume at Failure (ac-ft): 18.1

After filling to the failure elevation, the imposed reservoir volume matched 100.0% of the prototype volume.

3.3 Data Sources

1. Digital Elevation Models

Sources: USGS 2018 National Elevation Dataset, NOAA, DEM provided by group.

Resolutions: 2, 1, 1/3, 1/9, 0.15 arc-seconds, 1 meter, and 10 feet based on availability

Vertical Datum: NAVD88

Horizontal Datum: NAD83

2. National Land Use/Land Cover Data

Source: USGS 2016 National Land Cover Database

Resolution: 30 m

3. National Levee Database

Source: USACE

3.4 Digital Elevation Model




Image Dimensions: N-S: 3.327 miles E-W: 0.702 miles
Figure 2. Map of Digital Elevation Model with Levees for AOI.

3.5 Reservoir Boundary and Breaching Structure





Image Dimensions: N-S: 0.077 miles E-W: 0.145 miles
Figure 3. Map of Reservoir Boundary and Breached Structure.

3.6 Reservoir Initial Depth Profile



3.7 Land Use/Land Cover



Image Dimensions: N-S: 3.327 miles E-W: 0.702 miles






















Figure 5. Map of Land Use for AOI.

4.0 Simulation Results

4.1 Simulation Summary

Simulation Request Received:	06:23 AM CST (11/16/2020)
Simulation Start Time:	06:24 AM CST (11/16/2020)
Simulation End Time:	06:26 AM CST (11/16/2020)
DEM resolution used for simulation (ft):	15.0
DEM resolution requested (ft):	15.0
Final distance reached downstream (miles):	3.3
Maximum downstream distance requested (miles):	5
Elapsed simulation time after breach initiation (hrs):	22.0
Remaining reservoir volume at termination (%):	1.155
Termination condition:	Water stopped spreading.

4.2 Land Use and Manning's Roughness Coefficient for Inundated Area

Land Use Description	% of Inundated Area	n-Value($m^{-1/3}s$)	Code	Color
Hay/Pasture	40.42	0.0350	81	
Woody Wetlands	18.57	0.1500	90	
Evergreen Forest *	12.41	0.1000	42	
Mixed Forest *	8.16	0.1200	43	
Developed, Low Intensity	7.12	0.0678	22	
Developed, Open Space	4.45	0.0404	21	
Developed, Medium Intensity	3.54	0.0678	23	
Deciduous Forest *	3.10	0.1000	41	
Emergent Herbaceous Wetlands	1.91	0.1825	95	
Barren Land	0.26	0.0113	31	
Developed, High Intensity	0.03	0.0404	24	
unclassified	0.00	0.0350	0	
Open Water	0.00	0.0330	11	
Perennial Snow/Ice	0.00	0.0100	12	
Dwarf Scrub *	0.00	0.0350	51	
Shrub/Scrub	0.00	0.0400	52	
Grassland/Herbaceous	0.00	0.0400	71	
Sedge/Herbaceous *	0.00	0.0350	72	
Lichens *	0.00	0.0350	73	
Moss *	0.00	0.0350	74	
Cultivated Crops	0.00	0.0700	82	

Note: * indicates a n-value estimated by NCCHE. Other values are taken from literature.

4.3 Coverage and Sources of DEM Raster Datasets







Figure 6. Coverage of DEM Raster Datasets in the Inundation Area.

DEM Source	Source Resolution	Source Dataset	Color
USGS	1 arc-second	usgs_1as	
USGS	1/3 arc-seconds	usgs_13as	
USGS	1 meter	usgs_utm_z18_1m	

Note: The DEM for this job was created from the source DEM raster datasets listed above. These DEM raster datasets were resampled and reprojected to the user defined cell size and UTM zone, respectively. Resampled and projected DEM raster datasets were then stacked in the order specific to the group under which this simulation was submitted.

4.4 Maximum Flood Depth





Image Dimensions: N-S: 3.310 miles E-W: 0.713 miles

Figure 7. Maximum Flood Depth Map.

4.5 Flood Arrival Time

Flood arrival time is measured from the beginning of the simulation.



4.6 Computed Breach Hydrograph through the Breaching Structure

The positive discharges (Q^+) are measured in the positive direction with respect to each observation line.




Figure 9. Breach Discharge Measured at: Structure 1.

4.7 Observation Line Hydrograph(s)

The positive discharges (Q^+) are measured in the positive direction with respect to each observation line.

No observation lines were defined.

4.8 Reservoir Time History

The reservoir water surface elevation as a function of time was computed by summing the water depth and bed elevation at a regular interval at the user-specified reservoir point.




Figure 10. Reservoir Water Surface Elevation.

The reservoir volume as a function of time was computed by the following formula:

$V_t = V_{init} - V_{net}$, where V_t is the reservoir volume at a given time, V_{init} is the reservoir's initial imposed volume, and V_{net} is the net volume that has crossed downstream across any part of the breaching structure's centerline up to that point. Since this only considers water which has completely exited the breach, it should be taken as an approximation.




Figure 11. Reservoir Volume.

4.9 Downloading Simulation Results

The simulation results can be accessed at the following web address:

<https://dsswiseweb.ncche.olemiss.edu/download>

Job ID: 34459

Attachment C:



FEMA

DSS-WISE™ HCOM HUMAN CONSEQUENCE REPORT

Hands Mill Dam

Run #2

NAXXXXX

November 16, 2020

DSS-WISE Lite Simulation ID: 34459



FOR OFFICIAL USE ONLY

Disclaimer

The National Center for Computational Hydroscience and Engineering (NCCHE), at the University of Mississippi, makes no representations pertaining to the suitability of the results provided herein for any purpose whatsoever. All content contained herein is provided “as is” and is not presented with any warranty of any form. NCCHE hereby disclaims all conditions and warranties in regard to the content, including but not limited to any and all conditions of merchantability and implied warranties, suitability for a particular purpose or purposes, non-infringement and title. In no event shall NCCHE be liable for any indirect, special, consequential or exemplary damages or any damages whatsoever, including but not limited to the loss of data, use or profits, without regard to the form of any action, including but not limited to negligence or other tortious actions that arise out of or in connection with the copying, display or use of the content provided herein.

Table of Contents

List of Figures	iv
List of Tables	v
List of Maps	vi
1.0 Overview	3
2.0 List of Abbreviations	4
3.0 HCOM DATA SETS	5
3.1 DSS-WISE Lite Results Files	5
3.2 Population Data Sets Used by DSS-WISE HCOM	5
4.0 FLOOD HAZARD MAPPING	7
4.1 Potential Flood Hazard for Humans Caught Outdoors	7
4.2 Flood Hazard for Humans Caught Indoors	10
5.0 MAPPING POTENTIALLY LETHAL FLOOD ZONES (PLFZs) FOR CHILDREN AND ADULTS	11
6.0 POPULATION AT RISK (PAR) ANALYSIS	12
6.1 PAR Analysis Using Census Block Population Data	12
6.2 PAR Analysis Using LandScan USA Gridded Population Data	16
7.0 RESULTS FILES GENERATED BY DSS-WISE HCOM	17
8.0 REFERENCES	19

List of Figures

Figure 1. Evolution of total inundated area as a function of time. 1

Figure 2. Evolution of nighttime PAR as a function of time. 2

Figure 3. Evolution of daytime PAR as a function of time. 2

List of Tables

Table 1. DSS-WISE Lite results files used by DSS-WISE HCOM. 5

Table 2. Potential flood hazard levels for humans caught outdoors by the flood (adapted from Cox et al. 2010). 9

Table 3. Potential flood hazard levels for humans caught indoors based on the BC Hydro LSM Building Stability Criteria..... 10

Table 4. Definition of potentially lethal flood zones (PLFZs) for different categories (Feinberg, 2017). 11

Table 5. Attributes of the census block polygons in the shapefile and the corresponding columns in the worksheet “CensusBlock_Analysis” of the MS Excel file accompanying the present report. 12

Table 6. List of results files generated by DSS-WISE HCOM..... 17

List of Maps

Map 01: Flood Maximum Depth..... 20

Map 02: Flood Arrival Time..... 21

Map 03: Flood Maximum Velocity..... 22

Map 04: Flood Maximum DV..... 23

Map 05: Flood Maximum DV Arrival Time..... 24

Map 06: Census Blocks: Population Count..... 25

Map 07: Nighttime Population Density..... 26

Map 08: Daytime Population Density..... 27

Map 09: Potential Flood Hazard Level for People Outdoors..... 28

Map 10: Potential Flood Hazard Level for People Indoors..... 29

Map 11: Potentially Lethal Flood Zones (PLFZ)..... 30

EXECUTIVE SUMMARY

This document reports the human consequences assessment for the DSS-WISE Lite simulation ID: **34459**

INUNDATION EXTENT

Total inundated area (acres)(see [figure 1](#)): 63.44




Figure 1. Evolution of total inundated area as a function of time.

ANALYSIS BASED ON CENSUS BLOCK DATA

Population in completely or partially inundated census blocks:	301
Housings in completely or partially inundated census blocks:	130
Number of states in inundated area:	1
Number of counties in inundated area:	2
Number of census blocks in inundated area:	20

ANALYSIS BASED ON GRIDDED LANDSCAN USA DATA

Total Nighttime PAR in inundated area (see figure 2):	40
Total Daytime PAR in inundated area (see figure 3):	94




Figure 2. Evolution of nighttime PAR as a function of time.




Figure 3. Evolution of daytime PAR as a function of time.

1.0 Overview

This report is produced DSS-WISE HCOM, which is part of the DSS-WISE Web system developed by the National Center for Computational Hydroscience and Engineering, at the University of Mississippi. Funding for DSS-WISE HCOM was provided by the U.S. Federal Emergency Management Agency (FEMA) through a contract with Argonne National Laboratory (ANL).

The results provided to the user by DSS-WISE HCOM include the following:

- the present report,
- a Microsoft Excel file containing data, results and plots, and
- a series of geospatial results files (in the form of polygon shapefiles).

These files can be used for further analysis and decision making for preparedness or during the response to an emergency. The files can also be used for hazard classification, risk prioritization preparing Emergency Actions Plans (EAPs).

DSS-WISE HCOM interfaces two-dimensional flood simulation results provided by DSS-WISE Lite with the population data provided by the U.S. Census Bureau and LandScan USA.

Please send any questions or suggestions to
admin@dsswiseweb.ncche.olemiss.edu

2.0 List of Abbreviations

ft	feet
hrs	hours
ft^2/s	Unit discharge, feet-squared per second
m^2/s	Unit discharge, meters squared per second
ft/s	feet per second
$ft.lb.$	foot-pounds
$m.kg.$	Meter-kilograms
D_{max}	Maximum depth
DV	Depth times velocity, unit discharge
DV_{max}	Maximum depth times velocity, maximum unit discharge
q_{max}	Maximum unit discharge, also called DV_{max}
DSS-WISE	Decision Support System for Water Infrastructural Security
DSS-WISE Web	Decision Support System for Water Infrastructural Security Web, the web-based system housing DSS-WISE Lite and other tools
DSS-WISE Lite	Decision Support System for Water Infrastructural Security Lite, the web-based version of DSS-WISE dam-break and flood modeling software
HCOM	Human Consequence Module
NCCHE	National Center for Computational Hydroscience and Engineering
PLFZ	Potentially Lethal Flood Zones
PAR	Population At Risk
EAP	Emergency Action Plan
NIDID	National Inventory of Dams (NID) Identifier
USCB	United States Census Bureau, or officially the Bureau of the Census
FEMA	Federal Emergency Management Agency
ANL	Argonne National Laboratory
ORNL	Oak Ridge National Laboratory
ESRI	Environmental Systems Research Institute
LSM	Life Safety Model

3.0 HCOM DATA SETS

3.1 DSS-WISE Lite Results Files

The human consequence analysis in this report are provided by DSS-WISE HCOM based on the raster results files for the following dam-break flood modeling simulation with DSS-WISE Lite:

DSS-WISE Lite simulation ID:	34459
Project Name:	Hands Mill Dam
Scenario Name:	Run #2
NIDID:	NAXXXXX
Scenario Description:	Sudden Failure at maximum pool with 5.5 feet between normal and max pools.
Simulation distance requested (<i>miles</i>):	5.0
Simulation cell size (<i>ft</i>):	15.0
Simulation duration requested (<i>days</i>):	2.0

Table 1. DSS-WISE Lite results files used by DSS-WISE HCOM.

File Name	Type	Units	Description
34459_Hmax_ft_upto_final.tif	Raster	<i>ft</i>	Maximum flood depth
34459_Arrival_Time_hr_upto_final.tif	Raster	<i>hrs</i>	Flood Arrival Time
34459_Vmax_ftps_upto_final.tif	Raster	<i>ft/s</i>	Maximum flood velocity
34459_DVmax_ft2ps_upto_final.tif	Raster	<i>ft²/s</i>	Magnitude of the maximum specific discharge
34459_DVmax_ft2ps_upto_final.tifArrivalTime	Raster	<i>hrs</i>	Arrival time of the maximum value of specific discharge

3.2 Population Data Sets Used by DSS-WISE HCOM

DSS-WISE HCOM uses two different sets of population data to estimate the Population at Risk (PAR) potentially affected by the flood:

1. 2010 Census Block data provided by the United States Census Bureau (USCB), which is federal government agency in charge of producing data about the people and economy of the U.S. A census block is the smallest geographic unit for which USCB collects data from all the houses in the unit (rather than a sample of houses). Census Blocks are bounded by visible features such as streets, roads, streams and nonvisible features such as property lines and limits of city, township, school district, and counties, etc. They are defined as polygons in a shapefile covering the entire territory of the U.S. including Puerto Rico and the Island areas. The attributes of the census block polygons include 2010 Census Housing Unit Count and 2010 Census Population Count. The latter should be considered as 2010 nighttime population data.
2. LandScan USA gridded population data developed and maintained by the Oak Ridge National Laboratory (ORNL) located in Oak Ridge, TN. LandScan USA (<https://landscan.ornl.gov/>) is a collection of gridded nighttime and daytime population datasets developed by the Oak Ridge National Laboratory (ORNL), Department of Energy. These gridded population datasets are available as raster files with a resolution of 3 arc-second (90m or 295.28ft.). They were developed by combining satellite remote sensing data, geospatial infrastructure datasets, and demographic data from USCB. Researchers at ORNL used “Intelligent” dasymetric modeling method to assign the population counts to the grid cells (Dobson et al. 2000 and Bhaduri et al. 2007) by defining a habitability index and by maintaining the total count of cells in a census block to be equal to the total population of the census block. The LandScan USA datasets used in this report are projections for 2016 (McKee et al. 2014). Daytime data is generated using specially developed techniques for population dynamics (Bhaduri 2007).

Detailed explanations on the methodologies used by DSS-WISE HCOM are provided in the technical manual, which can be downloaded from documentation page of the DSS-WISE Web website.

4.0 FLOOD HAZARD MAPPING

Flood-hazard mapping consists of partitioning the inundation extent into zones of pre-defined potential danger classes for humans. The resulting map is an ESRI shapefile of polygon type. The polygons correspond to different levels of potential danger for humans caught outdoors and indoors.

The potential danger classes are identified based on the ranges of the value of the maximum specific discharge, DV_{max} . The ranges of $q_{max} \equiv DV_{max}$ values are different for persons caught outdoors or indoors.

4.1 Potential Flood Hazard for Humans Caught Outdoors

For humans caught outdoors, the ranges of DV_{max} corresponding to five potential hazard (or danger) levels identified by different color codes are summarized in [Table 2](#), which is adapted from [Cox et al. \(2010\)](#). The potential hazard levels are:

1. “Very Low Hazard: Shallow flow or deep standing water”;
2. “Low Hazard: Dangerous to children”;
3. “Moderate Hazard: Dangerous to some adults”;
4. “Significant Hazard: Dangerous to most adults”; and
5. “Extreme Hazard: Dangerous to all”.

The three rightmost columns of [Table 2](#) correspond to the interpretation of five potential hazard levels by [Cox et al. \(2010\)](#) for three population categories defined by an index value corresponding to the product of height (H) and mass (M) of the individual as listed at the bottom of [Table 2](#).

1. “Infants and small Children”,
2. “Children”, and
3. “Adults”;

The five polygons corresponding to the five potential flood hazard levels for people caught outdoors as listed in [Table 2](#) are provided as an ESRI shapefile of polygon type.

Cox et al. (2010) notes that the limits of DV_{max} in Table 2 correspond loosely to the loss of stability of different population categories. However, it is important to note that the ranges of DV_{max} given in Table 2 should not be considered as strict limits. Various other factors may influence the stability of individuals caught outdoors by the flood, such as:

- Bottom conditions (uneven surface, slippery surface, visible or invisible obstacles);
- Flow conditions (floating debris, low temperature, poor visibility, unsteady flow and flow aeration);
- Human subject (standing or moving, experience and training, clothing and footwear, physical attributes, such as height, mass and muscular development, disabilities, and psychological factors); and
- Other factors (strong wind, poor lighting, feeling unsafe or complete loss of footing).

Table 2. Potential flood hazard levels for humans caught outdoors by the flood (adapted from Cox et al. 2010).

DV_{max}				Potential Hazard Category	Explanation		
m^2/s		ft^2/s			Adults	Children	Infants, Small Children and Frail/Older Persons
from	to	from	to				
0.0	0.4	0.0	4.3	HZ01 Very Low Hazard: Shallow flow or deep standing water	Low Hazard	Low Hazard	Extreme Hazard Dangerous to all Infants, small Children and Frail/Older Persons
0.4	0.6	4.3	6.5	HZ02 Low Hazard: Dangerous to Children		Significant Hazard; Dangerous to most Children	
0.6	0.8 ⁽²⁾	6.5	8.6 ⁽²⁾	HZ03 Moderate Hazard: Dangerous to some adults	Moderate Hazard: Dangerous to some adults		
0.8	1.2 ⁽³⁾	8.6	13 ⁽³⁾	HZ04 Significant Hazard: Dangerous to most adults	Significant Hazard: Dangerous to most adults	Extreme Hazard: Dangerous to all children	
1.2 ⁽³⁾		13 ⁽³⁾		HZ05 Extreme Hazard: Dangerous to all	Extreme Hazard: Dangerous to all		
1) Small children, children and adult categories are defined based on $height(H) \times mass(M)$ Small children: $H \times M \leq 25l(m.kg.)$ $H \times M \leq 181(ft.lb.)$ Children: $25 < H \times M(m.kg.) \leq 50$ $181 < H \times M(m.kg.) \leq 362$ Adult: $50 < H \times M(m.kg.)$ $362 < H \times M(ft.lb.)$							
2) Recommended upper limit of tolerable working flow regime for trained safety workers or experience and well-equipped persons							
3) Above this value, the hazard is extreme according to majority of the past studies.							

Results file package of DSS-WISE HCOM contains an ESRI shapefile of polygon type containing up to five polygons (see [Table 6](#)) corresponding to the five potential flood hazard levels for humans caught outdoors by the flood, which are listed in [Table 2](#). For convenience, [Map 09](#) of this report shows the inundation extent colored by the five potential flood hazard levels listed in [Table 2](#).

4.2 Flood Hazard for Humans Caught Indoors

For people caught indoors by the flood, it is assumed that the potential danger is associated with the collapses of the building (see [FEMA 2011, p.43](#)). This implicitly assumes that the people indoors are in potential danger of loss of life if the building collapses due to inundation by floodwaters.

[Table 3](#) list the DV_{max} values for the potential collapse of different types of buildings, which are taken from the technical report of the Life Safety Model (LSM) developed by British Columbia Hydro ([BCH 2006](#)).

Table 3. Potential flood hazard levels for humans caught indoors based on the BC Hydro LSM Building Stability Criteria.

DV_{max}		Color Code	Building Type
(m^2/s)	(ft^2/s)		
≥ 5	≥ 54		HZ06: Poorly constructed building
≥ 10	≥ 108		HZ07: Well-built timber building
≥ 15	≥ 161		HZ08: Well-built masonry building
≥ 20	≥ 215		HZ09: Concrete building
≥ 35	≥ 377		HZ10: Large concrete building

Results file package of DSS-WISE HCOM contains an ESRI shapefile of polygon containing up to five stacked polygons (see [Table 6](#)) corresponding to the five potential flood hazard levels for humans caught indoors by the flood, which are listed in [Table 3](#). For convenience, [Map 10](#) of this report shows the inundation extent colored by the five potential flood hazard levels listed in [Table 3](#).

5.0 MAPPING POTENTIALLY LETHAL FLOOD ZONES (PLFZs) FOR CHILDREN AND ADULTS

The mapping of potentially lethal flood zones (PLFZs) for humans consists of partitioning the inundation extent into zones of predefined potential lethality classes for humans. The resulting map is an ESRI shapefile of polygon type for each category. The polygons correspond to different levels of potential lethality that are defined based on the maximum depth, D_{max} , and maximum specific discharge, DV_{max} . The PLFZs for different categories of people caught outdoors, cars, mobile homes and typical residential structures are listed in [Table 4](#) ([Feinberg, 2017](#)).

Table 4. Definition of potentially lethal flood zones (PLFZs) for different categories ([Feinberg, 2017](#)).

Category	Color Code	D_{max} (<i>ft.</i>)		DV_{max} (<i>ft</i> ² / <i>s</i>)
Children caught outdoors (tent camping, fishing, hiking, etc.)		≥ 2	or	≥ 5.4
Adults caught outdoors (tent camping, fishing, hiking, etc.)		≥ 4	or	≥ 6.5
Motor vehicle (compact car) floating	None	≥ 1	or	≥ 4.3
Motor vehicle (compact car) sliding/toppling	None			≥ 5.4
Mobile homes	None	≥ 2	or	≥ 30
Typical residential structures	None	≥ 4	or	≥ 75

Results file package of DSS-WISE HCOM contains an ESRI shapefile of polygon type containing two stacked polygons corresponding to the first two categories in [Table 4](#). These two polygons were extracted using the maximum flow depth and maximum specific discharge files provided in the results package of DSS-WISE Lite simulation (see [Table 6](#)). For convenience, [Map 11](#) of this report shows the extents of these two PLFZ polygons.

The polygons for the remaining PLFZ zones can also be extracted from the D_{max} and DV_{max} raster files using a suitable GIS software.

6.0 POPULATION AT RISK (PAR) ANALYSIS

The population at risk (PAR) analysis aims to provide an estimate of the number of people that will be potentially affected by the propagation of the dam-break flood. DSS-WISE HCOM provides two different types of PAR analysis based on the two different population data sets that are available (see [Section 3.2](#)).

6.1 PAR Analysis Using Census Block Population Data

The results of the PAR analysis using 2010 census block population are given in two different forms:

- The list of the census blocks that are inundated (completely or partially) by the dam-break flood is provided in the “CensusBlock_Analysis” worksheet of the MS Excel file accompanying the present report.
- The polygons of the census blocks that are inundated (completely or partially) by the dam-break flood are provided in a shapefile accompanying the present report. The attributes of the census block polygons are the same as the data columns in the MS Excel file.

The polygons of census blocks included in the inundation extent (completely or partially) are provided as an ESRI shapefile (see [Table 6](#)) in the results package of DSS-WISE HCOM. The worksheet “CensusBlock_Analysis” lists all the census blocks and their attributes, which include various data extracted by DSS-WISE HCOM. The attributes of the census-block polygons are the same as the columns in the worksheet “CensusBlock_Analysis” of the MS Excel file accompanying the present report.

These attributes of the census blocks are listed and explained in [Table 5](#). [Map 06](#) in this report shows the census block polygon outlines overlaid on the flood extent.

Table 5. Attributes of the census block polygons in the shapefile and the corresponding columns in the worksheet “CensusBlock_Analysis” of the MS Excel file accompanying the present report.

ExcelFile		Shapefile	Unit	Description
Col	Title	Attributes		
A	State Name	STATE_NAME		Abbreviation of the state name
B	County Name	CNTY_NAME		County Name

C	State FIPS CODE	STATEFP10		2010 Census state FIPS code
D	County FIPS CODE	COUNTYFP10		2010 Census county FIPS code
E	Tract CODE	TRACTCE10		2010 Census tract code
F	Tabulation Block Number	BLOCKCE		2010 Census tabulation block number
G	Block ID Number	BLOCKID10		Census block identifier; A concatenation of 2010 Census state FIPS code, 2010 Census county FIPS code, 2010 Census tract code , and 2010 Census block number
H	Partial Block Indicator	PARTFLG		<i>Y</i> = partial block <i>N</i> = whole block
I	Total Number of Housing	HOUSING10	<i>Count</i>	2010 Census Housing Unit Count
J	Total Number of Population	POP10	<i>Count</i>	2010 Census Population Count
K	Total Area	AREATOT	<i>Acres</i>	Total area of the census block. This information is extracted from the geometry of the census block
L	Inundated Area	AREAINUND	<i>Acres</i>	Area of the census block inundated. This information is extracted by intersecting the inundation extent with the census block.
M	Percent Area Inundated	AINUND_PCT	%	This quantity is calculated in the MS Excel spreadsheet by the dividing the AREAINUND (column L) by the AREATOT (column K).

N	Flood Arrival Time (Avg)	FLDAT_AVG	<i>hrs</i>	This quantity is extracted from the arrival time raster. It corresponds to the average value of the arrival times of all computational cells within the extent of the census block.
O	Flood Arrival Time (Min)	FLDAT_MIN	<i>hrs</i>	This quantity is extracted from the arrival time raster. It corresponds to the minimum value of the arrival times of all computational cells within the extent of the census block.
P	Flood Arrival Time (Max)	FLDAT_MAX	<i>hrs</i>	This quantity is extracted from the arrival time raster. It corresponds to the maximum value of the arrival times of all computational cells within the extent of the census block.
Q	Flood Maximum Depth (Avg)	HMAX_AVG	<i>ft</i>	This quantity is extracted from the maximum flood depth raster. It corresponds to the average value of the maximum flood depths of all computational cells within the extent of the census block.
R	Flood Maximum Depth (Min)	HMAX_MIN	<i>ft</i>	This quantity is extracted from the maximum flood depth raster. It corresponds to the minimum value of the maximum flood depths of all computational cells within the extent of the census block.
S	Flood Maximum Depth (Max)	HMAX_MAX	<i>ft</i>	This quantity is extracted from the maximum flood depth raster. It corresponds to the maximum value of the maximum flood depth of all computational cells within the extent of the census block.

T	Flood Maximum DV Arrival Time (Avg)	DVMAXATAVG	<i>hrs</i>	This quantity is extracted from the arrival time of maximum specific discharge raster. It corresponds to the average value of the maximum specific discharge arrival times of all computational cells within the extent of the census block.
U	Flood Maximum DV Arrival Time (Min)	DVMAXATMIN	<i>hrs</i>	This quantity is extracted from the arrival time of maximum specific discharge raster. It corresponds to the minimum value of the maximum specific discharge arrival times of all the computational cells within the extent of the census block.
V	Flood Maximum DV Arrival Time (Max)	DVMAXATMAX	<i>hrs</i>	This quantity is extracted from the arrival time of maximum specific discharge raster. It corresponds to the maximum value of the maximum specific discharge arrival times of all the computational cells within the extent of the census block.
W	Flood Maximum DV (Avg)	DVMAX_AVG	ft^2/s	This quantity is extracted from the maximum specific discharge raster. It corresponds to the average value of the maximum specific discharge of all the computational cells within the extent of the census block.
X	Flood Maximum DV (Min)	DVMAX_MIN	ft^2/s	This quantity is extracted from the maximum specific discharge raster. It corresponds to the minimum value of the maximum specific discharge of all the computational cells within the extent of the census block.

Y	Flood Maximum DV (Max)	DVMAX_MAX	ft^2/s	This quantity is extracted from the maximum specific discharge raster. It corresponds to the maximum value of the maximum specific discharge of all the computational cells within the extent of the census block.
---	------------------------------	-----------	----------	--

6.2 PAR Analysis Using LandScan USA Gridded Population Data

The PAR analysis using LandScan USA 3 arc-second gridded population data provides three sets of tabular results classified in up to 17 flood times and 10 flood hazard categories based on DV_{max} :

- Tabular summary of inundation areas as a function of flood time is presented in the worksheet “InundatedArea” of the MS Excel file accompanying the present report. The inundation area values are presented as a stacked column plot in the same worksheet.
- Tabular summary of nighttime PAR counts as a function of flood time is presented in the worksheet “Nighttime_PAR” of the MS Excel file accompanying the present report. The nighttime PAR counts are plotted as a stacked column plot in the same worksheet.
- Tabular summary of daytime PAR counts as a function of flood time is presented in the worksheet “Daytime_PAR” of the MS Excel file accompanying the present report. The tabular data is also plotted as a stacked column plot.

The nighttime and daytime PAR counts were obtained from nighttime and daytime population densities, which were extracted from LandScan USA following the methodologies described in the technical manual for DSS-WISE HCOM. [Map 07](#) and [Map 08](#) in this report show the nighttime and daytime population densities over the inundation area.

7.0 RESULTS FILES GENERATED BY DSS-WISE HCOM

All the results files generated by DSS-WISE HCOM are listed [Table 6](#).

Table 6. List of results files generated by DSS-WISE HCOM.

No	Name	Type	Description
1	34459_HCOM_Final_Report.pdf	PDF	The present report.
2	34459_HCOM_Analysis.xlsx	Ms Excel	Ms Excel file accompanying this report. It contains four worksheets: 1. InundatedArea 2. Nighttime_PAR 3. Daytime_PAR 4. CensusBlock_Analysis
3	34459_HCOM_Census_Block_polygons.shp	ESRI Shapefile	This ESRI shapefile of polygon type contains the polygons of the census blocks completely or partially included in the inundation extent. The attributes of the polygons are the same as the columns in the worksheet “CensusBlock_Analysis”. They are listed in Table 5 .
4	34459_HCOM_Outdoor_Hazard_Categories_polygons.shp	ESRI Shapefile	This ESRI shapefile of polygon type contains up to five polygons corresponding to the five potential flood hazard levels for humans caught outdoors by the flood as listed in Table 2 (Section 4.1)
5	34459_HCOM_Indoor_Hazard_Categories_polygons.shp	ESRI Shapefile	This ESRI shapefile of polygon type contains up to five polygons corresponding to the five potential flood hazard levels for humans caught indoors by the flood as listed in Table 3 (Section 4.2)

6	34459_HCOM_PLFZ_ polygons.shp	ESRI Shapefile	This ESRI shapefile of polygon type contains up to two stacked polygons corresponding to the PLFZ areas as listed in the first two rows of Table 4 .
7	34459_HCOM_NT_PopDensity_ persqmi_polygons.shp	ESRI Shapefile	This ESRI shapefile of polygons type contains polygon of nighttime population density per square mile extracted from LandScan USA data. This file should be treated as FOUO
8	34459_HCOM_DT_PopDensity_ persqmi_polygons.shp	ESRI Shapefile	This ESRI shapefile of polygons type contains polygon of daytime population density per square mile extracted from LandScan USA data. This file should be treated as FOUO

8.0 REFERENCES

BCH (2006). Life Safety Model System v1.0, Guidelines, Procedures, Calibration and Support Manual. Technical Report Engineering Report E310, British Columbia Hydro (BCH).

Bhaduri, B., Bright, E., Coleman, Ph., Urban, M.L. (2007). LandScan USA: a high-resolution geospatial and temporal modeling approach for population distribution and dynamics. *Geojournal* 69:103-117. DOI 10.1007/s10708-007-9105-9

Bhaduri, B. (2007). Workshop Presentation.
<https://www.csm.ornl.gov/workshops/RAMSworkshop07/presentation/bhaduri.ppt>

Cox, R.J., Yee, M. and Ball, J.E. (2004). Safety of People in Flooded Streets and Floodways. 8th National Conference on Hydraulics in Water Engineering, Gold Coast. The Institution of Engineers, Australia.

Cox, R.J., Shand, T.D., and Blacka, M.J. (2010). Australian Rainfall and Runof, Revision Project 10: Appropriate Criteria for People. AR&R Report Number P10/S1/006. Engineers Australia, Water Engineering. ISBN 978-085825-9454. <http://arr.ga.gov.au/revision-projects/project-list/projects/project-10>

Dobson, J.E., Bright, E.A., Coleman, Ph.R., Durfee, R.C., and Worley, B.A. (2000). LandScan: A Global Population Database for Estimating Populations at Risk. *Photogrammetric Engineering & Remote Sensing*, Vol. 66, NO. 7, pp. 849-857. https://www.asprs.org/wp-content/uploads/pers/2000journal/july/2000_jul_849-857.pdf

Feinberg, B. (2017). Using Potentially Lethal Flood Zones to Assess Downstream Impacts from Dam Failure. Presentation at National Dam Safety Training Seminar.


FEMA (2011). Estimating Loss of Life for Dam Failure Scenarios. Draft version.

McKee, J.J., Rose, A.N., Bright, E.A., Huynh, T., and Bhaduri, B.L. (2014). Locally adaptive, spatially explicit projection of US population for 2030 and 2050. *PNAS*, 112(5), 1344-1349. <http://www.pnas.org/content/pnas/112/5/1344.full.pdf>

Map 01: Flood Maximum Depth



Map 02: Flood Arrival Time




Map 03: Flood Maximum Velocity







Map 05: Flood Maximum DV Arrival Time




Map 06: Census Blocks: Population Count



Map 07: Nighttime Population Density




Map 08: Daytime Population Density




Map 09: Potential Flood Hazard Level for People Outdoors



Map 10: Potential Flood Hazard Level for People Indoors



Map 11: Potential Lethal Flood Zones (PLFZ)



Attachment 5: Town of Washington Local Hazard Mitigation Plan

**Town Of Washington, VT
Local Hazard Mitigation Plan
Created August 2013 – Adopted April 2014
Prepared by the Town of Washington and CVPRC**

1. Introduction	2
2. Purpose	2
3. Community Profile	2
4. Planning Process and Maintenance	4
4.1 Planning Process	4
4.2 Plan Maintenance	5
5. Community Vulnerability by Hazard	6
5.1 Hazard Identification.....	6
5.2 Worst Threat Hazards	8
Dam Failure	8
Flooding/Flash Flooding/Fluvial Erosion	9
Structure Fire	11
5.3 Moderate Threat Hazards	12
Tornado	12
6. Mitigation.....	13
6.1 Municipal Plan (2013) Goals and Policies that Support Local Hazard Mitigation.....	13
6.2 Proposed Hazard Mitigation Programs, Projects and Activities	15
Attachments.....	16
Areas of Local Concern Map	18
CERTIFICATE OF ADOPTION	19

1. Introduction

The impact of expected, but unpredictable natural and human-caused events can be reduced through community planning. The goal of this Local Hazard Mitigation Plan is to provide a local mitigation plan that makes the Town of Washington more disaster resistant.

Hazard mitigation is any sustained action that reduces or eliminates long-term risk to people and property from natural and human-caused hazards and their effects. Based on the results of previous Project Impact efforts, FEMA and State agencies have come to recognize that it is less expensive to prevent disasters than to repeatedly repair damage after a disaster has struck. This Plan recognizes that communities have opportunities to identify mitigation strategies and measures during all of the other phases of emergency management – preparedness, response, and recovery. Hazards cannot be eliminated, but it is possible to determine what the hazards are, where the hazards are most severe and identify local actions that can be taken to reduce the severity of the hazard.

Hazard mitigation strategies and measures alter the hazard by eliminating or reducing the frequency of occurrence, avert the hazard by redirecting the impact by means of a structure or land treatment, adapt to the hazard by modifying structures or standards, or avoid the hazard by preventing or limiting development.

This Washington Local Hazard Mitigation Plan will be submitted as a single jurisdiction plan and is the Town of Washington's first hazard mitigation planning effort. Washington has not previously been part of a multi-jurisdictional hazard mitigation planning process.

2. Purpose

The purpose of this Local Hazard Mitigation Plan is to assist the Town of Washington in recognizing hazards facing the region and their community and identify strategies to begin reducing risks from acknowledged hazards. The long term and overall goal of this plan is to protect life and property from harm/damages caused by natural and man-made disasters.

3. Community Profile

The Town of Washington is 38.8 square miles and is located in the northwest quadrant of Orange County. It is bordered by Orange to the north, Corinth to the east, Chelsea to the south and Williamstown to the west. As stated in the *Washington Town Plan, 2013* ("municipal plan") Washington is "rugged and picturesque" and "hilly but not mountainous." It is about 84% forested, with only about 3% of its land area developed. Approximately 13% of Washington's land area is cropland, pasture, or open land. Wetlands and surface waters comprise less than one percent of the Town's total area. With about 1,400 feet of topographical relief, Washington is located at the headwaters of three watersheds: the Winooski, the Waits and the White River.

As stated in the Town Plan "Washington is one of the least populous and most rural towns in the Central Vermont Region." According to the 2010 U.S. Census, Washington has a total population of 1,039 people living in approximately 570 housing units. From 2000 to 2010 the

population had decreased by 2%. In 2010, about 15 % of residents were employed in town; Washington is primarily a bedroom community. Development in Washington is primarily limited rural residential. Washington adopted zoning in 2007 with two identifiable land use districts: a Village District and a Rural Residential District. Despite limitations of steep slopes and soils in the Rural Residential District, there are areas which are well suited for residential development, particularly along the roadways. It also has the land that is closest to the rapidly expanding Barre area. For this reason it is this district which has seen the most dramatic increase in housing starts over the past several years and where growth pressures will be most pronounced in coming years. At the time of writing this plan, no new commercial or residential developments were planned.

Vermont Route 110 is the principle vehicular transportation corridor through Washington and is the only paved road in town. The historic Village of Washington is located on Route 110 which is the hub of official activity.

The Green Mountain Power Corporation provides electrical service to residential and commercial development in the northern section of Washington, the remainder of the town is serviced by the Washington Electric Cooperative. A municipal water system provides water to 64 users and all other homes and businesses rely on individual or small-scale community wells and springs for their water supply and private waste water treatment systems. The State of Vermont now oversees all waste water permitting.

Washington does not have a local police department or a Town Constable. Washington has contracted with the Orange County Sheriff's Department located in Chelsea since 1996 for limited police protection. Residents can also call 911 in an emergency and the nearest State Police unit, K Troop Headquarters, located in Middlesex will respond.

Fire protection is provided by the Washington Volunteer Fire Department with 22 active members. The Department is a member of the Capital Fire Mutual Aid System. According to the *Town of Washington, Vermont Annual Report* Volunteer Fire Department responded to 42 calls during 2012. Washington also has a FAST Squad which responds to emergency medical situations in conjunction with the Barre Town Ambulance Service. The FAST Squad responded to a total of 63 calls during 2012 (calls from both the Towns of Orange and Washington).

Washington prepared a Rapid Response Plan early in 1999 that is updated annually, most recently on April 14th of 2013. Harry Roush is Washington's E.M. Coordinator. The Washington Village School, the Universalist Church (seasonal), the Baptist Church and the Town Offices are designated as emergency shelters. Other potential seasonal shelters include the town airport hangers.

The municipal plan, adopted in 2013, includes discussion, goals, and objectives in regards to *Physical Geography, Utilities, Facilities, and Services, and Transportation*. Washington does have zoning bylaws with two identifiable land use districts: a Village District and a Rural Residential District. No future large or small scale developments are currently planned.

4. Planning Process and Maintenance

4.1 Planning Process

The Central Vermont Regional Planning Commission (CVRPC) and Town Clerk, Carol Davis, coordinated the Washington Local Hazard Mitigation Plan process. A meeting was held in Washington on August 13, 2013 in order to gain an inventory of the town's vulnerability to hazards and its current and future mitigations programs, projects and activities. Input was received from:

- Scott Blanchard, Select Board
- Harry Roush, Emergency Manager
- Carol Davis, Town Clerk
- Maxine Durbrow, Emergency Services
- Robert Blanchard, Select Board
- Donald Milne, Select Board
- Kim McKee, CVRPC

The meeting indicated that the Town is most vulnerable to dam failure, flood/flash flood/fluvial erosion, structure fire and tornadoes. Washington is most focused on flooding hazards as these events are the most common and most destructive.

The draft plan was made available at the Washington Town Clerks office and notice posted at both the Town Clerks Office and Post Office for a two-week public comment period. Washington does not have a public web page. The notice of the draft update was also announced on the CVRPC blog and facebook page and made available for download. An announcement of the draft update was also emailed to emergency management directors in the surrounding towns of Williamstown, Orange, Corinth and Chelsea. No comments were received. Once the plan is conditionally approved by FEMA, the plan will go before the Select Board for adoption. During future updates, additional stakeholders who provide service to the jurisdiction and major business owners will be invited to the meetings. This Washington Local Hazard Mitigation Plan will be submitted as a single jurisdiction plan.

Existing Mitigation Programs, Projects and Activities

The ongoing or recently completed programs, projects and activities are listed by mitigation strategy and were reviewed for the development of the plan. The 2013 municipal plan, 2012 Town Report, CVRPC's past Regional Mitigation Plan, and Basic Emergency Operations Plan, and past newspaper articles were reviewed for pertinent information. The 2010 culvert and short structure inventory, Stream Geomorphic Assessments of the Stevens Branch Williamstown and Barre City Upstream of the Confluence with the Jail Branch, and Washington DFIRM maps were reviewed as well.

Community Preparedness Activities

- Rapid Response Plan/ Basic Emergency Operations Plan - 2013
- Capital Equipment Fund
- School Emergency Evacuation Plan

Insurance Programs

- Participation in NFIP

Land use Planning/Management

- Steep Slopes: Land development on slopes greater than 15% subject to Conditional Use Permit
- Protection of Rivers, Streams, and Bodies of Water: No land development shall occur within vegetated buffer strip of at least 50 ft from each bank of streams and rivers and from the shores of naturally occurring lakes and ponds except as approved by the Board of Adjustments.

Hazard Control & Protective Works of Infrastructure and Critical Facilities

- Maintenance Programs – bridge and culvert surveys
- Dry Hydrants - 8
- Clean Up Recovery Plan
- Capital Mutual Aid System

Public Awareness, Training & Education

- CPR Trainings
- School Fire Safety Program
- Fire safety educational programs
- First responder CPR & hazmat trainings

4.2 Plan Maintenance

The Washington Local Hazard Mitigation Plan will be updated and evaluated annually at a September Select Board meeting. Updates and evaluation by the Select Board will also occur within three months after every federal disaster declaration and as updates to town plan/zoning and river corridor plans come into effect. The plan will be reviewed by the Select Board, Town Clerk, Emergency Manager and public at the abovementioned September select board meeting. CVRPC will help with updates or if no funding is available, the Town Clerk and Emergency Manager will update the plan.

The process of evaluating and updating the plan will include continued public participation through public notices posted at the municipal offices, in the town newsletter and CVRPC newsletter and blog inviting the public to the scheduled Select Board (or specially scheduled) meeting. These efforts will be coordinated by the Town Clerk and Emergency Manager.

Updates may include changes in community mitigation strategies; new town bylaws, zoning and planning strategies; progress of implementation of initiatives and projects; effectiveness of

implemented projects or initiatives; and evaluation of challenges and opportunities. If new actions are identified in the 5 year interim period, the plan can be amended without formal re-adoption during regularly scheduled Select Board meetings.

Washington shall also consider incorporation of mitigation planning into their long term land use and development planning documents. It is recommended the Town reviews and incorporates elements of the Local Hazard Mitigation Plan when updating the Municipal Plan and during development of flood hazard bylaws. The incorporation of the Local Mitigation Plan into the municipal plan, possible future zoning regulations and additional flood hazard bylaws will also be considered after declared or local disasters. The Town shall also consider reviewing future Stevens Branch Corridor planning documents for ideas on future mitigation projects and hazard areas.

5. Community Vulnerability by Hazard

5.1 Hazard Identification

The following natural disasters were discussed and the worst threat hazards were identified based upon the likelihood of the event and the community's vulnerability to the event. Hazards not identified as a "worst threat" may still occur. Greater explanations and mitigation strategies of moderate threat hazards can be found in the State of Vermont's Hazard Mitigation Plan.

Hazard	Likelihood ¹	Community Vulnerability ²	Worst Threat
Landslide	Low	No	
Dam Failures	Med	Yes	✓
Drought	Low	No	
Earthquake	Low	No	
Extreme Cold/Winter Storm/Ice Storm	Med	No	
Flood/Flash Flood/Fluvial Erosion	Med	Yes	✓
High Wind	Low	No	
Ice Jam	Low	No	
Hurricane/Severe Storms	Low	No	
Structure Fire	High	Yes	✓
Tornado	Low	Yes	
Water Supply	Low	No	

¹ High likelihood of happening: Near 100% probability in the next year.

Medium likelihood of happening: 10% to 100% probability in the next year or at least once in the next 10 years.

Low likelihood of happening: 1% to 10% probability in the next year or at least once in the next 100 years.

² Does the hazard present the threat of disaster (Yes)? Or is it just a routine emergency (No)?

Contamination			
Wildfire/Forest Fire	Med	No	

The Town of Washington identified the following disasters as presenting the worst threat to the community:

- Dam Failure
- Flash Flood/Flooding
- Structure Fire

Moderate threat hazards include:

- Tornado

A discussion of each significant hazard is included in the proceeding subsections and a map identifying the location of each hazard is attached (See map titled *Areas of Local Concern*.) Future updates will include profiles on hazards that are “highly likely.” Each subsection includes a list of past occurrences based upon County-wide FEMA Disaster Declarations (DR-#) plus information from local records, a narrative description of the hazard and a hazard matrix containing the following overview information:

Hazard	Location	Vulnerability	Extent	Impact	Likelihood
Type of hazard	General areas within municipality which are vulnerable to the identified hazard.	Types of structures impacted	<p><u>Minimal:</u> Limited and scattered property damage; no damage to public infrastructure contained geographic area (i.e., 1 or 2 communities); essential services (utilities, hospitals, schools, etc.) not interrupted; no injuries or fatalities.</p> <p><u>Moderate:</u> Scattered major property damage (more than 50% destroyed); some minor infrastructure damage; wider geographic area (several communities) essential services are briefly interrupted; some injuries and/or fatalities.</p> <p><u>Severe:</u> Consistent major property damage; major damage to public</p>	Dollar value or percentage of damages.	<p><u>High:</u> 10% to 100% probability within the next year or at least once in the next 10 years.</p> <p><u>Medium:</u> less than 10% to 100% probability within the within the next year or less than once in the next 10 years.</p>

			infrastructure (up to several days for repairs); essential services are interrupted from several hours to several days; many injuries and fatalities.		
--	--	--	---	--	--

5.2 Worst Threat Hazards

Dam Failure

The Hands Mill Dam is located just south of the village area of Washington on the Jail House Branch of the Winooski River. Construction on the dam was completed in 1860. The dam is of earthen construction and is approximately 20 feet high and 325 wide. The pool behind the dam is approximately 2 acres and stores about 12 acre feet of water including sediments. At maximum capacity the dam stores approximately 16 acre feet of water. To date, there have been no breaches of the dam or any major failure event. However, the probability of the dam failing increases daily.

An inspection in June 2007 by the VT Department of Environmental Conservation revealed that the dam is in poor condition and continues to deteriorate. An inspection in 2001 also revealed the poor condition of the dam. The inspection reveals that the dam is considered a significant hazard, and sudden failure of the dam would cause probably loss of life and property damage. Recommendations from the report included – reconstruction of the dam; removal of the dam and restoration of the upstream channel; improved maintenance including clearing and brushing of the dam along the crest, upstream slope, downstream slope and ten feet below the dam; development of an emergency action plan to evacuate possible inundation areas and notify people downstream of the dam.

The Town of Washington would be most interested in removal of the dam, as it no longer serves a purpose. Alteration or reconstruction of the dam would require prior approval from the VT DEC as the dam impounds more than 500,000 cubic feet of water and sediment. Areas which could be inundated are Route 110, Creamery Road, the Town Clerks office, and Washington Village School. The Hazard Analysis Map highlights areas which could be affected by inundation if the dam were to break.

Hazard	Location	Vulnerability	Extent	Impact	Probability
--------	----------	---------------	--------	--------	-------------

Dam Failure	Hands Mill Dam Downstream Areas – highlighted on map	East Village center, Washington School Church, Roads downstream	Severe	\$ 2,000,000 +	Medium – Increasing daily
--------------------	--	--	--------	----------------	------------------------------

Flooding/Flash Flooding/Fluvial Erosion

Recent History of Occurrences (presidential declarations and NCDC query search information. The closest flood gauge is located in Montpelier on the Winooski River, approximately 15 miles downstream):

Date	Event	Location	Extent
8/28/2011	Flood/Tropical Storm	Statewide, Washington	Montpelier Flood gauge at 19.05 feet (flood stage is at 15 feet) DR 4022
5/27/2011	Flash Flood	Washington	Montpelier flood gauge at 17.59 feet, 3-5" of rain DR 4001
4/23/2011- 5/9/2011	Flood	Washington	DR 1995
7/2009	Flood	Washington	\$45,000 in local infrastructure damages
8/02/2008	Flash Flood	Washington	No extent data
7/11/2007	Flash Flood	Washington	3-6" of rain in 2 hrs, DR 1715
7/21/2003	Flood	County Wide	DR 1488
12/17/2000	Flood	County Wide	3" of rain, \$1 M in damages
7/14/2000	Flood	County Wide	DR 1336
9/16/1999	Tropical Storm Floyd	County Wide	Montpelier flood gauge at 9.30 feet, 5-7" rain county wide DR 1307

6/27/1998	Flash Flood	County Wide	\$5M in damages, 3-6" rain across county DR 1228
1/19/1996	Flood; ice jam	County Wide	Montpelier flood gauge at 14.64 feet
8/4/1995	Flood	County wide	Montpelier flood gauge at 6.94 feet; \$1.5M damages county wide
8/5/1976	Flood	County Wide	Montpelier flood gauge at 12.31 feet DR 518
6/30/1973	Flash Flood	Washington	Montpelier flood gauge at 17.55 feet DR 397
9/22/1938	Flood, Hurricane	County Wide	Montpelier flood gauge at 14.11 feet
11/03/1927	Flood	County Wide	Montpelier flood gauge at 27.10 feet

Washington, like other towns in Vermont, is prone to flooding and flash flooding during rainy seasons and extreme weather events. The head waters of the Jail Branch are located in Washington. The River flows north to Barre City and Barre Town where it conjoins with the Stevens Branch of the Winooski River. Two studies have been conducted on the Jail and Stevens Branch to gauge the health of the river and identify flood prone areas, where construction should be avoided, and areas constricted by bridges/culverts.

Six of the nine largest floods have occurred in the past 35 years. These floods are a result of intense cloudbursts, hurricanes and snowmelt. A USGS study found that since 1970, an increase in precipitation has occurred due to climate change.

The greatest threat to flooding is caused by changes in land use and increased development near river banks and in type A floodplain areas. Increased development and encroachment on rivers and streams leads to greater volumes stormwater runoff and greater erosion of stream banks. Improperly built private driveways also disrupt stormwater flow and can overload culverts with additional stormwater. The Hazard Analysis Map highlights 11 road/stream intersections which are consistently flooded or need repair work from flooding. Two flooding events in July 2009 caused approximately \$45,000 in damages at these stream/road intersections. The Scales Hill Road suffered the greatest amount of damage and a culvert was replaced in pre-cast concrete in 2012. Three other problem areas identified in 2011 have had bridge and culvert upgrades including Johnson Lane and the intersection of Stellar Road and Williamstown Road. However, flooding is not limited to the intersections highlighted on the map.

The most recent damaging floods were in May and August (TS Irene) of 2011. Washington suffered the most damage in the August 2011 TS Irene flood event. The following roads were damaged (repair costs included):

East Orange/Morrie Road - \$2,170.44

Notch Road - \$2,619.84

Poor Farm Road Bridge - \$2,619.84

West Corinth Road - \$18,371.11

The total documented damages from the TS Irene flood event cost about \$58,241.59 with the Town share totaling \$7,280.39. This total for the repair of the above sites went over \$1,000 each and, therefore, qualified for reimbursement from FEMA and the State of Vermont. There were other roads that were damaged and required work that impacted the 2011 road budget over and above \$7,280.39.

The stream assessments make several recommendations to prevent help decrease the likelihood of flooding and flash flooding. These recommendations are to: have a 25ft no development buffer on all waterways, replace bridges which constrict the river, develop a culvert maintenance plan, and properly manage stormwater in developed areas (consideration of soils/deposits, septic systems, channel/fluvial migration zones.) Washington does participate in the NFIP. There is no floodplain data for the town of Washington and therefore no properties have been identified as being in the floodplain. DFIRM maps do identify some limited Zone A areas. Washington also does not have record of any repetitive loss properties. There are currently no large or small developments planned in Washington that would be considered in the floodplain.

Hazard	Location	Vulnerability	Extent	Impact	Probability
Flooding/ Flash Flooding/ Fluvial Erosion	Along Jail Branch and major tributaries which flow to Stevens Branch; highlighted intersections on Hazards Analysis Map	Bridges, culverts, roadways, Clerk's Office, Washington School, structures within 25 ft of waterway, See Hazard Analysis Map	Moderate	\$100,000 for roadwork depending on severity – Higher if actual buildings are damaged (based off current grand list)	Medium

Structure Fire

Seven of the calls received in 2012 by Washington's FAST squad were fire related incidents – structure, electrical and chimney fires. Although many structures in Washington are less than 100 years old, many residents heat their homes with wood or pellet burning stoves. The remoteness and distance from fire and emergency services of many homes also increases the likelihood of a home being completely, opposed to partially, destroyed by a fire. The south eastern section of the town is more remote and more forested than the northern portion of the

town. Three additional dry hydrants were installed recently at Cyr Pond on Route 110 south of the village, at the intersection of Stellar/Williamstown Roads, and at Duranleau Pond on Cheney Road. The Town Clerk's office does not have a sprinkler system, which is a great concern to Town residents. To date, there have been no large structure fires.

Hazard	Location	Vulnerability	Extent	Impact	Probability
Structure Fire	Town wide with emphasis on the south east section of town	Wood structures, especially older than 100 yrs, homes that use wood burning stoves for heat	Moderate	\$150, 000 per home based on median grand list value	Medium


5.3 Moderate Threat Hazards

Tornado

Tornados in Vermont are especially rare due to the mountainous topography of the State. The National Weather Service reports that only about one tornado occurs in Vermont every two years. Only 32 tornadoes have occurred in Vermont between 1950 and 1995. On May 9, 2009 a tornado touched down in the northwest section of Washington. This area is highlighted on the Hazard Analysis Map. The tornado that occurred on this date was the second earliest confirmed tornado in Vermont since 1950.

The tornado was rated an EF1 on the enhanced Fujita scale and had winds around 100 mph. The path of the tornado was roughly a half mile long and traveled through the village of Washington before dissipating. No one was hurt in the tornado; however there was severe damage which occurred to trees and structures in the swath. A six unit apartment complex had its roof torn off. Damage also occurred to the roof of the Washington School in the village area. New radios were installed in 2012 to improve town-wide and inter-town communications in the case of an extreme weather event or hazard incident such as a tornado.

The picture below is courtesy of the National Weather Service, and highlights the damage that occurred along the tornado path.



Hazard	Location	Vulnerability	Extent	Impact	Probability
Tornado	Valley areas, but hard to pinpoint exactly	Any structure in Path – mobile homes, multi-story buildings, older/historic structures	Minimal	\$750,000	Low

6. Mitigation

6.1 Municipal Plan (2013) Goals and Policies that Support Local Hazard Mitigation

- To plan for the public investment in the construction or expansion of infrastructure such as fire and police protection, emergency medical services, schools and solid waste disposal, and others, to meet future needs should reinforce the general character and planned growth patterns of the town.
- To provide for safe, convenient, economic and energy efficient transportation systems that respects the integrity of the natural environment.
- To protect and preserve important natural and historic, recreational, scenic and cultural features of the landscape including air, water, wildlife, and land resources.

- Trees and other vegetation along streams, rivers, and lake shores serve to: protect property from flood flow and ice jams, prevent bank erosion, enhance aesthetic appeal, and maintain the oxygen level of the water for fish habitat and effluent assimilation capacity. For these reasons, undisturbed areas of vegetation should be retained and encouraged along the banks of surface waters.

The next time the Town of Washington updates its Municipal Plan, it may consider adding additional mitigation goals.

The goals of this Local Hazard Mitigation Plan are:

- To take actions to reduce or eliminate the long-term risk to human life and property from:
 - Dam failure
 - Flooding/Flash Flooding/Fluvial Erosion
 - Structure Fire
 - Tornado

Specific hazard mitigation strategies related to goals of the Plan include:

- Ensure existing and future drainage systems are adequate and functioning properly
- Preserve and prevent development in areas where natural hazard potential is high
- Provide residents with adequate warning of potential hazards
- Ensure that all residents and business owners are aware of the hazards that exist within Washington and ways they can protect themselves and insure their property
- Ensure that emergency response services and critical facilities functions are not interrupted by natural hazards
- Provide adequate communication systems for emergency personnel and response units

Hazard mitigation is a relatively new planning topic to Washington. Over the course of the next five years, Washington will look into incorporating more mitigation planning into their daily planning activities and projects. The mitigation goals and strategies outlined in this Local Mitigation Plan are the first steps in making Washington more disaster resistant. The hazards identified in this plan cause the greatest impacts and damage and are the priority hazards for the Town of Washington. In order to have continuous achievement of mitigation goals and implementation mitigation strategies, the Town will spend time each year assessing progress of and future funding sources for the outlined mitigation strategies. This session can be performed during Town Meeting Day or an annual session of another set date can be held during a public Select Board Meeting.

6.2 Proposed Hazard Mitigation Programs, Projects and Activities

Hazard mitigation programs, projects and activities that were identified for implementation at the Town Local Hazard Mitigation meeting are:

Hazard Mitigated	Mitigation Action	Local Leadership	Prioritization	Possible Resources	Time Frame
Dam Failure	Removal of Hands Mill Dam	Select board, ANR,	High	HMGP	ASAP – no more than 2 years
Dam Failure	Development of Cleanup Recovery Plan	Select board, road dept, fire dept	Med	VEM, Red Cross,	2-3 years
Flooding/Flash Flooding/Fluvial Erosion	Replacement and expansion of highlighted problem culverts as prioritized by the Select Board	Select Board, Road Crew	Med	HMGP, general fund	3-4 years
Flooding/Flash Flooding/Fluvial Erosion	Development of flood bylaws	Select Board	Med	CVRPC	2-3 years
Structure Fire	Improved fire education materials for homeowners	Select board, fire department, Washington school children	Med	FM Global Fire Prevention Grant Program	2 years
Structure Fire	Installation of E911 number signs	Road crew	Med	General fund	1-2 years
Structure Fire	Sprinkler systems for municipal buildings	Select board, fire department	Low	Dept of Homeland Security	4 years
Structure Fire	Communications Sign	Select board, volunteers, fire department	Med	Dept of Homeland Security, general fund	2 years
Tornado	Installation of mobile home tie downs	Select board, fire department, home owners	Low	HMGP	4-5 years

Flooding/Flash Flooding/Fluvial Erosion	Participate in Community Rating System	Select board, planning commission	Med	General fund	3 years
---	--	-----------------------------------	-----	--------------	---------

VEM also emphasizes a collaborative approach to achieving mitigation on the local level, by partnering with ANR, VTrans, ACCD, Regional Planning Commissions, FEMA Region 1 and other agencies, all working together to provide assistance and resources to towns interested in pursuing mitigation projects and planning initiatives.

The Hazard Mitigation Activities Matrix (Attached) lists mitigation activities in regards to local leadership, possible resources, implementation tools, and prioritization. Prioritization was based upon the economic impact of the action, the Community's need to address the issue, the action's cost, and the availability of potential funding. The action's cost was evaluated in relation to its benefit as outlined in the STAPLEE³ guidelines.

Washington understands that in order to apply for FEMA funding for mitigation projects, a project must meet FEMA benefit cost criteria. In addition, the Town must also have a FEMA approved Hazard Mitigation Plan.

A High prioritization denotes that the action is either critical or potential funding is readily available and should have a timeframe of implementation of less than two years. A Medium prioritization is warranted where the action is less critical or the potential funding is not readily available and has a timeframe for implementation of more than two years but less than four. A Low prioritization indicates that the timeframe for implementation of the action, given the action's cost, availability of funding, and the community's need to address the issue, is more than four years.

Attachments


- Areas of Local Concern Map
- 5 year plan maintenance and review process
- Town Resolution Adopting the Plan

³ A method of evaluating mitigation actions based on **S**ocial, **T**echnical, **A**dministrative, **P**olitical, **E**conomic, **E**nvironmental criteria


5-Year Plan Review/Maintenance




After Plan Adoption-Annually Implement and Evaluate



Fifth Year, and After Major Disaster Evaluate and Revise



Areas of Local Concern Map



CERTIFICATE OF ADOPTION

The Town of Washington
Select Board
A Resolution Adopting the Local Hazard Mitigation Plan
_____, 2014

WHEREAS, the Town of Washington has worked with the Central Vermont Regional Planning Commission to identify hazards, analyze past and potential future losses due to natural and manmade-caused disasters, and identify strategies for mitigating future losses; and

WHEREAS, the Washington Local Hazard Mitigation Plan contains several potential projects to mitigate damage from disasters that could occur in the Town of Washington; and

WHEREAS, a duly-noticed public meeting was held by the Town of Washington Select Board on _____, 2014 to formally adopt the Washington Local Hazard Mitigation Plan;

NOW, THEREFORE BE IT RESOLVED that the Washington Select Board adopts the Washington Local Hazard Mitigation Plan.

Chair of Select Board

Member of Select Board

ATTEST

Washington Clerk

Attachment 6: 16 Woodchuck Hollow Road Topographic Survey Image

Hands Mill Dam Removal – BCA Analysis


16 Woodchuck Hollow Road – Location of Topographic Survey Shot to Estimate Finished Flood Elevation

December, 2020

Source: Bing Maps



Attachment 7: Ecosystem Benefits Map




- Legend**
- Survey Control Point
 - Major Contour
 - Minor Contour
 - Parcel Boundaries
 - Edge of Road
 - Guard Rail
 - Overhead Utility
 - Vegetation Line
 - Tree
 - River Top of Bank (OHW)
 - Existing Wetland (See Note 6)
 - Thalweg Spot Elevations
 - Utility Pole
 - Manhole
 - Sanitary Manhole or Septic Cover
 - Well
 - Vent
 - Hydrant
 - Water Valve
 - Stormwater Pipe
 - Stormwater Swale
 - Proposed Limits of Disturbance
 - Proposed Contours
 - Dam Removal Line

Site Plan
Scale: 1" = 40'

**30% DESIGN PLANS, NOT FOR
PERMITTING OR CONSTRUCTION**

DRAWING CREDITS	#	DATE	DRWN	CHK'D	APP'D	DESCRIPTION
DRAWN ON: 9/4/2020						
DRAWN BY: GMB						
CHECKED ON:						
CHECKED BY:						
PROJECT NO: 20-007						




 **STONE ENVIRONMENTAL**


535 Stone Cutters Way / Montpelier / VT / 05602 / USA
802.229.4541 / info@stone-env.com / www.stone-env.com


HANDS MILL DAM REMOVAL
AT JAIL BRANCH
CHANNEL RESTORATION PLAN - ECOSYSTEM BENEFITS

WASHINGTON VERMONT

Attachment 8: HEC-RAS Output Figures








Legend

- WS Q500 - HM_Existing_Trib
- WS Q500 - HM_Proposed_trib
- WS Q100 - HM_Existing_Trib
- WS Q50 - HM_Existing_Trib
- WS Q100 - HM_Proposed_trib
- WS Q50 - HM_Proposed_trib
- WS Q10 - HM_Existing_Trib
- WS Q10 - HM_Proposed_trib
- Ground
- Bank Sta

Station 3+34



Attachment 9: Historical Documents

Listed on State Register

VT ACHP

Date:

9-14-89

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Orange
TOWN:	Washington
LOCATION:	Adjacent to Old Saw Mill site, at intersection of Woodchuck Hollow Road (T.H.#9) and Corinth Road (T.H.#1).
COMMON NAME:	Armand and Edith Vermette House
FUNCTIONAL TYPE:	House
OWNER:	Armand and Edith Vermette
ADDRESS:	Washington, VT 05675
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone ☒ Brick ☐ Concrete ☒ Concrete Block ☐
2. Wall Structure
 - a. Wood Frame: Post & Beam ☐ Balloon ☒
 - b. Load Bearing Masonry: Brick ☐ Stone ☐ Concrete ☐ Concrete Block ☐
 - c. Iron ☐ d. Steel ☐ e. Other:
3. Wall Covering: Clapboard ☒ Board & Batten ☐ Wood Shingle ☐ Shiplap ☐ Novelty ☐ Asbestos Shingle ☐ Sheet Metal ☐ Aluminum ☐ Asphalt Shingle ☐ Brick Veneer ☐ Stone Veneer ☐ Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood ☒ Iron ☐ Steel ☐ Concrete ☐
 - b. Other:
5. Roof Covering: Slate ☐ Wood Shingle ☐ Asphalt Shingle ☐ Sheet Metal ☒ Built Up ☐ Rolled ☐ Tile ☐ Other:
6. Engineering Structure:
7. Other:

Appendages: Porches ☒ Towers ☐ Cupolas ☐ Dormers ☐ Chimneys ☒ Sheds ☐ Ells ☐ Wings ☒ Bay Window ☒ Other:

Roof Style: Gable ☒ Hip ☐ Shed ☐ Flat ☐ Mansard ☐ Gambrel ☐ Jerkinhead ☐ Saw Tooth ☐ With Monitor ☐ With Bellcast ☐ With Parapet ☐ With False Front ☐ Other:

Number of Stories: 2½

Number of Bays: 5 x 3

Entrance Location: center, front

Approximate Dimensions: 32' x 24' plus side wing

SURVEY NUMBER: 0915-26

NEGATIVE FILE NUMBER:
79-A-108-1UTM REFERENCES:
Zone/Easting/Northing
18/705660/4886580U.S.G.S. QUAD. MAP:
East Barre Quad. 15'PRESENT FORMAL NAME:
Vermette HouseORIGINAL FORMAL NAME:
Rodney Clough House

PRESENT USE: Residence

ORIGINAL USE: Wagon Shop

ARCHITECT/ENGINEER:
UnknownBUILDER/CONTRACTOR:
Rodney Clough (?)PHYSICAL CONDITION OF STRUCTURE:
Excellent ☐ Good ☒
Fair ☐ Poor ☐

STYLE: vernacular Queen Anne

DATE BUILT: c. 1840, remodled c. 1890

THREAT TO STRUCTURE:

No Threat ☒ Zoning ☐ Roads ☐
Development ☐ Deterioration ☐
Alteration ☐ Other:

LOCAL ATTITUDES:

Positive ☒ Negative ☐
Mixed ☐ Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Although this structure was originally used as a wagon shop, it was substantially remodeled c. 1890 to serve as a residence. Queen Anne Revival style is evidenced by a projecting bay having brackets under the eave. The gable is detailed with shingles, some having a heraldic pattern most frequently found in the Barre Graniteville area. The foundation includes slabs of granite that were split from local field boulders. This part of the foundation may well be part of the original wagon shop foundation. The south gable was damaged by a fire that destroyed the adjacent W. and C.W. Huntington Saw Mill in 1914. (The dam and part of the foundation remain.) A rear corner wing was added in the mid-1900's and the one bay gable-roofed garage was built c. 1950.

RELATED STRUCTURES: (Describe)

1. One bay garage 10' x 16'. Gable roof.


STATEMENT OF SIGNIFICANCE:

This structure was built by Rodney Clough c. 1840 and originally served as a wagon shop. Adjacent to the shop were the Huntington saw mill and the "Washington Manufacturing Co.". Together, the buildings comprised the industrial center of Washington in the mid-19th century. Although some of the original framing of the wagon shop still exists, the structure was rebuilt as a residence, probably by a member of the Cheney family. The design of the house, especially the gable shingle work, indicates the building associations that Washington had with the Barre/Graniteville area during the height of the granite industry in the 1890's.

REFERENCES:

1,2,3,4,7.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land ☒ Woodland ☐
Scattered Buildings ☒
Moderately Built Up ☐
Densely Built Up ☐
Residential ☒ Commercial ☐
Agricultural ☐ Industrial ☐
Roadside Strip Development ☐
Other:
C. 200 yards east of Route 110
and the center of Washington
Village.

RECORDED BY:

Philip C. Marshall

ORGANIZATION:

Div. of Historic Preservation

DATE RECORDED:

6/3/79



0915-26

Hands Mill Dam 225.01
Washington

MEMORANDUM

TO: To The File
FROM: Steven Hanna, Dam Safety Engineer
DATE: December 9, 2016
SUBJECT: Inspection of Hands Mill Dam, Washington.

On August 11, 2016, Stephen Bushman, P.E., Steven Hanna and Louisa Deering made a routine inspection of the Hands Mill Pond Dam in Washington, Vermont, State Identification Number 225.01. The inspection was carried out under the provisions of Title 10 of Vermont Statutes Annotated, Section 1105. The Town of Washington owns the dam. A number of photographs and field notes were taken. The dam was last inspected by the Department on August 5, 2013, and the report of that inspection is on file. This report updates previous observations and records additional information.

OVERALL CONDITION

The overall condition of the dam is **POOR** and the dam is currently **Partially Breached**. The dam is continuing to deteriorate and progressively breach.

DOWNSTREAM HAZARD CLASSIFICATION

The dam is classified as a Class 2, “Significant Hazard” dam. Significant hazard potential category structures are those located in predominantly rural or agricultural areas where failure may damage isolated homes, secondary highways or minor railroads, or cause interruption of service of relatively important public utilities. **The potential for loss of life is few and the potential economic loss is appreciable.**

JURISDICTION

Since the dam impounds more than 500,000 cubic feet, any alteration, reconstruction or breaching would require prior approval from the Department under provisions of 10 VSA Chapter 43.

RECOMMENDATIONS FOR OWNER

1. Retain a professional engineer experienced in the design and investigation of dams to develop plans to remove the dam and restore the upstream channel. The dam is progressively breaching. **A failure of the dam could cause public and private property damage and loss of life downstream.**
2. Develop, implement and keep current an Emergency Action Plan (EAP) for use during an unusual or emergency event at the dam. The purpose of an EAP is to reduce the risk of human life loss and injury and minimize property damage. The EAP should be reviewed and tested at least annually. Submit a copy of the EAP to the Dam Safety Program.

3. Clear the dam crest, the upstream slope and the downstream slope of trees, woody vegetation, and debris extending 15 feet beyond the toe of the dam, outlet structure, and both abutments.

INSPECTION

The inspection of the dam was conducted on August 11, 2016 at 1430 hours. The weather was partly cloudy and humid with temperatures in the mid-80s. The ground conditions were dry. The following was observed:

1. Embankment Section: The earth embankment section is primarily left of the spillway tying into the left abutment that was a firm parking lot. The downstream slope of this section was covered in grass and thick brush.
2. Downstream Wall: The wall consists of cyclopean concrete (concrete with large round stones). The concrete is deteriorating and there are several areas of the wall with significant stone loss. The area to the left of the spillway had a large area of scour and several loose stones where there had been concrete loss. Several large pieces of concrete had fallen off the wall about 50 feet to the right of the spillway. This area also appeared to be impacted by overtopping events. At the extreme left end, the downstream wall consisted of large rounded stone dry-laid. The wall was irregular but appeared more stable than the rest, most likely because it has been less impacted by high flows. Most of the downstream wall had moderate to large trees growing on or adjacent to it. These are also destabilizing the wall. There were multiple areas of seepage on both sides of the spillway.
3. Upstream Wall: The right end of the dam consisted of a concrete wall. Most of the wall was covered in thick brush but the exposed section had significant cracking. The spillway and left end of the dam had significant scour. The additional large stone that has been placed appeared stable at the time of the inspection.
4. Crest: The crest was in poor condition, covered in grass, heavy brush, and trees. There were multiple locations with signs of overtopping, erosion. The dam was partially breached near its mid-section, with fallen concrete and concrete that was leaning up to 10 feet downstream.
5. Toe: Trees, woody vegetation and debris covered the toe.
6. Principal Concrete Spillway:
 - a) Approach Channel: The approach channel was clear of debris. The concrete of the spillway was cracked and eroded along the whole width of the channel.
 - b) Weir: The weir structure was in poor condition, the left end has been partially breached and the rest of the weir was highly eroded and in poor condition. Large rock had been placed along the contact between the spillway and left crest as protection from high flows. This erosion appears to be a continuing problem, based on previous inspections.
 - c) Downstream Section: The downstream section is a cyclopean wall that has eroded. There is stone and concrete loss and water is flowing through (within) the structure.

- d) Discharge Channel: The downstream channel was clear of debris.
7. Sluice: The low level sluiceway was in poor condition and is inoperable. The sluiceway channel was about 12 feet long through the dam. The sluice gate was either closed or stop logs were in place and there was seepage coming through the logs. There were multiple seepages with water flowing heavily.

HYDROLOGY AND HYDRAULICS

The drainage area at this site is about 4,130 acres (6.45 square miles). The pond area at the normal pool is 2 acres with storage of about twelve acre-feet including sediments. At the top of the crest the dam stores 16 acre-feet. The maximum spillway capacity is about 800 cubic feet per second.

MEMORANDUM

TO: To The File
FROM: Stephen Bushman, P.E., Dam Safety Engineer
DATE: August 8, 2013
SUBJECT: Inspection of Hands Mill Dam, Washington.

On August 5, 2013, Stephen P. Bushman, P.E., and Steve Hanna, made a routine inspection of the Hands Mill Pond Dam in Washington, Vermont. A number of photographs were taken. The dam was last inspected by the Department on May 30, 2007, and the report of that inspection is on file. This report updates that report and records additional information. The inspection was carried out under the provisions of 10 VSA 1105.

OVERALL CONDITION

The overall condition of the dam is POOR. With authorization of the VT Department of Environmental Conservation, the dam should either be removed or repaired.

DOWNSTREAM HAZARD CLASSIFICATION

The dam is a Class 2, "significant hazard" dam.

JURISDICTION

Since the dam impounds more than 500,000 cubic feet, any alteration, reconstruction or breaching would require prior approval from the Department under provisions of 10 VSA Chapter 43.

RECOMMENDATIONS FOR OWNER

1. Retain a professional engineer experienced in the design and investigation of dams to develop plans to either remove or reconstruct the dam and restore the upstream channel. The dam is progressively breaching. **A sudden failure of the dam during regional high water could cause public and private property damage and loss of life downstream.**
2. Until a professional engineer is retained, monitor the condition of the dam. Report any changes to your engineer.
3. Maintenance of the dam should be improved to include clearing and brushing of the dam along the crest, the upstream slope, and the downstream slope. Brushing should be pushed 10-15 feet past the toe of the dam, 15 feet around any outlet structure, and 15 feet surrounding both abutments.
4. An emergency action plan (EAP) should be developed, implemented, and tested. The plan should indicate who would be responsible for routine and flood-time observation of the dam, the conditions

which would be cause for alarm and the way in which people possibly affected downstream would be notified.

INSPECTION

The inspection of the dam was conducted on August 5, 2013, at 1400 hours. The weather was sunny and in the 70's. The ground was dry. The following was observed:

1. Embankment Section: Most of the earth embankment section is left of the spillway (looking downstream). The left abutment was a firm parking lot, and the downstream slope of this section was covered in grass and thick brush.
2. Stone Section:
 - a) Downstream Wall: The downstream wall consists of cyclopean concrete for about 50 feet to the left of the spillway, in the spillway section, and for about 100 feet to the right of the spillway. There were several areas where significant stone loss had occurred: Immediately to the left of the spillway and about 50 feet to the right. The area to the left of the spillway had a large area of scour in addition to several loose stones where the concrete had been loss. This area appears to be impacted by high flows since it is on the bend of the river. Based on the photos from 2007, this section has deteriorated rapidly, probably as a result of TS Irene and recent high water. About 50 feet to the right of the spillway, several large pieces of concrete had fallen off the wall. This area appeared to be impacted by overtopping also. At the extreme left end, the downstream wall consisted of large rounded stone dry-laid. The wall was irregular but appeared more stable than the rest, most likely because it has been less impacted by high flows. Most of the downstream wall had moderate to large trees growing on or adjacent to it. These are also destabilizing the wall. There were multiple areas of seepage on both sides of the spillway.
 - b) Upstream Slope: The right end of the dam consisted of a concrete wall. Most of the wall was covered in thick brush but the exposed section had significant cracking. The area to the left of the spillway had significant scour that was noted in the previous inspection. However, additional large stone had been added and the area appeared stable at the time of the inspection.
 - c) Crest: The crest was found to be in poor condition. The crest was covered in grass, heavy brush, and trees. Structurally, there were multiple signs of overtopping, erosion, and the dam was partially breached near its mid-section. The mid-section of the dam had severe damage with fallen concrete and concrete that was leaning up to 10 feet downstream.
 - d) Toe: Woody vegetation covered the toe.
3. Principal Concrete Spillway:
 - a) Approach Channel: The approach channel was clear of debris. The concrete of the spillway was cracked and eroded along the whole width of the channel.
 - b) Weir: The weir structure was in poor condition. The left end of the weir has been partially breached, and the rest of the weir was highly eroded and in poor condition. Large rock, as noted

above, had been placed along the contact between the spillway and left crest as protection from high flows. This appears to be a continuing problem, based on previous inspections.

- c) Downstream Section: The downstream section of the spillway is a cyclopean wall. At the time of the inspection a significant amount of water was flowing over it preventing a thorough inspection. Based on the surrounding walls and weir condition, it is expected that there is some stone and concrete loss.
- d) Discharge Channel: The outlet channel downstream was clear of debris.
- 4. Sluice: The sluiceway appeared to be in poor condition. There were multiple signs of seepage with water flowing heavily.

HYDROLOGY AND HYDRAULICS

The drainage area at this site is about 4,130 acres. The pond area at the normal pool is 2 acres with storage of about twelve acre-feet including sediments. At the top of the crest the dam stores sixteen acre-feet. The maximum spillway capacity is about 800 cfs.



Vermont Department of Environmental Conservation
Facilities Engineering Division, Dam Safety and Hydrology Section
103 South Main Street, [phone] 802-241-3450
Waterbury, VT 05671-0511 [fax] 802-244-4516

Agency of Natural Resources

June 25, 2007

Carol Davis
Town Clerk
2974 VT Route 110
Washington, VT 05675

Re: Inspection of Hands Mill Dam in Washington, VT

Dear Ms. Davis,

Attached is a report of our May 30, 2007 inspection of Hands Mill Dam owned by the Town of Washington in Washington, Vermont. As was identified in 2001 the dam is in poor condition and continues to deteriorate. At that time, a recommendation to retain a professional engineer experienced in the design of dams to develop plans to either reconstruct or remove the dam and restore the upstream channel was made. That same recommendation is being made at this time. The dam is considered a significant hazard, and a sudden failure of the dam would cause probable loss of life and property damage. Consultation with your Town attorney about the liabilities of dam ownership would be prudent.

The report outlines the condition of the dam, recommendations for the owner and information about the jurisdiction of the Department under the statute on dams (10 VSA Chapter 43).

Please contact me if you have any questions on the report or recommendations.

Sincerely,

A handwritten signature in black ink, appearing to read "Stephen Bushman".

Stephen P. Bushman, P.E.
Dam Safety Engineer



Vermont Department of Environmental Conservation

Facilities Engineering Division, Dam Safety and Hydrology Section

103 South Main Street,

[phone] 802-241-3450

Waterbury, VT 05671-0511

[fax] 802-244-4516

Agency of Natural Resources

MEMORANDUM

TO: For the File

FROM: Stephen Bushman, P.E., Dam Safety Engineer *SB*

DATE: June 25, 2007

SUBJECT: Inspection of Hands Mill Dam, Washington.

On May 30, 2007, Stephen P. Bushman, P.E., Brian Terhhune, and Henry Nyenbrink, made a routine inspection of the Hands Mill Pond Dam in Washington, Vermont. A number of photographs were taken. The dam was last inspected by the Department on June 20, 2001, and the report of that inspection is on file. This report updates that report and records additional information. The inspection was carried out under the provisions of 10 VSA 1105.

OVERALL CONDITION

The overall condition of the dam is poor.

DOWNSTREAM HAZARD CLASSIFICATION

The dam is a Class 2, "significant hazard" dam.

RECOMMENDATIONS FOR OWNER

1. The owner should retain a professional engineer experienced in the design of dams to develop plans to either reconstruct or remove the dam and restore the upstream channel. Even though the dam has withstood flood and weather for decades, it will not last forever. A sudden failure of the dam during regional high water could cause public and private property damage and loss of life downstream.
2. Maintenance of the dam should be improved to include clearing and brushing of the dam along the crest, the upstream slope, and the downstream slope to ten feet below the toe of the dam.

3. Remove the trailers and tractors from the left abutment so this area can be properly inspected and monitored for sinkholes.
4. An emergency action plan (EAP) should be developed, implemented, and tested. The plan should indicate who would be responsible for routine and flood-time observation of the dam, the conditions which would be cause for alarm and the way in which people possibly affected downstream would be notified

INSPECTION

The inspection of the dam was conducted on May 30, 2007, between 1430 and 1515 hours. The weather was partly cloudy and in the 60's. The ground was dry. The following was observed:

1. Embankment Section.
 - a) Upstream Slope. The upstream slope was covered in grass and thick brush. There were multiple signs of erosion. The left abutment was severely eroded while the right abutment appeared sound. There was an exposed concrete cutoff wall near the right end of the dam in a deteriorated condition.
 - b) Downstream Slope. The slope was covered in grass and moderate brush and trees. At the mid-point of the wall there was an eroded section that was about five-feet wide by twelve-feet high. There were multiple signs of seepage to the right of the spillway. The portion of the downstream embankment with a large rip rap wall was in fair condition.
 - c) Crest. The crest was found to be in poor condition. The crest was covered in grass, heavy brush, and trees. There were multiple signs of overtopping and erosion near the mid-point of the dam. There was a portion of the concrete on the crest that has failed. There were logs and woody debris along the length of the crest. In June, 2001 a sinkhole was reported on the crest to the left of the spillway. This area is now covered with trailers and tractors, presumable from the adjacent farm, so it could not be inspected.
 - d) Toe. The toe was wet from the multiple seeps. There was woody vegetation along the toe.
2. Principal Concrete Spillway.
 - a) Approach. The approach was clear of debris, but the pond is largely filled in with sediment. The concrete of the spillway was cracked and eroded along the whole width of the channel.
 - b) Weir. The weir structure was in poor condition. The left end of the weir appears to be failing and it is noticeably lower than the remaining structure. Excessive erosion and channel cutting was occurring around the left end of the weir structure.
 - c) Downstream Section. The downstream slope is a cyclopean wall that had a substantial amount of stone and concrete that was in a deteriorated state or missing. Portions of the

wall were covered with seeps, moss, ferns, and small trees.

d) Outlet Channel. The outlet channel was clear of debris.

3. Sluice. The sluice was difficult to inspect but appeared to be in poor condition. There were multiple signs of seepage at the sluice.

HYDROLOGY AND HYDRAULICS

The drainage area at this site is about 4,130 acres. The pond area at the normal pool is 2 acres with storage of about twelve acre-feet including sediments. At the top of the crest the dam stores sixteen acre-feet. The maximum spillway capacity is about 800 cfs.

JURISDICTION

Since the dam impounds more than 500,000 cubic feet, any alteration, reconstruction or breaching would require prior approval from the Department under provisions of 10 VSA Chapter 43.

Please don't hesitate to call me at 241-3450 if I can be of further assistance.

State of Vermont
Department of Environmental Conservation
Dam Safety Section
103 South Main Street
Waterbury, VT 05671-0407

DAM INSPECTION CHECK LIST

Dam HANDS Mill DEC ID. No. _____
Town WASHINGTON NatDam ID No: VT000 _____
Owner TOWN OF Inspection Date 5-30-07
Address _____ Time 1210 1430-1515
_____ Last Inspected/by _____
Telephone _____ Last D/S Haz Class _____
Right of Entry _____

PERSONS PRESENT AT TIME OF INSPECTION (Name and Organization)

Inspection Party SPB, BAT, MN

Others _____

I. Conditions at Time of Inspection

Weather: Today PT CLOUDY, GA. Previous Clear, 70s
Ground Conditions DRY Other _____
Water Level _____ w/r/t _____
Accessibility _____
Reservoir Area _____
Remarks POOR CONDITION, DAM SHOULD BE REMOVED & CHANNEL
W/S RESTORED

II. Condition of Main Structure

Type of Construction CYCLOPEAN CONCRETE / EARTH ENCRUSTMENT

A. Upstream Face or Slope

1. Vegetative Cover GRASS / THICK BRUSH
2. Erosion MODERATE ALONG ENCRUSTMENT SECTION
3. Slumps, Slides, Cracks _____
4. Animal Burrows NN
5. Slope Protection _____
6. Debris _____
7. Structural _____
8. Abutments LT ABUTMENT ERODED / RT ABUTMENT SOUND
9. Alignment _____
10. Movement _____
11. Remarks EXPOSED CONCRETE CUT-OFF WALL NEAR RT END.
DETERIORATED CONDITION.

B. Downstream Face or Slope and Toe

1. Vegetative Cover GRASSES, MODERATE BUSH & TREES
2. Erosion _____
3. Slumps, Slides, Cracks MID POINT OF DAM HAS AN
ERODED SECTION \approx 5' WIDE X 12' HIGH
4. Animal Burrows _____
5. Slope Protection _____
6. Debris _____
7. Seepage NOTED JUST RT OF SPILLWAY THROUGH CYCLOPEAN
WALL.
8. Piping _____
9. Boils _____
10. Toe Drains NONE
11. Scour _____
12. Structural CYCLOPEAN WALL HAS LOST SUBSTANTIAL AMOUNT
OF STONE, IN DETERIORATED STATE
13. Abutments RT SOUND, LT ERODED LT ALSO HAS TRAILING
& TRACED ON THAT IMPROVE INSPECTION

14. Alignment _____

15. Movement _____

16. Remarks STONE WALL SECTION AT RIGHT END BULGES OUTWARD
IN SEVERAL PLACES.

C. Top of Dam

1. Vegetative Cover GRASS, HEAVY BUSH & TREES

2. Erosion _____

3. Evidence of Overtopping YES, ABOUT AT MID-POINT. PORTION
OF CONCRETE ON CREST HAS FALLEN
4. Settlement, Cracks _____

5. Animal Burrows NN

6. Debris LOGS, WOODY DEBRIS

7. Use of crest (road, trail, etc.) NONE

8. Structural POOR CONDITION

9. Abutments RT: FAIR. LT: SEVERELY DAMAGED

10. Alignment _____

11. Remarks _____

III. Condition of Outlet Works

A. Principal Spillway

Type CYCLOPEAN CONCRETE

Controlled or Uncontrolled UNC

1. Approach Channel CLEAN, BUT IN GENERAL POND V/S OF DAM FULL OF SEDIMENT
2. Transition _____
3. Control Section CONCRETE SEVERELY DETERIORATED
4. Discharge Channel CLEAN
5. Intake Structure _____
6. Conduit _____
7. Outlet Structure _____
8. Trash Racks _____
9. Anti-vortex Devices _____

10. Stop Logs, Flash Boards _____

11. Remarks _____

B. Emergency Spillway

Type _____

Controlled or Uncontrolled _____

1. Approach Channel _____

2. Transition _____

3. Control Section _____

4. Discharge Channel _____

5. Remarks _____

C. Drawdown Facilities, Gates, Drains, Appurtenances, Etc.

1. Drawdown Facility _____

Condition _____

2. Other Gates, Drains, Appurtenances _____

Condition _____

3. Remarks _____

IV. Operation and Maintenance

V. Inspection Summary

A. Information Obtained

1. Photographs _____

2. Dimensions _____

3. Other _____

B. Additional Information Needed

C. Overall Condition of Dam

VI Owner Interview Yes No When/where _____

(A) Plans, inspection reports, photos, other records? _____

(B) History of dam _____

(C) Performance, floods, operation, etc. _____

(D) Property lines, access, water rights, etc. _____

(E) Other Information _____

VII. General Comments

Check List completed by Name _____

Title _____

Date _____

Attachments: _____



State of

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
RELAY SERVICE FOR THE HEARING IMPAIRED
1-800-253-0191 TDD>Voice
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

November 14, 2001

Carol Davis
Town Clerk
2974 VT Route 110
Washington, VT 05675

Re: Hands Mill Dam - Washington

Dear Ms. Davis,

Attached is a report of our June 20, 2001 inspection of the dam owned by the Town of Washington in Washington, Vermont. Some items in the recommendations of the reports should be given early attention.

The report outlines the condition of the dam, recommendations for the owner and information about the jurisdiction of the Department under the statute on dams (10 VSA Chapter 43).

Please contact me if you have any questions on the report or recommendations.

Sincerely,

Robert B. Finucane, P.E.
Dam Safety Engineer

cc: Larry R. Fitch, P.E., Director, Facilities Engineering Division.



State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
RELAY SERVICE FOR THE HEARING IMPAIRED
1-800-253-0191 TDD>Voice
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

MEMORANDUM

TO: For the Record

FROM: Robert B. Finucane, P.E., Assistant Dam Safety Engineer

DATE: November 14, 2001

SUBJECT: Inspection of the Hands Mill Pond Dam, Washington

On June 20, 2001, Robert B. Finucane, and Jennifer Vosburgh, made a routine inspection of the Hands Mill Pond Dam in Washington, Vermont. A number of photographs were taken. A second visit to the site was made on August 3, 2001 to set a benchmark. The dam was last inspected by the Department on November 14, 1984, and the report of that inspection is on file. This report updates that report and records additional information. The inspection was carried out under the provisions of 10 VSA 1105. Permission to inspect the dam was given by Selectman Don Milne in a phone conversation on June 19.

OVERALL CONDITION

The overall condition of the dam is poor. The spillway section is partially failed at the left end and exhibits widespread concrete deterioration, spalling and erosion. The embankment section is overgrown with trees and brush.

RECOMMENDATIONS FOR OWNER

Recommendations for the owner include:

- 1) The owner should retain an professional engineer experienced in the design of dams to develop plans to either reconstruct or remove the dam. Even though the dam has withstood flood and weather for decades, it will not last forever. A sudden failure of the dam during regional high water could cause public and private property damage and loss of life downstream.
- 2) Maintenance of the dam should be improved to include clearing and brushing of the dam along the crest, the upstream slope, and the downstream slope to ten feet below the toe of the dam.
- 3) An emergency action plan (EAP) should be developed, implemented, and tested. The plan should indicate who would be responsible for routine and flood-time observation of the

dam, the conditions which would be cause for alarm and the way in which people possibly affected downstream would be notified

INSPECTION

The inspection of the dam was conducted on June 20, 2001, between 1300 and 1430 hours. The weather was partly cloudy and in the 80's. The pond level on August 3, 2001 was 0.2 feet below the PK nail set in a 4x4 in the crest of the dam and about the same as during the June 20 inspection. The ground was dry. Portions of the first visit to the site were observed by Ann Jennings and Brian Fitzgerald from the Water Quality Division. Washington Selectman, Don Milne was also present. The following was observed:

1. Embankment Section.

a) Upstream Slope. The upstream slope was in fair condition, and was found to be firm, dry, and irregular and heavily overgrown with brush and trees.

b) Downstream Slope. The downstream slope of the dam was also overgrown, steep, dry and irregular. Portions of the slope on the right side of the spillway are covered with riprap. At the right of the spillway, there is evidence of historic overtopping and sloughing of the embankment. On the left side of the spillway, the foundations of the old mill building form the slope.

c) Crest. The crest was found to be in poor condition. The crest to the right of the spillway is narrow, and overgrown with vegetation, including trees twelve inches in diameter breast high. The roots of these trees grow into the embankment generating pathways which allow water to enter and cause the embankment to deteriorate and eventually fail.

A 4-inch diameter, 12 inch deep hole was found in the crest to the left of the spillway, and a grade stake with flagging on it was placed in the hole. When revisited on August 3, the hole had grown to 18 inches diameter and 12 inches deep. It is believed that the hole is caused by topsoil washing into the old stone mill foundation.

d) Toe. The toe was firm, dry, and irregular and overgrown with vegetation on the right side of the spillway. Seepage was found flowing at approximately 5-10 gallons per minute from the old mill sluice that had been previously filled in at the left end of the spillway.

2. Principal Spillway.

a) Approach. The approach was in fair condition. The pond is largely silted in and with the crest of the dam lowered, the stream meanders through the sediments to form a small pool above the spillway.

b) Weir. The weir structure was in poor condition. The height of the dam appears to be

the same as it was as it was at the last inspection in 1984. The weir is constructed of cyclopean concrete. Portions of the wall were covered with seepage and moss, ferns, and other small plants. Spalling was observed up to twelve inches in depth on the right side of the spillway, and seepage with various flow rates was found along the entire length of the wall to the right of the spillway. Portions of the wall have failed and debris has collected at the end of the wall on the right side of the downstream slope. Comparison with the 1979 photos documents widespread concrete deterioration.

c) Outlet Channel. The outlet channel is clear. A concrete training wall downstream of the right side of the spillway visible in the 1979 photographs has collapsed.

3. Sluice. The sluice was in fair condition. Minor seepage and efflorescence was observed.

HYDROLOGY AND HYDRAULICS

The drainage area at this site is about 4,130 acres. The pond area at the normal pool is 2 acres with storage of about twelve acre-feet including sediments. At the top of the crest the dam stores sixteen acre-feet. The maximum spillway capacity is about 800 cfs.

DOWNSTREAM HAZARD CLASSIFICATION

The dam is a Class 2, "significant hazard" dam.

JURISDICTION

Since the dam impounds more than 500,000 cubic feet, any alteration, reconstruction or breaching would require prior approval from the Department under provisions of 10 VSA Chapter 43.



Hands Mill Dam, Washington
2001

Spillway. Note vegetation,
seepage, and concrete
deterioration on walls and
rubble in spillway crest.



Spillway from left abutment.

Handy Mine

8/3/61

NBF

JMV

WL = 0.1' below PK road
set in road 4×4 in
spiral

Sink hole in left about now
18' dia x 12" deep
previously noted and
flagged at 4" dia


Flatts Mill dam

6/20/01
RBT
JMV

← fens
water dripping from
d d d

← water flowing
from under rock

right embankment completely
saturated by water (bottom 1/2)



concrete wall flow
broken up

Spoke To Mr. Allen,
Washington Suburban,





He will meet me at the
then Clerk's Office at
at 1:30 to do inspection
at home



01-31-01

< >22+01 NHH-02AU 183

**DOCUMENTS
WERE FOUND
STUCK
TOGETHER**



1-31-24

Hands Malt 6/20
[2001]

Carbon stone to exhibit
Trees up to 12" dbh
heavy brush
diameter
brush high

oak

1300

cyc conc main

mile

spun


BT fitz

ann, ening

RBF

JMV

PC 80c



core spalled
up to 12"
deep
sec up
generally

end
RT side crest failed
visible d/s wall failed

hole coes till but
sticks + flag

old mill sluice filled in
5-10 years

new sluice 2 x 7 plants up

Filename: Document4
Directory:
Template: C:\Documents and Settings\paulak\Application
Data\Microsoft\Templates\Normal.dot
Title:
Subject:
Author: Staff
Keywords:
Comments:
Creation Date: 12/9/2004 10:04 AM
Change Number: 1
Last Saved On:
Last Saved By:
Total Editing Time: 0 Minutes
Last Printed On: 12/9/2004 10:06 AM
As of Last Complete Printing
Number of Pages: 1
Number of Words: 0 (approx.)
Number of Characters: 4 (approx.)



State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
RELAY SERVICE FOR THE HEARING IMPAIRED
1-800-253-0191 TDD>Voice
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

**Dam Safety Section
Facilities Engineering Division
103 South Main Street
Waterbury, VT 05671-0407**

Telephone (802) 241-3451
FAX (802) 241-3273
peter.barranco@anrmail.anr.state.vt.us

May 4, 1999

Carol Davis
Town Clerk
2974 VT. Route 110
Washington VT 05675

Re: Hands Mill Dam - Washington

Dear Ms. Davis:

This will confirm our telephone conversation this morning regarding the Department's request to make a routine safety inspection of the Hands Mill Dam this summer under provisions of 10 VSA Section 1105 (copy enclosed). The dam was last inspected by the Department in 1984 and a report sent to the Town.

It is my understanding that you will bring this to the attention of the Selectmen for their consideration. I would appreciate it if you or the Select Board could write me confirming we have the Town's permission to make the inspection. We will let you know in advance of the inspection date in the event someone from the Town would like to accompany us. A report will be prepared following the inspection and a copy will be sent to the Town.

Thank you for your assistance. Please give me a call if you have any questions or we can be of any help.

Sincerely,

A. Peter Barranco, Jr., P.E.
Dam Safety Engineer

Enclosure as noted.

c: Harry K. Roush, Fire Chief, Washington
Larry R. Fitch, P.E., Director, Facilities Engineering

3/4/99
SPD

Hande Mill Day - Washington
3/4/99 @ 0800 Helen Harry Beach (Fire Chief) ²⁴¹⁻³⁵⁸⁷
re: status of ~~Hande~~ → still partially break off
rid, & salted in. Advised plan to suggest
the ~~number~~ - who should we contact?

→ Carol Davis TC @ 833-~~2218~~ 2218

@ 0930 then Carol Davis - OK &
do investigations - she will advise Election -
Harry Beach called her already - will send
her letter + call again when we have
it scheduled (renewal convention).

2974 VT Route 110

Washington VT 05675

7/31/91
ADD

HANDS MILL VT 00308 DEC 225-1

Add to Net Dam Flow

tentative Class 2 (changed for class 3
even though silted in until further
verified).

USGS 44-B

$$\begin{aligned} \text{Lat} & 44 \quad 05 + \left(\frac{20.3}{37.9} \right) (2.5) = 44 \quad 06.34 \\ \text{Lon} & 72 \quad 25 + \left(\frac{8.9}{27.4} \right) (2.5) = 72 \quad 25.81 \end{aligned}$$

dimension from file - reports

L = 325' (incl. spillway)

H = ? 22' SHH

Spillway 28' x 2' (min) cyclo, conc.

? 18' DHS
(scale of plan)
bottom of conc. spill

DA = $\frac{6 \times 45 \text{ m}^2}{2.4} = 4128 \text{ A}$

H \downarrow 2.4

C = 2.8 @ 2'

to stream bed?

3.1 @ 3'

say H = 20' \pm



orig dam c. 1860

pond shown a old maps

conc. spill c. 1923

SHH says (1950) at least 45'
 years old

Heater spill water
and in 1927 (land)

1972 survey Top of embank - irregular 2'-3'

above spillway crest

Call it 2.5' for no overlapping at all

possible 0.5' at rt. end spill

very approx

$$Q = (3.0)(68)(2.5)^{1.5} = 806 \text{ cfs} \approx 800$$

(doesn't not include flow through partial
breach)

DHS report used 1025 cfs

(~~1025~~)

VERMONT DAM INVENTORY

Dam name HANDS MILL	State ID	225-1
	National ID	VT00308
Other name	FERC No	0
	Basin No	8
Hydro Fac Name	Basin name	WINOOSKI RIVER
Hydro Fac Owner		
Town WASHINGTON	County ORANGE	
Latitude 44- 6.34	Longitude 72-25.81	
River or Stream JAIL BRANCH	Downstream Hazard	2
Nearest City/Town WASHINGTON	Size Category	
Distance Nearest City/Town .00 MI	Hazard subclass	
Owner Name(1) TOWN OF WASHINGTON	Purposes	0
Address WASHINGTON, VT 05675	Year Completed	1860
	Status	ABANDONED
Telephone	Owner type(1) L	
Owner Name(2)	Dam type	RE
Address	Constr type EARTHFILL	
	Dam height	20 FT
Telephone	Owner type(2)	
Non-Fed Dam on Fed Prop N	Dam length	325 FT
	Maximum storage	16 AF
	Nor storage	12 AF
Orig const date 1860	Purpose MILL POWER	
Design	St Auth NR	
Recon/Mod 1 date 1928	Purpose CONC SPILLWAY	
Design UNKNOWN	St Auth NR	
Recon/Mod 2 date	0 Purpose	
Design	St Auth	
Dike Type	Height	0 FT
D/S Haz	Stor:Nor	0 AF
	Max	0 AF
	Structural height	20 FT
	Hydraulic height	20 FT
Prin spill CYCL CONC OVERFALL 68'L X 2.5'D	Hydro fac type	
Design cap	0 CFS	
Max cap	800 CFS	
Emer spill NONE	Hydro devel date	0
Design cap	0 CFS	
Max cap	0 CFS	
	Installed capacity	0 KW
Plans NO	Specs NO	
Field dwg YES	Photos YES	
Des. docs NO	Other SURVEY	
	Phase I inspection	N
	Phase I insp date	
	Phase I report	
USGS Quad 44-B Corps L-9	VT7420-16-155	
Other AP VT-62-H-47-167	Ortho	
Other maps	Inspection date	11/14/84
	Inspected by DEC	
	Authority	10 VSA 1105
Remark ORIG DAM MAY DATE TO 1860'S. TIMBER	Emergency action plan	NR
SPILLWAY WASHED OUT IN 1927 FLOOD,		
REPLACED WITH CONCRETE C.1928.	Last State inspection	1984
POND SILTED-IN. MAY BE CLASS 3.		
	Next State insp due	0
	RECORD	590

7/31/91

7/19/99
HDB

Hande Hill Dam

7/19/99 1415 Don Walne, Secretary of
Washington called to say we have
town's permission to proceed. It would
look to be good. The town is interested
in getting and what they should do
with the dam. They're concerned with
the condition even though it is well.

828-247 work

Advised we would be glad to have
him here and will call in advance.
Expect it would be during the first
two weeks of August.

VERMONT DEPARTMENT OF WATER RESOURCES
INFORMATION SHEET

Name of Dam Hands Mill Town Washington

Owner Town of Washington Name of Stream Sail Brook

Address _____ Classification _____

Vermont

U.S.G.S. Coordinates: Lat. 44° 3' 24" Long. 72° 23' 54"

U.S.G.S. Map East Barre Aerial Photos VT-62-H 47-166 to 167

U.S.G.S. Elev. @ Spillway _____

Total Length of Dam 260' Crest Width of Emergency 60-70'
Spillway

Width of Top 2.35' Maximum Height 20' 19' check

Spillway Capacity: Principal _____ Emergency 3600 cfs

Pond Area 2 acres Drainage Area 6.45 sq mi.

Pond Volume: Normal Water Level _____ Design High Water Level _____

Maximum Water Depth: Normal Water Level _____ Design High Water
Level

Storage Before Emergency Spillway is Used _____

Use of Reservoir N/A

Description of Dam: Earth filled with heavy concrete spillway

Description of Spillway(s): Concrete 60-70' wide
2' below top of dam 3' in 1' downstream
1' in 1' upstream

Designed by _____ Year Built 1928*

Hearing Date _____ Order Date _____

Additional Remarks: * Concrete section; unknown for rest.



State of Vermont

AGENCY OF ENVIRONMENTAL CONSERVATION

Department of Fish and Game
Department of Forests, Parks, and Recreation
Department of Water Resources & Environmental Engineering
Natural Resources Conservation Council

Montpelier, Vermont 05602
Department of Water Resources
and
Environmental Engineering

(802) 828-2761

November 18, 1984

Ms. Patricia Woodward
Town of Washington
P.O. Box 5
Washington, Vermont 05676

Re: Hands Mill Dam - Washington

Dear Ms. Woodward:

Enclosed is a copy of the Department's 1975 report on the Hands Mill Dam which you requested by telephone on November 14.

The dam has been inspected by the Department in 1950, 1953, 1972, 1973, 1975, 1979 and most recently on November 14, 1984. The latter was a cursory inspection due to snow, ice and stream conditions. The dam is judged to be in very poor condition and deterioration has been noted over the years.

Further failure of the structure could occur during periods of high inflows, or at other times. Since the pond has very small storage due to the sedimentation, damages due to a failure would be less severe than if the pond was at the original capacity. However, a major failure would undoubtedly damage the road and structures below the dam. Direct threat to loss of life due to discharges associated with a failure of the dam itself, i.e. not considering concurrent flooding from the watershed, is probably low in its present silted-in condition.

The Department recommends that the Town either rehabilitate the dam to an acceptable condition or remove part or all of the spillway to reduce the risk of failure and resulting damages. The latter approach would necessitate an acceptable plan to stabilize sediments behind the dam and prevent their release downstream. Since the dam is or was capable of impounding more than 500,000 cu. ft., prior approval from the Department is needed to reconstruct, alter or breach the dam under provisions of 10 VSA Chapter 43, Dams (copy enclosed).

Should you or other town officials have any questions,
please get in touch,

Sincerely,



A. PETER BARRANCO, Jr., P.E.
Dam Safety Engineer

APB:j

cc: Board of Selectman, Town of Washington

encl: (1) 1975 report and transmittal letter
(2) Copy of 10 VSA Chapter 43

HANDS MILL DAM

6-7-79



79-15-21



CREST OF E/F SECTION



LOOKING UPS (1) HILLSIDE

(SILTED IN)

AGENCY OF ENVIRONMENTAL CONSERVATION

MONTPELIER, VERMONT

AGENCY MEMORANDUM

SUBJECT

TO:


FROM:

DATE:

HOLDS MILL DAM
6-7-79



79-15-25



79-15-28

WASTE GATE TO RIGHT OF
SPILLWAY

AGENCY OF ENVIRONMENTAL CONSERVATION

MONTPELIER, VERMONT

AGENCY MEMORANDUM

SUBJECT

TO:

FROM:

DATE:

HANDS MILL DAM
C-7-79



79-15-30

UNDERMINING @ RIGHT-
ABUTMENT OF MAIN
SECTION

AGENCY OF ENVIRONMENTAL CONSERVATION

MONTPELIER, VERMONT


AGENCY MEMORANDUM

SUBJECT

TO:

FROM:

DATE:




2000
JAN 10 1991
10:00 AM

INDS MILL DAM Washington



79-15-25

15



79-15-31

TAIL RACE IN BACK OF LEFT SIDE
MILL WHEEL SHOWN PHOTO 25

TO:
FROM:
DATE:

SUBJECT

AGENCY MEMORANDUM

AGENCY OF ENVIRONMENTAL CONSERVATION


GOVERNMENT OF VERMONT

WINDS MILL DAM
Washington
6-7-79




78-15-23

79-15-24 ~~SPILLWAY~~ BREACH



LOOKING DOWN VIS ~~VIEW~~ OF
~~SPILLWAY~~ BREACH TO LEFT OF SPILLWAYS

ARC



79-15-26



27

D/S FACE



79-15-10



79-15-10

2-14
44405 ALL DAM
6-2-79

AGENCY OF ENVIRONMENTAL CONSERVATION

MONTPELIER, VERMONT

AGENCY MEMORANDUM

SUBJECT

TO:

FROM:

DATE:

HINDS MILL DAM

11-14-64



CT-51-25



CT-51-30

D/S Face spillway adjacent to breach

?



CT-51-32

APB

ANDS MILL DAM

11-14-84

Left end
breed



84-51-23

Looking d/s along
right side mill wall
and wheel pit structure.

D/S
↑




84-51-24

Collapsed and eroded area at
right end spillway at embankment (w/isth).

APB

HANDS MILL DAM

11-14-84



84-51-21

84-51-22

view of breach to left of spillway

HANDS MILL DAM

11-14-84



8:51-19

D/S Channel




8:51-20

"Reservoir" as viewed from
crest of dam on R/S spillway near breach
- looking U/S.

APB

HANDS MILL DAM

11-14-64



84-51-18

Crest and d/s slope near right abutment.

HARPS MILL DAM

11-14-84



← left
embankment

84-S1-34 ↑
Spill way

↑
Structure or chamber
for wheel (?)



84-S1-35
Left embankment and wheel
chamber(?)

HANDS MILL DAM


11-14-84



84-51-31 Remnants of well at
right end spillway and
embankment




84-51-36 Breach at left end of spillway.



84-51-33

HANDS MILL DAM

11-14-84



D/S Face of right embankment. Note dry boulder
wall containing embankment along part of d/s face.

wed 11-14-84 APR 5
35° clear, windy, 4" [±] snow

Hands Mill Dam on ground

1350-1430 inspected dam.

Cursorry inspection due to
snow, ice and water conditions.

Rt. Embankment: Crest & up slope -
brush; up slope + toe brush,
trees up to 18" including large
snags: d/s well intact but irregular
and bulging (may be the way
constructed - large boulders - not
cut stone).

Lt. Embankment: Too much snow
to inspect. Brush.

Spillway: d/s face; seepage,
deeply eroded, crumbling; cyclopean
concrete: crest snow covered.
(OVER)

11-14-64

Left spillway abut. - breach
looks about the same - est
0.5' water through breach.

Right Spillway abut. Appear to
be further erosion + movement of
remnants of abut. wall. Depression
in "silt" on up side wall in this
area - probably passed water at
high pond levels or is result of
piping.

Overall in very poor condition.
Only apparent change is further
erosion / undermining at right
abutment of spillway.

Photos

HANDS MILL DAM

3-10-80
HAB

$$GP = 44.05 + \left(\frac{1.50}{5.82}\right)(5) = 44.06.29$$

$$72.25 + \left(\frac{0.70}{4.19}\right)(5) = 72.2584$$

$$SA = 2A \pm$$

$$\text{MAX Vel} = 20 \times 1.4 \times 2 = 16 \text{ AF (cilled in)}$$

$$NL = 16 - 4 = 12 \text{ AF (cilled in)}$$

Air photos

VT-62-H 47-167

VT 7420 16-155

225-1 Hanks Mine - Washington 6-7-79 AMB



- looks like gate chamber (wheel pit?)
- partially broken left end (may have been old ^{headwork} ~~gate~~)
- d/s face eroded - cycloped concrete
- sand filled in
- right abut - undermined
- stable



pot. { - 35th KA $\frac{1}{2}$ up down - $\frac{1}{2}$ up 1st floor - left side before
 { - 2 " " $\frac{1}{4}$ below long probably old ^{burst}
 { - ^{single} ~~reps~~ entire d/s face for ~~to~~ to $\frac{1}{2}$ way up

shows
no
straps

reps through old tail race



11-12-75

HANDS MILL DAM



" HANDS MILL DAM - WASHINGTON
'BREACH' AT LEFT END OF SPILLWAY.
W/L IS 2.3' BELOW THE CREST
OF THE SPILLWAY.

11-12-75 DON SPIES "

ROUTING	
GENERAL	
AS	6/27/75
AM	
W	
JEC	PC
SUSPEND TO	
FILE	Hand's Mill Dam

MANAGEMENT & ENGINEERING DIVISION

June 25, 1975

Chairman, Board of Selectmen
Washington
Vermont 05673

Gentlemen:

The Department of Water Resources is pleased to present you with a copy of its recently completed report on Hand's Mill Dam in Washington.

Essentially, the investigation found the dam to be in a further deteriorated condition since our previous visit. Your attention is invited to the recommendations contained within the report.

We are, of course, available to meet with you and welcome any comments you may have.

Sincerely yours,

Andre J. Bouleau
Assistant Director

AJR/jcl

cc: Catherine Rothell, Water Resources Board

Agency of Environmental Conservation
Department of Water Resources
Management & Engineering Division
June, 1975

INSPECTION REPORT

on

HAND'S MILL DAM
Washington, Vermont

Owner	Town of Washington
Date Built	Prior to 1927 (original construction) 1928 (partial reconstruction)
Type of Structure	Earth fill flanking a concrete gravity spillway
Watershed Area	6.45 square miles
Probable Spillway Capacity	1,025 cfs (no freeboard)
Peak Flood Inflow Used In Analysis	715 cfs (100-year frequency)

TABLE OF CONTENTS

	<u>Page</u>
I. INTRODUCTION	1
II. PURPOSE	1
III. SCOPE	2
IV. WATERSHED DESCRIPTION	2
V. SITE DESCRIPTION	3
VI. STRUCTURE	3
A. DESCRIPTION	3
B. CONDITION	3
C. SPILLWAY ANALYSIS	4
1. HYDRAULIC	4
2. HYDROLOGIC	4
D. CLASSIFICATION	5
VII. RECOMMENDATIONS	5
VIII. SELECTED REFERENCES	6
IX. APPENDICES	6ff

HAND'S MILL DAM

I. INTRODUCTION

Vermont has a long history of major floods during which loss of life and considerable property damage has occurred. The failure of dams has added materially to the peak flood flows and related losses. Basically, many of these failures are a result of either inadequate spillways; improper design and/or construction; or improper or insufficient maintenance.

Under Chapter 43, Title 10, Vermont Statutes Annotated, the Water Resources Board has jurisdiction over all dams impounding more than 500,000 cubic feet of water and not incident to the generation of electric energy for public use. The Department of Water Resources assists the Board by conducting a continuing program of inspection and investigation of existing statute-size dams. These investigations serve as a means of obtaining up-to-date information on existing dams, particularly with regards to their maintenance and their safety. As part of this program, an examination was made of the Hand's Mill Dam.

II. PURPOSE

1. To summarize the findings from the Department's investigation of the Hand's Mill Dam in the Town of Washington, Orange County, State of Vermont.
2. To report on the present condition of the structure and on the adequacy of its maintenance.
3. To determine the capacity of the spillway and evaluate its ability to pass reasonable flood flows.

(Continued)

4. To recommend appropriate action to be taken with regards to any flood hazards associated with the existing structure.

5. To recommend necessary repairs and alterations.

III. SCOPE

The scope of this investigation included a topographic survey and visual inspection of the structure on June 19 and 20, 1972. Additional inspections were made on July 17, 1973 and April 23, 1975. Office studies of the spillway capacity and the ability of the structure to pass flood flows were conducted. The summarization of the various findings have been incorporated into this report.

IV. WATERSHED DESCRIPTION

The watershed above Hand's Mill Dam has a drainage area of approximately 6.45 Square miles (see Appendix 1) and can be divided into two sub-basins—one for the Jail Branch and one for a tributary with its confluence at Hand's Mill Pond. The Jail Branch starts in the southeastern corner of the watershed and drops more than 1,050 feet before reaching the pond; this sub-basin is basically oval-shaped with its major axis oriented along an approximate northwest-to-southeast line. The other stream begins in the northeastern corner of the watershed and has a drop of about 1,075 feet before reaching the pond; this sub-basin is roughly rectangular in shape with its major axis along an approximate northeast-to southwest line. Both streams have steep gradients. The watershed terrains are predominantly hilly and about evenly divided between farm land and forest cover. There are no significant bodies of water above the site.

(Continued)

V. SITE DESCRIPTION

Hand's Mill Pond is an artificial impoundment located on the Jail Branch in the southeast corner of the Village of Washington. The pond has a surface area of approximately two acres and is roughly circular in shape. At the present, the pond is almost entirely silted in. The only apparent purpose the pond now serves is as a home to some waterfowl and beavers.

VI. STRUCTURE

A. DESCRIPTION

Hand's Mill Dam consists of a concrete gravity section, which serves as the spillway, and flanking earth embankment sections. Portions of the embankments adjacent to the spillway are backfilled against dry stone walls which form the downstream face.

Little is known about the history of this dam. It is known a mill existed at the site as early as 1866; since the mill ran on water power, it is assumed there was a mill pond and dam. The concrete section was built after 1927, its timber predecessor having been destroyed during the flood of November in that year.

B. CONDITION

The east embankment is overgrown with trees and brush and also appears to have insufficient cross-section. The west embankment has small brush on its downstream face. No seepage was noted along the embankment sections.

The concrete is badly deteriorated. The downstream face is severely spalled, and there is seepage through much of the section. The downstream

(Continued)

abutment wall at the east end of the spillway has collapsed but doesn't appear to have weakened the spillway. At the west end, a section of the abutment has collapsed allowing water to pass around the end of the spillway. This section has gradually increased in size over the years. The owner of the dam has dumped granite grout on the adjacent embankment to reduce the erosion.

The dam is in poor condition, but it does not appear to be in immediate danger of failing.

C. SPILLWAY ANALYSIS

1. Hydraulic

The existing conditions were analyzed by considering the eroded section as a spillway section. The eroded area was treated as a broad-crested spillway, and the spillway was treated as a sharp-crested weir. With the water level approximately up to the low section of the embankment, the combined flow through the spillway area is approximately 1,025 cubic feet per second (cfs).

2. Hydrologic

Flows of the Hand's Mill Dam were determined from the records of an adjoining gaged watershed. A 100-year-return flood at the dam has a peak flow of about 715 cfs. The surcharge storage in the pond is virtually negligible, resulting in little reduction of the peak in-flow; thus, the peak out-flow will be almost identical to the peak in-flow. For the 100-year flood, the peak water level will be less than six inches below the low section of the embankment.

(Continued)

D. CLASSIFICATION

Each dam under the jurisdiction of the Water Resources Board is classed into one of three categories according to the potential amount of downstream damage that particular dam could inflict should it fail. Class I dams are all structures, due to their size and/or location, a failure of which would result in major downstream damage, including the destruction of buildings, major disruption of utilities and/or transportation facilities, or the possible loss of human life. Class II dams are those due to size and/or location whose failure would result in some downstream damage including damages to buildings and possible disruption of utilities and/or transportation facilities, but would probably not result in the loss of life. Dams in Class III are those, due to size and/or location, whose failure would result in only minor damage.

Below Hand's Mill Dam is a house, Town Highway No. 9 , and Bridge No.29 which could possibly suffer some damage from a failure of the dam. The house is likely to be limited to minor damage—such as silt and water damage—to the basement and first floor. The highway could suffer erosional damage, particularly the gravel-surface bridge approaches; a severance of the highway would not isolate anyone, but it would force them to go several miles out of their way. The bridge, which has concrete abutments and a cast-in-place concrete deck on steel beams, will probably not suffer any direct damage, but it could become plugged with debris. Therefore, Hand's Mill Dam is classified as a Class II Dam.

VII. RECOMMENDATIONS

Due to the present condition and the continuing deterioration, it is

(Continued)


recommended that the concrete spillway be removed. The Town through its Selectmen should prepare a program suitable to the Department of Water Resources for removal of the spillway and removal and/or stabilization of the sediment in the pond.

VIII. SELECTED REFERENCES

- 1) "Design Of Small Dams", Bureau of Reclamation, 1973.

IX. APPENDICES

- 1) Watershed Map.
- 2) Location Map.
- 3) Photographs.
- 4) Plans.




APPENDIX 1

HAND'S MILL DAM

WATERSHED BOUNDARY

WASHINGTON COUNTY

WASHINGTON STATE FOREST



HAND'S MILL DAM



Looking across spillway toward east embankment



Upstream face of west embankment

(Continued)

APPENDIX 3



Downstream face of spillway

The undersigned representatives of the U.S. Army Corps of Engineers,
New England Division visually inspected the _____ Dam on
_____ 1973 between the hours of _____, and _____.
On the basis of visual observations, the following comments are made:

CF:

• (Town Official):
Vt. Water Resources Board
Coordinator, COE
Dam Inspection Team
Mr. E. P. Gould

Location: Town of _____, County of _____, State of Vermont
Stream: _____
Map Coords.: _____
Other: _____


Owner: _____

Function of Dam: _____


JULY 17, 1973



Photos taken during damaged survey inspection
by DWR & COE following 1973 flood.



INSET (3)
WASHINGTON



Hand's Will Dab

Washington

6-19-72

Warm
Overcast

N Don Spies
N Jim Huntington
O Jim Thompson

6-20-72

Warm
Overcast

N DHS
N 4/4
O 4/4

COPY

Sta.	Rod Reading	Stadia Interval	Distance	Horiz. 4	Vert. 4
	(B.S.)	(H.I.)			
BM #1	1.50	101.50			
BM #1	1.50	0.53	53	39° 24'	-
1	3.00	0.69	69	18° 5'	-
2	3.18	0.61	61	2° 14'	-
3	2.07	0.60	60	353° 48'	-
4	4.56	0.33	33	15° 21.5'	-
5	4.57	0.32	32	14° 56'	-
6	7.72	0.39	39	348° 46'	-
7	4.97	0.22	22	348° 46'	-
8	5.41	0.19	19	320° 33'	-
9	2.50	0.22	22	320° 33'	-
10	4.65	0.07	7	320° 33'	-
11	4.99	0.13	13	292° 48'	-
12	5.17	0.27	27	271° 8'	-
13	5.47	0.28	28	283° 43'	-
14	7.43	0.32	32	289° 43'	-
15	7.68	0.35	35	289° 43'	-
16	5.60	0.32	32	281° 0'	-
17	7.22	0.38	38	281° 0'	-
18	7.71	0.42	42	281° 0'	-
19	5.35	0.34	34	273° 10'	-
20	7.74	0.48	48	273° 10'	-
21	5.54	0.43	43	263° 13'	-

100.00

0° 0' S 21° 30' E (100)

100.00

X checked in back outcrop
on east side of road

100.00

98.5

1 edge of road

98.32

2 edge of road

94.13

3 bottom of bank

96.94

4 edge of bank

96.93

5 top of bank

93.78

6 bottom of bank

96.03

7 top of bank

96.03

8 top of bank

94.00

9 edge of bank

96.03

10 E. of dam

96.03

11 E. of dam

94.13

12 S. of dam

96.03

13 top of bank

93.07

14 bottom of bank

93.82

15 edge of water

95.00

16 top of bank

94.28

17 bottom of bank

93.09

18 edge of water

96.15

19 top of bank

93.06

20 edge of water

95.36

21 top of bank

Sta.	Rod Reading	Stadia Interval	Distance	Horiz. 4	Vert. 4
22	9.06	0.52	52	263°-13'	-
23	5.98	0.48	48	261°-0'	-
24	6.43	0.53	53	257°-24'	-
25	6.04	0.47	47	257°-24'	-
26	6.12	0.36	36	259°-36'	-
27	5.56	0.33	33	259°-36'	-
28	8.26	0.33	33	251°-5'	-
29	5.92	0.14	14	252°-0'	-
30	5.10	0.06	6	249°-33'	-
31	5.53	0.06	6	125°-0'	-
32	6.39	0.13	13	126°-53'	-
33	7.92	0.29	29	145°-11'	-
34	8.05	0.31	31	141°-32'	-
35	7.90	0.45	45	116°-59'	-
36	5.05	0.10	10	30°-30'	-
37	8.23	0.12	12	208°-52'	-
38	10.78	0.18	18	176°-8'	-
39	12.02	0.24	24	206°-36'	-
40	12.47	0.29	29	203°-41'	-
41	11.55	0.26	26	187°-0'	-
42	9.16	0.23	23	154°-33'	-
43	7.53	0.13	13	151°-45'	-
44	9.68	0.23	23	245°-47'	-
45	10.49	0.26	26	229°-13'	-

Elev.

0° 0' = mag 521° 30' E

92.44

22

top of bank

95.55

23

top of bank

95.07

24

top of bank

95.12

25

top of bank

94.63

26

top of bank

94.17

27

top of bank

93.24

28

bank

95.52

29

top of bank

96.10

30

top of bank

95.97

31

top of bank

94.17

32

top of bank

95.28

33

top of bank

93.45

34

edge of road

93.65

35

edge of road

96.45

36

top of dam

93.20

37

bank

90.22

38

bottom of bank

90.15

39

bottom of bank

89.03

40

bank

89.95

41

bank

92.34

42

bank

93.97

43

bank

91.50

44

bank

91.50

45

bank

Sta.	Rod Reading	Stadia Interval	Distance	Horiz. \angle	Vert. \angle
	(B.S.)	(H.I.)			
BM #1	1.09	10.109			
BM #1	1.09	0.88	88	58°-3'	-
1	4.61	0.40	40	81°-42'	-
2	9.43	0.07	7	192°-38'	-
3	7.55	0.12	12	135°-3'	-
4	8.64	0.15	15	162°-15'	-
5	9.70	0.29	29	207°-23'	-
6	6.38	0.42	42	200°-48'	-
-7-	14.00	0.19		162°-2'	12°-45'
8	12.63	0.33	32	202°-29'	8°-17'
9	14.51	0.19	19	164°-34'	2°-39'
10	8.39	0.17	17	246°-36'	-
11	8.95	0.14	14	228°-35'	-
12	8.88	0.27	27	234°-26'	-
13	8.68	0.22	22	251°-8'	-
14	11.44	0.24	24	250°-47'	-
15	7.13	0.26	26	276°-15'	-
16	8.73	0.22	22	272°-0'	-
17	10.93	0.25	25	269°-25'	-
18	6.99	0.51	51	278°-0'	-
19	6.99	0.88	88	278°-44'	-
20	6.98	0.90	90	280°-14'	-
21	4.84	0.92	92	280°-17'	-

1 km

0° - 0' = mag 5 21° - 30'E

100.00

100.00

99.66

93.59

92.45

91.31

91.21

83.75

85.70

82.43

82.14

82.21

82.1

81.60

93.96

92.36

90.12

91.20

86.20

82.2

82.25

1 1st Set Top

2 bottom of bank

3 top of concrete wall

4 top of concrete wall

5 bottom of concrete wall

6 bottom of concrete wall

7 bottom of concrete wall

8 bottom corner

9 bottom of concrete wall

10 bottom of bank

11 bottom of bank

12 end of bank

13 end of bank

14 top of concrete wall (downstream)

15 top of concrete wall (downstream)

16 top of concrete wall (downstream)

17 top of concrete wall (downstream)

18 top of concrete wall (downstream)

19 top of concrete wall (downstream)

20 top of concrete wall (downstream)

21 top of concrete wall (downstream)

Note: width top of spillway = 2.35'

Sta.	Kod Reading	Stadia Interval	Distance	Horiz. \angle	Vert. \angle
22	14.00	0.88	87	272° 4'	4° 57'
23	14.00	0.76	75	274° 31'	5° 28'
24	14.03	0.50	49	274° 6'	9° 28'
25	14.50	0.26	24	269° 10'	16° 41'
	(B.S.)	(H.I.)			
BM #1	2.41	102.41			
BM #1	2.41	1.87	187	82° 46'	-
1	5.92	1.54	154	96° 32'	-
2	6.25	0.19	19	113° 58'	-
3	5.41	0.16	16	113° 58'	-
4	7.85	0.16	16	99° 22'	-
5	8.52	0.17	17	89° 40'	-
6	7.18	0.15	15	137° 36'	-
7	10.66	0.34 ^(0.24)	34 ⁽²⁴⁾	150° 9'	-
8	13.38	0.26	26	156° 6'	-
9	9.19	0.08	8	30° 36'	-
10	6.13	0.09	9	193° 6'	-
11	8.42	0.15	15	196° 47'	-
12	14.40	0.16	16	196° 47'	-
13	4.68	0.07	7	281° 40'	-
14	9.38	0.25	25	308° 43'	-
15	4.90	0.23	23	289° 17'	-
16	5.92	0.25	25	274° 5'	-

0° 0' = mag 5 21° 30' E

80.84

22

spillway wall

79.52

23

bottom spillway wall

78.95

24

bottom spillway wall

77.74

25

bottom spillway wall

140.00

140.00

96.49

1

1st spillway point

96.16

2

top abutment

11.41

3

& dam

11.16

4

bottom at bank

93.83

5

edge of water

93.43

6

bank

91.15

7

top stone wall

89.03

8

bottom stone wall, road

93.22

9

edge of water

94.25

10

bank

93.43

11

top stone wall

91.15

12

bottom stone wall

92.73

13

A of stone

93.03

14

edge of water

94.51

15

& of dam

96.49

16

bank

Sta.	Rod Reading	Stadia Interval	Distance	Horiz. \angle	Vert. \angle
17	14.81	0.29	29	166° 0'	-
18	14.58	0.22	22	201° 0'	-
6-20-72					
	(B.S.)	(H.I.)			
BM #1	2.49	102.49			
BM #1	2.49	1.88	188	61° 18'	-
1	6.92	1.09	109	103° 49'	-
2	8.23	1.01	101	98° 9'	-
BM #2	6.32	0.19	19	89° 51'	-
	(B.S.)	(H.I.)			
BM #2	7.23	103.40			
BM #2	7.23	0.44	44	89° 36'	-
1	5.19	0.24	24	90° 54'	-
2	7.55	0.11	11	161° 31'	-
3	12.79	0.11	11	167° 31'	-
4	8.66	0.28	28	286° 22'	-
5	4.60	0.27	27	272° 26'	-
6	7.40	0.28	28	254° 56'	-
7	11.65	0.29	29	239° 37'	-
8	13.23	0.33	33	229° 24'	-

Liev.

0° 0' = mag S 21° 30' E

87.13

17 in field

87.88

18 in field

0° 0' E mag S

100.00

100.00

95.57

1 bottom station

94.26

2 bottom station

96.17

top station at intersection of each fi

96.17

96.17

98.21

1 3rd station point

95.95

2 top station wall

90.61

3 bottom station wall

94.74

4 edge of water

98.80

5 E of dam

96.00

6 bank

91.75

7 bottom of bank

90.14

8 in field

Sta.	Rod Reading	Stadia Interval	Distance	Angle	Bearing
9	14.52	0.24	24	168°-14'	-
10	7.35	0.17	17	245°-12'	-
11	9.98	0.17	17	243°-18'	-
	(B.S.)	(H.I.)			
BM #2	6.59				
BM #2	6.59	1.18		93°-22'	-
	(B.S.)	(H.I.)			
BM #2	6.27	102.44			
BM #2	6.27	1.18	118	93°-25'	-
1	4.96	0.74	74	95°-23'	-
2	9.44	0.31	31	86°-13'	-
3	4.92	0.29	29	100°-29'	-
4	8.21	0.28	28	113°-53'	-
5	11.91	0.30	30	127°-49'	-
6	12.79	0.32	32	135°-20'	-
7	8.69	0.10	10	37°-29'	-
8	8.26	0.08	8	46°-28'	-
9	4.83	0.08	8	100°-58'	-
10	7.50	0.07	7	155°-29'	-
11	10.95	0.11	11	166°-7'	-
12	11.69	0.17	17	170°-14'	-

Elev.

0° 0' - mag. S

88.88

in field

96.15

10 end of wall top

93.12

end of wall bottom

96.17

96.17

92.48

1 4th setup point

95.00

2 edge of wall

97.52

3 4 of dam

94.75

4 bank

90.53

5 bottom of bank

97.5

6 in field

93.75

7 edge of 4th

94.13

8 bottom of bank

91.61

9 E of dam

94.24

10 bank

91.49

11 bottom of bank

90.75

12 in field

[illegible]

lev

o' o' mag S

93.76

13 edge of water

94.04

14 bottom of bank

95.31

15 E of dam

96.31

16 bank

93.00

17 bottom of bank

92.79

18 in field

93.71

19 edge of water

95.06

20 bottom of bank

98.32

21 E of dam

96.08

22 bank

94.57

23 bottom of bank

98.08

24 E of dam

95.06

25 E of dam

93.71

26 in field

96.95

27 in field

94.22

28 in mud flat

99.98

Washington

1/2

$$Q = P L H^{3/2} \quad C = 3.50$$

$$= 3.50 (64) (2.0)^{3/2} \quad L = 64'$$

$$= 224 (2.83) \quad H = 2.0'$$

$$= 634 \text{ cfs.}$$

revised

546.75

DHS

Drainage Area

1st

2nd

3rd

4th

Average

47.22

53.87

60.41

67.04

6.75

40.47

47.22

53.87

60.41

6.65

6.75

6.65

6.54

6.63

6.54

6.63

4 | 26.57

6.64 sq. in.

1 sq. in. = 0.973 sq. mi.

$$D.A. = 6.64 (0.973) = 6.45 \text{ sq. mi.}$$

WILLIAMSTOWN 15.9 N.

(BARRE)

WILLIAMSTOWN

Mount Pleasant
Elev. 2002



C O R I

Hand's Mill Dam

Don Spies
May 16, 1975

Hydrology

Flows at Hand's Mill Dam will be determined from the adjacent East Orange Brook Watershed. The fifty-year and one hundred year peak flows were calculated for East Orange and transposed to Hand's Mill using the following formula:

$$Q_{\text{at site}} = Q_{\text{at gage}} \left(\frac{\text{Drainage Area at Site}}{\text{Drainage Area at Gage}} \right)$$

	Q_{50}	Q_{100}
E. Orange Brook	790	914
Hand's Mill Dam	618	715

Hydraulic

The eroded section will be treated as a broad crested weir with a bottom width of eight feet, crest elevation two lower than the spillway and one end contraction. The spillway will be considered as a sharp crested weir with a crest length of 68' and one end contraction.

flow through eroded area:

$$Q_1 = 2.85 L_1 \left(H_1 + \frac{V_{a1}^2}{2g} \right)^{3/2}$$

$$\text{where } L_1 = 8 - 0.1 \left(H_1 + \frac{V_{a1}^2}{2g} \right)$$

flow over spillway

$$Q_2 = 3.30 L_2 \left(H_2 + \frac{V_{a2}^2}{2g} \right)^{3/2}$$

$$\text{where } L_2 = 68 - 0.1 \left(H_2 + \frac{V_{a2}^2}{2g} \right)$$

$$\text{and } H_2 = H_1 - 2.0$$

Table of Stage versus Discharge

	H_1	Q_1	Q_2	Total
	0	0	0	0
	1	30	0	30
	2	84	0	84
	3	148	259	407
	4	221	804	1025

Assuming a straight line relation for discharge between $H_1 = 3'$ and $H_1 = 4'$ then the stage for the 50-year flow is:

$$H_1 = 3 + \frac{618 - 407}{1025 - 407} = 3 + \frac{211}{618} = 3.34' \text{ and}$$

for the 100-year flow is:

$$H_1 = 3 + \frac{715 - 407}{618} = 3 + \frac{308}{618} = 3.50'$$

4-23-75

Long's Mill Dam

Lower bridge covered ~~with~~^{by} concrete. Deck on
steel beams ~~girders~~

16' wide x 8.5' high.

Clayey material placed on lower
end dam. $4\frac{1}{2}$ ~ 1' below top spillway
water going around south end.

Face of spillway badly deteriorated.
all level practically at top spillway.

Setup # 2

sta. 8

$$H.I. = 101.09 \quad \alpha = 8^{\circ} 17'$$

$$R = 0.33$$

$$\text{Rod Reading} = 12.63$$

From Table II, Elementary Surveying

$$h = 97.92 \quad ; \quad v = 14.26$$

$$H = 97.92 (0.33) = 32'$$

$$V = 14.26 (0.33) = 4.71'$$

$$\text{Elev.} = 101.09 - 12.63 - 4.71$$

$$= 101.09 - 17.34$$

$$= 83.75$$

sta. 9

$$H.I. = 101.09 \quad \alpha = 2^{\circ} 39'$$

$$R = 0.19$$

$$\text{Rod Reading} = 14.51$$

From Table II, Elementary Surveying

$$h = 99.78 \quad ; \quad v = 4.62$$

$$H = 99.78 (0.19) = 19'$$

$$V = 4.62 (0.19) = 0.88$$

$$\text{Elev.} = 101.09 - 14.51 - 0.88$$

$$= 101.09 - 15.39$$

$$= 85.70$$

Sta. 22

$$H.I. = 101.09 \quad \angle = 4^{\circ} 57'$$

$$R = 0.88 \quad \text{Rod Reading} = 14.00$$

From Table II, Elementary Surveying

$$h = 99.25 ; v = 8.60$$

$$H = 99.25(0.88) = 87'$$

$$V = 8.60(0.88) = 7.57'$$

$$\begin{aligned} \text{Elev.} &= 101.09 - 14.00 - 7.57 \\ &= 101.09 - 21.57 \\ &= 79.52 \end{aligned}$$

Sta. 23

$$H.I. = 101.09 \quad \angle = 5^{\circ} 28'$$

$$R = 0.76 \quad \text{Rod Reading} = 14.00$$

From Table II, Elementary Surveying

$$h = 99.09 ; v = 9.48$$

$$H = 99.09(0.76) = 75'$$

$$V = 9.48(0.76) = 7.20'$$

$$\begin{aligned} \text{Elev.} &= 101.09 - 14.00 - 7.20 \\ &= 101.09 - 21.20 \\ &= 80.89 \end{aligned}$$

Sta. 24

$$H.I. = 101.09 \quad \angle = 9^{\circ} 28'$$

$$R = 0.50 \quad \text{Rod Reading} = 14.03$$

From Table II, Elementary Surveying

$$h = 97.29; \quad v = 16.22$$

$$H = 97.29(0.50) = 49'$$

$$V = 16.22(0.50) = 8.11'$$

$$\begin{aligned} \text{Elev.} &= 101.09 - 14.03 - 8.11 \\ &= 101.09 - 22.14 \\ &= 78.95 \end{aligned}$$

Sta. 25

$$H.I. = 101.09 \quad \angle = 16^{\circ} 41'$$

$$R = 0.26 \quad \text{Rod Reading} = 14.50$$

From Table II, Elementary Surveying

$$h = 91.75; \quad v = 27.50$$

$$H = 91.75(0.26) = 24'$$

$$V = 27.50(0.26) = 7.15'$$

$$\begin{aligned} \text{Elev.} &= 101.09 - 14.50 - 7.15 \\ &= 101.09 - 21.65 \\ &= 79.44 \end{aligned}$$

9-21-72
GUS. BARRE-MONT

Water Resources Approves Of Washington Pond

WASHINGTON — The Department of Water Resources has found the water quality of the Hand's Mill Pond to be well within the limit suitable for recreation purposes. The pond has been considered by the Washington Planning Commission as a possible recreation site for the town.

John Malter, an official of Water Resources Department, told members about the survey findings in their meeting at the Town Clerk's Office Wednesday night. He and Donald Spies, also from the department, discussed the site with members.

Spies, who took a survey of the dam, consisting of a concrete spillway and land banks said another spring like the last could cause a slight rupture of the dam. Although he said the danger is not great in the event of the rupture, the cellar of an adjacent home could be flooded. He said trees and shrub on the banks also serve to weaken the structure because they attract and hold water. A report on the structure will be available in the winter and Spies said there is nothing binding about the findings.

Members and officials discussed possible methods of eliminating the hazard which included the possibility of lowering the dam and reducing the pond level.

George Plumb offered to evaluate the pond as a recreation site and he will inspect the site with Paul Vermette, selectman.

Members also approved the extension of a power line requested by the Washington Electric Cooperative of East Montpelier. The extension received earlier approval from town selectmen and the Central Vermont Regional Planning Commission. The line will run adjacent to the road.

MEMORANDUM

TO: Fred Kent, Chief, Water Resources Laboratory
 FROM: John Malter
 RE:
 DATE: August 14, 1972

ROUTING		
GENERAL		
TO	NOTED	DATE
JAM		
RJW		
JEC		
SUSPEND TO		
FILE	Hands Mill Dam	

The Town of Washington is currently assessing potential water-based recreation sites. The impoundment behind the Hands Mill Dam in Washington is of major interest. I would like three water samples from this site analyzed for total and fecal coliform. This should give us a handle as to whether the water quality at this site is suitable for a water-based recreation area in this town. George Plumb from the Division of Recreation is obtaining the samples.

Thank you for your assistance.

ROUTING		
GENERAL		
TO	NOTED	DATE
JEC	<i>[Signature]</i>	
DHS	<i>[Signature]</i>	5-17-72
SUSPEND TO		
FILE	<input checked="" type="checkbox"/>	

May 17, 1972

Board of Selectmen
Town of Washington
Washington, Vermont 05675

Dear Sir:

The Vermont Water Resources Board is charged with the authority to investigate certain dams under the jurisdiction of the Board. The investigations are primarily to assure the public that the dams are in a safe state of upkeep and repair, and are also adequate to pass the flows of water which may reasonably be expected. This does not in any way relieve the owners of the structure from their usual responsibility, however.

In order to obtain factual data regarding the structure, the Department of Water Resources will be making an investigation which will include an inspection of the structure (dam), an analysis of the capacity and adequacy of the spillway, and other related data, to be submitted in a report form.

Several investigations will be conducted between June 1, 1972 and September 1, 1972. Hand's Mill Dam has been selected for such an investigation. The report and conclusions of the investigations will be available to the owners and other interested parties at the office of the Department of Water Resources. If you have any questions regarding the procedure or information, please feel free to contact this office. Your cooperation with our agents will be greatly appreciated.

Sincerely yours,

John E. Cerutti, Director
Management & Engineering Division

JEC/DHS/kmp

OFFICE MEMORANDUM

ROUTING		
GENERAL		
TO	NOTED	DATE
DEC		
DHS	DHS	
SUSPEND TO		
FILE <i>Green Dam</i>		

TO: File

FROM: Donald H. Spies

SUBJECT: Meeting of Board of Selectmen, Washington, Vermont

DATE: May 21, 1971

and Hand's Mill Dam ✓

On May 19, 1970, this writer attended the subject meeting in order to keep informed of the situation regarding the town road at the Green Dam site and also, to inform the Selectmen of the situation at the Hand's Mill Dam. Mr. Raymond Green and a neighbor, Mr. Harold Heinzelman, were present and gave testimony on their own behalf in favor of having the road removed from the town lists and changing it to a trail. The Selectmen were in favor of abandoning the road, however, they were hesitant to do so because they were not sure of the legalities involved. The end result, so far as the Department is concerned, is that the Town will attempt to have the road removed from their list, and if this is not possible, Mr. Green will have the road relocated around his impoundment. The Selectmen are to send a letter to this writer stating their views and the final decision reached at the meeting.

After the above discussion, this writer informed the Selectmen of the erosion of the west abutment of Hand's Mill Dam. It was pointed out to the Selectmen that immediate action was not absolutely essential, but that they should consider some sort of remedial action. They stated that the matter would be taken into consideration.

APRIL 12, 1953

Inspection by John E. Cerutti
Dept. of Water Resources

Washington Dam

April 2 1953

je

- North wing wall has fallen down and water has started to erode the earth embankment behind it.

Earth embankment is 3' above spillway section and appears quite stable

- Section of dam south of spillway appears to be in worse condition. Water is leaking thru the south abut. of spillway. Old retaining wall is badly broken up & water going thru it. Water is leaking thru part of dam that forms foundation of mill.

There is about a 30' section of dam to south of the mill. This section has been crisscrossed and the downstream slope is eroded. Top of this section is about 2' above spillway.

Although there may be a slight apron at the bottom of the spillway the water appears to be quite deep and it is believed some erosion is taking place & may be working back under the spillway apron.

je

WINSTON L. PROUTY, CHAIRMAN
WALTER B. RENFREW
FRANCIS LEACH

1.
PHILIP SHUTLER, COMMISSIONER



STATE OF VERMONT
WATER CONSERVATION BOARD

MONTPELIER, VERMONT

REPORT ON HAND'S MILL DAM
IN WASHINGTON, VERMONT

A report is made herein on the weakened condition of a dam in the town of Washington, Vermont.

GENERAL

This dam is located on Jail Branch on the upstream edge of the Village of Washington. It is presently owned by Mr. Clarence H. Hand who acquired the property in 1947. The mechanical power feature of this development has been abandoned, its principle purpose now is for the storage of logs for the saw mill at the site.

For this dam the pondage is small being about 2 acres in surface area and a little over 500,000 cubic feet in volume. The drainage area is 6 square miles.

Layout of the dam

The dam, about 260 feet long, is made up of an earth embankment section flanking a heavy concrete spillway section. This spillway section is between 60 and 70 feet long and reaches a maximum depth of 22 feet above channel bottom.

In cross section, it indicates a flat crest 2 feet wide and 2 feet below the top of the dam, with both faces sloping outward about 3 on 1 on the downstream side and 1 on 1 on the upstream side. Rubble concrete end-walls retain the embankment. Also a short concrete apron 5 to 6 feet wide, is provided at the downstream toe. No flashboards are used on the crest.

Extending northward from the spillway is an earth embankment about 180 feet long and about 10 feet high at maximum section. It has an average top width of 8 feet and side slopes at a natural angle of repose. A short length of this embankment is retained on the downstream side by a stone wall.

To the south of the spillway is a short embankment section which also serves as part of the foundation for the saw mill. It is topped by a masonry wall, partly extended into the embankment. An abandoned intake and a sluiceway exist at this end of the spillway.

Observations and comments

From an examination of the dam, made on May 23, 1950, the writer noted the physical condition of the dam as follows:

The dam is an old structure (probably over 45 years) in a somewhat abandoned stage. Originally, it has a timber spillway section, but this was destroyed in the November 1927 flood, and afterwards replaced by the present massive concrete section. This "newer" section is in the best condition. As indicated in Figure 1, it has a minor degree of surface scaling. Some scour of the soft foundation material underneath the apron has occurred, particularly along the north half, but its progress has not reached a stage where stability of the section might be seriously concerned.

The older, original masonry end sections, are badly broken up. In such a condition is the south abutment wall shown in Figure 2. This is the top portion which has partly failed and leaks considerably. The lower portion of the section is still in a sound condition.

Figure 3 shows the condition of the north abutment wall which also serves to

retain the embankment. The poor quality concrete has been eroded away in time so that stability of the wall is in question. Not only has the base of this wall been decomposed but also some of the material behind it has been washed out. A deep hole, about 6 feet in diameter and 10 feet deep now exists. Here is a likely point of failure, much so if aggravated by high water.


The embankment section, in general, has settled and stabilized itself. It is uneven and overgrown with brush. Beavers have burrowed into the section and have caused small local cave-ins. Some seepage was detected. The nature of the material making up the embankment is not known.

A check on the probable maximum flow (in ~~proportion~~ ^{proportion} to the November 1927 flood) indicates that a peak flow of 3600 c.f.s. is possible. Because of a limited discharge capacity, the dam would be overtopped with this size of flood. With this type of dam, overtopping would mean failure.

CONCLUSIONS

From a routine investigation the writer comes up with this dam which, in his opinion, is in a weakened condition. The ~~impending~~ ^{impending} failure of the dam would cause flooding in the vicinity. However, the extent of flood damage is limited because of the relatively small storage volume involved.

The dam needs immediate repairs to restore its stability. Consideration should also be given to improving the discharge capacity.


Stephen H. Haybrook
Hydraulic Engineer

July 6, 1950
Report # 141



Figure 1.-Spillway face and apron of the dam. The north embankment section continues in the background.



Figure 2.-Disintegrated condition of the south abutment wall.



Figure 3.-A closeup of the north abutment wall. Note the scour through and under the section.