

30% Design Report: Hands Mill Dam Removal



PROJECT NO.

20-007

REVIEWED BY:

MRA

PREPARED FOR:

Gianna Petito / District Manager
Winooski Natural Resources Conservation
District (WNRCD)
617 Comstock Road, Suite 1
Berlin / VT 05602
gianna@winooskinrcd.org
802.828.4493 x3178

SUBMITTED BY:

Gabe Bolin, PE / Senior Water Resources Engineer
Stone Environmental, Inc.
535 Stone Cutters Way
Montpelier / VT 05602
gbolin@stone-env.com
603.809.6101

30% Design Report: Hands Mill Dam Removal

*Cover Photo: View
of Hands Mill Dam
looking upstream.*

Contents

| | |
|--|-----------|
| 30% Design Report | 4 |
| 1.1. Introduction | 4 |
| 1.2. Site Description | 4 |
| 1.3. Existing Conditions | 5 |
| 1.3.1. Review of Existing Data..... | 5 |
| 1.3.2. Infrastructure Stability Analysis..... | 5 |
| 1.3.3. Topographic Survey | 6 |
| 1.3.4. Initial Geomorphic Survey | 7 |
| 1.3.5. Vegetation Survey..... | 9 |
| 1.3.6. Impounded Sediment Analysis..... | 10 |
| 1.4. Geotechnical Analysis and Report | 13 |
| 1.5. Wetlands Delineation | 16 |
| 1.6. Alternatives Considered | 16 |
| 1.7. Selected Alternative | 18 |
| 1.8. Hydrologic Analysis | 19 |
| 1.9. Hydraulic Modeling | 20 |
| 1.10. Proposed Project | 22 |
| 1.10.1. 30% Design..... | 22 |
| 1.10.2. Photo Simulation | 24 |
| 1.10.3. Permit Requirements..... | 25 |
| 1.10.4. Operations and Maintenance Considerations | 27 |
| 1.11. Conclusions | 28 |
| Attachment 1: Dam Breach Report | 29 |
| Attachment 2: Historical Property Information | 30 |
| Attachment 3: Dam Inspection Reports | 31 |
| Attachment 4: Final 30% Designs..... | 32 |
| Attachment 5: Geotechnical Memo | 33 |
| Attachment 6: Opinion of Probable Cost (OPC)..... | 34 |
| Attachment 7: Hydraulic Modeling Output | 35 |

Table of Tables

| | |
|--|----|
| Table 1: Infrastructure of Interest Within the Project Vicinity | 6 |
| Table 2: Initial Geomorphic Assessment Results..... | 7 |
| Table 3: Bankfull Measurements in Reference Reach and Unnamed Tributary..... | 9 |
| Table 4: Vegetation Survey Summary..... | 9 |
| Table 5: Probing Results Upstream of Dam | 11 |

| | |
|---|----|
| Table 6: Grain Size Distribution of Channel Samples..... | 15 |
| Table 7: Phosphorus Content of Channel Samples..... | 15 |
| Table 8: Soil Characteristics of Floodplain Samples ³ | 15 |
| Table 9: Summary of Costs for Alternatives | 17 |
| Table 10: Life Cycle Costs for Each Alternative | 18 |
| Table 11: Summary of Peak Flows at Jail Branch..... | 19 |
| Table 12: Fish Passage Flows at Jail Branch..... | 20 |
| Table 13: Water Surface Elevation Comparison at Dam for the 100-Year Recurrence Interval Flow. 22 | |
| Table 14: Channel Velocity Model Results for Fish Passage Flows (Proposed Conditions)..... | 22 |

Table of Figures

| | |
|--|----|
| Figure 1. Photo of existing conditions at Hands Mill looking upstream. | 24 |
| Figure 2: Photographic simulation of project site following dam removal..... | 24 |

30% Design Report

1.1. Introduction

In July 2020, Stone Environmental, Inc. (Stone) was retained by the Winooski Natural Resource Conservation District (Winooski NRCD) to provide a 30% conceptual engineering design for the removal of Hands Mill Dam and restoration of Jail Branch within the vicinity of the dam. The dam is currently owned by the Town of Washington, and in 2016 the Vermont Department of Environmental Conservation (VTDEC) classified the dam as a Class 2 “significant hazard dam” following a dam safety inspection that found the dam to be in poor condition. Removal of the dam has the potential to increase aquatic organism passage (AOP) along the Jail Branch and connect 14.7 miles of fish habitat. The goals of this project include developing 30% designs for the removal of the Hands Mill Dam for risk mitigation, and restoration of the upstream channel to return to dynamic stream equilibrium, improve water quality, decrease flooding risk, connect native Eastern Brook Trout to high-quality refuge habitat, and grow riparian corridor integrity.

The following text provides a summary of the work completed to evaluate existing conditions at the site and describes the development of conceptual designs for the removal of the Hands Mill Dam, improvement of aquatic organism passage (AOP), and restoration of stream equilibrium.

1.2. Site Description

The Hands Mill Dam is a partially breached stone and concrete structure located along the Jail Branch in the Town of Washington, Orange County, Vermont (The Town). The Town is located near the geographical center of Vermont and is part of the Vermont Piedmont physiographic region. The Vermont Piedmont is hilly with low mountains, with slopes that are moderately steep. The Town’s soils are predominately glacial till, with often steep, occasionally wet glaciated soils.

The dam is situated on Jail Branch near the intersection of Woodchuck Hollow Road (formerly called Brown Road) and West Corinth Road (formerly known just as the ‘Corinth Road’) on a 3.5-acre property owned by the Town (Town Parcel #7105.000). The town property abuts five other private residential properties. The dam impounds a pond with a surface area of about 2 acres at normal pool elevation that is substantially filled with sediment. The dam is currently partially breached and in poor condition. As part of this project, a dam breach analysis was completed by the Vermont Department of Environmental Conservation Dam Safety Division. The dam breach analysis indicated that dam failure could potentially impact several road crossings, homes and business, and a school located downstream. Water depths, velocities, and time of arrival of flooding at immediately downstream properties pose a potential loss of life risk. The 2020 DSS Wise Lite Dam Flood Mapping Report from the Vermont Department of Environmental Conservation Dam Safety Division is provided as Attachment 1 to this report.

The Hands Mill Dam obstructs flow and AOP along the Jail Branch, also known as Jail Brook, a tributary to the Winooski River. Downstream of the dam, Jail Branch runs over 8 miles north and northwest into Barre, where it converges with the Stevens Branch. The Stevens Branch then flows a similar distance northwest to its confluence with the Winooski River in the southeast portion of Montpelier. The watershed area draining to

the Hands Mill Dam location (at 44.10569, -72.43000) is 6.65 mi² (StreamStats, 2020). The watershed is 84% forested, 8% agricultural, 4% developed, 2% shrubs and grasses, and 2% wetlands. (NLCD 2011 classes 21-24; StreamStats, 2020).

1.3. Existing Conditions

1.3.1. Review of Existing Data

Stone completed a review of existing data for the dam and surrounding property. The review was limited to data and files collected and provided by the Winooski NRCD as part of the RFP and 30% design development. These documents include historical property information (Attachment 2), VTDEC Dam Safety Inspection reports from 1953 through 2020 (Attachment 3), septic system information for the house at 16 Woodchuck Hollow Road directly adjacent to the dam on river left, and the Town's Hazard Mitigation Plan. The VTDEC is expected to have a new Dam Safety Inspection Report available in Spring or Summer 2021. Despite efforts to find additional documents online via internet searches, no additional data was found.

A review of the Dam Safety Inspection Reports indicated continued deterioration of the dam over recent decades, specifically the downstream wall, crest of the dam and the concrete training wall. The following provides a summary:

- Downstream Wall – The wall is made up of concrete and large stones. Multiple reports indicated the loss of stones from the wall. Reports of scour to the left of the spillway were also mentioned frequently. In the 2013 inspection report, it was reported that this area has ‘deteriorated rapidly, probably as a result of Tropical Storm Irene and recent high water’.
- Dam Crest – The crest was consistently reported to be in poor condition. Reports stated it was covered with vegetation and signs of overtopping, erosion, and evidence of a partial breach near the mid-section with fallen concrete at the dam bottom, in line with this location.
- Concrete Training Wall – The training wall to the right of the dam was reported as being consistently covered with vegetation with cracking visible at exposed sections.
- Reports of the dam in ‘poor’ or ‘weakened’ condition date back to inspections from 1953. The 1953 report states that ‘the north wing wall has fallen down and water has started to erode the earth embankment behind it’, with additional reports of seepage through the south abutment.
- Suggestions by the state for repairs date back to the 1953 report, and suggestions for retaining a professional engineer to develop plans to either reconstruct or remove the dam date back to 2001.
- A hydrologic study in a 1975 report indicated that the ‘East Orange Brook’ watershed was used as a reference to develop peak flood estimates for recurrence interval storm events at the dam. Similarly, Stone selected the East Orange Branch USGS gage for our hydrologic analysis; see Task 3.

1.3.2. Infrastructure Stability Analysis

Stone conducted a preliminary infrastructure inventory and analysis using knowledge of the project site, publicly available information, and state culvert and bridge inventories. Stormwater, drinking water, wastewater, and overhead utilities (i.e., electric and telecom) were investigated. Infrastructure investigated included bridges, roadways, rights-of-ways, and the dam itself. Following our review of this data, a total of four infrastructure items were thought to require additional review with respect to dam removal and potential stability and/or conflict issues. A summary of these items is provided in Table 1 below. The bridge dimension data provided in the table was obtained from the state inventories.

Table 1: Infrastructure of Interest Within the Project Vicinity

| Item | Location | Location Relative to Dam | Ownership | Notes | Vulnerability |
|------------------------------|---|---|-----------|---|---------------|
| West Corinth Road Bridge | Jail Branch at West Corinth Road | Upstream | Town | Span 15', width 28' (in direction of flow) | Low |
| Woodchuck Hollow Road Bridge | Jail Branch at Woodchuck Hollow Road | Downstream | Town | Span 18', width 26' (in direction of flow) | Low |
| Roadways | West Corinth Road and Woodchuck Hollow Road | Those directly adjacent to project area | Town | West Corinth Rd. newly paved; Woodchuck Hollow Rd. gravel | Low |
| Water Hydrant | Corner of West Corinth Road and Vermette Lane | Upstream, outside of project vicinity | Unknown | No record of potable water system in state GIS databases | NA |

*Source: Stone site visits, VTrans Online Bridge and Culvert Inventory
Date and Author: 09-23-20 / GMB*

1.3.3. Topographic Survey

Stone staff completed a topographic survey of the project site on August 11 and 12, 2020 using a GPS base and rover. The GPS base and rover were used 1) to set control points throughout the project establishing horizontal and vertical control, 2) to collect longitudinal profile and cross-section data upstream and downstream of the dam, and 3) to collect details of structures such as the dam, bridges, infrastructure, and utilities.

Stone established four control points in the vicinity of the dam and downstream of the Woodchuck Hollow Road bridge. Control points were set in road pavement, at utility poles, and at the downstream bridge headwall. Locations and descriptions of control points are provided on Sheet 2 of the design plans in Attachment 4. As a quality control measure, Stone regularly checked back to control points to assess equipment precision and data accuracy. Any discrepancies found to be over 0.1 feet resulted in resurveying of relevant data.

The extent of the survey data is shown on Sheet 2 of the design plans (Attachment 4). Approximately 2,200 feet of longitudinal profile were collected along Jail Branch, extending from upstream reference reaches to a few hundred feet downstream of the Woodchuck Hollow Road bridge. Additionally, several unnamed tributaries to Jail Branch were surveyed. Typical features collected as part of the longitudinal profiles along Jail Branch and the unnamed tributaries included top and bottom of steps, pool head and tail crest, maximum pool depth, riffle head and tail, etc. While these features are useful in developing a stream profile and assessing reach slopes, they are also useful in assessing fish habitat and will be used during the final design of the channel bed. Longitudinal profile data was used to define reach slopes for the preliminary design of the pilot channel. A longitudinal profile along the thalweg of the stream channel is provided on Sheet 7 of the design plans (Attachment 4).

Cross section data was collected along the main channel within the project area and reference reach, including top of bank, bottom of bank, thalweg, bars, and other bed features. The dam was surveyed and detailed, and roads and utilities were also located during the survey. Where Stone was unable to access land to survey, we combined the survey data with LiDAR data made available by the State.

Stone staff developed the project basemap in AutoCAD using both the survey and LiDAR data to develop a 3-dimensional surface (i.e., triangular irregular network, or TIN) of the project site. The TIN was used to develop 1-foot contours through the project extent. Contours for existing conditions are shown on Sheet 3 of the 30% design plans (Attachment 4).

1.3.4. Initial Geomorphic Survey

On September 4, 2020, Stone completed a limited geomorphic assessment of Jail Branch upstream and downstream of the dam, along the primary unnamed tributary entering Jail branch river right at station 14+30, and along a reference reach on Jail Branch approximately 1,430 feet upstream of the dam.

Initial Survey of Project Area

The first portion of the assessment consisted of collecting bankfull width and depth measurements upstream and downstream of the dam to determine entrenchment ratios of Jail Branch, to get a general sense of geomorphic conditions throughout the project area. Observations and measurements were obtained at six locations, three upstream and three downstream of the dam. The results of this initial geomorphic assessment are presented in Table 2. Station data is provided on Sheet 3 of the design plans (Attachment 4).

Table 2: Initial Geomorphic Assessment Results

| Location | Distance Upstream from Dam (ft) | Bankfull Width (ft) | Bankfull Depth (ft) | Flood-Prone Width (ft) | Entrenchment Ratio | Channel Description |
|-------------|---------------------------------|---------------------|---------------------|------------------------|--------------------|---------------------|
| US3 | 13+35 | 43.5 | 3.4 | 337.5 | 7.8 | pool head |
| US2 | 10+12 | 28.6 | 4.0 | 494.0 | 17.3 | riffle |
| US1 | 9+27 | 32.7 | 4.1 | 280.2 | 8.6 | riffle |
| DS1 | 4+32 | 30.4 | 5.3 | 145.2 | 4.8 | step |
| DS2 | 2+28 | 28.6 | 6.1 | 78.3 | 2.7 | riffle |
| DS3 | 1+78 | 35.0 | 3.3 | 47.0 | 1.3 | riffle |
| <i>Avg.</i> | | <i>33.1</i> | <i>4.4</i> | | | |

Source: Stone site visits

Date and Author: 09-23-20 / GMB

Flood-prone widths were measured at an elevation equal to twice the bankfull depth at each location, using LiDAR and knowledge of the site. Entrenchment ratios were calculated by dividing the flood-prone width by the bankfull width. Per the Rosgen Stream Classification Technique (USDA, 2007), entrenchment ratios of greater than 2.2 are considered 'Slightly Entrenched', indicating the stream is generally well connected to adjacent floodplains. Entrenchment ratios at the site ranged from 1.3 (DS3) to 17.3 (US2), with floodplain connection upstream of the dam generally greater than floodplain connection downstream of the dam. The lowest entrenchment ratio was recorded at the furthest downstream location (DS3), where the channel is deep and channelized for a few hundred feet downstream of the Woodchuck Hollow Road Bridge. Moving upstream from DS3, channel entrenchment is gradually reduced and floodplain connectivity increased.

The average of bankfull width and depth measurements through the project area are 33.1 feet and 4.4 feet, respectively (

Table 3). The largest bankfull width value of 43.5 feet measured at the most upstream location (US3) could be considered exaggerated since it is just downstream of the junction between Jail Branch and the largest unnamed tributary to Jail Branch. This junction is suspected to be a dynamic area during high flow events, with flow and sediment transport highly influencing bank full geometry in the immediate area. The average bankfull width of 33.1 feet matches well with the calculated bankfull width based on the Vermont Regional Hydraulic Geometry Curves, where a width of 30 feet, depth of 1.8 feet and a cross sectional area of 51 ft² were calculated (VTANR 2006). However, the average bankfull depth measured in the field (4.4 feet) does not align with the regional curve estimate (1.8 feet). One potentially reason for the difference, is that during large storm events the dam causes backwater conditions, slowing down floodplain waters in the impoundment area. The reduction in floodplain water velocity may lead to excessive settling of sediments on floodplain surfaces overtime. The ‘building up’ of those floodplain surfaces has potentially increased floodplain surface elevations relative to the streambed, resulting in deeper bankfull depths.

Reference Reach Assessment

Stone staff completed a geomorphic assessment in a reference reach to inform design and restoration plans. Stone staff identified reference reach conditions approximately 100 feet south of the culvert at Jail Branch and West Corinth Road during the topographic survey. From that point, the reach extends another 200 feet upstream along Jail Branch. Upon review of all reaches of Jail Branch and tributaries, this section of stream was selected as a reference because it was clearly out of the impounded area, it was not overly influenced by anthropogenic impacts, it visually appeared to be in equilibrium, and it contains a fair amount of habitat features in the bed (pools, backwatered areas, favorable bed substrate, etc.). On Sheet 2 of the plans, the reference reach extends upstream from about station 20+00 to 22+00 (south of West Corinth Road, and potentially extending past this station).

Stone staff characterized the stream bed, collected bankfull measurements, and collected cross section data in the reference reach. Stream bed data included the delineation of bed habitat features (i.e., step, riffle, pool, run, etc.), bed feature length, width, elevation features, and frequency. For instance, three pools were found within the reference reach, with an average length of 23’, average width of 10.7’, and average max pool depth of 1.3’. The bed material within the pools consisted of 50% cobble with small boulders, and occasional large boulders providing cover and refuge for aquatic organisms. Key pieces, or small to large boulders that made up individual stone steps found in the reach, had an average intermediate measurement of 21 inches, among the 20 pieces that were measured. The roundedness of these stones ranged from rounded to angular, with the majority of pieces being rounded, while the embeddedness of the pieces in the stream bed ranged from 0 to 50% embedded. Roughness boulders were also observed in the reach. Roughness boulders are stones that are not included in a bed structure but exist in a random nature throughout the stream bed and tend to add roughness to the channel. The measured roughness boulders had an average intermediate measurement of 24.6 inches, a roundedness that ranged from rounded to sub-angular, and were 5 to 50% embedded in the channel. Two pebble counts were performed in the reference reach as well. The purpose of these counts is to characterize the gradation of the bed material, or distribution of different sized stones within the bed matrix. A plot of the count data as a grain size distribution is provided in Attachment 5.

Bankfull measurements were collected in the reference reach. Similar measurements were also obtained in the primary unnamed tributary to Jail Branch, conveying flow from the northeast. Table 3 below provides a summary of bankfull measurements from each reach, along with averages. Note that while the unnamed tributary was not used as a reference reach, this tributary did exhibit reference reach characteristics and could be further investigated as a reference reach if needed, during Phase 2 design.

Table 3: Bankfull Measurements in Reference Reach and Unnamed Tributary

| Reach | Location | Bankfull Width (ft) | Bankfull Depth (ft) |
|-----------------------------------|-------------|---------------------|---------------------|
| Jail Branch Reference Reach | BF1 | 25.2 | 2.33 |
| | BF2 | 25.8 | 1.8 |
| | BF3 | 19.3 | 1.68 |
| | <i>Avg.</i> | <i>23.4</i> | <i>1.9</i> |
| Unnamed Tributary | TRIB-BF1 | 18.2 | 2.22 |
| | TRIB-BF2 | 17.9 | 1.84 |
| | TRIB-BF3 | 20.2 | 1.68 |
| | <i>Avg.</i> | <i>18.8</i> | <i>1.9</i> |

Source: Stone site visits

Date and Author: 09-23-2020 / GMB

1.3.5. Vegetation Survey

During the topographic survey and a second site visit in October 2020, Stone developed an inventory of trees over 3" diameter at breast height (dbh) within the limits of disturbance that may require removal during construction of the project. Table 4 provides a summary of those trees. Note that at this time the project design is at the conceptual level (i.e., 30% design level) and certain trees along the boundary of the limits of disturbance may or may not need to be removed, depending on the details of final design. Because of this current uncertainty, the column 'Likelihood of Removal' has been included to capture the possibility of removal relative to final design.

Table 4: Vegetation Survey Summary

| # | Species | Size (dbh, inches) | Location | Likelihood of Removal |
|----|--------------|--------------------|--|-----------------------|
| 1 | Black Willow | 32 | River left, near parking area | High |
| 2 | White Birch | 6, double | On top of dam | High |
| 3 | Pine | 24 | River left, on 16 Woodchuck Hollow Road property | Medium |
| 4 | Sugar Maple | 18 | River right, ~station 9+00 | Medium |
| 5 | Pine | 24 | River left, ~station 10+00 | High |
| 6 | Pine | 20 | River right, ~station 10+50 | Low |
| 7 | Oak | 20 | River right, ~station 11+50 | Low |
| 8 | Pine | 18 | River right, ~station 13+50 | Low |
| 9 | Sugar Maple | 18 | River right, ~station 13+75 | Low |
| 10 | Sugar Maple | 16 | River right, ~station 14+00 | Low |
| 11 | Green Ash | 10 | River right, ~station 6+00 | Low |
| 12 | Green ash | 4 | River right, ~station 6+00 | Low |
| 13 | Green Ash | 4 | River right, ~station 5+50 | Low |
| 14 | Sugar Maple | 8 | River right, ~station 5+50 | Low |
| 15 | Green ash | 12 | River left, ~station 12+00 | Very low |

| # | Species | Size (dbh, inches) | Location | Likelihood of Removal |
|----|--------------|-----------------------|-----------------------------|--------------------------|
| 16 | Green ash | 6 | River left, ~station 12+50 | Very low |
| 17 | Black willow | 6 | River left, ~station 13+50 | Very low |
| 18 | Black willow | 4 | River left, ~station 13+50 | Very low |
| 19 | Sugar Maple | 11 | River right, ~station 14+00 | Low |

Source: Stone site visits

Date and Author: 03-10-2021 / GMB and MRA

1.3.6. Impounded Sediment Analysis

1.3.6.1. Sediment Probing

Probing Methods

On August 26, 2020, Stone performed sediment probing within the impoundment, from directly behind the dam to approximately 130 feet upstream using an extendible steel tile rod. Probing was completed at 15 locations as shown on Sheet 3 (Attachment 4). At each location, the steel tile rod was advanced into the streambed by hand or driven into the streambed using a hammer, depending on the difficulty advancing the probe into the bed sediment. When the steel rod was unable to be driven further into the streambed, the nature of refusal, including resistance, vibrations, and audible cues, were noted.

To compare the probing depths to the bottom of the dam elevation and to ultimately assess the potential for AOP following dam removal, a temporary datum of 0.0' was set at the impoundment water surface. The bottom of the dam relative to this datum measured approximately 11-13' down, along the face of the dam. Therefore, at any probing location where we were able to drive 12' or more of rod under the water surface, we considered the tip of the rod to be approximately even with, or below, the bottom of the dam.

At each probing location, in addition to refusal data, the total rod depth from the water surface to refusal, water depths, and location data were recorded.

Probing Results

Overall, exploratory probing provided insight into refusal elevations and the nature of refusal immediately upstream of the dam. The results at each location are summarized in Table 5. Locations where the tip of the rod was approximately even with, or below, the bottom of the dam are indicated in bold.

Where vibrations and audible cues indicated refusal via bedrock at a few locations, a lack of refusal at other locations suggests either 1) the absence of bedrock and/or an AOP barrier, or 2) a different type of material at depth that would require additional driving of the probing rod. At many of these locations, substantial hammering and effort would typically only result in a half inch or inch advancement. And at a few locations that followed the thalweg, suction force (in the presence of muck) or resistance force (in the presence of sand/gravel) posed major challenges in retrieving the probing equipment, and therefore some explorations were abandoned for fear of losing equipment. When a probing location was abandoned, a new probing location was attempted close by to eliminate any spatial data gaps.

Overall, Stone staff attempted to drive the probe to 12' below water surface to confirm a lack of bedrock and/or barrier at the estimated bottom of dam elevation. While the results in the table indicate that there seems to be a path upstream of the dam where bedrock and/or barriers are not present down to the bottom of dam

elevation, it is important to understand that the probe diameter used for the explorations is approximately ½” in diameter and the accuracy of this data should be considered coarse, with limitations based on the equipment used and density of explorations.

Table 5: Probing Results Upstream of Dam

| Probe ID | Water Depth (ft) | Description | Height Above Dam Bottom (ft) |
|----------|------------------|---|------------------------------|
| P-1 | | No data – equipment malfunction | |
| P-2 | | No data – equipment malfunction | |
| P-3 | 3.15 | No refusal, hard sand layer (?), abandon | 5.85 |
| P-3-2 | 3.18 | Refusal, boulder/bedrock | 4.8 |
| P-4 | 3.16 | Refusal, boulder/bedrock | 4.5 |
| P-5 | 2.15 | No refusal, muck, abandon | 3.3 |
| P-6 | 2.56 | No refusal | -0.31 |
| P-7 | 2.45 | Refusal, no boulder/bedrock, but hard layer | 8.45 |
| P-8 | 0.92 | No refusal | 0.00 |
| P-9 | 2.34 | Refusal, sand/debris | 3.98 |
| P-10 | 1.75 | Refusal, sand/debris | 8.89 |
| P-11 | 1.75 | No refusal | 3.08 |
| P-12 | 0.37 | Refusal, boulder/bedrock | 1.94 |
| P-13 | 2.32 | No refusal, muck, abandon | 3.14 |
| P-14 | 1.4 | No refusal | 0.55 |
| P-15 | 1.94 | No refusal | 0.27 |
| P-16 | 2.05 | No refusal | 0.43 |

Source: Stone site visits

Date and Author: 09-23-2020 / GMB

Recommendations for Potential AOP

Further inspection of the data suggests that a path for aquatic organism passage exists from P-6 and P-8 at the dam extending upstream to P-15, P-16, and P-14. No obstructions at the bottom of dam elevation were encountered at these probing locations. However, it should be noted that explorations just upstream of the dam (i.e., 5-10 feet upstream) at locations P-7, P-9 and P-10 indicated refusal due to hard layers and/or debris. While probing results like this are expected along the perimeter of a dam due to potentially variability in dam construction and dimensions, our probing efforts cannot confirm what the dam is directly built on. Therefore, bedrock or an AOP barrier may still exist just under the dam structure or within a few feet of its perimeter. Confirmation of what the dam was built on can potentially be confirmed via ground penetration radar (GPR) surveys, or via dam removal during the construction phase. For the purposes of this conceptual design, Stone has confirmed that there seems to be a path with no obstructions at the bottom of dam elevation, from about 15 feet behind the dam to approximately 125 feet upstream, adjacent to the visible portion of the training wall along river right.

1.3.6.2. Impounded Sediment Characterization

Impounded Sediment Volume Estimate

Stone estimated the volume of impounded sediment wedge behind the dam based on 1) the topographic survey data, 2) the probing data, and 3) the use of the proposed pilot channel slope and section, as a proxy for the historical channel. The topographic survey data was used as the existing, or current surface, while the probing depths and proposed pilot channel section were used to mimic the channel that existed prior to dam construction. Using the pilot channel as a proxy to the relic channel was feasible since the pilot channel is set to slopes and bankfull dimensions similar to adjacent reaches. This methodology provided a good initial

estimate of the impounded sediment wedge volume behind the dam, in the channel, and in the immediate bank areas.

Additionally, Stone estimated the amount of impounded sediment that may have settled on relic floodplains. The existing conditions surface within the project area (see Sheet 2) show a relatively wide and flat floodplain along river left that extends almost to West Corinth Road, while the contours on river right slope gently from uplands towards the river right bank of the Jail Branch and show a narrower floodplain. While pre-dam floodplain elevations along either bank are unavailable, one can assume that prior to dam construction, much of the natural floodplain area for this system within the project area existed along river left. Due to the impounding nature of the dam, it is likely that this natural floodplain filled in with sediment, similar to the channel, over the approximately 160 years since dam construction. To account for settling of sediments not only in the channel but in the floodplains as well, for this conceptual calculation Stone revised the pilot channel cross section to include an 80-foot-wide floodplain bench. Note, the pilot channel floodplain bench designed for these impounded sediment calculations does not have the same dimensions as the floodplain bench in the final 30% designs (See the 'Typical Channel Cross Section' detail on Sheet 7 (Attachment 4)). Using the pilot channel slope and this altered section as a proxy for the historical channel and floodplain area, for the purposes of this calculation only, we estimate that a total of 14,300 CY of impounded sediment exists behind the dam, above the relic channel and within the historic floodplain along river left. The limit of impounded sediment, based on our interpretation of the bed sediment, topographic data, and sediment wedge is at approximate Station 13+25, and is indicated by a note on Sheets 3 and 4 (Attachment 4).

Volume Potentially Released During an Uncontrolled Failure

Stone developed a conceptual level estimate of the potential volume of sediment mobilized during an uncontrolled dam failure. Due to the conceptual level of this study and lack of a project sediment transport model, it is difficult to accurately estimate this. However, if we assume the sediment transported will be limited to the impounded area, and that the stream will want to migrate to a stable slope soon after a hypothetical large storm event, we can assume that the channel will headcut back to approximate station 14+00 based on our assessment of stable slopes within the project area and reaches adjacent to the project.

Assumptions regarding the amount of dam failure were also made in the sediment volume calculations. Considering the dam removal alternatives presented in Section 1.6 below, we assumed that the extent of dam failure is equal to the median value of proposed dam removal, or 94 linear feet of dam failure.

While the extent of potential headcut matches the upstream limit of our pilot channel construction, and since the extent of dam failure matches Alternative A3, for the purposes of this exercise we make the conservative assumption that the amount of material that may be mobilized during an uncontrolled failure is equal to the amount of material we proposed to remove as part of Alternative A3, or 11,100 CY. The details of proposed sediment removal for this alternative are discussed further under Task 4-1.

Note that the assumptions made to support this calculation are arbitrary and were only made to develop a rough conceptual idea and estimate of potential material that could move beyond the dam given a dam failure. In the event of a failure, many different variables would be at play and several different factors could lead to a wide range of release scenarios.

Volume Released During and After Dam Removal

Similar to other dam removal projects in Vermont, this project will require a state Stream Alteration Permit, a US Army Corps of Engineers Vermont Category 2 General Permit, and other similar permits, where the prevention of sediment transport to downstream reaches is of primary concern. These permits will require the contractor to have erosion protection and sediment controls in place prior to any work; will require that a plan

be in place for bypassing flows around the work area; and may require staged land disturbance to ensure limitations of concurrent soil disturbances. However, even with these controls in place, a small amount of sediment may bypass these controls and be transported downstream. Based on our experience with dam removals, the transported amount can usually be considered negligible, or, as a temporary negative impact (i.e., lasting hours to days) that is outweighed by the long-term gain (lasting years to decades) realized by the completion of a large dam removal and/or restoration project, where benefits include restoration of geomorphic functions, floodplain connectivity, aquatic organism passage, etc.

Based on the text and calculations presented in this section, the theoretical maximum quantity of sediment that could be released after dam removal is the total impounded sediment volume of 14,300 CY minus the quantity of sediment proposed for removal as part of the conceptual design (13,940 CY for A4), or 360 CY. However, the proposed final 30% design pilot channel 'Typical Channel Cross Section' as shown on Sheet 7 will incorporate the establishment of vegetation and erosion controls to stabilize remaining impounded sediment. The vegetation selected should be native and relatively quick growing, with rooting systems that will ensure soil stability over the life of the project. Stone staff observed robust stands of willow within the floodplains and along the stream banks during field work. The revegetation plan should include planting of these existing onsite willows, in addition to other native species on disturbed surfaces to ensure quick establishment of deep rooting vegetation. Erosion control fabric made of natural fibers (i.e., coir or coconut fiber matting) can also be used along new surfaces to promote stability while vegetation takes time to root and establish.

It is possible that the sediment volume released following dam removal will be below the amount calculated in the paragraph above (360 CY). The successful implementation of the design and establishment of vegetation will minimize erosion and most likely reduce the total sediment volume released over time. Additionally, the potential quantity mobilized will depend on channel adjustments the system might develop as a result of dam removal and pilot channel construction. For example, if following dam removal, the Jail Branch attempts to find equilibrium by moving significantly further into a meander bend that is part of the final design, then erosion along the meander bank may result in sediment conveyed downstream. The released quantity can be estimated from the amount of soil loss at the meander and quantified by field measurements. Given the tendency of natural systems to adjust and considering typical design and construction tolerances, post-project adjustments are common and almost inevitable. Predicting their quantity in terms of sediment volume, however, is difficult in any design stage.

Overall, if the pilot channel is designed at a slope that reasonably matches adjacent channel slopes (i.e., within +/- 25% of adjacent slopes), and stabilization of disturbed surfaces is successful, the majority of sediment conveyed after dam removal should equal the bed load of the fluvial system. Additions to that quantity are possible if there are post-project channel adjustments that result in bed, bank or floodplain surface erosion, as discussed in the preceding paragraph.

1.4. Geotechnical Analysis and Report

Stone completed desktop, field, and laboratory geotechnical investigations at the Hands Mill Dam as part of the overall 30% design effort. The following sections provide a summary of these investigations including field and laboratory methods, data logs, and the implications of the data for site design and construction processes. Additional detail is provided in the Geotechnical Memo in Attachment 5.

Desktop Evaluation

A preliminary desktop evaluation was performed to determine the potential extents of sampling. Aerial imagery of the Hands Mill Dam location (44.10569, -72.43000) from Google Earth shows aggradation of

sediment, likely coarse grained, for approximately 750 linear feet upstream of the Hands Mill Dam. Visible changes in bed slope and material indicated that the direct impact of the dam on the sediment impoundment was likely limited to approximately 600 linear feet upstream. (See Figure 1 in Attachment 5). This area was further investigated in the field to confirm sampling locations. The number of channel samples to be collected (six in total) was predetermined and included a combination of pebble counts and laboratory grain size analyses (methodologies defined below). The number of floodplain samples to be collected (three in total) was also predetermined to represent the spatial extent of the left-bank floodplain.

Field and Laboratory Investigations

Channel sediment sampling was focused within the 600-foot impoundment extent identified in the desktop evaluation. Exact sampling locations were selected to maximize the range of outcomes of the grain size analyses in order to assess the variability of grain size distribution throughout the channel. One sample, HM-S6, was excluded from further analysis and was sent to archive due to extensive similarity to sample HM-S4. Floodplain samples were spaced at equidistant intervals (approximately 150 - 200 feet apart) throughout the left bank floodplain.

Grain size analyses were performed using one (or more) of three methods at each channel sampling location: modified Wolman pebble count, laboratory sieve analysis, and/or laboratory hydrometer analysis. The modified Wolman pebble counts were performed using the methodology of Leopold (1970) where individual grains are selected using heel-to-toe spacing along cross-sectional transects. For laboratory testing, bulk sediment samples were collected to a depth of approximately 6-10 inches below the surface using a hand shovel. The samples were sent to the University of Vermont (UVM) Agricultural & Environmental Testing Laboratory (Lab) given the Lab's ability to perform a specific phosphorus content test. Laboratory sieve analyses were performed on the coarse fraction of bulk sediment samples, and laboratory hydrometer analyses were performed on the fine fraction of bulk sediment samples. Bulk sediment samples were also sent to the UVM laboratory for phosphorus content analysis via microwave digestion and inductively coupled plasma (ICP) analysis. Results of the laboratory analysis are included in Attachment 5.

Floodplain soil/sediment samples were collected to a depth of approximately three (3) feet using a hand auger. Soil characteristics, including color, moisture, consistency, and field assessed USCS classifications were recorded on a soil boring log for each of the three samples (see Attachment 5). Field-assessed USCS classifications were determined in accordance with ASTM standards D-2487 and D-2488.

Geotechnical Analysis Results

The results of the channel and floodplain investigations are shown in Table 6 through Table 8. Pebble count data were aligned with the size classes tested via hydrometer and sieve analyses at the UVM Lab for direct comparison. Figure 2 in Attachment 5 shows the cumulative grain size distribution at each of the channel sampling sites (note that the curves for HM-S4 and HM-S5 were generated from pebble count data).

Table 6: Grain Size Distribution of Channel Samples

| Sampling Site | Sample Type | Cumulative Percent Retained (%) | | | | | | | | |
|---------------|-------------|--------------------------------------|-----------|-----------|-----------|----------|-----------|------|------|-------------------|
| | | Larger than 3/4 Sieve ² | 3/4 Sieve | 1/2 Sieve | 1/4 Sieve | #5 Sieve | #10 Sieve | Sand | Silt | Clay |
| HM-S1 | B/L | - | 100.0 | 100.0 | 100.0 | 99.9 | 99.7 | 5.9 | 2.0 | 0.1 |
| HM-S2 | B/L | - | 100.0 | 85.0 | 73.3 | 60.8 | 55.2 | 46.6 | 4.7 | 1.2 |
| HM-S3 | B/L | - | 100.0 | 99.9 | 99.9 | 99.3 | 98.6 | 95.8 | 3.4 | 1.6 |
| HM-S4 | B/L | - | 100.0 | 99.4 | 90.2 | 77.3 | 69.8 | 52.4 | 3.4 | 1.0 |
| Sampling Site | Sample Type | Cumulative Percent by Size Class (%) | | | | | | | | |
| | | Larger than 3/4 | 3/4 Sieve | 1/2 Sieve | 1/4 Sieve | #5 Sieve | #10 Sieve | Sand | Silt | Clay ¹ |
| HM-S4 | PC | 100.0 | 88.0 | 70.0 | 48.0 | 38.0 | 36.0 | 4.0 | 0.1 | - |
| HM-S5 | PC | 100.0 | 66.7 | 56.6 | 49.5 | 42.4 | | 9.1 | 0.1 | - |

Abbreviations: B/L = bulk samples sent to UVM lab for analysis; PC = pebble count sample

¹Results not recorded for this combination of methodology and size class

Date and Author: 11-16-2020 / MS

Table 7: Phosphorus Content of Channel Samples

| Sampling Site | Test Description | P-Content (mg/kg) |
|---------------|-------------------------|-------------------|
| HM-S1 | Phosphorus (P) from ICP | 267.9 |
| HM-S2 | Phosphorus (P) from ICP | 343.3 |
| HM-S3 | Phosphorus (P) from ICP | 206.1 |
| HM-S4 | Phosphorus (P) from ICP | 426.5 |

Date and Author: 11-16-2020 / MS

Table 8: Soil Characteristics of Floodplain Samples³

| Sampling Site | Composite Relative Soil Moisture | Composite Soil Color | Predominant USCS Classification |
|---------------|----------------------------------|----------------------|---------------------------------|
| HM-FP1 | Moist to Wet | Dark Brown | SM (Silty Sand) |
| HM-FP2 | Moist to Wet | Brown | SM (Silty Sand) |
| HM-FP3 | Moist to Wet | Brown/Grey Brown | SM/ML (Silt with Fine Sand) |

Date and Author: 11-16-2020 / MS

Discussion of Geotechnical Analysis Results

As is common with pebble counts, the sampling data show that the pebble count samples tended towards the coarser fraction of the impounded bed sediment material than the Lab tested bulk samples. However, both the Lab samples and pebble counts indicate that the median grain size (d₅₀) of the channel material is less than 10 mm (1 cm) in diameter. Particles of this size are highly mobile via both rolling and entrainment during

common storm events. Both sample types also indicate that approximately 75% or more of the impounded bed sediment is finer than 25 mm (approximately 1 inch) in diameter. Coarse gravel in this size class is still likely to mobilize during storm flow events based on a simple incipient motion approximation using the critical Shields Number.

The average phosphorus (P) content of the impounded channel sediment is approximately 311 mg P/kg sediment. The total amount of phosphorus removed can be estimated based on 1) the extent of the impoundment, 2) an assumption that much of the phosphorus is contained within the active sediment layer (top 10 cm), and 3) an assumption that approximately 30% of the phosphorus is biologically available (value provided by the VANR workgroup). Review of publicly available LiDAR and aerial photography, and confirmation with field-run survey yields a total area of approximately 15,000 ft² of sediment impoundment. Based on the above assumptions and an average P loading of 311 mg/kg, the total bioavailable phosphorus to be removed associated with the proposed dam removal is 21 kg (or 46 lbs.). This estimate is limited to the sediment impounded within the confines of the channel. Floodplain sediments were not tested for P content, however utilizing the same assumptions as above, the same loading rate of 311 mg/kg, and the surface area of the proposed floodplain bench excavation (approximately 18,000 ft²) an additional 25 kg (55 lbs.) of phosphorus would be removed. If the entire impounded depth were assumed to contain phosphorus-laden sediments, the total P removals from channel and floodplain sediments would increase to 317 kg (699 lbs.) and 381 kg (840 lbs.), respectively. See Attachment 5 for supporting calculations.

Field evaluation of floodplain soils revealed that the floodplain soils are predominantly silty sands, or USCS classification SM. Based on this characterization, the soils are likely limited to a maximum grade of 2H:1V outside of the channel limits. The internal friction angle of SM soils is approximately 30 to 35 degrees, depending upon the fractions of silt and sand, therefore precluding the ability to permanently grade these soils to a slope exceeding 2H:1V. Sandy soils do not generally achieve high levels of compaction in comparison to silty or clayey soils, and silty soils are subject to the highest relative amounts of post-construction settlement, particularly in regions with highly active freeze-thaw. Caution should therefore be taken to limit steep grading to the maximum extent practicable.

1.5. Wetlands Delineation

Wetland boundaries were delineated by Karina Dailey of the Vermont Natural Resources Council (VNRC) on October 8, 2020. The wetland delineation was performed in accordance with the U.S. Army Corps of Engineers Wetland Delineation Manual, Technical Report Y-87-1, January 1987, Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northcentral and Northeast Region (Version 2.0), January 2012, and Section 3.2 of the Vermont Wetland Rules. Wetland boundaries are shown on Sheet 3 of the design plans (Attachment 4). Additional wetland boundary investigations will be performed at the potential sediment disposal sites during the final design phase of the project.

1.6. Alternatives Considered

An alternatives analysis was completed as part of this project. Stone developed and assessed a total of four options for dam removal, including a ‘no action’ alternative of leaving the dam in place. A phased dam removal was also discussed with stakeholders; however due to the poor conditions of the dam, phased removal was not further examined as part of this project. Stone presented the alternative to the District and stakeholders at the stakeholder check-in meeting on September 28, 2020. The four presented alternatives are as follows:

- A1 - No Action – The dam and impounded sediment remain in place. Given the trajectory of historical inspections and current state of the dam, the potential for dam failure would be expected to increase over time.
- A2 - Removal of 44 linear feet – Includes the embankment section and principal concrete spillway only. While this alternative would not allow the continuance of a floodplain bench through the dam area, this alternative is included for comparison purposes.
- A3 - Removal of 94 linear feet – Including the embankment section and principal concrete spillway, and 50 linear feet of the concrete/stone wall. This would remove all the concrete/stone wall and only leave the concrete training wall in place.
- A4 - Removal of entire dam - 165 linear feet plus any dam portions that are buried (~30 linear feet). This alternative may be required if cuts in the dam area are deep enough (i.e., ~12-14 feet) such that the concrete training wall is undermined and would not be stable over the long term.

Costs were developed for each alternative based on estimated construction quantities. Table 9 below provides a summary of the typical engineering opinion of probable costs (OPCs) for each alternative, in addition to life cycle costs calculated per Attachment B of the RFP.

Table 9: Summary of Costs for Alternatives

| Alternative | Typical Engineering OPC (\$) | Life Cycle Costs (\$) |
|-------------|------------------------------|-----------------------|
| A1 | \$0 | \$0 |
| A2 | \$340,100 | \$181,843 |
| A3 | \$372,000 | \$193,442 |
| A4 (30%) | \$476,600 | \$285,960 |

Date and Author: 09-21-2020 / GMB

The OPCs were developed to the 15% design level for alternatives A1, A2, and A3. Costs include volumes for concrete and sediment removal, and other quantities estimated from the drawings and knowledge of the site. Unit costs based on 2-year average unit cost data maintained by VTtrans (<http://vtrans.vermont.gov/cost-estimating>), and unit costs from recent construction projects for similar bid items were used to develop the OPCs. The OPC for the selected alternative, A4, was developed to the 30% design level. The 30% design OPC includes volumes for concrete and sediment removal, and other quantities estimated from the drawings and knowledge of the site, such as conceptual costs for survey layout, construction access, erosion prevention and sediment control measures, flow bypass measures, channel realignment, installation of grade controls, bank stabilization features and soil stabilization. Per standard cost estimating methodologies developed by the US Army Corps of Engineers, each OPC includes a 20% contingency to account for unforeseen construction costs related to site conditions, variability in pricing, etc. Also, per Corps standards, as the project advances through subsequent design refinements and estimates of costs become more certain, the contingency for the selected alternative will be reduced down to 10% for the 100% design submittal. The costs also include mobilization/demobilization costs, estimated at 10% of the construction costs. The costs developed to the 15% design level do not include final design engineering fees, permitting, or bid phase services; however, those costs are provided in the final 30% design OPC for the chosen alternative, A4 (see Attachment 6).

Life cycle costs were based on Attachment B to the RFP, and the United States Department of Agriculture Rural Utilities Service Bulletin 1780-2, Preliminary Engineering Reports for the Water and Waste Disposal

Program, as provided on the state's State Revolving Fund website (<https://dec.vermont.gov/water-investment/water-financing/srf/srfstep1/PER>). Life cycle cost analysis (LCCA) consists of adding all initial and ongoing costs of the project over the life of the project, subtracting the salvage value of the project at the end of that time, and adjusting for inflation. With regards to annual costs, Stone assumed an annual cost of \$2,000 to account for vegetation establishment and/or management, over an assumed 20-year project life. We also assumed \$5,000 of 'repairs' every five years of the course of the project, accounting for any repairs or stabilization that may be required due to channel adjustments or any other unforeseen issues. Life cycle costs for each alternative are provided in detail in Table 11 below.

Table 10: Life Cycle Costs for Each Alternative

| Alternative | Total Project Cost ¹ | PW Annual O&M Cost ² | PW Bank Repair Cost ³ (20 yrs, 5 yr interval) | PW Salvage Value ⁴ (20 yrs, 0.25%) | Present Value | PW (Cost + Present Value) |
|-------------|---------------------------------|---------------------------------|--|---|---------------|---------------------------|
| A1 | - | - | - | - | - | - |
| A2 | \$287,696 | \$38,969 | \$19,387 | (\$164,209) | (\$105,853) | \$181,843 |
| A3 | \$314,719 | \$38,969 | \$19,387 | (\$179,633) | (\$121,277) | \$193,442 |
| A4 | \$476,600 | \$38,969 | \$19,387 | (\$195,748) | (\$137,392) | \$285,960 |

¹Capital Total Project Costs based on estimated construction cost in report

²Present Worth (PW) O&M costs based on estimated O&M cost in report

³PW Bank Repair Costs (5 yr interval)

⁴Estimated PW Salvage Value based on OMB Circular No. A-94 rate

⁵Present Worth of Salvage Value

Date and Author: 03-11-2021 / MRA

1.7. Selected Alternative

Alternative 4 (A4) was selected as the final alternative, which includes removal of the entire visible portion of the dam (165 linear feet) plus a portion of the dam that is buried along river right. The removal extents include the embankment section and principal concrete spillway, 67 linear feet of the concrete/stone wall, 70 linear feet of the visible portion of the concrete training wall and 30 linear feet of the buried portion of the concrete training wall.

Alternative A4 was selected over other alternatives due to the depth of sediment removal directly behind the dam (approximately 14' deep) and the need to remove most of the concrete training wall due to long-term stability concerns. Besides the length and extent of dam removal, all other project components were the same across each alternative. Additionally, alternative A4 allows for channel and floodplain restoration within the vicinity of the dam. The ecological and hazard mitigation benefits associated with channel and floodplain restoration are not captured in the life cycle cost analysis.

A1 was discarded because it failed to address the existing hazards and the potential for flooding and dam failure was expected to increase over time with this alternative. A2 removed only the principal concrete spillway but blocked full restoration of a floodplain bench, so it was discarded in favor of either A3 or A4, which would both remove the dam and allow for floodplain restoration to alleviate both the flooding and dam failure hazards. A3 and A4 were discussed in depth by the stakeholder group at the September 28, 2020

stakeholder meeting and it was determined that A4 was the most logical removal alternative due to the required excavation depths behind the dam. Staged removal was also discussed during the meeting, and it was decided that given the age and condition of the dam, it was uncertain whether partial removal under the A4 scenario would be technically feasible or whether partial removal would undermine the remaining structure and increase risk of infrastructure failure. Ultimately the stakeholders concurred that A4 via conventional removal methods was the best alternative to address all hazards of concern.

1.8. Hydrologic Analysis

Peak Flow Analysis

Stone staff delineated the geographical region contributing flow to the site and determined the watershed size to be 6.65 mi². Streamflow data from nearby USGS gages were used to determine peak flow rates using a gage transfer technique. Stone located 3 gages within 50 miles of the site and chose 2 of those 3 gages for further analysis based on watershed size relative to the Jail Branch watershed, geology and surficial soils, length of period of record, and presence of obstructions to flow (ex. dam or withdrawal). At each gage, a Log-Pearson Type III distribution was used to determine the 2-, 5-, 10-, 25-, 50- and 100-yr recurrence interval design flows. For each gage, an additional hydrologic analysis was performed that compared records to data collected after 1970, to identify if the hydrology at each site was impacted by a recent shift in hydrologic regimes as a result of climate change. The resulting distributions were plotted and compared to the StreamStats distribution.

The East Orange Branch, near East Orange, Vermont gage (#01139800) was selected to determine peak flows at the site due to its long period of record (61 years), its comparable watershed size (8.8 mi²), proximity to the site, location along an unregulated stream and current status as an active gage. Because the post-1970 flows were higher than those corresponding to the entire record at this particular gage, the post-1970 flows were used for our analyses.

The USGS gage transfer technique was used to relate the calculated peak flows at the East Orange Branch gage to the site using the following equation:

$$Q_u = \left(\frac{A_u}{A_g} \right)^b Q_g$$

where Q_u is the estimated flow statistic for the ungaged site, A_u is the drainage area for the ungaged site, A_g is the drainage area for the stream gauging station, Q_g is the flow statistic for the stream gauging station, and b , depending on the state, may be the exponent of drainage area from the appropriate regression equation, a value determined by the author of the state report, or 1 where not defined in the state report (for this project a value of 1 was used).

The resulting peak storm flows for Jail Branch are provided in Table 11.

Table 11: Summary of Peak Flows at Jail Branch

| Recurrence Interval (years) | Flow (ft ³ /s) |
|-----------------------------|---------------------------|
| 2 | 215 |

| Recurrence Interval (years) | Flow (ft ³ /s) |
|-----------------------------|---------------------------|
| 5 | 336 |
| 10 | 433 |
| 25 | 576 |
| 50 | 701 |
| 100 | 839 |

Abbreviations: ft = feet; s = second

Date and Author: 09-14-2020 / MRA

Fish Passage Flows Analysis

High and low fish passage flows were estimated to assess potential fish passage conditions at the site following dam removal. Daily streamflow data was downloaded from the East Orange Branch gage and used to calculate the 5% and 95% exceedance flows (seasonal high and low flow) during September to November, when brook trout migration is likely. The 5% and 95% exceedance flows were also calculated using daily streamflow data from the entire year. The fish passage flows calculated for both time intervals are provided in Table 12.

Table 12: Fish Passage Flows at Jail Branch

| Flow | Sept – Nov Fish Passage Flow (ft ³ /s) | All Months Fish Passage Flow (ft ³ /s) |
|------|---|---|
| High | 15.6 | 31.7 |
| Base | 4.0 | 6.7 |
| Low | 1.2 | 1.3 |

Abbreviations: ft = feet; s = second

Date and Author: 09-14-2020 / MRA

The design flow and fish passage flow scenarios above were simulated using a one-dimensional hydraulic model described below.

1.9. Hydraulic Modeling

Model Development

Stone used the US Army Corps of Engineers (USACE) Hydrologic Engineering Center's River Analysis System model (HEC-RAS; <http://www.hec.usace.army.mil/software/hecras/>) to develop a one-dimensional, steady flow hydraulic model of Jail Branch, the dam and its floodplains. This model was used to simulate the peak flows and fish passage flows for existing and proposed conditions.

The basemap developed as part of Stone's assessment of the existing conditions at the site was the source of the topography and bathymetry for the existing conditions hydraulic model. The basemap was developed in a

relative datum and will be tied to NAVD88 datum during 100% design. Stone staff exported the TIN surface as a digital elevation model (DEM) and then imported the DEM into HEC-RASMapper to create a terrain model, which supported the development of the geometry file in HEC-RAS.

Once the geometry file was created, the dam structure and features such as natural levees, ineffective flow areas, stream bank stations, distances between cross-sections, and Manning's roughness coefficient at each cross-section were more fully defined. Survey data collected by Stone staff were used to specify the dam locations and dimensions in the existing conditions model. Manning's n values were selected based on channel surface roughness, vegetation, and channel features such as pools.

HES-RAS requires boundary conditions to set the starting water surface elevation at the upstream and/or downstream ends of the river system being modeled. Additionally, a flow regime (subcritical, supercritical, or mixed) must be selected for each analysis. For this 30% design, each steady flow analysis was completed using a subcritical flow regime, which is well suited for preliminary dam removal evaluations. Since the subcritical flow regime was used, only a downstream boundary condition was specified. The downstream boundary condition was set to normal depth with an energy slope of 0.0055, for all flow profiles. The energy slope was estimated based on the channel slope in the vicinity of the downstream cross sections. The boundary condition was set at cross-sections sufficiently far away from the area of interest as to minimize errors due to estimating the starting water surface elevation.

The peak flow and fish passage flow values calculated using gage transfer and statistical techniques were entered into the HEC-RAS flow file that was used for both the existing conditions and the proposed conditions model. For this final 30% design deliverable, the model included the tributary junction at Jail Branch and the Unnamed Tributary and incoming flows were apportioned to each tributary based on tributary watershed size. Table 13 lists the peak flow conditions simulated and Table 14 lists the fish passage flow simulated.

Existing Conditions Hydraulic Analysis

The hydraulic analysis completed for the existing conditions provides insight into the expected water surface elevations, water velocities, flood inundation limits, and barriers to fish passage for the flow scenarios analyzed. A longitudinal profile and water surface elevation results for selected cross sections under existing conditions, is provided in Attachment 7.

Proposed Conditions Hydraulic Analysis

Stone developed a one-dimensional hydraulic model to simulate flow conditions for the selected alternative (Alternative A4). The model for Alternative A4 was developed based on approximately 195 total linear feet of dam removal, the extents of which are shown on Sheets 5 and 6 of the plans. The model also incorporates the removal of approximately 13,940 CY of impounded sediment behind the dam, which is simulated in the model via a revised pilot channel slope as shown on Sheet 7 (see dashed blue line in the profile at top of sheet) and the dimensions of the Typical Channel Cross Section also provided on Sheet 7, which includes bank stabilization measures and incorporation of a 30' wide floodplain bench along river left (green shaded area on Sheet 6).

The proposed alternative lowers the modeled water surface elevation in the vicinity of the Hand Mill Dam for the modeled recurrence interval floods. Under existing conditions, the 100- and 500-year WSEs at the dam are 1,279.79 and 1,280.01' respectively (Table 13). Based on hydraulic modeling completed using USACE's HEC-RAS model, the WSEs for the 100- and 500-year at the dam location are 1,265.15' and 1,266.21' respectively, and lower than existing conditions (Table 13). Longitudinal profile and selected cross section results are provided in Attachment 7.

Table 13: Water Surface Elevation Comparison at Dam for the 100-Year Recurrence Interval Flow

| Scenario | 100-yr WSE ¹ (ft) | Linear Feet of Dam Removed |
|----------------|------------------------------|----------------------------|
| Existing | 1279.79 | 0 |
| Alternative A4 | 1265.15 | 195 |

Abbreviations: ft = feet; WSE = water surface elevation

¹WSE presented references a relative datum and will be tied to NAVD88 during 100% design development

Date and Author: 1-5-2021 / MRA/GMB

It is evident that Alternative A4 provides significant reduction in water surface elevations compared to those of the existing conditions, with a peak water surface reduction of 14.64 feet for the 100-year recurrence interval storm event. Similar reductions apply for other significant recurrence intervals (i.e., 10-, 25- and 50-year intervals). In addition to these peak water surface elevation reductions and mitigation of flooding, the dam removal also improves public safety by removing a high hazard dam that has been deteriorating over the past few decades.

Fish passage modeling results indicate that the channel velocities and main channel water depth support adult brook trout passage and generally support juvenile brook trout passage under low, base, and high fish passage flows (Table 14). While stream velocities exceed the maximum velocity for brook trout passage at some cross sections during peak flows, it is anticipated that brook trout will find refuge in slowly moving pools and eddies during these conditions.

Table 14: Channel Velocity Model Results for Fish Passage Flows (Proposed Conditions)

| Flow | Sept – Nov Channel Velocity ¹ (ft/s) | All Months Channel Velocity ¹ (ft/s) |
|------|---|---|
| High | 2.11 | 2.65 |
| Base | 1.58 | 1.68 |
| Low | 1.19 | 1.22 |

¹Average channel velocity at dam location after dam removal under Alternative A4

Date and Author: 03-11-2021 / MRA

1.10. Proposed Project

1.10.1. 30% Design

Conceptual Design

Stone developed a 30% conceptual design based on characteristics of the reference reach, keeping in mind infrastructure constraints throughout the project area, maintenance of floodplain connection, construction access and reasonable construction costs.

Based on inspection of the longitudinal profile developed from the topographic survey, the average slope of the reference reach was 1.5%. A similar average slope of 1.7% was observed in the unnamed tributary. Considering site constraints and reasonable anticipated construction costs, a slope of approximately 2.0% was used as a basis of design for the pilot channel.

Typical of other dam removal and channel restoration projects, a downstream starting point, or tie in point where the pilot channel would begin was required. As shown on Sheet 7 (Attachment 4), there is a large sediment wedge just downstream of the dam. This material consists of medium to large sized boulders and is most likely comprised of dam material that has broken off over the past few decades, material that has been transported downstream and over the dam during large storm events, and native surficial material that has been exposed due to high erosive forces. We expect that this material is immobile except during extreme storm events. Because most of this material is sourced from the dam itself and its presence in this location is not geomorphically appropriate, we proposed to remove the sediment wedge material and tie in the pilot channel just downstream of the wedge, at the first downstream grade control at approximate station 5+08. It is estimated that the sediment wedge is made up of approximately 550 CY and it is anticipated that this material will be incorporated into other parts of the design (as stone steps, bank stabilization, etc.).

A summary of the final 30% design components is provided below with additional detail in the plans provided in Attachment 4.

Dam Removal – The 30% design plans for the proposed alternative include the removal of approximately 165 linear feet of the dam, plus 30 linear feet of the buried dam, totaling approximately 453 CY of material. The removal includes the embankment section and principal concrete spillway, 67 linear feet of the concrete/stone wall, 70 linear feet of the visible portion of the concrete training wall and 30 linear feet of the buried portion of the concrete training wall. Additionally, large stone material that has accumulated downstream of the dam will be removed. No bedrock will be removed as part of dam removal. See Sheet 5 in Attachment 4 for Dam Demolition plans.

Pilot Channel Construction – The limits of the proposed channel restoration and pilot channel construction are from station 5+08 to 14+00. The overall slope of the pilot channel is 2.1%, with approximately 1' elevation drops included at proposed step locations. Steps have been incorporated to provide channel bed grade control and channel stability in the vicinity of residential properties and provide the needed elevation drop through the pilot channel. The pilot channel bankfull width will be approximately 31 ± 2 feet. Existing tree fall in the project vicinity and trees removed to allow for site access will be used as wood additions and bank stabilization practices. See Sheets 6 and 7 in Attachment 4 for additional details on pilot channel design and construction.

Floodplain Bench Construction – The proposed design includes the construction of a 30 ft wide floodplain bench along river left of the pilot channel. The floodplain bench will be tied into existing grades along its extents. The slope from existing grade to the floodplain bench will be approximately 2:1 with a varying width. The slope of the floodplain bench toe to top of bank will be approximately 5%. Live stakes, fascines, vegetation, and stabilization measures from top of bank to existing grade will be determined in 100% designs.

Ancillary Components – Ancillary components of the design include site access, haul out of materials, bypass pumping, and erosion and sediment control. Primary access for pilot channel construction and sediment haul out will be off West Corinth Road (Sheet 4, Attachment 4). While the final design plans will provide an example of site access and bypass pumping, ultimately the Contractor will be required to provide an access and material removal plan to be approved by the Engineer prior to mobilization. During construction, the Contractor will grade and create a temporary ramp into the floodplain, to be restored to existing conditions following dam removal and channel and floodplain work.

1.10.2. Photo Simulation

Stone completed a photographic simulation of post dam removal conditions at the site. The photo simulation was completed using a photo taken downstream of the dam and looking upstream, with the assumption that approximately 195 linear feet of the dam is removed. A photo of the existing conditions at the site is provided in Figure 1 and a photo simulation of the site following dam removal is provided in Figure 2.



Figure 1. Photo of existing conditions at Hands Mill looking upstream.



Figure 2: Photographic simulation of project site following dam removal

1.10.3. Permit Requirements

- Project activities and designs have been developed with input from several local, state, and federal entities to ensure that the proposed scope of work meets all permitting requirements, and that design plans are technically feasible and will result in community and ecosystem benefits. Partnering entities who have ensured the technical feasibility of this project include: 1) The Vermont Department of Environmental Conservation (DEC) - Dam Safety Division; 2) DEC - Floodplains Manager; 3) DEC - River Management Program; 4) DEC - Wetlands Program; 5) Vermont State Historical Preservation Office; 6) Vermont Emergency Management; 7) Vermont Fish and Wildlife Department; 8) United States Army Corps of Engineers; and 9) United States Fish and Wildlife Service. Below is a summary of potential permits needed and relevant regulatory review considerations.
- Local Permits
 - State Floodplain Permit –or– Municipal Flood Hazard Permit and EO11988: Project will include stream channel and stream bank restoration to install a floodplain bench for natural flood control and is not expected to negatively impact the floodplain zone. The project includes construction of 0.41 acres of floodplain bench located directly adjacent to the pilot channel. This bench will contain the majority of floods post dam removal and will also provide a means to minimize impacts to adjacent properties and infrastructure. There is no alternative to operating within the floodplain and wetland as the dam is currently located in the floodplain and is surround by wetlands. Project partners including the State Floodplain Manager and Wetlands staff have provided input on the designs to ensure construction activities minimize long-term impacts to the wetlands and floodplains. The project involves dam removal and the dam is currently mapped by approximate methods as Zone A. The project budget and scope of work includes expenses for developing as-built topography, an updated hydraulic model, and re-delineation of Zone AE at the close of construction. The project is under jurisdiction of the Town of Washington with regards
 - to work in the Special Flood Hazard Area.
- State Permits
 - Stream Alteration Permit: The project will establish a new pilot channel for the Jail Branch within the project limits of disturbance to include new streambank contours and a floodplain bench. If natural grade controls are not found during construction, grade control rock steps will be installed in strategic locations within the pilot channel limits to prevent any rapid changes in bed elevations and prevent upstream migration of a head cut following construction. These grade controls will also prevent bed adjustments in upstream tributaries post-construction. Instream restoration work will require a state Stream Alteration Permit from the River Management Program. To date an engineer from this program has participated in all stakeholder meetings and provided feedback on the design so we foresee no barriers to securing this permit once final designs are completed.
 - Chapter 43 Dam Order Permit: Hands Mill Dam impounds more than 500,000 cubic feet of water and sediment from the lowest non-overflow portion of the dam and therefore falls under the Dam Safety Program's jurisdiction. The project will need a Dam Order under 10 VSA Chapter 43.
 - Stormwater Construction Discharge Permit: This permit is typically required if the project disturbs more than 1 acre of land. The extent of disturbance will be confirmed during the 100% design phase).
 - Wetlands Permit: We anticipate not needing this permit, as the project is considered an 'Allowed Use' under Section 6 of the Vermont Wetland Rules.

-
- 401 Water Quality Certificate: We anticipate this permit not being required if the project qualifies for a USACE VT General Permit. This will be determined during the 100% design phase.)
 - State Historic Preservation Office Concurrence: Anticipated following completion of historic preservation tasks (see Archeological Resources section below).
 - Act 250: Not anticipated to be required, however this will be explored during the 100% design phase.
 - Federal Permits
 - US Army Corps of Engineers Vermont General Permit, Category 2: The project may qualify for a Pre-Construction Notification (PCN) under General Permit #10 of the Vermont General Permits (GPs).
 - Historical Buildings and Structures: The Area of Potential Effect (APE) includes or is in close proximity to the following buildings and structures older than 50 years: 1) Hands Mill Dam; 2) 16 Woodchuck Hollow Road, 3) a shed that is now part of 39 Woodchuck Hollow Road, 4) 110 Woodchuck Hollow Road; 5) 273 West Corinth Road, 6) 53 Vermette Lane, and 7) 111 Vermette Lane. Only the dam and its connected mill foundation is recommended for significance and National Register eligibility and dam removal will result in an Adverse Effect, so the scope of work includes a Historic Resources Documentation Package and Historic Resource Mitigation. SHPO concurs with these recommendations.
 - Archeological Resources: 30% Design Plans show the extent of ground disturbance totaling 1.45 acres largely in-stream and along graded contours. Designs show spatial relationship with three areas delineated as sensitive for pre-Contact Native American Archeological sites. Ground disturbance will avoid two of the three sensitive areas (both upstream). The project is proceeding with Phase 1 and (if necessary) Phase 2 archeological work for the impacted downstream site in 2021 in advance of the Implementation Phase. The project budget includes site delineation for the avoided sensitive sites prior to construction. The APE is recommended as not sensitive for historic period archaeological resources. SHPO concurs with these recommendations.
 - Endangered Species Act and Wildlife Coordination: There are no mapped occurrences of rare, threatened, or endangered species within the APE and VFWD correspondence attached indicates no concerns for aquatic or terrestrial species. The dam site is approximately 6.67 miles from the nearest known occurrence of federally listed Northern Long-eared Bats. The project site is considered "potential summer habitat" but not "known summer or winter habitat." There are 1213 acres of forested habitat within a mile of the project site and proposed vegetation clearing at the project site falls below threshold of concern (1%) for impact. The VFWD supports the project to connect 14.7 miles of Eastern Native Brook Trout habitat. Trees greater than 3" DBH were identified. The Vermont Wetlands Program performed an in-field bio-assessment of plant species within the APE for more refined details on impacted vegetation and will share this information during 100% design work.
 - Clean Water Act, Rivers and Harbors Act, EO11990: Wetlands delineation was completed in summer 2020 and wetland boundaries are included in the 30% Design Plans. The dam impounds a roughly 2-acre pond which is now heavily sedimented and providing ideal wetland habitat. There are no mapped wetlands from the National Wetlands Inventory within the APE, but the Vermont State Wetlands Program determined that a regulated Class 2 wetland is present. Correspondence with wetlands program staff indicates removal of the dam will likely qualify as an Allowed Use under Section 6 of the Vermont Wetland Rules as a restoration activity provided it follows all other applicable laws. Stream restoration projects

including dam removals are an allowed use that do not require a permit if the designs are approved by the Secretary.

- EO12898 (Environmental justice for low income and minorities): A low-income family inhabits a property directly adjacent to the project area (16 Woodchuck Hollow Road). There are no disproportionate effects to these populations. An H&H analysis performed by a certified Professional Engineer has confirmed that this property will not be impacted by any additional flooding risk after dam removal and that the 500-year peak WSE for proposed conditions is still below the existing Finished Floor Elevation. Residents have been contacted regularly throughout the preliminary design phase of this project.

1.10.4. Operations and Maintenance Considerations

The Town, as the owner of the property, will have primary responsibility over the annual maintenance responsibilities and associated operating budget. For this dam removal and floodplain restoration project, we anticipate the annual operating budget will largely consist of monitoring since all dam infrastructure will be removed from the property. As part of project funding applications, the Town of Washington submitted a maintenance agreement that commits the Town to long-term maintenance of the site. The agreement will be refined and updated during the 100% design work to include details about schedule and expected maintenance obligations. Successful maintenance will most likely entail ensuring buffer plant survivorship and protection of the streambank and floodplain from further encroachment. Tree care maintenance costs are expected to be minimal and at the expense of the Town to include regular watering and weeding until the buffer plants are well established (1 year of care) and replacement plantings for three non-consecutive years if survivorship falls below 75% within the five-year monitoring timeframe required by the U.S. Army Corps of Engineers. Total maintenance costs over the life of the project are expected to be roughly \$7,308, plus approximately \$4,000 for bank sloughing monitoring work over the first five years following construction.

1.10.5. Ecosystem Benefits

Removal of the Hands Mill dam will result in possible positive ecosystem benefits including improved water quality, connection of native Eastern Brook Trout to high-quality refuge habitat, and increased riparian corridor integrity.

Conservative estimates of water quality benefits, in terms of removal of bioavailable phosphorus, indicate that dam removal will have a positive water quality impact. The total amount of phosphorus removed can be estimated based on 1) the extent of the impoundment, 2) an assumption that much of the phosphorus is contained within the active sediment layer (top 10 cm), and 3) an assumption that approximately 30% of the phosphorus is biologically available (value provided by the VANR workgroup). Based on the above assumptions and an average P loading of 311 mg/kg, the total bioavailable phosphorus to be removed associated with the proposed dam removal is 21 kg (or 46 lbs.).

Dam removal will also eliminate the existing risk of flooding due to dam failure. A risk which only increases as climate change brings more frequent and intense storm systems to New England. Hydraulic modeling completed as part of 30% design development indicates that dam removal provides significant reduction in water surface elevations compared to those of the existing conditions, with a peak water surface reduction of 14.64 feet for the 100-year recurrence interval storm event. Similar reductions apply for other significant recurrence intervals (i.e., 10-, 25- and 50-year intervals). Given that dam failure poses the highest flooding risk to the community, removal of the dam will immediately and successfully mitigate this hazard and will provide measurable decreases in community risks in the face of climate change.

Sediment probing completed to determine the existence of underlying bedrock below the dam indicate that there is a path upstream of the dam where bedrock and/or barriers are not present down to the bottom of dam elevation. Consequently, these investigations indicate that removal will provide habitat reconnection benefits. Overall, the project will result in the removal of one stream barrier, the Hands Mill Dam, and reconnection of 14.7 miles of brook trout habitat. Additionally, the project will improve instream habitat and riparian corridor integrity with the construction of a pilot channel restoring 897 linear feet of instream habitat and the inclusion of riparian area plantings.

1.11. Conclusions

The alternatives analyzed for this project varied in scope from no action to full dam removal. Given the existing condition of the dam, potential for mitigating a significant hazard, and opportunity to increase connectivity for brook trout habitat and floodplain restoration, alternative A4 (full dam removal) is recommended as the proposed alternative. Further details regarding design components will be determined during the development of 100% designs for the project. Additional field work and analysis will be completed as needed to develop the 100% design.

Attachment 1: Dam Breach Report

Vermont Department of Environmental Conservation

Water Investment Division
1 National Life Drive, Davis 3
Montpelier, VT 05620
Phone: 802-622-4093

Agency of Natural Resources

MEMORANDUM

TO: Town of Washington, Care of Carol Davis, Town Clerk, Dam Owner
FROM: Benjamin Green, PE, Dam Safety Program (DSP), Engineer
Katherine King, DSP, Assistant
DATE: November 18, 2020
SUBJECT: DSS-Wise Lite Dam Failure Analysis and Flood Inundation Maps
Hands Mill Dam, Washington, Vermont
State ID No: 225.01 | National ID No: VT00308

This memorandum summarizes the methods, assumptions, and results of dam failure and downstream flood inundation analysis using the Decision System for Water Infrastructural Security (DSS-Wise Lite) model for the Hands Mill Dam. Hands Mill Dam and its floodway are in the Town of Washington. The following attachments are included:

- **Attachment A:** Dam Failure Flood Inundation Map
- **Attachment B:** DSS-Wise Lite Simulation Results Final Report
- **Attachment C:** DSS-Wise Lite Human Consequences Final Report

It should be noted that **Attachments B** and **C** are automatically generated reports by the DSS-Wise Lite Program.

Purpose:

The analysis was performed to investigate the hazard potential classification of the dam and potential downstream consequences in the event of a dam failure.

Dam Overview:

Hands Mill Dam is a partially breached concrete and stone rubble gravity dam with a principal spillway and outlet works founded on bedrock and/or earth. It is our understanding that dam removal is being considered and a feasibility study is currently underway.

The dam is currently classified as a SIGNIFICANT hazard potential dam. According to our files, the dam has a total length of approximately 325 feet and a structural height of 20 feet. The principal spillway consists of an eroding concrete and stone rubble weir with a total length of about 20 feet. To the left of the principal spillway is an approximately 40-foot long training wall and an old mill foundation comprised of concrete and stone rubble with an abandoned intake and concrete sluiceway. There is no auxiliary spillway. The low-level outlet (LLO) to the right of the principal spillway is an approximately 2-foot by 2-foot square opening on the downstream face that is reportedly inoperable/plugged and abandoned. To the right of the principal spillway is an approximately 300-foot-long non-overflow concrete wall that extends to the right abutment at the valley wall.

Our records dating back to 1950 indicate that the dam was built circa 1860 and was repaired after the 1927 flood. No records exist of repairs as of the 1947 ownership transfer for use as a sawmill. The dam impounds a pond with a surface area of about 2 acres at normal pool elevation that is substantially filled with sediment. It is our understanding the dam and pond currently serve no current social or economic purpose. The upstream drainage area is approximately 4,128 acres. The normal and maximum storage of the dam were estimated as 11.2 and 18.1 acre-feet in 2020 by Stone Environmental, Inc. (STI) an engineering consultant working on the dam removal feasibility study. These storage estimates compare well with historic estimates.

Downstream Conditions:

The Hands Mill Dam flows into the Jail Branch River which flows through the Town of Washington to the East Barre Dam and northerly into the City of Barre. East Barre Dam is a large, State owned and operated flood control dam that would safely contain dam failure flood waters, preventing damage further downstream. It appears that a dam failure could potentially impact several road crossings, several homes and businesses, and a school downstream.

Methods:

The DEC DSP prepared a DSS-Wise Lite model of the Hands Mill Dam and the downstream area. DSS-Wise Lite is a publicly available flood modeling and consequence analysis tool developed by The National Center for Computational Hydroscience and Engineering at the University of Mississippi. DSS-Wise Lite is a web-based program that allows the user to setup an automated two-dimensional dam breach model with minimal inputs and provides results including inundation maps, flood arrival times, hydrographs, and other life consequence information. As noted in program literature, DSS-Wise Lite is a simplified analysis producing rough, approximate results that are not intended to replace more detailed modeling processes/programs. The following limitations of DSS-Wise Lite should be considered:

- While a flood hydrograph can be manually input into DSS-Wise Lite to simulate a storm day dam failure, the program does run most reliably under sunny day failure scenarios. For this reason, a sunny dam failure during maximum pool conditions (water level at the dam crest) was modeled. This scenario is possible assuming that the principal spillway was clogged, and the water level were to rise to the dam crest. This approach also assumes normal, base flow in the downstream channel, allowing for a more easily understood incremental impact of dam breach flooding than would be present during a storm event. The failure is assumed to occur rapidly and completely to model a worst-case scenario.
- The model defaults to the use of publicly available digital elevation models (DEMs). For the area of this project, the resolution of the DEMs used in the model is 1 meter (3.281 feet).
- The program does not allow for the modeling of culverts at downstream road crossings. Accordingly, culverts are not included in the model. This does depict a somewhat worst case but observed scenario where downstream culverts become plugged with debris during a flood flow and are ineffective. Large bridges can be input in the model but are modeled as an opening with no deck.

Model Inputs:

The model inputs are summarized in **Attachment B**. Based on the DEMs, the following elevation and storage data was used (all elevations reference the North American Datum of 1988, NAVD88, in feet):

- | | |
|--------------------------|----------------|
| • Normal Pool Elevation | El. 1,287 |
| • Normal Pool Storage | 11.2 acre-feet |
| • Maximum Pool Elevation | El. 1,292.5 |
| • Maximum Pool Storage | 18.1 acre-feet |
| • Dam height | 20 feet |

Several challenges are present when performing dam breach and flood inundation analyses/mapping at Hands Mill Dam. As noted above, the normal and maximum storage inputs are based on preliminary estimates by STI. STI also estimated the volume of impounded sediment behind the dam at 14,300 cubic yards. This estimated sediment volume is equivalent to about 386,100 cubic feet, or 8.9 acre-feet. With estimated normal and maximum storage volumes of the dam of 11.2 and 18.1 acre-feet, respectively, the impounded sediment makes up approximately 80% of the impounded volume at normal pool and 50% of the impounded volume at maximum pool. It is anticipated that in the event of a dam failure, a portion of this sediment would be mobilized downstream. It is generally recognized that saturated sediment or mud flows can result in a dam failure wave that would move slower, maintain its height and shape further downstream, but perhaps travel less distance overall when compared to its clear water equivalent. This analysis was performed assuming that all impounded liquids would perform as clear water. Accordingly, it is anticipated that in the event of a dam failure, it is possible that flood depths near the dam may be greater than predicted, but the flood wave may also dissipate more quickly.

Model Results:

The DSS-Wise Lite model results are summarized in *Attachments A* through *C*. The estimated inundation limits were overlain on a ANR Atlas satellite image map. The following results are provided at select locations downstream of the dam.

| Location | Max. Estimated Flood Depth (ft) | Max. Estimated Flood Flow Velocity (ft/s) | Estimated Arrival Time of Peak Flood (hours) |
|------------------------------------|---------------------------------|---|--|
| At Dam | NA ¹ | NC ² | NA |
| 16 Woodchuck Hollow Road | 3 to 6 | 3 to 6 | Immediate |
| Woodchuck Hollow Road crossing | 3 to 12 | 6 to 15 | Immediate |
| 39 Woodchuck Hollow Road | 0 to 2 | 3 to 10 | <0.25 |
| 64 West Corinth Road | <1 | <1 | |
| 29 Woodchuck Hollow Road | <1 | 0 to 3 | |
| 31 Woodchuck Hollow Road | <1 | 0 to 3 | |
| 33 Woodchuck Hollow Road | <1 | <1 | |
| 57 Fairgrounds Road | <1 | 0 to 3 | |
| 56 Fairgrounds Road | 1 to 2 | 3 to 6 | |
| 73 Fairgrounds Road | <1 | 1 to 6 | |
| 2985 VT Route 110 | 1 to 2 | 1 to 3 | |
| 2973 VT Route 110 (Baptist Church) | 1 to 2 | 1 to 3 | |
| 40 School Lane | 1 to 3 | 3 to 6 | |
| 72 School Lane (School) | <1 | 0 to 3 | |
| School Lane crossing | 3 to 6 | 10 to 15 | |
| Creamery Road crossing | 3 to 6 | 10 to 15 | 0.25 to 0.5 |
| Tucker Road crossing | 2 to 3 | 3 to 6 | 1 to 1.5 |

(1) Not applicable

(2) Not calculated

Hazard Potential Classification:

As noted above, this dam is currently as a SIGNIFICANT hazard. The current hazard potential classification definitions from the Vermont Dam Safety Rule are provided below:

| Classification | General Definition |
|----------------|---|
| HIGH | Dams where failure or mis-operation will probably cause loss of human life. |
| SIGNIFICANT | Dams where failure or mis-operation results in no probable loss of human life but can cause economic loss, environment damage, disruption of lifeline facilities, or impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure. |
| LOW | Dams where failure or mis-operation results in no probable loss of human life and low economic and environmental losses. |
| MINIMAL | A dam that meets the LOW hazard definition, above, but is only capable of impounding less than 500,000 cubic feet. |

The Hazard Consequence Model (HCom) estimated the Population at Risk (PAR) resulting from the simulated dam failure of the Hands Mill Dam. The PAR is the estimated number of people within an inundation limits of a simulated dam failure. The HCom estimated a Nighttime PAR of 40 and a Daytime PAR of 94. The daytime and nighttime PAR vary based on the number of homes where people are typically at night, versus business, churches, or schools, where people are typically during the day.

Based on the results, the primary risk driver is the 16 Woodchuck Hollow Road property immediately downstream of the dam. While the occupancy of this property is not clear, it is noted that there was both a house and a mobile home recently observed on the lot. In the event of dam failure, the estimated depths and velocities at these structures would approach to slightly exceed accepted, survivable limits at the house and would exceed survivable limits at the mobile home. In either case, given the proximity to the dam, there would be little to no warning/evacuation time. Accordingly, there appears to be a potential for probable loss of life at the property during a dam failure.

In addition, approximately 10 buildings, including homes, a farm, and a church, would experience minor flooding that does not appear to rise to the level of probable loss of human life, but is indicative of economic loss. Also, four roadways would be overtopped, but the anticipated low daily traffic and low travel speeds suggest it is not likely this damage would result in probable loss of human life but does infer economic loss. One of the downstream roadways, School Lane, is the primary entry and exit to the Washington Village School, the failure of which could strand or limit access. According to the model results, some minor, low velocity flooding is anticipated up to and around portions of the school. This flooding is not anticipated to cause probable loss of human life but should be given extra consideration given the vulnerable population involved.

Given the results of this study, a hazard classification of HIGH or SIGNIFICANT hazard potential should be considered. A determination of the occupancy status of the 16 Woodchuck Hollow Road property is necessary to classify the dam based on this work. Also, given the close proximity of the school, a more detailed analysis may be warranted to better understand risks associated with this vulnerable population, particularly if dam removal is not pursued in the near future or if either no action or dam rehabilitation alternatives instead considered.

As the feasibility study for the dam removal project is currently underway, a prudent risk reduction measure to undertake until dam removal can be implemented would be the development of an Emergency Action Plan (EAP). The DSP would be happy to assist in the development of an EAP, which would include the flood inundation map attached here-in, pre-planned actions in the case of a dam incident or failure, and identification of key emergency personnel as well as potential evacuees.

Y:\WID_DamSafety\Dams\H\HandsMill\Hazard Classification\Hands Mill Dam (No. 225.01) – DSS Wise Lite Dam Flood Mapping

Attachment A:



LEGEND

- Buildings (E911)
- Roads
 - Interstate
 - US Highway; 1
 - State Highway
 - Town Highway (Class 1)
 - Town Highway (Class 2,3)
 - Town Highway (Class 4)
 - State Forest Trail
 - National Forest Trail
 - Legal Trail
 - Private Road/Driveway
 - Proposed Roads
- Stream/River
 - Stream
 - Intermittent Stream
- Town Boundary
- Flow Direction

Approximate Limits of Possible Shallow Flooding, <1 ft.


- 73 Fairgrounds Rd.
- 57 Fairgrounds Rd.
- 56 Fairgrounds Rd.
- 33 Woodchuck Hollow Rd.
- 31 Woodchuck Hollow Rd.
- 29 Woodchuck Hollow Rd.
- 39 Woodchuck Hollow Rd. (Farm)

Estimated Dam Failure Flood Inundation Limits

Note: The dam breach flooding information and inundation areas shown on this map are approximate and should be used only as a guideline for establishing evacuation zones. Actual flooding conditions may differ from those depicted on the map. The results of the maximum pool (water level at dam crest), rapid failure breach scenario is shown.

NOTES

Prepared by VTDEC Dam Safety Program using DSS-Wise Lite, November 2020. Represents maximum pool, rapid failure estimated flood inundation map.



DISCLAIMER: This map is for general reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable. ANR and the State of Vermont make no representations of any kind, including but not limited to, the warranties of merchantability, or fitness for a particular use, nor are any such warranties to be implied with respect to the data on this map.



Attachment B:



DSS-WISE™ Lite Flood Simulation Report

Run #2

Hands Mill Dam

NAXXXXX

November 16, 2020

Contact Information:

DSS-WISE™ Lite modeling questions: admin@dsswiseweb.ncche.olemiss.edu

FOR OFFICIAL USE ONLY

Table of Contents

| | |
|---|-----------|
| 1.0 Overview | 1 |
| 2.0 Modeling Parameters and Conditions | 3 |
| 2.1 Project Information | 3 |
| 2.2 Simulation Parameters | 3 |
| 2.3 Impounding Structure(s) Characteristics | 3 |
| 2.4 Bridge(s) to be Removed | 3 |
| 2.5 Reservoir Characteristics | 3 |
| 2.6 Failure Conditions | 4 |
| 3.0 Automated Data Preparation and Job Flow Summary | 5 |
| 3.1 Job Flow Summary | 5 |
| 3.2 Reservoir Bathymetry and Filling | 6 |
| 3.3 Data Sources | 7 |
| 3.4 Digital Elevation Model | 8 |
| 3.5 Reservoir Boundary and Breaching Structure | 9 |
| 3.6 Reservoir Initial Depth Profile | 10 |
| 3.7 Land Use/Land Cover | 11 |
| 4.0 Simulation Results | 12 |
| 4.1 Simulation Summary | 12 |
| 4.2 Land Use and Manning's Roughness Coefficient for Inundated Area | 13 |
| 4.3 Coverage and Sources of DEM Raster Datasets | 14 |
| 4.4 Maximum Flood Depth | 16 |
| 4.5 Flood Arrival Time | 17 |
| 4.6 Computed Breach Hydrograph through the Breaching Structure | 18 |
| 4.7 Observation Line Hydrograph(s) | 19 |
| 4.8 Reservoir Time History | 19 |
| 4.9 Downloading Simulation Results | 21 |

1.0 Overview

The Decision Support System for Water Infrastructure Security (DSS-WISE™) is an integrated software package combining 2D numerical flood modeling capabilities with a series of GIS-based decision support tools. It was developed by the National Center for Computational Hydroscience and Engineering (NCCHE) at the University of Mississippi and was initiated by the US Department of Homeland Security (DHS) Science and Technology Directorate through the Southeast Region Research Initiative (SERRI) Program.

A simplified, and fully automated, version of the DSS-WISE™ software suite (DSS-WISE™ Lite Ver 1.0) was developed on behalf of the US Army Corps of Engineers (USACE) Critical Infrastructure Protection and Resilience (CIPR) Program and the DHS Office of Infrastructure Protection. This simplified dam break flood modeling capability was available to interested parties through the Dams Sector Analysis Tool (DSAT) secure web portal until November 2014. An updated version with more features was developed on behalf of Federal Emergency Management (FEMA) and is available at dsswiseweb.ncche.olemiss.edu.

The DSS-WISE™ Lite software suite, running on NCCHE servers, automatically processes input files for dam-break modeling scenarios submitted by an user. DSS-WISE™ Lite further simplifies simulations by making several general overarching assumptions in an effort to streamline data preparation and computations.

The results produced by this simplified dam-break flood simulation tool represent a rough approximation. They are not intended to replace more detailed flood inundation modeling and mapping products or capabilities developed by hydraulic and hydrologic engineers and GIS professionals.

The user is, therefore, warned that professional engineering judgment should be used in the interpolation of the results generated by this simplified and automated dam-break flood analysis.

To learn more about DSS-WISE™ and DSS-WISE™ Lite visit us at:
<https://dsswiseweb.ncche.olemiss.edu>

Disclaimer

The National Center for Computational Hydroscience and Engineering (NCCHE), The University of Mississippi, makes no representations pertaining to the suitability of the results provided herein for any purpose whatsoever. All content contained herein is provided "as is" and is not presented with any warranty of any form. NCCHE hereby disclaims all conditions and warranties in regard to the content, including but not limited to any and all conditions of merchantability and implied warranties, suitability for a particular purpose or purposes, non-infringement and title. In no event shall NCCHE be liable for any indirect, special, consequential or exemplary damages or any damages whatsoever, including but not limited to the loss of data, use or profits, without regard to the form of any action, including but not limited to negligence or other tortious actions that arise out of or in connection with the copying, display or use of the content provided herein.

Elevation Datum

All reported elevations use the North American Vertical Datum of 1988 (NAVD 88).

2.0 Modeling Parameters and Conditions

2.1 Project Information

| | |
|-----------------------|--|
| Project Name: | Hands Mill Dam |
| Scenario Name: | Run #2 |
| NIDID: | NAXXXXXX |
| Scenario Description: | Sudden Failure at maximum pool with 5.5 feet between normal and max pools. |
| User e-mail: | katherine.king@partner.vermont.gov |

2.2 Simulation Parameters

| | |
|--|------|
| Simulation distance requested (miles): | 5 |
| Simulation cell size requested (ft): | 15.0 |
| Simulation duration requested (days): | 2 |

2.3 Impounding Structure(s) Characteristics

Number of Structures: 1

| | |
|------------------------|-------------|
| Structure Name: | Structure 1 |
| Structure Type: | Embankment |
| Hydraulic Height (ft): | 20.0 |
| Crest Elevation (ft): | 1292.5 |
| Length (ft): | 495.0 |

2.4 Bridge(s) to be Removed

Number of Bridges: 0

2.5 Reservoir Characteristics

| | |
|--|------------------------------|
| Selected Reservoir Point (Latitude/Longitude): | 44.1054194801/-72.4297714233 |
|--|------------------------------|

| | |
|---------------------------------------|--------|
| Pool Elevation @ Max Storage (ft): | 1292.5 |
| Maximum Storage Volume (ac-ft): | 18.1 |
| Pool Elevation @ Normal Storage (ft): | 1287.0 |
| Normal Storage Volume (ac-ft): | 11.2 |

2.6 Failure Conditions

| | |
|---------------------------------------|-----------------------------|
| Structure Name: | Structure 1 |
| Structure Type: | Embankment |
| Failure Mode: | Total Dam Breach |
| Breach Type: | Embankment |
| Pool Elevation @ Failure (ft): | 1292.5 |
| Storage Volume @ Failure (ac-ft): | 18.1 |
| Breach Location (Latitude/Longitude): | 44.105464754/-72.4298403157 |

3.0 Automated Data Preparation and Job Flow Summary

3.1 Job Flow Summary

1. Prepare Digital Elevation Model (DEM) and Land Use/Land Cover (LULC) tiles for the Area of Interest (AOI) based on requested cellsize and maximum downstream distance.
2. Burn U.S. Army Corps of Engineers (USACE) levee lines into DEM for the AOI.
3. Assign Manning's coefficients based on LULC classifications.
4. Validate user provided simulation input parameters.
5. Remove user identified bridges from the DEM.
6. Estimate reservoir bathymetry.
7. Extend impounding structures if the specified reservoir level cannot be contained.
8. Fill reservoir to specified failure elevation.
9. Prepare boundary condition and all input data for simulation.

3.2 Reservoir Bathymetry and Filling




Figure 1. Stage-Volume Curve for Reservoir

Prototype: Theoretical cubic Hermite spline curve generated from user-provided reservoir elevation and volume information.

Imposed: Measured from reservoir bathymetry after filling to the failure elevation.

The reservoir water surface was detected to be in the DEM, so bathymetry estimation was performed using the prototype stage-volume curve shown above.

User-given Storage Volume at Failure (ac-ft): 18.1

Imposed Storage Volume at Failure (ac-ft): 18.1

After filling to the failure elevation, the imposed reservoir volume matched 100.0% of the prototype volume.

3.3 Data Sources

1. Digital Elevation Models

Sources: USGS 2018 National Elevation Dataset, NOAA, DEM provided by group.

Resolutions: 2, 1, 1/3, 1/9, 0.15 arc-seconds, 1 meter, and 10 feet based on availability

Vertical Datum: NAVD88

Horizontal Datum: NAD83

2. National Land Use/Land Cover Data

Source: USGS 2016 National Land Cover Database

Resolution: 30 m

3. National Levee Database

Source: USACE

3.4 Digital Elevation Model




Image Dimensions: N-S: 3.327 miles E-W: 0.702 miles
Figure 2. Map of Digital Elevation Model with Levees for AOI.

3.5 Reservoir Boundary and Breaching Structure




Image Dimensions: N-S: 0.077 miles E-W: 0.145 miles
Figure 3. Map of Reservoir Boundary and Breached Structure.

3.6 Reservoir Initial Depth Profile




Figure 4. Map of Initial Depths in Reservoir at Failure Conditions.

3.7 Land Use/Land Cover



Image Dimensions: N-S: 3.327 miles E-W: 0.702 miles






















Figure 5. Map of Land Use for AOI.

4.0 Simulation Results

4.1 Simulation Summary

| | |
|--|---------------------------|
| Simulation Request Received: | 06:23 AM CST (11/16/2020) |
| Simulation Start Time: | 06:24 AM CST (11/16/2020) |
| Simulation End Time: | 06:26 AM CST (11/16/2020) |
| DEM resolution used for simulation (ft): | 15.0 |
| DEM resolution requested (ft): | 15.0 |
| Final distance reached downstream (miles): | 3.3 |
| Maximum downstream distance requested (miles): | 5 |
| Elapsed simulation time after breach initiation (hrs): | 22.0 |
| Remaining reservoir volume at termination (%): | 1.155 |
| Termination condition: | Water stopped spreading. |

4.2 Land Use and Manning's Roughness Coefficient for Inundated Area

| Land Use Description | % of Inundated Area | n-Value($m^{-1/3}s$) | Code | Color |
|------------------------------|---------------------|------------------------|------|---|
| Hay/Pasture | 40.42 | 0.0350 | 81 |  |
| Woody Wetlands | 18.57 | 0.1500 | 90 |  |
| Evergreen Forest * | 12.41 | 0.1000 | 42 |  |
| Mixed Forest * | 8.16 | 0.1200 | 43 |  |
| Developed, Low Intensity | 7.12 | 0.0678 | 22 |  |
| Developed, Open Space | 4.45 | 0.0404 | 21 |  |
| Developed, Medium Intensity | 3.54 | 0.0678 | 23 |  |
| Deciduous Forest * | 3.10 | 0.1000 | 41 |  |
| Emergent Herbaceous Wetlands | 1.91 | 0.1825 | 95 |  |
| Barren Land | 0.26 | 0.0113 | 31 |  |
| Developed, High Intensity | 0.03 | 0.0404 | 24 |  |
| unclassified | 0.00 | 0.0350 | 0 |  |
| Open Water | 0.00 | 0.0330 | 11 |  |
| Perennial Snow/Ice | 0.00 | 0.0100 | 12 |  |
| Dwarf Scrub * | 0.00 | 0.0350 | 51 |  |
| Shrub/Scrub | 0.00 | 0.0400 | 52 |  |
| Grassland/Herbaceous | 0.00 | 0.0400 | 71 |  |
| Sedge/Herbaceous * | 0.00 | 0.0350 | 72 |  |
| Lichens * | 0.00 | 0.0350 | 73 |  |
| Moss * | 0.00 | 0.0350 | 74 |  |
| Cultivated Crops | 0.00 | 0.0700 | 82 |  |

Note: * indicates a n-value estimated by NCCHE. Other values are taken from literature.

4.3 Coverage and Sources of DEM Raster Datasets







Figure 6. Coverage of DEM Raster Datasets in the Inundation Area.

| DEM Source | Source Resolution | Source Dataset | Color |
|------------|-------------------|-----------------|---|
| USGS | 1 arc-second | usgs_1as |  |
| USGS | 1/3 arc-seconds | usgs_13as |  |
| USGS | 1 meter | usgs_utm_z18_1m |  |

Note: The DEM for this job was created from the source DEM raster datasets listed above. These DEM raster datasets were resampled and reprojected to the user defined cell size and UTM zone, respectively. Resampled and projected DEM raster datasets were then stacked in the order specific to the group under which this simulation was submitted.

4.4 Maximum Flood Depth





Image Dimensions: N-S: 3.310 miles E-W: 0.713 miles

Figure 7. Maximum Flood Depth Map.

4.5 Flood Arrival Time

Flood arrival time is measured from the beginning of the simulation.



4.6 Computed Breach Hydrograph through the Breaching Structure

The positive discharges (Q^+) are measured in the positive direction with respect to each observation line.




Figure 9. Breach Discharge Measured at: Structure 1.

4.7 Observation Line Hydrograph(s)

The positive discharges (Q^+) are measured in the positive direction with respect to each observation line.

No observation lines were defined.

4.8 Reservoir Time History

The reservoir water surface elevation as a function of time was computed by summing the water depth and bed elevation at a regular interval at the user-specified reservoir point.




Figure 10. Reservoir Water Surface Elevation.

The reservoir volume as a function of time was computed by the following formula:

$V_t = V_{init} - V_{net}$, where V_t is the reservoir volume at a given time, V_{init} is the reservoir's initial imposed volume, and V_{net} is the net volume that has crossed downstream across any part of the breaching structure's centerline up to that point. Since this only considers water which has completely exited the breach, it should be taken as an approximation.




Figure 11. Reservoir Volume.

4.9 Downloading Simulation Results

The simulation results can be accessed at the following web address:

<https://dsswiseweb.ncche.olemiss.edu/download>

Job ID: 34459

Attachment C:



FEMA

DSS-WISE™ HCOM HUMAN CONSEQUENCE REPORT

Hands Mill Dam

Run #2

NAXXXXX

November 16, 2020

DSS-WISE Lite Simulation ID: 34459



FOR OFFICIAL USE ONLY

Disclaimer

The National Center for Computational Hydroscience and Engineering (NCCHE), at the University of Mississippi, makes no representations pertaining to the suitability of the results provided herein for any purpose whatsoever. All content contained herein is provided “as is” and is not presented with any warranty of any form. NCCHE hereby disclaims all conditions and warranties in regard to the content, including but not limited to any and all conditions of merchantability and implied warranties, suitability for a particular purpose or purposes, non-infringement and title. In no event shall NCCHE be liable for any indirect, special, consequential or exemplary damages or any damages whatsoever, including but not limited to the loss of data, use or profits, without regard to the form of any action, including but not limited to negligence or other tortious actions that arise out of or in connection with the copying, display or use of the content provided herein.

Table of Contents

List of Figures iv

List of Tables v

List of Maps vi

1.0 Overview 3

2.0 List of Abbreviations 4

3.0 HCOM DATA SETS 5

 3.1 DSS-WISE Lite Results Files..... 5

 3.2 Population Data Sets Used by DSS-WISE HCOM..... 5

4.0 FLOOD HAZARD MAPPING 7

 4.1 Potential Flood Hazard for Humans Caught Outdoors..... 7

 4.2 Flood Hazard for Humans Caught Indoors 10

5.0 MAPPING POTENTIALLY LETHAL FLOOD ZONES (PLFZs) FOR CHILDREN AND ADULTS 11

6.0 POPULATION AT RISK (PAR) ANALYSIS 12

 6.1 PAR Analysis Using Census Block Population Data..... 12

 6.2 PAR Analysis Using LandScan USA Gridded Population Data..... 16

7.0 RESULTS FILES GENERATED BY DSS-WISE HCOM..... 17

8.0 REFERENCES 19

List of Figures

Figure 1. Evolution of total inundated area as a function of time. 1

Figure 2. Evolution of nighttime PAR as a function of time. 2

Figure 3. Evolution of daytime PAR as a function of time. 2

List of Tables

Table 1. DSS-WISE Lite results files used by DSS-WISE HCOM. 5

Table 2. Potential flood hazard levels for humans caught outdoors by the flood (adapted from Cox et al. 2010). 9

Table 3. Potential flood hazard levels for humans caught indoors based on the BC Hydro LSM Building Stability Criteria..... 10

Table 4. Definition of potentially lethal flood zones (PLFZs) for different categories (Feinberg, 2017). 11

Table 5. Attributes of the census block polygons in the shapefile and the corresponding columns in the worksheet “CensusBlock_Analysis” of the MS Excel file accompanying the present report. 12

Table 6. List of results files generated by DSS-WISE HCOM..... 17

List of Maps

Map 01: Flood Maximum Depth..... 20

Map 02: Flood Arrival Time..... 21

Map 03: Flood Maximum Velocity..... 22

Map 04: Flood Maximum DV..... 23

Map 05: Flood Maximum DV Arrival Time..... 24

Map 06: Census Blocks: Population Count..... 25

Map 07: Nighttime Population Density..... 26

Map 08: Daytime Population Density..... 27

Map 09: Potential Flood Hazard Level for People Outdoors..... 28

Map 10: Potential Flood Hazard Level for People Indoors..... 29

Map 11: Potentially Lethal Flood Zones (PLFZ)..... 30

EXECUTIVE SUMMARY

This document reports the human consequences assessment for the DSS-WISE Lite simulation ID: **34459**

INUNDATION EXTENT

Total inundated area (acres)(see [figure 1](#)): 63.44




Figure 1. Evolution of total inundated area as a function of time.

ANALYSIS BASED ON CENSUS BLOCK DATA

| | |
|--|-----|
| Population in completely or partially inundated census blocks: | 301 |
| Housings in completely or partially inundated census blocks: | 130 |
| Number of states in inundated area: | 1 |
| Number of counties in inundated area: | 2 |
| Number of census blocks in inundated area: | 20 |

ANALYSIS BASED ON GRIDDED LANDSCAN USA DATA

| | |
|--|----|
| Total Nighttime PAR in inundated area (see figure 2): | 40 |
| Total Daytime PAR in inundated area (see figure 3): | 94 |




Figure 2. Evolution of nighttime PAR as a function of time.




Figure 3. Evolution of daytime PAR as a function of time.

1.0 Overview

This report is produced DSS-WISE HCOM, which is part of the DSS-WISE Web system developed by the National Center for Computational Hydroscience and Engineering, at the University of Mississippi. Funding for DSS-WISE HCOM was provided by the U.S. Federal Emergency Management Agency (FEMA) through a contract with Argonne National Laboratory (ANL).

The results provided to the user by DSS-WISE HCOM include the following:

- the present report,
- a Microsoft Excel file containing data, results and plots, and
- a series of geospatial results files (in the form of polygon shapefiles).

These files can be used for further analysis and decision making for preparedness or during the response to an emergency. The files can also be used for hazard classification, risk prioritization preparing Emergency Actions Plans (EAPs).

DSS-WISE HCOM interfaces two-dimensional flood simulation results provided by DSS-WISE Lite with the population data provided by the U.S. Census Bureau and LandScan USA.

Please send any questions or suggestions to
admin@dsswiseweb.ncche.olemiss.edu

2.0 List of Abbreviations

| | |
|---------------|--|
| ft | feet |
| hrs | hours |
| ft^2/s | Unit discharge, feet-squared per second |
| m^2/s | Unit discharge, meters squared per second |
| ft/s | feet per second |
| $ft.lb.$ | foot-pounds |
| $m.kg.$ | Meter-kilograms |
| D_{max} | Maximum depth |
| DV | Depth times velocity, unit discharge |
| DV_{max} | Maximum depth times velocity, maximum unit discharge |
| q_{max} | Maximum unit discharge, also called DV_{max} |
| DSS-WISE | Decision Support System for Water Infrastructural Security |
| DSS-WISE Web | Decision Support System for Water Infrastructural Security Web, the web-based system housing DSS-WISE Lite and other tools |
| DSS-WISE Lite | Decision Support System for Water Infrastructural Security Lite, the web-based version of DSS-WISE dam-break and flood modeling software |
| HCOM | Human Consequence Module |
| NCCHE | National Center for Computational Hydroscience and Engineering |
| PLFZ | Potentially Lethal Flood Zones |
| PAR | Population At Risk |
| EAP | Emergency Action Plan |
| NIDID | National Inventory of Dams (NID) Identifier |
| USCB | United States Census Bureau, or officially the Bureau of the Census |
| FEMA | Federal Emergency Management Agency |
| ANL | Argonne National Laboratory |
| ORNL | Oak Ridge National Laboratory |
| ESRI | Environmental Systems Research Institute |
| LSM | Life Safety Model |

3.0 HCOM DATA SETS

3.1 DSS-WISE Lite Results Files

The human consequence analysis in this report are provided by DSS-WISE HCOM based on the raster results files for the following dam-break flood modeling simulation with DSS-WISE Lite:

| | |
|---|--|
| DSS-WISE Lite simulation ID: | 34459 |
| Project Name: | Hands Mill Dam |
| Scenario Name: | Run #2 |
| NIDID: | NAXXXXX |
| Scenario Description: | Sudden Failure at maximum pool with 5.5 feet between normal and max pools. |
| Simulation distance requested (<i>miles</i>): | 5.0 |
| Simulation cell size (<i>ft</i>): | 15.0 |
| Simulation duration requested (<i>days</i>): | 2.0 |

Table 1. DSS-WISE Lite results files used by DSS-WISE HCOM.

| File Name | Type | Units | Description |
|---|--------|-------------------------|---|
| 34459_Hmax_ft_upto_final.tif | Raster | <i>ft</i> | Maximum flood depth |
| 34459_Arrival_Time_hr_upto_final.tif | Raster | <i>hrs</i> | Flood Arrival Time |
| 34459_Vmax_ftps_upto_final.tif | Raster | <i>ft/s</i> | Maximum flood velocity |
| 34459_DVmax_ft2ps_upto_final.tif | Raster | <i>ft²/s</i> | Magnitude of the maximum specific discharge |
| 34459_DVmax_ft2ps_upto_final.tifArrivalTime | Raster | <i>hrs</i> | Arrival time of the maximum value of specific discharge |

3.2 Population Data Sets Used by DSS-WISE HCOM

DSS-WISE HCOM uses two different sets of population data to estimate the Population at Risk (PAR) potentially affected by the flood:

1. 2010 Census Block data provided by the United States Census Bureau (USCB), which is federal government agency in charge of producing data about the people and economy of the U.S. A census block is the smallest geographic unit for which USCB collects data from all the houses in the unit (rather than a sample of houses). Census Blocks are bounded by visible features such as streets, roads, streams and nonvisible features such as property lines and limits of city, township, school district, and counties, etc. They are defined as polygons in a shapefile covering the entire territory of the U.S. including Puerto Rico and the Island areas. The attributes of the census block polygons include 2010 Census Housing Unit Count and 2010 Census Population Count. The latter should be considered as 2010 nighttime population data.
2. LandScan USA gridded population data developed and maintained by the Oak Ridge National Laboratory (ORNL) located in Oak Ridge, TN. LandScan USA (<https://landscan.ornl.gov/>) is a collection of gridded nighttime and daytime population datasets developed by the Oak Ridge National Laboratory (ORNL), Department of Energy. These gridded population datasets are available as raster files with a resolution of 3 arc-second (90m or 295.28ft.). They were developed by combining satellite remote sensing data, geospatial infrastructure datasets, and demographic data from USCB. Researchers at ORNL used “Intelligent” dasymetric modeling method to assign the population counts to the grid cells (Dobson et al. 2000 and Bhaduri et al. 2007) by defining a habitability index and by maintaining the total count of cells in a census block to be equal to the total population of the census block. The LandScan USA datasets used in this report are projections for 2016 (McKee et al. 2014). Daytime data is generated using specially developed techniques for population dynamics (Bhaduri 2007).

Detailed explanations on the methodologies used by DSS-WISE HCOM are provided in the technical manual, which can be downloaded from documentation page of the DSS-WISE Web website.

4.0 FLOOD HAZARD MAPPING

Flood-hazard mapping consists of partitioning the inundation extent into zones of pre-defined potential danger classes for humans. The resulting map is an ESRI shapefile of polygon type. The polygons correspond to different levels of potential danger for humans caught outdoors and indoors.

The potential danger classes are identified based on the ranges of the value of the maximum specific discharge, DV_{max} . The ranges of $q_{max} \equiv DV_{max}$ values are different for persons caught outdoors or indoors.

4.1 Potential Flood Hazard for Humans Caught Outdoors

For humans caught outdoors, the ranges of DV_{max} corresponding to five potential hazard (or danger) levels identified by different color codes are summarized in [Table 2](#), which is adapted from [Cox et al. \(2010\)](#). The potential hazard levels are:

1. “Very Low Hazard: Shallow flow or deep standing water”;
2. “Low Hazard: Dangerous to children”;
3. “Moderate Hazard: Dangerous to some adults”;
4. “Significant Hazard: Dangerous to most adults”; and
5. “Extreme Hazard: Dangerous to all”.

The three rightmost columns of [Table 2](#) correspond to the interpretation of five potential hazard levels by [Cox et al. \(2010\)](#) for three population categories defined by an index value corresponding to the product of height (H) and mass (M) of the individual as listed at the bottom of [Table 2](#).

1. “Infants and small Children”,
2. “Children”, and
3. “Adults”;

The five polygons corresponding to the five potential flood hazard levels for people caught outdoors as listed in [Table 2](#) are provided as an ESRI shapefile of polygon type.

Cox et al. (2010) notes that the limits of DV_{max} in Table 2 correspond loosely to the loss of stability of different population categories. However, it is important to note that the ranges of DV_{max} given in Table 2 should not be considered as strict limits. Various other factors may influence the stability of individuals caught outdoors by the flood, such as:

- Bottom conditions (uneven surface, slippery surface, visible or invisible obstacles);
- Flow conditions (floating debris, low temperature, poor visibility, unsteady flow and flow aeration);
- Human subject (standing or moving, experience and training, clothing and footwear, physical attributes, such as height, mass and muscular development, disabilities, and psychological factors); and
- Other factors (strong wind, poor lighting, feeling unsafe or complete loss of footing).

Table 2. Potential flood hazard levels for humans caught outdoors by the flood (adapted from Cox et al. 2010).

| DV_{max} | | | | Potential Hazard Category | Explanation | | |
|---|--------------------|-------------------|--------------------|--|--|--|---|
| m^2/s | | ft^2/s | | | Adults | Children | Infants, Small Children and Frail/Older Persons |
| from | to | from | to | | | | |
| 0.0 | 0.4 | 0.0 | 4.3 | HZ01 Very Low Hazard: Shallow flow or deep standing water | Low Hazard | Low Hazard | Extreme Hazard Dangerous to all Infants, small Children and Frail/Older Persons |
| 0.4 | 0.6 | 4.3 | 6.5 | HZ02 Low Hazard: Dangerous to Children | | Significant Hazard; Dangerous to most Children | |
| 0.6 | 0.8 ⁽²⁾ | 6.5 | 8.6 ⁽²⁾ | HZ03 Moderate Hazard: Dangerous to some adults | Moderate Hazard: Dangerous to some adults | | |
| 0.8 | 1.2 ⁽³⁾ | 8.6 | 13 ⁽³⁾ | HZ04 Significant Hazard: Dangerous to most adults | Significant Hazard: Dangerous to most adults | Extreme Hazard: Dangerous to all children | |
| 1.2 ⁽³⁾ | | 13 ⁽³⁾ | | HZ05 Extreme Hazard: Dangerous to all | Extreme Hazard: Dangerous to all | | |
| 1) Small children, children and adult categories are defined based on $height(H) \times mass(M)$ Small children: $H \times M \leq 25l(m.kg.)$ $H \times M \leq 181(ft.lb.)$ Children: $25 < H \times M(m.kg.) \leq 50$ $181 < H \times M(m.kg.) \leq 362$ Adult: $50 < H \times M(m.kg.)$ $362 < H \times M(ft.lb.)$ | | | | | | | |
| 2) Recommended upper limit of tolerable working flow regime for trained safety workers or experience and well-equipped persons | | | | | | | |
| 3) Above this value, the hazard is extreme according to majority of the past studies. | | | | | | | |

Results file package of DSS-WISE HCOM contains an ESRI shapefile of polygon type containing up to five polygons (see [Table 6](#)) corresponding to the five potential flood hazard levels for humans caught outdoors by the flood, which are listed in [Table 2](#). For convenience, [Map 09](#) of this report shows the inundation extent colored by the five potential flood hazard levels listed in [Table 2](#).

4.2 Flood Hazard for Humans Caught Indoors

For people caught indoors by the flood, it is assumed that the potential danger is associated with the collapses of the building (see [FEMA 2011, p.43](#)). This implicitly assumes that the people indoors are in potential danger of loss of life if the building collapses due to inundation by floodwaters.

[Table 3](#) list the DV_{max} values for the potential collapse of different types of buildings, which are taken from the technical report of the Life Safety Model (LSM) developed by British Columbia Hydro ([BCH 2006](#)).

Table 3. Potential flood hazard levels for humans caught indoors based on the BC Hydro LSM Building Stability Criteria.

| DV_{max} | | Color Code | Building Type |
|------------|------------|------------|-----------------------------------|
| (m^2/s) | (ft^2/s) | | |
| ≥ 5 | ≥ 54 | | HZ06: Poorly constructed building |
| ≥ 10 | ≥ 108 | | HZ07: Well-built timber building |
| ≥ 15 | ≥ 161 | | HZ08: Well-built masonry building |
| ≥ 20 | ≥ 215 | | HZ09: Concrete building |
| ≥ 35 | ≥ 377 | | HZ10: Large concrete building |

Results file package of DSS-WISE HCOM contains an ESRI shapefile of polygon containing up to five stacked polygons (see [Table 6](#)) corresponding to the five potential flood hazard levels for humans caught indoors by the flood, which are listed in [Table 3](#). For convenience, [Map 10](#) of this report shows the inundation extent colored by the five potential flood hazard levels listed in [Table 3](#).

5.0 MAPPING POTENTIALLY LETHAL FLOOD ZONES (PLFZs) FOR CHILDREN AND ADULTS

The mapping of potentially lethal flood zones (PLFZs) for humans consists of partitioning the inundation extent into zones of predefined potential lethality classes for humans. The resulting map is an ESRI shapefile of polygon type for each category. The polygons correspond to different levels of potential lethality that are defined based on the maximum depth, D_{max} , and maximum specific discharge, DV_{max} . The PLFZs for different categories of people caught outdoors, cars, mobile homes and typical residential structures are listed in [Table 4](#) ([Feinberg, 2017](#)).

Table 4. Definition of potentially lethal flood zones (PLFZs) for different categories ([Feinberg, 2017](#)).

| Category | Color Code | D_{max} (<i>ft.</i>) | | DV_{max} (<i>ft</i> ² / <i>s</i>) |
|--|------------|-----------------------------|----|---|
| Children caught outdoors (tent camping, fishing, hiking, etc.) | | ≥ 2 | or | ≥ 5.4 |
| Adults caught outdoors (tent camping, fishing, hiking, etc.) | | ≥ 4 | or | ≥ 6.5 |
| Motor vehicle (compact car) floating | None | ≥ 1 | or | ≥ 4.3 |
| Motor vehicle (compact car) sliding/toppling | None | | | ≥ 5.4 |
| Mobile homes | None | ≥ 2 | or | ≥ 30 |
| Typical residential structures | None | ≥ 4 | or | ≥ 75 |

Results file package of DSS-WISE HCOM contains an ESRI shapefile of polygon type containing two stacked polygons corresponding to the first two categories in [Table 4](#). These two polygons were extracted using the maximum flow depth and maximum specific discharge files provided in the results package of DSS-WISE Lite simulation (see [Table 6](#)). For convenience, [Map 11](#) of this report shows the extents of these two PLFZ polygons.

The polygons for the remaining PLFZ zones can also be extracted from the D_{max} and DV_{max} raster files using a suitable GIS software.

6.0 POPULATION AT RISK (PAR) ANALYSIS

The population at risk (PAR) analysis aims to provide an estimate of the number of people that will be potentially affected by the propagation of the dam-break flood. DSS-WISE HCOM provides two different types of PAR analysis based on the two different population data sets that are available (see [Section 3.2](#)).

6.1 PAR Analysis Using Census Block Population Data

The results of the PAR analysis using 2010 census block population are given in two different forms:

- The list of the census blocks that are inundated (completely or partially) by the dam-break flood is provided in the “CensusBlock_Analysis” worksheet of the MS Excel file accompanying the present report.
- The polygons of the census blocks that are inundated (completely or partially) by the dam-break flood are provided in a shapefile accompanying the present report. The attributes of the census block polygons are the same as the data columns in the MS Excel file.

The polygons of census blocks included in the inundation extent (completely or partially) are provided as an ESRI shapefile (see [Table 6](#)) in the results package of DSS-WISE HCOM. The worksheet “CensusBlock_Analysis” lists all the census blocks and their attributes, which include various data extracted by DSS-WISE HCOM. The attributes of the census-block polygons are the same as the columns in the worksheet “CensusBlock_Analysis” of the MS Excel file accompanying the present report.

These attributes of the census blocks are listed and explained in [Table 5](#). [Map 06](#) in this report shows the census block polygon outlines overlaid on the flood extent.

Table 5. Attributes of the census block polygons in the shapefile and the corresponding columns in the worksheet “CensusBlock_Analysis” of the MS Excel file accompanying the present report.

| ExcelFile | | Shapefile | Unit | Description |
|-----------|-------------|------------|------|--------------------------------|
| Col | Title | Attributes | | |
| A | State Name | STATE_NAME | | Abbreviation of the state name |
| B | County Name | CNTY_NAME | | County Name |

| | | | | |
|---|----------------------------------|------------|--------------|--|
| C | State FIPS CODE | STATEFP10 | | 2010 Census state FIPS code |
| D | County FIPS CODE | COUNTYFP10 | | 2010 Census county FIPS code |
| E | Tract CODE | TRACTCE10 | | 2010 Census tract code |
| F | Tabulation Block Number | BLOCKCE | | 2010 Census tabulation block number |
| G | Block ID Number | BLOCKID10 | | Census block identifier; A concatenation of 2010 Census state FIPS code, 2010 Census county FIPS code, 2010 Census tract code , and 2010 Census block number |
| H | Partial Block Indicator | PARTFLG | | <i>Y</i> = partial block <i>N</i> = whole block |
| I | Total Number of Housing | HOUSING10 | <i>Count</i> | 2010 Census Housing Unit Count |
| J | Total Number of Population | POP10 | <i>Count</i> | 2010 Census Population Count |
| K | Total Area | AREATOT | <i>Acres</i> | Total area of the census block. This information is extracted from the geometry of the census block |
| L | Inundated Area | AREAINUND | <i>Acres</i> | Area of the census block inundated. This information is extracted by intersecting the inundation extent with the census block. |
| M | Percent Area Inundated | AINUND_PCT | % | This quantity is calculated in the MS Excel spreadsheet by the dividing the AREAINUND (column L) by the AREATOT (column K). |

| | | | | |
|---|---------------------------|-----------|------------|---|
| N | Flood Arrival Time (Avg) | FLDAT_AVG | <i>hrs</i> | This quantity is extracted from the arrival time raster. It corresponds to the average value of the arrival times of all computational cells within the extent of the census block. |
| O | Flood Arrival Time (Min) | FLDAT_MIN | <i>hrs</i> | This quantity is extracted from the arrival time raster. It corresponds to the minimum value of the arrival times of all computational cells within the extent of the census block. |
| P | Flood Arrival Time (Max) | FLDAT_MAX | <i>hrs</i> | This quantity is extracted from the arrival time raster. It corresponds to the maximum value of the arrival times of all computational cells within the extent of the census block. |
| Q | Flood Maximum Depth (Avg) | HMAX_AVG | <i>ft</i> | This quantity is extracted from the maximum flood depth raster. It corresponds to the average value of the maximum flood depths of all computational cells within the extent of the census block. |
| R | Flood Maximum Depth (Min) | HMAX_MIN | <i>ft</i> | This quantity is extracted from the maximum flood depth raster. It corresponds to the minimum value of the maximum flood depths of all computational cells within the extent of the census block. |
| S | Flood Maximum Depth (Max) | HMAX_MAX | <i>ft</i> | This quantity is extracted from the maximum flood depth raster. It corresponds to the maximum value of the maximum flood depth of all computational cells within the extent of the census block. |

| | | | | |
|---|--|------------|------------|--|
| T | Flood Maximum DV Arrival Time (Avg) | DVMAXATAVG | <i>hrs</i> | This quantity is extracted from the arrival time of maximum specific discharge raster. It corresponds to the average value of the maximum specific discharge arrival times of all computational cells within the extent of the census block. |
| U | Flood Maximum DV Arrival Time (Min) | DVMAXATMIN | <i>hrs</i> | This quantity is extracted from the arrival time of maximum specific discharge raster. It corresponds to the minimum value of the maximum specific discharge arrival times of all the computational cells within the extent of the census block. |
| V | Flood Maximum DV Arrival Time (Max) | DVMAXATMAX | <i>hrs</i> | This quantity is extracted from the arrival time of maximum specific discharge raster. It corresponds to the maximum value of the maximum specific discharge arrival times of all the computational cells within the extent of the census block. |
| W | Flood Maximum DV (Avg) | DVMAX_AVG | ft^2/s | This quantity is extracted from the maximum specific discharge raster. It corresponds to the average value of the maximum specific discharge of all the computational cells within the extent of the census block. |
| X | Flood Maximum DV (Min) | DVMAX_MIN | ft^2/s | This quantity is extracted from the maximum specific discharge raster. It corresponds to the minimum value of the maximum specific discharge of all the computational cells within the extent of the census block. |

| | | | | |
|---|------------------------------|-----------|----------|--|
| Y | Flood Maximum DV (Max) | DVMAX_MAX | ft^2/s | This quantity is extracted from the maximum specific discharge raster. It corresponds to the maximum value of the maximum specific discharge of all the computational cells within the extent of the census block. |
|---|------------------------------|-----------|----------|--|

6.2 PAR Analysis Using LandScan USA Gridded Population Data

The PAR analysis using LandScan USA 3 arc-second gridded population data provides three sets of tabular results classified in up to 17 flood times and 10 flood hazard categories based on DV_{max} :

- Tabular summary of inundation areas as a function of flood time is presented in the worksheet “InundatedArea” of the MS Excel file accompanying the present report. The inundation area values are presented as a stacked column plot in the same worksheet.
- Tabular summary of nighttime PAR counts as a function of flood time is presented in the worksheet “Nighttime_PAR” of the MS Excel file accompanying the present report. The nighttime PAR counts are plotted as a stacked column plot in the same worksheet.
- Tabular summary of daytime PAR counts as a function of flood time is presented in the worksheet “Daytime_PAR” of the MS Excel file accompanying the present report. The tabular data is also plotted as a stacked column plot.

The nighttime and daytime PAR counts were obtained from nighttime and daytime population densities, which were extracted from LandScan USA following the methodologies described in the technical manual for DSS-WISE HCOM. [Map 07](#) and [Map 08](#) in this report show the nighttime and daytime population densities over the inundation area.

7.0 RESULTS FILES GENERATED BY DSS-WISE HCOM

All the results files generated by DSS-WISE HCOM are listed [Table 6](#).

Table 6. List of results files generated by DSS-WISE HCOM.

| No | Name | Type | Description |
|----|---|----------------|--|
| 1 | 34459_HCOM_Final_Report.pdf | PDF | The present report. |
| 2 | 34459_HCOM_Analysis.xlsx | Ms Excel | Ms Excel file accompanying this report. It contains four worksheets: 1. InundatedArea 2. Nighttime_PAR 3. Daytime_PAR 4. CensusBlock_Analysis |
| 3 | 34459_HCOM_Census_Block_polygons.shp | ESRI Shapefile | This ESRI shapefile of polygon type contains the polygons of the census blocks completely or partially included in the inundation extent. The attributes of the polygons are the same as the columns in the worksheet “CensusBlock_Analysis”. They are listed in Table 5 . |
| 4 | 34459_HCOM_Outdoor_Hazard_Categories_polygons.shp | ESRI Shapefile | This ESRI shapefile of polygon type contains up to five polygons corresponding to the five potential flood hazard levels for humans caught outdoors by the flood as listed in Table 2 (Section 4.1) |
| 5 | 34459_HCOM_Indoor_Hazard_Categories_polygons.shp | ESRI Shapefile | This ESRI shapefile of polygon type contains up to five polygons corresponding to the five potential flood hazard levels for humans caught indoors by the flood as listed in Table 3 (Section 4.2) |

| | | | |
|---|---|-------------------|--|
| 6 | 34459_HCOM_PLFZ_ polygons.shp | ESRI Shapefile | This ESRI shapefile of polygon type contains up to two stacked polygons corresponding to the PLFZ areas as listed in the first two rows of Table 4 . |
| 7 | 34459_HCOM_NT_PopDensity_ persqmi_polygons.shp | ESRI Shapefile | This ESRI shapefile of polygons type contains polygon of nighttime population density per square mile extracted from LandScan USA data. This file should be treated as FOUO |
| 8 | 34459_HCOM_DT_PopDensity_ persqmi_polygons.shp | ESRI Shapefile | This ESRI shapefile of polygons type contains polygon of daytime population density per square mile extracted from LandScan USA data. This file should be treated as FOUO |

8.0 REFERENCES

BCH (2006). Life Safety Model System v1.0, Guidelines, Procedures, Calibration and Support Manual. Technical Report Engineering Report E310, British Columbia Hydro (BCH).

Bhaduri, B., Bright, E., Coleman, Ph., Urban, M.L. (2007). LandScan USA: a high-resolution geospatial and temporal modeling approach for population distribution and dynamics. *Geojournal* 69:103-117. DOI 10.1007/s10708-007-9105-9

Bhaduri, B. (2007). Workshop Presentation.
<https://www.csm.ornl.gov/workshops/RAMSworkshop07/presentation/bhaduri.ppt>

Cox, R.J., Yee, M. and Ball, J.E. (2004). Safety of People in Flooded Streets and Floodways. 8th National Conference on Hydraulics in Water Engineering, Gold Coast. The Institution of Engineers, Australia.

Cox, R.J., Shand, T.D., and Blacka, M.J. (2010). Australian Rainfall and Runof, Revision Project 10: Appropriate Criteria for People. AR&R Report Number P10/S1/006. Engineers Australia, Water Engineering. ISBN 978-085825-9454. <http://arr.ga.gov.au/revision-projects/project-list/projects/project-10>

Dobson, J.E., Bright, E.A., Coleman, Ph.R., Durfee, R.C., and Worley, B.A. (2000). LandScan: A Global Population Database for Estimating Populations at Risk. *Photogrammetric Engineering & Remote Sensing*, Vol. 66, NO. 7, pp. 849-857. https://www.asprs.org/wp-content/uploads/pers/2000journal/july/2000_jul_849-857.pdf

Feinberg, B. (2017). Using Potentially Lethal Flood Zones to Assess Downstream Impacts from Dam Failure. Presentation at National Dam Safety Training Seminar.


FEMA (2011). Estimating Loss of Life for Dam Failure Scenarios. Draft version.

McKee, J.J., Rose, A.N., Bright, E.A., Huynh, T., and Bhaduri, B.L. (2014). Locally adaptive, spatially explicit projection of US population for 2030 and 2050. *PNAS*, 112(5), 1344-1349. <http://www.pnas.org/content/pnas/112/5/1344.full.pdf>

Map 01: Flood Maximum Depth



Map 02: Flood Arrival Time




Map 03: Flood Maximum Velocity




Map 04: Flood Maximum DV




Map 05: Flood Maximum DV Arrival Time




Map 06: Census Blocks: Population Count



Map 07: Nighttime Population Density




Map 08: Daytime Population Density




Map 09: Potential Flood Hazard Level for People Outdoors



Map 10: Potential Flood Hazard Level for People Indoors



Map 11: Potential Lethal Flood Zones (PLFZ)



Attachment 2: Historical Property Information

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

Listed on State Register

VT ACHP

Date:

9-14-89

COUNTY: Orange
TOWN: Washington
LOCATION: Adjacent to Old Saw Mill site,
at intersection of Woodchuck Hollow Road
(T.H.#9) and Corinth Road (T.H.#1).
COMMON NAME:
Armand and Edith Vermette House
FUNCTIONAL TYPE: House
OWNER: Armand and Edith Vermette
ADDRESS: Washington, VT 05675

ACCESSIBILITY TO PUBLIC:
Yes ☐ No ☒ Restricted ☐

LEVEL OF SIGNIFICANCE:
Local ☐ State ☒ National ☐

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone ☒ Brick ☐ Concrete ☒ Concrete Block ☐
2. Wall Structure
 - a. Wood Frame: Post & Beam ☐ Balloon ☒
 - b. Load Bearing Masonry: Brick ☐ Stone ☐ Concrete ☐
Concrete Block ☐
 - c. Iron ☐ d. Steel ☐ e. Other:
3. Wall Covering: Clapboard ☒ Board & Batten ☐ Wood Shingle ☐
Shiplap ☐ Novelty ☐ Asbestos Shingle ☐ Sheet Metal ☐
Aluminum ☐ Asphalt Shingle ☐ Brick Veneer ☐ Stone Veneer ☐
Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood ☒ Iron ☐ Steel ☐ Concrete ☐
 - b. Other:
5. Roof Covering: Slate ☐ Wood Shingle ☐ Asphalt Shingle ☐
Sheet Metal ☒ Built Up ☐ Rolled ☐ Tile ☐ Other:
6. Engineering Structure:
7. Other:

Appendages: Porches ☒ Towers ☐ Cupolas ☐ Dormers ☐ Chimneys ☒
Sheds ☐ Ells ☐ Wings ☒ Bay Window ☒ Other:

Roof Style: Gable ☒ Hip ☐ Shed ☐ Flat ☐ Mansard ☐ Gambrel ☐
Jerkinhead ☐ Saw Tooth ☐ With Monitor ☐ With Bellcast ☐
With Parapet ☐ With False Front ☐ Other:

Number of Stories: 2½

Number of Bays: 5 x 3

Entrance Location: center, front

Approximate Dimensions: 32' x 24' plus side wing

THREAT TO STRUCTURE:

No Threat ☒ Zoning ☐ Roads ☐
Development ☐ Deterioration ☐
Alteration ☐ Other:

SURVEY NUMBER: 0915-26

NEGATIVE FILE NUMBER:
79-A-108-1

UTM REFERENCES:
Zone/Easting/Northing
18/705660/4886580

U.S.G.S. QUAD. MAP:
East Barre Quad. 15'

PRESENT FORMAL NAME:
Vermette House

ORIGINAL FORMAL NAME:
Rodney Clough House

PRESENT USE: Residence

ORIGINAL USE: Wagon Shop

ARCHITECT/ENGINEER:
Unknown

BUILDER/CONTRACTOR:
Rodney Clough (?)

PHYSICAL CONDITION OF STRUCTURE:
Excellent ☐ Good ☒
Fair ☐ Poor ☐

STYLE: vernacular Queen Anne

DATE BUILT: c. 1840, remodled c. 1890

LOCAL ATTITUDES:

Positive ☒ Negative ☐
Mixed ☐ Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Although this structure was originally used as a wagon shop, it was substantially remodeled c. 1890 to serve as a residence. Queen Anne Revival style is evidenced by a projecting bay having brackets under the eave. The gable is detailed with shingles, some having a heraldic pattern most frequently found in the Barre Graniteville area. The foundation includes slabs of granite that were split from local field boulders. This part of the foundation may well be part of the original wagon shop foundation. The south gable was damaged by a fire that destroyed the adjacent W. and C.W. Huntington Saw Mill in 1914. (The dam and part of the foundation remain.) A rear corner wing was added in the mid-1900's and the one bay gable-roofed garage was built c. 1950.

RELATED STRUCTURES: (Describe)


1. One bay garage 10' x 16'. Gable roof.

STATEMENT OF SIGNIFICANCE:

This structure was built by Rodney Clough c. 1840 and originally served as a wagon shop. Adjacent to the shop were the Huntington saw mill and the "Washington Manufacturing Co.". Together, the buildings comprised the industrial center of Washington in the mid-19th century. Although some of the original framing of the wagon shop still exists, the structure was rebuilt as a residence, probably by a member of the Cheney family. The design of the house, especially the gable shingle work, indicates the building associations that Washington had with the Barre/ Graniteville area during the height of the granite industry in the 1890's.

REFERENCES:

1,2,3,4,7.

MAP: (Indicate North in Circle)**SURROUNDING ENVIRONMENT:**

Open Land ☒ Woodland ☐
Scattered Buildings ☒
Moderately Built Up ☐
Densely Built Up ☐
Residential ☒ Commercial ☐
Agricultural ☐ Industrial ☐
Roadside Strip Development ☐
Other:
C. 200 yards east of Route 110
and the center of Washington
Village.

RECORDED BY:

Philip C. Marshall

ORGANIZATION:

Div. of Historic Preservation

DATE RECORDED:

6/3/79



0915-26

Attachment 3: Dam Inspection Reports

Hands Mill Dam 225.01
Washington

MEMORANDUM

TO: To The File
FROM: Steven Hanna, Dam Safety Engineer
DATE: December 9, 2016
SUBJECT: Inspection of Hands Mill Dam, Washington.

On August 11, 2016, Stephen Bushman, P.E., Steven Hanna and Louisa Deering made a routine inspection of the Hands Mill Pond Dam in Washington, Vermont, State Identification Number 225.01. The inspection was carried out under the provisions of Title 10 of Vermont Statutes Annotated, Section 1105. The Town of Washington owns the dam. A number of photographs and field notes were taken. The dam was last inspected by the Department on August 5, 2013, and the report of that inspection is on file. This report updates previous observations and records additional information.

OVERALL CONDITION

The overall condition of the dam is **POOR** and the dam is currently **Partially Breached**. The dam is continuing to deteriorate and progressively breach.

DOWNSTREAM HAZARD CLASSIFICATION

The dam is classified as a Class 2, “Significant Hazard” dam. Significant hazard potential category structures are those located in predominantly rural or agricultural areas where failure may damage isolated homes, secondary highways or minor railroads, or cause interruption of service of relatively important public utilities. **The potential for loss of life is few and the potential economic loss is appreciable.**

JURISDICTION

Since the dam impounds more than 500,000 cubic feet, any alteration, reconstruction or breaching would require prior approval from the Department under provisions of 10 VSA Chapter 43.

RECOMMENDATIONS FOR OWNER

1. Retain a professional engineer experienced in the design and investigation of dams to develop plans to remove the dam and restore the upstream channel. The dam is progressively breaching. **A failure of the dam could cause public and private property damage and loss of life downstream.**
2. Develop, implement and keep current an Emergency Action Plan (EAP) for use during an unusual or emergency event at the dam. The purpose of an EAP is to reduce the risk of human life loss and injury and minimize property damage. The EAP should be reviewed and tested at least annually. Submit a copy of the EAP to the Dam Safety Program.

3. Clear the dam crest, the upstream slope and the downstream slope of trees, woody vegetation, and debris extending 15 feet beyond the toe of the dam, outlet structure, and both abutments.

INSPECTION

The inspection of the dam was conducted on August 11, 2016 at 1430 hours. The weather was partly cloudy and humid with temperatures in the mid-80s. The ground conditions were dry. The following was observed:

1. Embankment Section: The earth embankment section is primarily left of the spillway tying into the left abutment that was a firm parking lot. The downstream slope of this section was covered in grass and thick brush.
2. Downstream Wall: The wall consists of cyclopean concrete (concrete with large round stones). The concrete is deteriorating and there are several areas of the wall with significant stone loss. The area to the left of the spillway had a large area of scour and several loose stones where there had been concrete loss. Several large pieces of concrete had fallen off the wall about 50 feet to the right of the spillway. This area also appeared to be impacted by overtopping events. At the extreme left end, the downstream wall consisted of large rounded stone dry-laid. The wall was irregular but appeared more stable than the rest, most likely because it has been less impacted by high flows. Most of the downstream wall had moderate to large trees growing on or adjacent to it. These are also destabilizing the wall. There were multiple areas of seepage on both sides of the spillway.
3. Upstream Wall: The right end of the dam consisted of a concrete wall. Most of the wall was covered in thick brush but the exposed section had significant cracking. The spillway and left end of the dam had significant scour. The additional large stone that has been placed appeared stable at the time of the inspection.
4. Crest: The crest was in poor condition, covered in grass, heavy brush, and trees. There were multiple locations with signs of overtopping, erosion. The dam was partially breached near its mid-section, with fallen concrete and concrete that was leaning up to 10 feet downstream.
5. Toe: Trees, woody vegetation and debris covered the toe.
6. Principal Concrete Spillway:
 - a) Approach Channel: The approach channel was clear of debris. The concrete of the spillway was cracked and eroded along the whole width of the channel.
 - b) Weir: The weir structure was in poor condition, the left end has been partially breached and the rest of the weir was highly eroded and in poor condition. Large rock had been placed along the contact between the spillway and left crest as protection from high flows. This erosion appears to be a continuing problem, based on previous inspections.
 - c) Downstream Section: The downstream section is a cyclopean wall that has eroded. There is stone and concrete loss and water is flowing through (within) the structure.

- d) Discharge Channel: The downstream channel was clear of debris.
7. Sluice: The low level sluiceway was in poor condition and is inoperable. The sluiceway channel was about 12 feet long through the dam. The sluice gate was either closed or stop logs were in place and there was seepage coming through the logs. There were multiple seepages with water flowing heavily.

HYDROLOGY AND HYDRAULICS

The drainage area at this site is about 4,130 acres (6.45 square miles). The pond area at the normal pool is 2 acres with storage of about twelve acre-feet including sediments. At the top of the crest the dam stores 16 acre-feet. The maximum spillway capacity is about 800 cubic feet per second.

MEMORANDUM

TO: To The File
FROM: Stephen Bushman, P.E., Dam Safety Engineer
DATE: August 8, 2013
SUBJECT: Inspection of Hands Mill Dam, Washington.

On August 5, 2013, Stephen P. Bushman, P.E., and Steve Hanna, made a routine inspection of the Hands Mill Pond Dam in Washington, Vermont. A number of photographs were taken. The dam was last inspected by the Department on May 30, 2007, and the report of that inspection is on file. This report updates that report and records additional information. The inspection was carried out under the provisions of 10 VSA 1105.

OVERALL CONDITION

The overall condition of the dam is POOR. With authorization of the VT Department of Environmental Conservation, the dam should either be removed or repaired.

DOWNSTREAM HAZARD CLASSIFICATION

The dam is a Class 2, "significant hazard" dam.

JURISDICTION

Since the dam impounds more than 500,000 cubic feet, any alteration, reconstruction or breaching would require prior approval from the Department under provisions of 10 VSA Chapter 43.

RECOMMENDATIONS FOR OWNER

1. Retain a professional engineer experienced in the design and investigation of dams to develop plans to either remove or reconstruct the dam and restore the upstream channel. The dam is progressively breaching. **A sudden failure of the dam during regional high water could cause public and private property damage and loss of life downstream.**
2. Until a professional engineer is retained, monitor the condition of the dam. Report any changes to your engineer.
3. Maintenance of the dam should be improved to include clearing and brushing of the dam along the crest, the upstream slope, and the downstream slope. Brushing should be pushed 10-15 feet past the toe of the dam, 15 feet around any outlet structure, and 15 feet surrounding both abutments.
4. An emergency action plan (EAP) should be developed, implemented, and tested. The plan should indicate who would be responsible for routine and flood-time observation of the dam, the conditions

which would be cause for alarm and the way in which people possibly affected downstream would be notified.

INSPECTION

The inspection of the dam was conducted on August 5, 2013, at 1400 hours. The weather was sunny and in the 70's. The ground was dry. The following was observed:

1. **Embankment Section:** Most of the earth embankment section is left of the spillway (looking downstream). The left abutment was a firm parking lot, and the downstream slope of this section was covered in grass and thick brush.
2. **Stone Section:**
 - a) **Downstream Wall:** The downstream wall consists of cyclopean concrete for about 50 feet to the left of the spillway, in the spillway section, and for about 100 feet to the right of the spillway. There were several areas where significant stone loss had occurred: Immediately to the left of the spillway and about 50 feet to the right. The area to the left of the spillway had a large area of scour in addition to several loose stones where the concrete had been loss. This area appears to be impacted by high flows since it is on the bend of the river. Based on the photos from 2007, this section has deteriorated rapidly, probably as a result of TS Irene and recent high water. About 50 feet to the right of the spillway, several large pieces of concrete had fallen off the wall. This area appeared to be impacted by overtopping also. At the extreme left end, the downstream wall consisted of large rounded stone dry-laid. The wall was irregular but appeared more stable than the rest, most likely because it has been less impacted by high flows. Most of the downstream wall had moderate to large trees growing on or adjacent to it. These are also destabilizing the wall. There were multiple areas of seepage on both sides of the spillway.
 - b) **Upstream Slope:** The right end of the dam consisted of a concrete wall. Most of the wall was covered in thick brush but the exposed section had significant cracking. The area to the left of the spillway had significant scour that was noted in the previous inspection. However, additional large stone had been added and the area appeared stable at the time of the inspection.
 - c) **Crest:** The crest was found to be in poor condition. The crest was covered in grass, heavy brush, and trees. Structurally, there were multiple signs of overtopping, erosion, and the dam was partially breached near its mid-section. The mid-section of the dam had severe damage with fallen concrete and concrete that was leaning up to 10 feet downstream.
 - d) **Toe:** Woody vegetation covered the toe.
3. **Principal Concrete Spillway:**
 - a) **Approach Channel:** The approach channel was clear of debris. The concrete of the spillway was cracked and eroded along the whole width of the channel.
 - b) **Weir:** The weir structure was in poor condition. The left end of the weir has been partially breached, and the rest of the weir was highly eroded and in poor condition. Large rock, as noted

above, had been placed along the contact between the spillway and left crest as protection from high flows. This appears to be a continuing problem, based on previous inspections.

- c) Downstream Section: The downstream section of the spillway is a cyclopean wall. At the time of the inspection a significant amount of water was flowing over it preventing a thorough inspection. Based on the surrounding walls and weir condition, it is expected that there is some stone and concrete loss.
- d) Discharge Channel: The outlet channel downstream was clear of debris.
- 4. Sluice: The sluiceway appeared to be in poor condition. There were multiple signs of seepage with water flowing heavily.

HYDROLOGY AND HYDRAULICS

The drainage area at this site is about 4,130 acres. The pond area at the normal pool is 2 acres with storage of about twelve acre-feet including sediments. At the top of the crest the dam stores sixteen acre-feet. The maximum spillway capacity is about 800 cfs.



Vermont Department of Environmental Conservation
Facilities Engineering Division, Dam Safety and Hydrology Section
103 South Main Street, [phone] 802-241-3450
Waterbury, VT 05671-0511 [fax] 802-244-4516

Agency of Natural Resources

June 25, 2007

Carol Davis
Town Clerk
2974 VT Route 110
Washington, VT 05675

Re: Inspection of Hands Mill Dam in Washington, VT

Dear Ms. Davis,

Attached is a report of our May 30, 2007 inspection of Hands Mill Dam owned by the Town of Washington in Washington, Vermont. As was identified in 2001 the dam is in poor condition and continues to deteriorate. At that time, a recommendation to retain a professional engineer experienced in the design of dams to develop plans to either reconstruct or remove the dam and restore the upstream channel was made. That same recommendation is being made at this time. The dam is considered a significant hazard, and a sudden failure of the dam would cause probable loss of life and property damage. Consultation with your Town attorney about the liabilities of dam ownership would be prudent.

The report outlines the condition of the dam, recommendations for the owner and information about the jurisdiction of the Department under the statute on dams (10 VSA Chapter 43).

Please contact me if you have any questions on the report or recommendations.

Sincerely,

A handwritten signature in cursive script that reads "Stephen P. Bushman".

Stephen P. Bushman, P.E.
Dam Safety Engineer



Vermont Department of Environmental Conservation

Facilities Engineering Division, Dam Safety and Hydrology Section

103 South Main Street,
Waterbury, VT 05671-0511

[phone] 802-241-3450
[fax] 802-244-4516

Agency of Natural Resources

MEMORANDUM

TO: For the File

FROM: Stephen Bushman, P.E., Dam Safety Engineer *SB*

DATE: June 25, 2007

SUBJECT: Inspection of Hands Mill Dam, Washington.

On May 30, 2007, Stephen P. Bushman, P.E., Brian Terhhune, and Henry Nyenbrink, made a routine inspection of the Hands Mill Pond Dam in Washington, Vermont. A number of photographs were taken. The dam was last inspected by the Department on June 20, 2001, and the report of that inspection is on file. This report updates that report and records additional information. The inspection was carried out under the provisions of 10 VSA 1105.

OVERALL CONDITION

The overall condition of the dam is poor.

DOWNSTREAM HAZARD CLASSIFICATION

The dam is a Class 2, "significant hazard" dam.

RECOMMENDATIONS FOR OWNER

1. The owner should retain a professional engineer experienced in the design of dams to develop plans to either reconstruct or remove the dam and restore the upstream channel. Even though the dam has withstood flood and weather for decades, it will not last forever. A sudden failure of the dam during regional high water could cause public and private property damage and loss of life downstream.
2. Maintenance of the dam should be improved to include clearing and brushing of the dam along the crest, the upstream slope, and the downstream slope to ten feet below the toe of the dam.

3. Remove the trailers and tractors from the left abutment so this area can be properly inspected and monitored for sinkholes.
4. An emergency action plan (EAP) should be developed, implemented, and tested. The plan should indicate who would be responsible for routine and flood-time observation of the dam, the conditions which would be cause for alarm and the way in which people possibly affected downstream would be notified

INSPECTION

The inspection of the dam was conducted on May 30, 2007, between 1430 and 1515 hours. The weather was partly cloudy and in the 60's. The ground was dry. The following was observed:

1. Embankment Section.
 - a) Upstream Slope. The upstream slope was covered in grass and thick brush. There were multiple signs of erosion. The left abutment was severely eroded while the right abutment appeared sound. There was an exposed concrete cutoff wall near the right end of the dam in a deteriorated condition.
 - b) Downstream Slope. The slope was covered in grass and moderate brush and trees. At the mid-point of the wall there was an eroded section that was about five-feet wide by twelve-feet high. There were multiple signs of seepage to the right of the spillway. The portion of the downstream embankment with a large rip rap wall was in fair condition.
 - c) Crest. The crest was found to be in poor condition. The crest was covered in grass, heavy brush, and trees. There were multiple signs of overtopping and erosion near the mid-point of the dam. There was a portion of the concrete on the crest that has failed. There were logs and woody debris along the length of the crest. In June, 2001 a sinkhole was reported on the crest to the left of the spillway. This area is now covered with trailers and tractors, presumable from the adjacent farm, so it could not be inspected.
 - d) Toe. The toe was wet from the multiple seeps. There was woody vegetation along the toe.
2. Principal Concrete Spillway.
 - a) Approach. The approach was clear of debris, but the pond is largely filled in with sediment. The concrete of the spillway was cracked and eroded along the whole width of the channel.
 - b) Weir. The weir structure was in poor condition. The left end of the weir appears to be failing and it is noticeably lower than the remaining structure. Excessive erosion and channel cutting was occurring around the left end of the weir structure.
 - c) Downstream Section. The downstream slope is a cyclopean wall that had a substantial amount of stone and concrete that was in a deteriorated state or missing. Portions of the

wall were covered with seeps, moss, ferns, and small trees.

d) Outlet Channel. The outlet channel was clear of debris.

3. Sluice. The sluice was difficult to inspect but appeared to be in poor condition. There were multiple signs of seepage at the sluice.

HYDROLOGY AND HYDRAULICS

The drainage area at this site is about 4,130 acres. The pond area at the normal pool is 2 acres with storage of about twelve acre-feet including sediments. At the top of the crest the dam stores sixteen acre-feet. The maximum spillway capacity is about 800 cfs.

JURISDICTION

Since the dam impounds more than 500,000 cubic feet, any alteration, reconstruction or breaching would require prior approval from the Department under provisions of 10 VSA Chapter 43.

Please don't hesitate to call me at 241-3450 if I can be of further assistance.

State of Vermont
Department of Environmental Conservation
Dam Safety Section
103 South Main Street
Waterbury, VT 05671-0407

DAM INSPECTION CHECK LIST

Dam HANDS Mill DEC ID. No. _____
Town WASHINGTON NatDam ID No: VT000 _____
Owner TOWN OF Inspection Date 5-30-07
Address _____ Time 1210 1430-1515
_____ Last Inspected/by _____
Telephone _____ Last D/S Haz Class _____
Right of Entry _____

PERSONS PRESENT AT TIME OF INSPECTION (Name and Organization)

Inspection Party SPB, BAT, MN

Others _____

I. Conditions at Time of Inspection

Weather: Today PT CLOUDY, GA. Previous Clear, 70s
Ground Conditions DRY Other _____
Water Level _____ w/r/t _____
Accessibility _____
Reservoir Area _____
Remarks POOR CONDITION, DAM SHOULD BE REMOVED & CHANNEL
W/S RESTORED

II. Condition of Main Structure

Type of Construction CYCLOPEAN CONCRETE / EARTH EMBANKMENT

A. Upstream Face or Slope

1. Vegetative Cover GRASS / THICK BRUSH
2. Erosion MODERATE ALONG EMBANKMENT SECTION
3. Slumps, Slides, Cracks _____
4. Animal Burrows NN
5. Slope Protection _____
6. Debris _____
7. Structural _____
8. Abutments LT ABUTMENT ERODED / RT ABUTMENT SOUND
9. Alignment _____
10. Movement _____
11. Remarks EXPOSED CONCRETE CUT-OFF WALL NEAR RT END.
DETERIORATED CONDITION.

B. Downstream Face or Slope and Toe

1. Vegetative Cover GRASSES, MODERATE BUSH & TREES
2. Erosion _____
3. Slumps, Slides, Cracks MID POINT OF DAM HAS AN
ERODED SECTION \approx 5' WIDE X 12' HIGH
4. Animal Burrows _____
5. Slope Protection _____
6. Debris _____
7. Seepage NOTED JUST RT OF SPEEDWAY THROUGH CYCLOPEAN
WALL.
8. Piping _____
9. Boils _____
10. Toe Drains NONE
11. Scour _____
12. Structural CYCLOPEAN WALL HAS LOST SUBSTANTIAL AMOUNT
OF STONE, IN DETERIORATED STATE
13. Abutments RT SOUND, LT ERODED LT ALSO HAS TRAILING
& TRACED ON THAT IMPROVE INSPECTION

14. Alignment _____

15. Movement _____

16. Remarks STONE WALL SECTION AT RIGHT END BULGES OUTWARD
IN SEVERAL PLACES.

C. Top of Dam

1. Vegetative Cover GRASS, HEAVY BUSH & TREES

2. Erosion _____

3. Evidence of Overtopping YES, ABOUT AT MID-POINT. PORTION
OF CONCRETE ON CREST HAS FALLEN
4. Settlement, Cracks _____

5. Animal Burrows NN

6. Debris LOGS, WOODEN DEBRIS

7. Use of crest (road, trail, etc.) NONE

8. Structural POOR CONDITION

9. Abutments RT: FAIR. LT: SEVERELY DAMAGED

10. Alignment _____

11. Remarks _____

III. Condition of Outlet Works

A. Principal Spillway

Type CYCLOPEAN CONCRETE

Controlled or Uncontrolled UNC

1. Approach Channel CLEAN, BUT IN GENERAL POND V/S OF DAM FULL OF SEDIMENT

2. Transition _____

3. Control Section CONCRETE SEVERELY DETERIORATED

4. Discharge Channel CLEAN

5. Intake Structure _____

6. Conduit _____

7. Outlet Structure _____

8. Trash Racks _____

9. Anti-vortex Devices _____

10. Stop Logs, Flash Boards _____

11. Remarks _____

B. Emergency Spillway

Type _____

Controlled or Uncontrolled _____

1. Approach Channel _____

2. Transition _____

3. Control Section _____

4. Discharge Channel _____

5. Remarks _____

C. Drawdown Facilities, Gates, Drains, Appurtenances, Etc.

1. Drawdown Facility _____

Condition _____

2. Other Gates, Drains, Appurtenances _____

Condition _____

3. Remarks _____

IV. Operation and Maintenance

V. Inspection Summary

A. Information Obtained

1. Photographs _____

2. Dimensions _____

3. Other _____

B. Additional Information Needed

C. Overall Condition of Dam

VI Owner Interview Yes No When/where _____

(A) Plans, inspection reports, photos, other records? _____

(B) History of dam _____

(C) Performance, floods, operation, etc. _____

(D) Property lines, access, water rights, etc. _____

(E) Other Information _____

VII. General Comments

Check List completed by Name _____

Title _____

Date _____

Attachments: _____



State of

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
RELAY SERVICE FOR THE HEARING IMPAIRED
1-800-253-0191 TDD>Voice
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

November 14, 2001

Carol Davis
Town Clerk
2974 VT Route 110
Washington, VT 05675

Re: Hands Mill Dam - Washington

Dear Ms. Davis,

Attached is a report of our June 20, 2001 inspection of the dam owned by the Town of Washington in Washington, Vermont. Some items in the recommendations of the reports should be given early attention.

The report outlines the condition of the dam, recommendations for the owner and information about the jurisdiction of the Department under the statute on dams (10 VSA Chapter 43).

Please contact me if you have any questions on the report or recommendations.

Sincerely,

Robert B. Finucane, P.E.
Dam Safety Engineer

cc: Larry R. Fitch, P.E., Director, Facilities Engineering Division.



State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
RELAY SERVICE FOR THE HEARING IMPAIRED
1-800-253-0191 TDD>Voice
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

MEMORANDUM

TO: For the Record

FROM: Robert B. Finucane, P.E., Assistant Dam Safety Engineer

DATE: November 14, 2001

SUBJECT: Inspection of the Hands Mill Pond Dam, Washington

On June 20, 2001, Robert B. Finucane, and Jennifer Vosburgh, made a routine inspection of the Hands Mill Pond Dam in Washington, Vermont. A number of photographs were taken. A second visit to the site was made on August 3, 2001 to set a benchmark. The dam was last inspected by the Department on November 14, 1984, and the report of that inspection is on file. This report updates that report and records additional information. The inspection was carried out under the provisions of 10 VSA 1105. Permission to inspect the dam was given by Selectman Don Milne in a phone conversation on June 19.

OVERALL CONDITION

The overall condition of the dam is poor. The spillway section is partially failed at the left end and exhibits widespread concrete deterioration, spalling and erosion. The embankment section is overgrown with trees and brush.

RECOMMENDATIONS FOR OWNER

Recommendations for the owner include:

- 1) The owner should retain an professional engineer experienced in the design of dams to develop plans to either reconstruct or remove the dam. Even though the dam has withstood flood and weather for decades, it will not last forever. A sudden failure of the dam during regional high water could cause public and private property damage and loss of life downstream.
- 2) Maintenance of the dam should be improved to include clearing and brushing of the dam along the crest, the upstream slope, and the downstream slope to ten feet below the toe of the dam.
- 3) An emergency action plan (EAP) should be developed, implemented, and tested. The plan should indicate who would be responsible for routine and flood-time observation of the

dam, the conditions which would be cause for alarm and the way in which people possibly affected downstream would be notified

INSPECTION

The inspection of the dam was conducted on June 20, 2001, between 1300 and 1430 hours. The weather was partly cloudy and in the 80's. The pond level on August 3, 2001 was 0.2 feet below the PK nail set in a 4x4 in the crest of the dam and about the same as during the June 20 inspection. The ground was dry. Portions of the first visit to the site were observed by Ann Jennings and Brian Fitzgerald from the Water Quality Division. Washington Selectman, Don Milne was also present. The following was observed:

1. Embankment Section.

a) Upstream Slope. The upstream slope was in fair condition, and was found to be firm, dry, and irregular and heavily overgrown with brush and trees.

b) Downstream Slope. The downstream slope of the dam was also overgrown, steep, dry and irregular. Portions of the slope on the right side of the spillway are covered with riprap. At the right of the spillway, there is evidence of historic overtopping and sloughing of the embankment. On the left side of the spillway, the foundations of the old mill building form the slope.

c) Crest. The crest was found to be in poor condition. The crest to the right of the spillway is narrow, and overgrown with vegetation, including trees twelve inches in diameter breast high. The roots of these trees grow into the embankment generating pathways which allow water to enter and cause the embankment to deteriorate and eventually fail.

A 4-inch diameter, 12 inch deep hole was found in the crest to the left of the spillway, and a grade stake with flagging on it was placed in the hole. When revisited on August 3, the hole had grown to 18 inches diameter and 12 inches deep. It is believed that the hole is caused by topsoil washing into the old stone mill foundation.

d) Toe. The toe was firm, dry, and irregular and overgrown with vegetation on the right side of the spillway. Seepage was found flowing at approximately 5-10 gallons per minute from the old mill sluice that had been previously filled in at the left end of the spillway.

2. Principal Spillway.

a) Approach. The approach was in fair condition. The pond is largely silted in and with the crest of the dam lowered, the stream meanders through the sediments to form a small pool above the spillway.

b) Weir. The weir structure was in poor condition. The height of the dam appears to be

the same as it was as it was at the last inspection in 1984. The weir is constructed of cyclopean concrete. Portions of the wall were covered with seepage and moss, ferns, and other small plants. Spalling was observed up to twelve inches in depth on the right side of the spillway, and seepage with various flow rates was found along the entire length of the wall to the right of the spillway. Portions of the wall have failed and debris has collected at the end of the wall on the right side of the downstream slope. Comparison with the 1979 photos documents widespread concrete deterioration.

c) Outlet Channel. The outlet channel is clear. A concrete training wall downstream of the right side of the spillway visible in the 1979 photographs has collapsed.

3. Sluice. The sluice was in fair condition. Minor seepage and efflorescence was observed.

HYDROLOGY AND HYDRAULICS

The drainage area at this site is about 4,130 acres. The pond area at the normal pool is 2 acres with storage of about twelve acre-feet including sediments. At the top of the crest the dam stores sixteen acre-feet. The maximum spillway capacity is about 800 cfs.

DOWNSTREAM HAZARD CLASSIFICATION

The dam is a Class 2, "significant hazard" dam.

JURISDICTION

Since the dam impounds more than 500,000 cubic feet, any alteration, reconstruction or breaching would require prior approval from the Department under provisions of 10 VSA Chapter 43.



Hands Mill Dam, Washington
2001

Spillway. Note vegetation,
seepage, and concrete
deterioration on walls and
rubble in spillway crest.



Spillway from left abutment.

Handy Mine

8/3/61

NBF

JMV

WL = 0.1' below PK road
set in road 4×4 in
spiral

Sink hole in left about now
18' dia x 12" deep
previously noted and
flagged at 4" dia


Flatts Mill dam

6/20/01
RBT
JMV

← fens
water dripping from
d d d

← water flowing
from under rock

right embankment completely
saturated by water (bottom 1/2)



concrete wall flow
broken up

Spoke To [unclear] At [unclear]
Washington, [unclear]





We will meet at the
then Clerk's Office [unclear]
at 1:30 to [unclear]
at [unclear]



01-31-01

< >22+01 NHH-02AU 183

**DOCUMENTS
WERE FOUND
STUCK
TOGETHER**



1-31-24

Hands Malt 6/20
[2001]

Carbon stone to exhibit
Trees up to 12" dbh
heavy brush
diameter
brush high

oak

1300

cyc conc main

mile

spun


BT fitz

ann, ening

RBF

JMV

PC 80c



core spalled
up to 12"
deep
sec up
green

end
RT side crest failed
visible d/s wall failed

hole coes till but
sticks + flag

old mill sluice filled in
5-10 years

new sluice 2 x 7 plants up

Filename: Document4
Directory:
Template: C:\Documents and Settings\paulak\Application
Data\Microsoft\Templates\Normal.dot
Title:
Subject:
Author: Staff
Keywords:
Comments:
Creation Date: 12/9/2004 10:04 AM
Change Number: 1
Last Saved On:
Last Saved By:
Total Editing Time: 0 Minutes
Last Printed On: 12/9/2004 10:06 AM
As of Last Complete Printing
Number of Pages: 1
Number of Words: 0 (approx.)
Number of Characters: 4 (approx.)



State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
RELAY SERVICE FOR THE HEARING IMPAIRED
1-800-253-0191 TDD>Voice
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation

**Dam Safety Section
Facilities Engineering Division
103 South Main Street
Waterbury, VT 05671-0407**

**Telephone (802) 241-3451
FAX (802) 241-3273
peter.barranco@anrmail.anr.state.vt.us**

May 4, 1999

Carol Davis
Town Clerk
2974 VT. Route 110
Washington VT 05675

Re: Hands Mill Dam - Washington

Dear Ms. Davis:

This will confirm our telephone conversation this morning regarding the Department's request to make a routine safety inspection of the Hands Mill Dam this summer under provisions of 10 VSA Section 1105 (copy enclosed). The dam was last inspected by the Department in 1984 and a report sent to the Town.

It is my understanding that you will bring this to the attention of the Selectmen for their consideration. I would appreciate it if you or the Select Board could write me confirming we have the Town's permission to make the inspection. We will let you know in advance of the inspection date in the event someone from the Town would like to accompany us. A report will be prepared following the inspection and a copy will be sent to the Town.

Thank you for your assistance. Please give me a call if you have any questions or we can be of any help.

Sincerely,

A. Peter Barranco, Jr., P.E.
Dam Safety Engineer

Enclosure as noted.

c: Harry K. Roush, Fire Chief, Washington
Larry R. Fitch, P.E., Director, Facilities Engineering

3/4/99
SPD

Hand Mill Dam - Washington
3/4/99 @ 0800 Helen Harry Beach (Fire Chief) ²⁴¹⁻³⁵⁸⁷
re: status of dam → still partially break off
side, salted in. Advised plan to suggest
the number - who should we contact?

→ Carol Davis TC @ 833-~~2218~~ 2218

@ 0930 thru Carol Davis - OK &
no suggestions - she will advise Election -
Harry Beach called her already - will send
her letter + call again when we have
it scheduled (summer convention).

2974 VT Route 110

Washington VT 05675

7/3/97
ADD

HANDS MILL VT 00308 DEC 225-1

Add to Net Dam Flow

tentative Class 2 (changed for class 3
even though silted in until further
verified).

USGS 44-B

$$\begin{aligned} \text{Lat} & 44 \quad 05 + \left(\frac{20.3}{37.9} \right) (2.5) = 44 \quad 06.34 \\ \text{Lon} & 72 \quad 25 + \left(\frac{8.9}{27.4} \right) (2.5) = 72 \quad 25.81 \end{aligned}$$

dimension from file - reports

L = 325' (incl. spillway)

H = ? 22' SHH

Spillway 28' x 2' (min) cyclo. conc.

? 18' DHS
(scale of plan)
bottom of conc. spill

DA = $\frac{6 \times 45 \text{ m}^2}{2.4} = 4128 \text{ A}$

H \downarrow 2.4

C = 2.8 @ 2'

to stream bed?

3.1 @ 3'

say H = 20' \pm



orig dam c. 1860

pond shown a old mps

conc. spill c. 1923

SHH says (1950) at least 45'
 years old

Heater spill water
and in 1927 (land)

1972 survey Top of embank - irregular 2'-3'

above spillway crest

Call it 2.5' for no overlapping at all

possible 0.5' at rt. end spill

very approx

$$Q = (3.0)(68)(2.5)^{1.5} = 806 \text{ cfs} \approx 800$$

(doesn't not include flow through partial
breach)

DHS report used 1025 cfs

VERMONT DAM INVENTORY

| | | |
|--|-----------------------|----------------|
| Dam name HANDS MILL | State ID | 225-1 |
| | National ID | VT00308 |
| Other name | FERC No | 0 |
| | Basin No | 8 |
| Hydro Fac Name | Basin name | WINOOSKI RIVER |
| Hydro Fac Owner | | |
| Town WASHINGTON | County ORANGE | |
| Latitude 44- 6.34 | Longitude 72-25.81 | |
| River or Stream JAIL BRANCH | Downstream Hazard | 2 |
| Nearest City/Town WASHINGTON | Size Category | |
| Distance Nearest City/Town .00 MI | Hazard subclass | |
| Owner Name(1) TOWN OF WASHINGTON | Purposes | 0 |
| Address WASHINGTON, VT 05675 | Year Completed | 1860 |
| | Status | ABANDONED |
| Telephone | Owner type(1) L | |
| Owner Name(2) | Dam type | RE |
| Address | Constr type EARTHFILL | |
| | Dam height | 20 FT |
| Telephone | Owner type(2) | |
| Non-Fed Dam on Fed Prop N | Dam length | 325 FT |
| | Maximum storage | 16 AF |
| | Nor storage | 12 AF |
| Orig const date 1860 | Purpose MILL POWER | |
| Design | St Auth NR | |
| Recon/Mod 1 date 1928 | Purpose CONC SPILLWAY | |
| Design UNKNOWN | St Auth NR | |
| Recon/Mod 2 date | 0 Purpose | |
| Design | St Auth | |
| Dike Type | Height | 0 FT |
| D/S Haz | Stor:Nor | 0 AF |
| | Length | 0 FT |
| | Max | 0 AF |
| | Structural height | 20 FT |
| | Hydraulic height | 20 FT |
| Prin spill CYCL CONC OVERFALL 68'L X 2.5'D | Hydro fac type | |
| Design cap | 0 CFS | |
| Max cap | 800 CFS | |
| Emer spill NONE | Hydro devel date | 0 |
| Design cap | 0 CFS | |
| Max cap | 0 CFS | |
| | Installed capacity | 0 KW |
| Plans NO | Specs NO | |
| Field dwg YES | Photos YES | |
| Des. docs NO | Other SURVEY | |
| | Phase I inspection | N |
| | Phase I insp date | |
| | Phase I report | |
| USGS Quad 44-B Corps L-9 | VT7420-16-155 | |
| Other AP VT-62-H-47-167 | Ortho | |
| Other maps | Inspection date | 11/14/84 |
| | Inspected by DEC | |
| | Authority | 10 VSA 1105 |
| Remark ORIG DAM MAY DATE TO 1860'S. TIMBER | Emergency action plan | NR |
| SPILLWAY WASHED OUT IN 1927 FLOOD, | | |
| REPLACED WITH CONCRETE C.1928. | Last State inspection | 1984 |
| POND SILTED-IN. MAY BE CLASS 3. | | |
| | Next State insp due | 0 |
| | RECORD | 590 |

7/31/91

7/19/99
HDD

Hande Hill Dam

7/19/99 1415 Don Walne, Secretary of
Washington called to say we have
town's permission to proceed. It would
look to be good. The town is interested
in getting and what they should do
with the dam. They're concerned with
the condition even though it is well m.

828-247 work

Advised we would be glad to have
him here and will call in advance.
Expect it would be during the first
two weeks of August.

VERMONT DEPARTMENT OF WATER RESOURCES
INFORMATION SHEET

Name of Dam Hands Mill Town Washington

Owner Town of Washington Name of Stream Sail Brook

Address _____ Classification _____

Vermont

U.S.G.S. Coordinates: Lat. 44° 3' 24" ^{6 15} Long. 72° 23' 54" ^{26 0}

U.S.G.S. Map East Barre Aerial Photos VT-62-H 47-166 to 167

U.S.G.S. Elev. @ Spillway _____

Total Length of Dam 260' Crest Width of Emergency 60-70'
Spillway

Width of Top 2.35' Maximum Height 20' 19' check

Spillway Capacity: Principal _____ Emergency 3600 cfs

Pond Area 2 acres Drainage Area 6.45 sq mi.

Pond Volume: Normal Water Level _____ Design High Water Level _____

Maximum Water Depth: Normal Water Level _____ Design High Water
Level

Storage Before Emergency Spillway is Used _____

Use of Reservoir N/A

Description of Dam: Earth filled with heavy concrete spillway

Description of Spillway(s): Concrete 60-70' wide
2' below top of dam 3' in 1' downstream
1 in 1' upstream

Designed by _____ Year Built 1928*

Hearing Date _____ Order Date _____

Additional Remarks: * Concrete section; unknown for rest.



State of Vermont

AGENCY OF ENVIRONMENTAL CONSERVATION

Department of Fish and Game
Department of Forests, Parks, and Recreation
Department of Water Resources & Environmental Engineering
Natural Resources Conservation Council

Montpelier, Vermont 05602
Department of Water Resources
and
Environmental Engineering

(802) 828-2761

November 18, 1984

Ms. Patricia Woodward
Town of Washington
P.O. Box 5
Washington, Vermont 05676

Re: Hands Mill Dam - Washington

Dear Ms. Woodward:

Enclosed is a copy of the Department's 1975 report on the Hands Mill Dam which you requested by telephone on November 14.

The dam has been inspected by the Department in 1950, 1953, 1972, 1973, 1975, 1979 and most recently on November 14, 1984. The latter was a cursory inspection due to snow, ice and stream conditions. The dam is judged to be in very poor condition and deterioration has been noted over the years.

Further failure of the structure could occur during periods of high inflows, or at other times. Since the pond has very small storage due to the sedimentation, damages due to a failure would be less severe than if the pond was at the original capacity. However, a major failure would undoubtedly damage the road and structures below the dam. Direct threat to loss of life due to discharges associated with a failure of the dam itself, i.e. not considering concurrent flooding from the watershed, is probably low in its present silted-in condition.

The Department recommends that the Town either rehabilitate the dam to an acceptable condition or remove part or all of the spillway to reduce the risk of failure and resulting damages. The latter approach would necessitate an acceptable plan to stabilize sediments behind the dam and prevent their release downstream. Since the dam is or was capable of impounding more than 500,000 cu. ft., prior approval from the Department is needed to reconstruct, alter or breach the dam under provisions of 10 VSA Chapter 43, Dams (copy enclosed).

Should you or other town officials have any questions,
please get in touch,

Sincerely,



A. PETER BARRANCO, Jr., P.E.
Dam Safety Engineer


APB:j

cc: Board of Selectman, Town of Washington

encl: (1) 1975 report and transmittal letter
(2) Copy of 10 VSA Chapter 43

HANDS MILL DAM

6-7-79



79-15-21



CREST OF E/F SECTION

LOOKING UPS (1) HILLSIDE

(SILTED IN)

AGENCY OF ENVIRONMENTAL CONSERVATION

MONTPELIER, VERMONT

AGENCY MEMORANDUM

SUBJECT

TO:

FROM:

DATE:

HOLDS MILL DAM
6-7-79



79-15-25



79-15-28

WASTE GATE TO RIGHT OF
SPILLWAY

AGENCY OF ENVIRONMENTAL CONSERVATION

MONTPELIER, VERMONT

AGENCY MEMORANDUM

SUBJECT

TO:

FROM:

DATE:

HANDS MILL DAM
6-7-79



79-15-30

UNDERMINING @ RIGHT-
ABUTMENT OF MARY
SECTION

AGENCY OF ENVIRONMENTAL CONSERVATION

MONTPELIER, VERMONT

AGENCY MEMORANDUM

SUBJECT

TO:

FROM:


DATE:

INDS MILL DAM Washington



79-15-25

15



79-15-3)

TAIL RACE IN BACK OF LEFT SIDE
MILL WHEEL SHOWN ON PHOTO 25

TO:
FROM:
DATE:

SUBJECT

AGENCY MEMORANDUM


AGENCY OF ENVIRONMENTAL CONSERVATION
MONTPELIER, VERMONT

WINDS MILL DAM
Washington
6-7-79



78-15-23

79-15-24 ~~SPILLWAY~~ BREACH



LOOKING DOWN VIS ~~VIEW~~ OF
~~SPILLWAY~~ BREACH TO LEFT OF SPILLWAYS



79-15-26



27

D/S FACE



79-15-10



79-15-10

2-14
444005 ALL DAM
6-2-79

AGENCY OF ENVIRONMENTAL CONSERVATION

MONTPELIER, VERMONT

AGENCY MEMORANDUM

SUBJECT

TO:

FROM:

DATE:

HINDS MILL DAM

11-14-64



CT-51-25



CT-51-30

D/S Face spillway adjacent to breach

?



CT-51-32

ANDS MILL DAM

11-14-84

Left end
breed



84-51-23

Looking d/c along
right side mill wall
and wheel pit structure.

D/S
↑



84-51-24

Collapsed and eroded area at
right end spillway at embankment (w/isth).

HANDS MILL DAM

11-14-84



84-51-21

84-51-22

view of breach to left of spillway

HANDS MILL DAM

11-14-84



8:51-19

D/S Channel




8:51-20

"Reservoir" as viewed from
crest of dam on R/S spillway near breach
- looking U/S.

HANDS MILL DAM

11-14-64



→ d/s

84-51-17

84-51-18

Crest and d/s slope near right abutment.

HARPS MILL DAM

11-14-84



← left
embankment

84-S1-34 ↑
Spill way

↑
Structure or chamber
for wheel (?)



84-S1-35 Left embankment and wheel
chamber (?)

HANDS MILL DAM


11-14-84



84-51-31 Remnants of well at
right end spillway and
embankment




84-51-36 Breach at left end of spillway.



84-51-33

HANDS MILL DAM

11-14-84



D/S Face of right embankment. Note dry boulder
wall containing embankment along part of d/s face.

Wed 11-14-84 Apr 5
35° clear, windy, 4" [±] snow

Hands Mill Dam on ground

1350-1430 inspected dam.

Cursorry inspection due to
snow, ice and water conditions.

Rt. Embankment: Crest & up slope -
brush; up slope + toe brush,
trees up to 18" including large
snags: d/s well intact but irregular
and bulging (may be the way
constructed - large boulders - not
cut stone).

Lt. Embankment: Too much snow
to inspect. Brush.

Spillway: d/s face; seepage,
deeply eroded, crumbling; cyclopean
concrete: crest snow covered.
(OVER)

11-14-64

Left spillway abut. - breach
looks about the same - est
0.5' water through breach.

Right Spillway abut. Appear to
be further erosion + movement of
remnants of abut. wall. Depression
in "silt" on up side wall in this
area - probably passed water at
high pond levels or is result of
piping.

Overall in very poor condition.
Only apparent change is further
erosion / undermining at right
abutment of spillway.

Photos

HANDS MILL DAM

3-10-80
HAB

$$GP = 44.05 + \left(\frac{1.50}{5.82}\right)(5) = 44.06.29$$

$$72.25 + \left(\frac{0.70}{4.19}\right)(5) = 72.2584$$

$$SA = 2A \pm$$

$$\text{MAX vel} = 20 \times 1.4 \times 2 = 16 \text{ AF (cilled in)}$$

$$NL = 16 - 4 = 12 \text{ AF (cilled in)}$$

Air photos VT-62-H 47-167

VT 7420 16-155

225-1 Hanks Mine - Washington 6-7-79 ~~APL~~



- looks like gate chamber (wheel pit?)
- partially broken left end (may have been old ^{headwork} ~~gate~~)
- d/s face eroded - cycloped concrete
- sand filled in
- right abut - undermined
- stable



pot. { - 3rdy KA $\frac{1}{2}$ up down = $\frac{1}{2}$ up 1st floor - left side before
 { - 2 " " $\frac{1}{4}$ below long probably old ^{burst}
 { - ^{single} ~~reps~~ entire d/s face for ~~to~~ to $\frac{1}{2}$ way up

shows
no
straps

reps through old tail race



11-12-75

HANDS MILL DAM



" HANDS MILL DAM - WASHINGTON
'BREACH' AT LEFT END OF SPILLWAY.
W/L IS 2.3' BELOW THE CREST
OF THE SPILLWAY.

11-12-75 DON SPIES "

| ROUTING | |
|------------|-----------------|
| GENERAL | |
| AS | 6/27/75 |
| AM | |
| W | |
| JEC | PC |
| SUSPEND TO | |
| FILE | Hand's Mill Dam |

MANAGEMENT & ENGINEERING DIVISION

June 25, 1975

Chairman, Board of Selectmen
Washington
Vermont 05673

Gentlemen:

The Department of Water Resources is pleased to present you with a copy of its recently completed report on Hand's Mill Dam in Washington.

Essentially, the investigation found the dam to be in a further deteriorated condition since our previous visit. Your attention is invited to the recommendations contained within the report.

We are, of course, available to meet with you and welcome any comments you may have.

Sincerely yours,

Andre J. Bouleau
Assistant Director

AJR/jcl

cc: Catherine Rothell, Water Resources Board

Agency of Environmental Conservation
Department of Water Resources
Management & Engineering Division
June, 1975

INSPECTION REPORT

on

HAND'S MILL DAM
Washington, Vermont

| | |
|---------------------------------------|--|
| Owner | Town of Washington |
| Date Built | Prior to 1927 (original construction) 1928 (partial reconstruction) |
| Type of Structure | Earth fill flanking a concrete gravity spillway |
| Watershed Area | 6.45 square miles |
| Probable Spillway Capacity | 1,025 cfs (no freeboard) |
| Peak Flood Inflow Used In Analysis | 715 cfs (100-year frequency) |

TABLE OF CONTENTS

| | <u>Page</u> |
|-------------------------------------|-------------|
| I. INTRODUCTION | 1 |
| II. PURPOSE | 1 |
| III. SCOPE | 2 |
| IV. WATERSHED DESCRIPTION | 2 |
| V. SITE DESCRIPTION | 3 |
| VI. STRUCTURE | 3 |
| A. DESCRIPTION | 3 |
| B. CONDITION | 3 |
| C. SPILLWAY ANALYSIS | 4 |
| 1. HYDRAULIC | 4 |
| 2. HYDROLOGIC | 4 |
| D. CLASSIFICATION | 5 |
| VII. RECOMMENDATIONS | 5 |
| VIII. SELECTED REFERENCES | 6 |
| IX. APPENDICES | 6ff |

HAND'S MILL DAM

I. INTRODUCTION

Vermont has a long history of major floods during which loss of life and considerable property damage has occurred. The failure of dams has added materially to the peak flood flows and related losses. Basically, many of these failures are a result of either inadequate spillways; improper design and/or construction; or improper or insufficient maintenance.

Under Chapter 43, Title 10, Vermont Statutes Annotated, the Water Resources Board has jurisdiction over all dams impounding more than 500,000 cubic feet of water and not incident to the generation of electric energy for public use. The Department of Water Resources assists the Board by conducting a continuing program of inspection and investigation of existing statute-size dams. These investigations serve as a means of obtaining up-to-date information on existing dams, particularly with regards to their maintenance and their safety. As part of this program, an examination was made of the Hand's Mill Dam.

II. PURPOSE

1. To summarize the findings from the Department's investigation of the Hand's Mill Dam in the Town of Washington, Orange County, State of Vermont.
2. To report on the present condition of the structure and on the adequacy of its maintenance.
3. To determine the capacity of the spillway and evaluate its ability to pass reasonable flood flows.

4. To recommend appropriate action to be taken with regards to any flood hazards associated with the existing structure.

5. To recommend necessary repairs and alterations.

III. SCOPE

The scope of this investigation included a topographic survey and visual inspection of the structure on June 19 and 20, 1972. Additional inspections were made on July 17, 1973 and April 23, 1975. Office studies of the spillway capacity and the ability of the structure to pass flood flows were conducted. The summarization of the various findings have been incorporated into this report.

IV. WATERSHED DESCRIPTION

The watershed above Hand's Mill Dam has a drainage area of approximately 6.45 Square miles (see Appendix 1) and can be divided into two sub-basins— one for the Jail Branch and one for a tributary with its confluence at Hand's Mill Pond. The Jail Branch starts in the southeastern corner of the watershed and drops more than 1,050 feet before reaching the pond; this sub-basin is basically oval-shaped with its major axis oriented along an approximate northwest-to-southeast line. The other stream begins in the northeastern corner of the watershed and has a drop of about 1,075 feet before reaching the pond; this sub-basin is roughly rectangular in shape with its major axis along an approximate northeast-to southwest line. Both streams have steep gradients. The watershed terrains are predominantly hilly and about evenly divided between farm land and forest cover. There are no significant bodies of water above the site.

(Continued)

V. SITE DESCRIPTION

Hand's Mill Pond is an artificial impoundment located on the Jail Branch in the southeast corner of the Village of Washington. The pond has a surface area of approximately two acres and is roughly circular in shape. At the present, the pond is almost entirely silted in. The only apparent purpose the pond now serves is as a home to some waterfowl and beavers.

VI. STRUCTURE

A. DESCRIPTION

Hand's Mill Dam consists of a concrete gravity section, which serves as the spillway, and flanking earth embankment sections. Portions of the embankments adjacent to the spillway are backfilled against dry stone walls which form the downstream face.

Little is known about the history of this dam. It is known a mill existed at the site as early as 1866; since the mill ran on water power, it is assumed there was a mill pond and dam. The concrete section was built after 1927, its timber predecessor having been destroyed during the flood of November in that year.

B. CONDITION

The east embankment is overgrown with trees and brush and also appears to have insufficient cross-section. The west embankment has small brush on its downstream face. No seepage was noted along the embankment sections.

The concrete is badly deteriorated. The downstream face is severely spalled, and there is seepage through much of the section. The downstream

(Continued)

abutment wall at the east end of the spillway has collapsed but doesn't appear to have weakened the spillway. At the west end, a section of the abutment has collapsed allowing water to pass around the end of the spillway. This section has gradually increased in size over the years. The owner of the dam has dumped granite grout on the adjacent embankment to reduce the erosion.

The dam is in poor condition, but it does not appear to be in immediate danger of failing.

C. SPILLWAY ANALYSIS

1. Hydraulic

The existing conditions were analyzed by considering the eroded section as a spillway section. The eroded area was treated as a broad-crested spillway, and the spillway was treated as a sharp-crested weir. With the water level approximately up to the low section of the embankment, the combined flow through the spillway area is approximately 1,025 cubic feet per second (cfs).

2. Hydrologic

Flows of the Hand's Mill Dam were determined from the records of an adjoining gaged watershed. A 100-year-return flood at the dam has a peak flow of about 715 cfs. The surcharge storage in the pond is virtually negligible, resulting in little reduction of the peak in-flow; thus, the peak out-flow will be almost identical to the peak in-flow. For the 100-year flood, the peak water level will be less than six inches below the low section of the embankment.

(Continued)

D. CLASSIFICATION

Each dam under the jurisdiction of the Water Resources Board is classed into one of three categories according to the potential amount of downstream damage that particular dam could inflict should it fail. Class I dams are all structures, due to their size and/or location, a failure of which would result in major downstream damage, including the destruction of buildings, major disruption of utilities and/or transportation facilities, or the possible loss of human life. Class II dams are those due to size and/or location whose failure would result in some downstream damage including damages to buildings and possible disruption of utilities and/or transportation facilities, but would probably not result in the loss of life. Dams in Class III are those, due to size and/or location, whose failure would result in only minor damage.

Below Hand's Mill Dam is a house, Town Highway No. 9 , and Bridge No.29 which could possibly suffer some damage from a failure of the dam. The house is likely to be limited to minor damage—such as silt and water damage—to the basement and first floor. The highway could suffer erosional damage, particularly the gravel-surface bridge approaches; a severance of the highway would not isolate anyone, but it would force them to go several miles out of their way. The bridge, which has concrete abutments and a cast-in-place concrete deck on steel beams, will probably not suffer any direct damage, but it could become plugged with debris. Therefore, Hand's Mill Dam is classified as a Class II Dam.

VII. RECOMMENDATIONS

Due to the present condition and the continuing deterioration, it is

(Continued)


recommended that the concrete spillway be removed. The Town through its Selectmen should prepare a program suitable to the Department of Water Resources for removal of the spillway and removal and/or stabilization of the sediment in the pond.

VIII. SELECTED REFERENCES

- 1) "Design Of Small Dams", Bureau of Reclamation, 1973.

IX. APPENDICES

- 1) Watershed Map.
- 2) Location Map.
- 3) Photographs.
- 4) Plans.



APPENDIX 1

HAND'S MILL DAM

WATERSHED BOUNDARY

WILLIAMSTOWN


WASHINGTON COUNTY

WASHINGTON STATE

FOREST

South Washington

Garden Hill



HAND'S MILL DAM



Looking across spillway toward east embankment



Upstream face of west embankment



Downstream face of spillway

The undersigned representatives of the U.S. Army Corps of Engineers,
New England Division visually inspected the _____ Dam on
_____ 1973 between the hours of _____, and _____.
On the basis of visual observations, the following comments are made:

CF:

• (Town Official):
Vt. Water Resources Board
Coordinator, COE
Dam Inspection Team
Mr. E. P. Gould

Location: Town of _____, County of _____, State of Vermont
Stream: _____
Map Coords.: _____
Other: _____

Owner: _____

Function of Dam: _____

JULY 17, 1973



Photos taken during damaged survey inspection
by DWR & COE following 1973 flood.



Hand's Will Dahl

Washington

6-19-72

Warm
Overcast

N Don Spies
N Jim Huntington
O Jim Thompson

6-20-72

Warm
Overcast

N DHS
N JH
O JH

COPY

| Sta. | Rod Reading | Stadia Interval | Distance | Hor. 4 | Vert. 4 |
|-------|----------------|--------------------|----------|-----------|------------|
| | (B.S.) | (H.I.) | | | |
| BM #1 | 1.50 | 101.50 | | | |
| BM #1 | 1.50 | 0.53 | 53 | 39° 24' | - |
| 1 | 3.00 | 0.69 | 69 | 18° 5' | - |
| 2 | 3.18 | 0.61 | 61 | 2° 14' | - |
| 3 | 2.07 | 0.60 | 60 | 353° 48' | - |
| 4 | 4.56 | 0.33 | 33 | 15° 21.5' | - |
| 5 | 4.57 | 0.32 | 32 | 14° 56' | - |
| 6 | 7.72 | 0.39 | 39 | 348° 46' | - |
| 7 | 4.97 | 0.22 | 22 | 348° 46' | - |
| 8 | 5.41 | 0.19 | 19 | 320° 33' | - |
| 9 | 2.50 | 0.22 | 22 | 320° 33' | - |
| 10 | 4.65 | 0.07 | 7 | 320° 33' | - |
| 11 | 4.99 | 0.13 | 13 | 292° 48' | - |
| 12 | 5.17 | 0.27 | 27 | 271° 8' | - |
| 13 | 5.47 | 0.28 | 28 | 283° 43' | - |
| 14 | 7.43 | 0.32 | 32 | 289° 43' | - |
| 15 | 7.68 | 0.35 | 35 | 289° 43' | - |
| 16 | 5.60 | 0.32 | 32 | 281° 0' | - |
| 17 | 7.22 | 0.38 | 38 | 281° 0' | - |
| 18 | 7.71 | 0.42 | 42 | 281° 0' | - |
| 19 | 5.35 | 0.34 | 34 | 273° 10' | - |
| 20 | 7.74 | 0.48 | 48 | 273° 10' | - |
| 21 | 5.54 | 0.43 | 43 | 263° 13' | - |

lev.

0° 0' S 21° 30' E (100)

100.00

X chiseled in bank on top
on east side of road

100.00

98.5

1 edge of road

98.32

2 edge of road

94.13

3 bottom of bank

96.94

4 edge of bank

96.93

5 top of bank

93.78

6 bottom of bank

96.03

7 top of bank

96.03

8 top of bank

94.00

9 edge of bank

96.03

10 E. of dam

96.03

11 E. of dam

94.13

12 S. of dam

96.03

13 top of bank

93.07

14 bottom of bank

93.82

15 edge of water

95.00

16 top of bank

94.28

17 bottom of bank

93.09

18 edge of water

96.15

19 top of bank

93.06

20 edge of water

95.36

21 top of bank

| Sta. | Rod Reading | Stadia Interval | Distance | Horiz. 4 | Vert. 4 |
|------|----------------|--------------------|----------|-------------|------------|
| 22 | 9.06 | 0.52 | 52 | 263°-13' | - |
| 23 | 5.98 | 0.48 | 48 | 261°-0' | - |
| 24 | 6.43 | 0.53 | 53 | 257°-24' | - |
| 25 | 6.04 | 0.47 | 47 | 257°-24' | - |
| 26 | 6.12 | 0.36 | 36 | 259°-36' | - |
| 27 | 5.56 | 0.33 | 33 | 259°-36' | - |
| 28 | 8.26 | 0.33 | 33 | 251°-5' | - |
| 29 | 5.92 | 0.14 | 14 | 252°-0' | - |
| 30 | 5.10 | 0.06 | 6 | 249°-33' | - |
| 31 | 5.53 | 0.06 | 6 | 125°-0' | - |
| 32 | 6.39 | 0.13 | 13 | 126°-53' | - |
| 33 | 7.92 | 0.29 | 29 | 145°-11' | - |
| 34 | 8.05 | 0.31 | 31 | 141°-32' | - |
| 35 | 7.90 | 0.45 | 45 | 116°-59' | - |
| 36 | 5.05 | 0.10 | 10 | 30°-30' | - |
| 37 | 8.23 | 0.12 | 12 | 208°-52' | - |
| 38 | 10.78 | 0.18 | 18 | 176°-8' | - |
| 39 | 12.02 | 0.24 | 24 | 206°-36' | - |
| 40 | 12.47 | 0.29 | 29 | 203°-41' | - |
| 41 | 11.55 | 0.26 | 26 | 187°-0' | - |
| 42 | 9.16 | 0.23 | 23 | 154°-33' | - |
| 43 | 7.53 | 0.13 | 13 | 151°-45' | - |
| 44 | 9.68 | 0.23 | 23 | 245°-47' | - |
| 45 | 10.49 | 0.26 | 26 | 229°-13' | - |
| | | | | | |
| | | | | | |

Elev.

0° 0' = mag 521° 30' E

| | | |
|-------|----|----------------|
| 92.44 | 22 | top of bank |
| 95.55 | 23 | top of bank |
| 95.07 | 24 | top of bank |
| 95.12 | 25 | top of bank |
| 94.63 | 26 | top of bank |
| 94.17 | 27 | top of bank |
| 93.24 | 28 | bank |
| 95.52 | 29 | top of bank |
| 96.10 | 30 | top of bank |
| 95.97 | 31 | top of bank |
| 94.17 | 32 | top of bank |
| 95.28 | 33 | top of bank |
| 93.45 | 34 | edge of road |
| 93.65 | 35 | edge of road |
| 96.45 | 36 | edge of dam |
| 93.20 | 37 | bank |
| 90.22 | 38 | bottom of bank |
| 89.15 | 39 | bottom of bank |
| 89.03 | 40 | bank |
| 89.95 | 41 | bank |
| 92.34 | 42 | bank |
| 93.97 | 43 | bank |
| 91.80 | 44 | bank |
| 91.52 | 45 | bank |

| Sta. | Rod Reading | Stadia Interval | Distance | Horiz. \angle | Vert. \angle |
|--------------|------------------|-----------------|----------|---------------------|--------------------|
| | (B.S.) | (H.I.) | | | |
| BM #1 | 1.09 | 10.109 | | | |
| BM #1 | 1.09 | 0.88 | 88 | 58°-3' | - |
| 1 | 4.61 | 0.40 | 40 | 81°-42' | - |
| 2 | 9.43 | 0.07 | 7 | 192°-38' | - |
| 3 | 7.55 | 0.12 | 12 | 135°-3' | - |
| 4 | 8.64 | 0.15 | 15 | 162°-15' | - |
| 5 | 9.70 | 0.29 | 29 | 207°-23' | - |
| 6 | 6.38 | 0.42 | 42 | 200°-48' | - |
| 7 | 14.00 | 0.19 | | 162°-21' | 12°-45' |
| 8 | 12.63 | 0.33 | 32 | 202°-29' | -8°-17' |
| 9 | 14.51 | 0.19 | 19 | 164°-34' | 2°-39' |
| 10 | 8.39 | 0.17 | 17 | 246°-36' | - |
| 11 | 8.95 | 0.14 | 14 | 228°-35' | - |
| 12 | 8.88 | 0.27 | 27 | 234°-26' | - |
| 13 | 8.68 | 0.22 | 22 | 251°-8' | - |
| 14 | 11.44 | 0.24 | 24 | 250°-47' | - |
| 15 | 7.13 | 0.26 | 26 | 276°-15' | - |
| 16 | 8.73 | 0.22 | 22 | 272°-0' | - |
| 17 | 10.93 | 0.25 | 25 | 269°-25' | - |
| 18 | 6.99 | 0.51 | 51 | 278°-0' | - |
| 19 | 6.99 | 0.88 | 88 | 278°-44' | - |
| 20 | 6.98 | 0.90 | 90 | 280°-14' | - |
| 21 | 4.84 | 0.92 | 92 | 280°-17' | - |

100.00

0° - 0' = mag 5 21° - 30'E

100.00

100.00

91.66

93.59

92.45

91.31

91.21

83.75

85.70

88.14

92.14

92.21

92.1

91.66

93.96

92.36

90.12

91.20

91.20

91.20

91.20

91.20

91.20

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

1st Set Top

bottom of bank

Top of concrete wall

top stone wall

bottom of bank

bottom of bank

bottom of bank

bottom of bank

bottom of bank

bottom of bank

bottom of bank

end of bank

end of bank

top concrete, downstream, outside edge

top concrete, downstream, outside edge

top concrete, downstream, outside edge

top concrete, downstream, outside edge

top concrete, downstream, outside edge

top concrete, downstream, outside edge

top concrete, downstream, outside edge

top concrete, downstream, outside edge

top concrete, downstream, outside edge

Note: width top of spillway = 235'

| Sta. | Kod Reading | Stadia Interval | Distance | Horiz. \angle | Vert. \angle |
|-------|-------------|------------------------|--------------------|-----------------|----------------|
| 22 | 14.00 | 0.88 | 87 | 272° 4' | 4° 57' |
| 23 | 14.00 | 0.76 | 75 | 274° 31' | 5° 28' |
| 24 | 14.03 | 0.50 | 49 | 274° 0' | 9° 28' |
| 25 | 14.50 | 0.26 | 24 | 269° 10' | 16° 41' |
| | (B.S.) | (H.I.) | | | |
| BM #1 | 2.41 | 102.41 | | | |
| BM #1 | 2.41 | 1.87 | 187 | 82° 46' | - |
| 1 | 5.92 | 1.54 | 154 | 96° 32' | - |
| 2 | 6.25 | 0.19 | 19 | 113° 58' | - |
| 3 | 5.41 | 0.16 | 16 | 113° 58' | - |
| 4 | 7.85 | 0.16 | 16 | 99° 22' | - |
| 5 | 8.52 | 0.17 | 17 | 89° 40' | - |
| 6 | 7.18 | 0.15 | 15 | 137° 36' | - |
| 7 | 10.66 | 0.34 ^(0.24) | 34 ⁽²⁴⁾ | 150° 9' | - |
| 8 | 13.38 | 0.26 | 26 | 156° 6' | - |
| 9 | 9.19 | 0.08 | 8 | 30° 36' | - |
| 10 | 6.13 | 0.09 | 9 | 193° 6' | - |
| 11 | 8.42 | 0.15 | 15 | 196° 47' | - |
| 12 | 14.40 | 0.16 | 16 | 196° 47' | - |
| 13 | 4.68 | 0.07 | 7 | 281° 40' | - |
| 14 | 9.38 | 0.25 | 25 | 308° 43' | - |
| 15 | 4.90 | 0.23 | 23 | 289° 17' | - |
| 16 | 5.92 | 0.25 | 25 | 274° 5' | - |

0° 0' = mag 5 21° 30' E

80.84

22

spillway wall

79.52

23

bottom spillway wall

78.95

24

bottom spillway wall

77.74

25

bottom spillway wall

140.00

140.00

96.49

1

1st spillway point

96.16

2

top abutment

11.41

3

& dam

11.16

4

bottom at bank

93.83

5

edge of water

93.43

6

bank

91.15

7

top stone wall

89.03

8

bottom stone wall, road

93.22

9

edge of water

94.25

10

bank

93.43

11

top stone wall

93.03

12

bottom stone wall

92.73

13

A of stone

93.03

14

edge of water

94.51

15

& of dam

96.49

16

bank

| Sta. | Rod Reading | Stadia Interval | Distance | Horiz. \angle | Vert. \angle |
|---------|-------------|-----------------|----------|-----------------|----------------|
| 17 | 14.81 | 0.29 | 29 | 166° 0' | - |
| 18 | 14.58 | 0.22 | 22 | 201° 0' | - |
| 6-20-72 | | | | | |
| | (B.S.) | (H.I.) | | | |
| BM #1 | 2.49 | 102.49 | | | |
| BM #1 | 2.49 | 1.88 | 188 | 61° 18' | - |
| 1 | 6.92 | 1.09 | 109 | 103° 49' | - |
| 2 | 8.23 | 1.01 | 101 | 98° 9' | - |
| BM #2 | 6.32 | 0.19 | 19 | 89° 51' | - |
| | (B.S.) | (H.I.) | | | |
| BM #2 | 7.23 | 103.40 | | | |
| BM #2 | 7.23 | 0.44 | 44 | 89° 36' | - |
| 1 | 5.19 | 0.24 | 24 | 90° 54' | - |
| 2 | 7.55 | 0.11 | 11 | 161° 31' | - |
| 3 | 12.79 | 0.11 | 11 | 167° 31' | - |
| 4 | 8.66 | 0.28 | 28 | 286° 22' | - |
| 5 | 4.60 | 0.27 | 27 | 272° 26' | - |
| 6 | 7.40 | 0.28 | 28 | 254° 56' | - |
| 7 | 11.65 | 0.29 | 29 | 239° 37' | - |
| 8 | 13.23 | 0.33 | 33 | 229° 24' | - |

Elev.

0° 0' = mag S 21° 30' E

87.13

17 in field

87.88

18 in field

0° 0' E mag S

100.00

100.00

95.57

1 bottom station

94.26

2 bottom station

96.17

top station at intersection of each fi

96.17

96.17

98.21

1 3rd station point

95.95

2 top station wall

90.61

3 bottom station wall

94.74

4 edge of water

98.80

5 E of dam

96.00

6 bank

91.25

1 bottom of bank

90.14

8 in field

| Sta. | Rod Reading | Stadia Interval | Distance | Angle | Bearing |
|------|-------------|-----------------|----------|----------|---------|
| 9 | 14.52 | 0.24 | 24 | 168°-14' | - |
| 10 | 7.35 | 0.17 | 17 | 245°-12' | - |
| 11 | 9.98 | 0.17 | 17 | 243°-18' | - |

| | | | | | |
|-------|--------|--------|--|--|--|
| | (B.S.) | (H.I.) | | | |
| BM #2 | 6.59 | | | | |

| | | | | | |
|-------|------|------|--|---------|---|
| BM #2 | 6.59 | 1.18 | | 93°-22' | - |
|-------|------|------|--|---------|---|

| | | | | | |
|-------|--------|--------|--|--|--|
| | (B.S.) | (H.I.) | | | |
| BM #2 | 6.27 | 102.44 | | | |

| | | | | | |
|-------|------|------|-----|---------|---|
| BM #2 | 6.27 | 1.18 | 118 | 93°-25' | - |
|-------|------|------|-----|---------|---|

| | | | | | |
|---|------|------|----|---------|---|
| 1 | 4.96 | 0.74 | 74 | 95°-23' | - |
|---|------|------|----|---------|---|

| | | | | | |
|---|------|------|----|---------|---|
| 2 | 9.44 | 0.31 | 31 | 86°-13' | - |
|---|------|------|----|---------|---|

| | | | | | |
|---|------|------|----|----------|---|
| 3 | 4.92 | 0.29 | 29 | 100°-29' | - |
|---|------|------|----|----------|---|

| | | | | | |
|---|------|------|----|----------|---|
| 4 | 8.21 | 0.28 | 28 | 113°-53' | - |
|---|------|------|----|----------|---|

| | | | | | |
|---|-------|------|----|----------|---|
| 5 | 11.91 | 0.30 | 30 | 127°-49' | - |
|---|-------|------|----|----------|---|

| | | | | | |
|---|-------|------|----|----------|---|
| 6 | 12.79 | 0.32 | 32 | 135°-20' | - |
|---|-------|------|----|----------|---|

| | | | | | |
|---|------|------|----|---------|---|
| 7 | 8.69 | 0.10 | 10 | 37°-29' | - |
|---|------|------|----|---------|---|

| | | | | | |
|---|------|------|---|---------|---|
| 8 | 8.26 | 0.08 | 8 | 46°-28' | - |
|---|------|------|---|---------|---|

| | | | | | |
|---|------|------|---|----------|---|
| 9 | 4.83 | 0.08 | 8 | 100°-58' | - |
|---|------|------|---|----------|---|

| | | | | | |
|----|------|------|---|----------|---|
| 10 | 7.50 | 0.07 | 7 | 155°-29' | - |
|----|------|------|---|----------|---|

| | | | | | |
|----|-------|------|----|---------|---|
| 11 | 10.95 | 0.11 | 11 | 166°-7' | - |
|----|-------|------|----|---------|---|

| | | | | | |
|----|-------|------|----|----------|---|
| 12 | 11.69 | 0.17 | 17 | 170°-14' | - |
|----|-------|------|----|----------|---|

Elev.

0° 0' - mag. S

88.88

in field

96.15

10 end of wall top

93.12

end of wall bottom

96.17

96.17

92.48

1 4th setup point

95.00

2 edge of wall

97.52

3 4 of dam

94.75

4 bank

90.53

5 bottom of bank

97.5

6 in field

93.75

7 edge of 4th

94.13

8 bottom of bank

91.61

9 E of dam

94.24

10 bank

91.49

11 bottom of bank

90.75

12 in field

[illegible]

lev

o' o' mag S

93.76

13 edge of water

94.04

14 bottom of bank

95.31

15 E of dam

96.31

16 bank

93.00

17 bottom of bank

92.79

18 in field

93.71

19 edge of water

95.06

20 bottom of bank

98.32

21 E of dam

96.08

22 bank

94.57

23 bottom of bank

98.08

24 E of dam

95.06

25 E of dam

93.71

26 in field

96.95

27 in field

94.22

28 in mud flat

99.98

RECORDED

Washington

1/2

$$Q = PLH^{3/2} \quad C = 3.50$$

$$= 3.50(64)(2.0)^{3/2} \quad L = 64'$$

$$= 224(2.83) \quad H = 2.0'$$

$$= 634 \text{ cfs.}$$

revised

546.75

DHS

Drainage Area

1st

2nd

3rd

4th

Average

47.22

53.87

60.41

67.04

6.75

40.47

47.22

53.87

60.41

6.65

6.75

6.65

6.54

6.63

6.54

6.63

4 | 26.57

6.64 sq. in.

1 sq. in. = 0.973 sq. mi.

$$D.A. = 6.64(0.973) = 6.45 \text{ sq. mi.}$$

(BARRE)

Mount Pleasant



Hydrology

Flows at Hand's Mill Dam will be determined from the adjacent East Orange Brook Watershed. The fifty-year and one hundred year peak flows were calculated for East Orange and transposed to Hand's Mill using the following formula:

$$Q_{\text{at site}} = Q_{\text{at gage}} \left(\frac{\text{Drainage Area at Site}}{\text{Drainage Area at Gage}} \right)$$

| | Q_{50} | Q_{100} |
|-----------------|----------|-----------|
| E. Orange Brook | 790 | 914 |
| Hand's Mill Dam | 618 | 715 |

Hydraulic

The eroded section will be treated as a broad crested weir with a bottom width of eight feet, crest elevation two lower than the spillway and one end contraction. The spillway will be considered as a sharp crested weir with a crest length of 68' and one end contraction.

flow through eroded area:

$$Q_1 = 2.85 L_1 \left(H_1 + \frac{V_{a1}^2}{2g} \right)^{3/2}$$

$$\text{where } L_1 = 8 - 0.1 \left(H_1 + \frac{V_{a1}^2}{2g} \right)$$

flow over spillway

$$Q_2 = 3.30 L_2 \left(H_2 + \frac{V_{a2}^2}{2g} \right)^{3/2}$$

$$\text{where } L_2 = 68 - 0.1 \left(H_2 + \frac{V_{a2}^2}{2g} \right)$$

$$\text{and } H_2 = H_1 - 2.0$$

Table of Stage versus Discharge

| | H_1 | Q_1 | Q_2 | Total |
|--|-------|-------|-------|-------|
| | 0 | 0 | 0 | 0 |
| | 1 | 30 | 0 | 30 |
| | 2 | 84 | 0 | 84 |
| | 3 | 148 | 259 | 407 |
| | 4 | 221 | 804 | 1025 |

Assuming a straight line relation for discharge between $H_1 = 3'$ and $H_1 = 4'$ then the stage for the 50-year flow is:

$$H_1 = 3 + \frac{618 - 407}{1025 - 407} = 3 + \frac{211}{618} = 3.34' \text{ and}$$

for the 100-year flow is:

$$H_1 = 3 + \frac{715 - 407}{618} = 3 + \frac{308}{618} = 3.50'$$

4-23-75

Long's Mill Dam

Lower bridge covered ^{by} ~~by~~ concrete. Deck on
steel beams ~~girders~~

16' wide x 8.5' high.

clayey material placed on lower
end dam. $4\frac{1}{2}$ ~ 1' below top spillway
water going around south end.

Face of spillway badly deteriorated.
still level practically at top spillway.

Setup # 2

Sta. 8

$$H.I. = 101.09 \quad \alpha = 8^{\circ} 17'$$

$$R = 0.33$$

$$\text{Rod Reading} = 12.63$$

From Table II, Elementary Surveying

$$h = 97.92 ; v = 14.26$$

$$H = 97.92 (0.33) = 32'$$

$$V = 14.26 (0.33) = 4.71'$$

$$\text{Elev.} = 101.09 - 12.63 - 4.71$$

$$= 101.09 - 17.34$$

$$= 83.75$$

Sta. 9

$$H.I. = 101.09 \quad \alpha = 2^{\circ} 39'$$

$$R = 0.19$$

$$\text{Rod Reading} = 14.51$$

From Table II, Elementary Surveying

$$h = 99.78 ; v = 4.62$$

$$H = 99.78 (0.19) = 19'$$

$$V = 4.62 (0.19) = 0.88$$

$$\text{Elev.} = 101.09 - 14.51 - 0.88$$

$$= 101.09 - 15.39$$

$$= 85.70$$

Sta. 22

$$H.I. = 101.09 \quad \angle = 4^{\circ} 57'$$

$$R = 0.88 \quad \text{Rod Reading} = 14.00$$

From Table II, Elementary Surveying

$$h = 99.25 ; v = 8.60$$

$$H = 99.25(0.88) = 87'$$

$$V = 8.60(0.88) = 7.57'$$

$$\begin{aligned} \text{Elev.} &= 101.09 - 14.00 - 7.57 \\ &= 101.09 - 21.57 \\ &= 79.52 \end{aligned}$$

Sta. 23

$$H.I. = 101.09 \quad \angle = 5^{\circ} 28'$$

$$R = 0.76 \quad \text{Rod Reading} = 14.00$$

From Table II, Elementary Surveying

$$h = 99.09 ; v = 9.48$$

$$H = 99.09(0.76) = 75'$$

$$V = 9.48(0.76) = 7.20'$$

$$\begin{aligned} \text{Elev.} &= 101.09 - 14.00 - 7.20 \\ &= 101.09 - 21.20 \\ &= 80.89 \end{aligned}$$

Sta. 24

$$H.I. = 101.09 \quad \angle = 9^{\circ} 28'$$

$$R = 0.50 \quad \text{Rod Reading} = 14.03$$

From Table II, Elementary Surveying

$$h = 97.29; \quad v = 16.22$$

$$H = 97.29(0.50) = 49'$$

$$V = 16.22(0.50) = 8.11'$$

$$\begin{aligned} \text{Elev.} &= 101.09 - 14.03 - 8.11 \\ &= 101.09 - 22.14 \\ &= 78.95 \end{aligned}$$

Sta. 25

$$H.I. = 101.09 \quad \angle = 16^{\circ} 41'$$

$$R = 0.26 \quad \text{Rod Reading} = 14.50$$

From Table II, Elementary Surveying

$$h = 91.75; \quad v = 27.50$$

$$H = 91.75(0.26) = 24'$$

$$V = 27.50(0.26) = 7.15'$$

$$\begin{aligned} \text{Elev.} &= 101.09 - 14.50 - 7.15 \\ &= 101.09 - 21.65 \\ &= 79.44 \end{aligned}$$

9-21-72
GUS. BARRE-MONT

Water Resources Approves Of Washington Pond

WASHINGTON — The Department of Water Resources has found the water quality of the Hand's Mill Pond to be well within the limit suitable for recreation purposes. The pond has been considered by the Washington Planning Commission as a possible recreation site for the town.

John Malter, an official of Water Resources Department, told members about the survey findings in their meeting at the Town Clerk's Office Wednesday night. He and Donald Spies, also from the department, discussed the site with members.

Spies, who took a survey of the dam, consisting of a concrete spillway and land banks said another spring like the last could cause a slight rupture of the dam. Although he said the danger is not great in the event of the rupture, the cellar of an adjacent home could be flooded. He said trees and shrub on the banks also serve to weaken the structure because they attract and hold water. A report on the structure will be available in the winter and Spies said there is nothing binding about the findings.

Members and officials discussed possible methods of eliminating the hazard which included the possibility of lowering the dam and reducing the pond level.

George Plumb offered to evaluate the pond as a recreation site and he will inspect the site with Paul Vermette, selectman.

Members also approved the extension of a power line requested by the Washington Electric Cooperative of East Montpelier. The extension received earlier approval from town selectmen and the Central Vermont Regional Planning Commission. The line will run adjacent to the road.

MEMORANDUM

TO: Fred Kent, Chief, Water Resources Laboratory
 FROM: John Malter
 RE:
 DATE: August 14, 1972

| ROUTING | | |
|------------|----------------|------|
| GENERAL | | |
| TO | NOTED | DATE |
| JAM | | |
| RJW | | |
| JEC | | |
| SUSPEND TO | | |
| FILE | Hands Mill Dam | |

The Town of Washington is currently assessing potential water-based recreation sites. The impoundment behind the Hands Mill Dam in Washington is of major interest. I would like three water samples from this site analyzed for total and fecal coliform. This should give us a handle as to whether the water quality at this site is suitable for a water-based recreation area in this town. George Plumb from the Division of Recreation is obtaining the samples.

Thank you for your assistance.

| ROUTING | | |
|------------|-------------------------------------|---------|
| GENERAL | | |
| TO | NOTED | DATE |
| JEC | <i>[Signature]</i> | |
| DHS | <i>[Signature]</i> | 5-17-72 |
| SUSPEND TO | | |
| FILE | <input checked="" type="checkbox"/> | |

May 17, 1972

Board of Selectmen
Town of Washington
Washington, Vermont 05675

Dear Sir:

The Vermont Water Resources Board is charged with the authority to investigate certain dams under the jurisdiction of the Board. The investigations are primarily to assure the public that the dams are in a safe state of upkeep and repair, and are also adequate to pass the flows of water which may reasonably be expected. This does not in any way relieve the owners of the structure from their usual responsibility, however.

In order to obtain factual data regarding the structure, the Department of Water Resources will be making an investigation which will include an inspection of the structure (dam), an analysis of the capacity and adequacy of the spillway, and other related data, to be submitted in a report form.

Several investigations will be conducted between June 1, 1972 and September 1, 1972. Hand's Mill Dam has been selected for such an investigation. The report and conclusions of the investigations will be available to the owners and other interested parties at the office of the Department of Water Resources. If you have any questions regarding the procedure or information, please feel free to contact this office. Your cooperation with our agents will be greatly appreciated.

Sincerely yours,

John E. Cerutti, Director
Management & Engineering Division

JEC/DHS/kmp

OFFICE MEMORANDUM

| ROUTING | | |
|-----------------------|-------|------|
| GENERAL | | |
| TO | NOTED | DATE |
| DEC | | |
| DHS | DHS | |
| SUSPEND TO | | |
| FILE <i>Green Dam</i> | | |

TO: File

FROM: Donald H. Spies

SUBJECT: Meeting of Board of Selectmen, Washington, Vermont

DATE: May 21, 1971

and Hand's Mill Dam ✓

On May 19, 1970, this writer attended the subject meeting in order to keep informed of the situation regarding the town road at the Green Dam site and also, to inform the Selectmen of the situation at the Hand's Mill Dam. Mr. Raymond Green and a neighbor, Mr. Harold Heinzelman, were present and gave testimony on their own behalf in favor of having the road removed from the town lists and changing it to a trail. The Selectmen were in favor of abandoning the road, however, they were hesitant to do so because they were not sure of the legalities involved. The end result, so far as the Department is concerned, is that the Town will attempt to have the road removed from their list, and if this is not possible, Mr. Green will have the road relocated around his impoundment. The Selectmen are to send a letter to this writer stating their views and the final decision reached at the meeting.

After the above discussion, this writer informed the Selectmen of the erosion of the west abutment of Hand's Mill Dam. It was pointed out to the Selectmen that immediate action was not absolutely essential, but that they should consider some sort of remedial action. They stated that the matter would be taken into consideration.

APRIL 12, 1953

Inspection by John E. Cerutti
Dept. of Water Resources

Washington Dam

April 2 1953

je

- North wing wall has fallen down and water has started to erode the earth embankment behind it.

Earth embankment is 3' above spillway section and appears quite stable

- Section of dam south of spillway appears to be in worse condition. Water is leaking thru the south abut. of spillway. Old retaining wall is badly broken up & water going thru it. Water is leaking thru part of dam that forms foundation of mill.

There is about a 30' section of dam to south of the mill. This section has been crumpled and the downstream slope is eroded. Top of this section is about 2' above spillway.

Although there may be a slight apron at the bottom of the spillway the water appears to be quite deep and it is believed some erosion is taking place & may be working back under the spillway apron.

je

WINSTON L. PROUTY, CHAIRMAN
WALTER B. RENFREW
FRANCIS LEACH

1.
PHILIP SHUTLER, COMMISSIONER



STATE OF VERMONT
WATER CONSERVATION BOARD

MONTPELIER, VERMONT

REPORT ON HAND'S MILL DAM
IN WASHINGTON, VERMONT

A report is made herein on the weakened condition of a dam in the town of Washington, Vermont.

GENERAL

This dam is located on Jail Branch on the upstream edge of the Village of Washington. It is presently owned by Mr. Clarence H. Hand who acquired the property in 1947. The mechanical power feature of this development has been abandoned, its principle purpose now is for the storage of logs for the saw mill at the site.

For this dam the pondage is small being about 2 acres in surface area and a little over 500,000 cubic feet in volume. The drainage area is 6 square miles.

Layout of the dam

The dam, about 260 feet long, is made up of an earth embankment section flanking a heavy concrete spillway section. This spillway section is between 60 and 70 feet long and reaches a maximum depth of 22 feet above channel bottom.

In cross section, it indicates a flat crest 2 feet wide and 2 feet below the top of the dam, with both faces sloping outward about 3 on 1 on the downstream side and 1 on 1 on the upstream side. Rubble concrete end-walls retain the embankment. Also a short concrete apron 5 to 6 feet wide, is provided at the downstream toe. No flashboards are used on the crest.

Extending northward from the spillway is an earth embankment about 180 feet long and about 10 feet high at maximum section. It has an average top width of 8 feet and side slopes at a natural angle of repose. A short length of this embankment is retained on the downstream side by a stone wall.

To the south of the spillway is a short embankment section which also serves as part of the foundation for the saw mill. It is topped by a masonry wall, partly extended into the embankment. An abandoned intake and a sluiceway exist at this end of the spillway.

Observations and comments

From an examination of the dam, made on May 23, 1950, the writer noted the physical condition of the dam as follows:

The dam is an old structure (probably over 45 years) in a somewhat abandoned stage. Originally, it has a timber spillway section, but this was destroyed in the November 1927 flood, and afterwards replaced by the present massive concrete section. This "newer" section is in the best condition. As indicated in Figure 1, it has a minor degree of surface scaling. Some scour of the soft foundation material underneath the apron has occurred, particularly along the north half, but its progress has not reached a stage where stability of the section might be seriously concerned.

The older, original masonry end sections, are badly broken up. In such a condition is the south abutment wall shown in Figure 2. This is the top portion which has partly failed and leaks considerably. The lower portion of the section is still in a sound condition.

Figure 3 shows the condition of the north abutment wall which also serves to

retain the embankment. The poor quality concrete has been eroded away in time so that stability of the wall is in question. Not only has the base of this wall been decomposed but also some of the material behind it has been washed out. A deep hole, about 6 feet in diameter and 10 feet deep now exists. Here is a likely point of failure, much so if aggravated by high water.

The embankment section, in general, has settled and stabilized itself. It is uneven and overgrown with brush. Beavers have burrowed into the section and have caused small local cave-ins. Some seepage was detected. The nature of the material making up the embankment is not known.

A check on the probable maximum flow (in ~~proportion~~ ^{proportion} to the November 1927 flood) indicates that a peak flow of 3600 c.f.s. is possible. Because of a limited discharge capacity, the dam would be overtopped with this size of flood. With this type of dam, overtopping would mean failure.

CONCLUSIONS

From a routine investigation the writer comes up with this dam which, in his opinion, is in a weakened condition. The ~~impending~~ ^{impending} failure of the dam would cause flooding in the vicinity. However, the extent of flood damage is limited because of the relatively small storage volume involved.

The dam needs immediate repairs to restore its stability. Consideration should also be given to improving the discharge capacity.

Stephen H. Haybrook
 Stephen H. Haybrook
 Hydraulic Engineer

July 6, 1950
 Report # 141



Figure 1.-Spillway face and apron of the dam. The north embankment section continues in the background.



Figure 2.-Disintegrated condition of the south abutment wall.



Figure 3.-A closeup of the north abutment wall. Note the scour through and under the section.


Attachment 4: Final 30% Designs

HANDS MILL DAM REMOVAL AT JAIL BRANCH TOWN OF WASHINGTON, VERMONT

PREPARED FOR:
WINOOSKI NATURAL RESOURCES
CONSERVATION DISTRICT

PREPARED BY:
STONE ENVIRONMENTAL, INC.

30% DESIGN
ISSUED: JANUARY, 2021



Project Vicinity
Scale: 1" = 4000'



Project Location
Scale: 1" = 400'

| DRAWING INDEX: | |
|----------------|---|
| SHEET | TITLE |
| 1 | COVER SHEET |
| 2 | SURVEY EXTENTS PLAN & LIMITS OF DISTURBANCE |
| 3 | EXISTING CONDITIONS PLAN |
| 4 | SITE ACCESS & MATERIAL REMOVAL PLAN |
| 5 | EXISTING DAM & DEMOLITION PLAN |
| 6 | CHANNEL RESTORATION PLAN |
| 7 | CHANNEL RESTORATION PROFILE & DETAILS |

30% DESIGN PLANS, NOT FOR
PERMITTING OR CONSTRUCTION

FILE:

| | | | | | | |
|---------------------|---|------|------|-------|-------|-------------|
| DRAWING CREDITS | # | DATE | DRWN | CHK'D | APP'D | DESCRIPTION |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| DRAWN ON: 11/2/2020 | | | | | | |
| DRAWN BY: GMB | | | | | | |
| CHECKED ON: | | | | | | |
| CHECKED BY: | | | | | | |
| PROJECT NO: 20-007 | | | | | | |




STONE ENVIRONMENTAL

535 Stone Cutters Way / Montpelier / VT / 05602 / USA
802.229.4541 / info@stone-env.com / www.stone-env.com

HANDS MILL DAM REMOVAL
AT JAIL BRANCH
COVER SHEET
WASHINGTON VERMONT

FIGURE NO.

1



Limits of Disturbance
Point Table


| Point | Latitude | Longitude |
|-------|-----------|------------|
| 1 | 44.105868 | -72.430835 |
| 2 | 44.106068 | -72.428349 |
| 3 | 44.105635 | -72.426226 |
| 4 | 44.104637 | -72.426656 |
| 5 | 44.103929 | -72.427335 |
| 6 | 44.104311 | -72.428325 |
| 7 | 44.104845 | -72.429264 |

Legend

- Major Contour
- Minor Contour
- Parcel Boundaries
- Edge of Road
- Proposed Limits of Disturbance
- Proposed Limits of Disturbance Point


30% DESIGN PLANS, NOT FOR
PERMITTING OR CONSTRUCTION

| # | DATE | DRWN | CHK'D | APP'D | DESCRIPTION |
|---|----------|------|-------|-------|--------------------|
| 1 | 9/4/2020 | BAM | GMB | | DRAWN ON: 9/4/2020 |
| 2 | | | | | DRAWN BY: BAM/GMB |
| 3 | | | | | CHECKED ON: |
| 4 | | | | | CHECKED BY: |
| 5 | | | | | PROJECT NO: 20-007 |



STONE ENVIRONMENTAL
535 Stone Cutters Way / Montpelier / VT / 05602 / USA
802.229.4541 / info@stone-env.com / www.stone-env.com

HANDS MILL DAM REMOVAL
AT JAIL BRANCH
SURVEY EXTENTS PLAN AND LIMITS OF DISTURBANCE
WASHINGTON VERMONT


















| Point Table | | | |
|-------------|------------------|--------------|---------------|
| Point | Description | Northing | Easting |
| 1 | Nail in Pole | 585021.9815' | 1658864.2012' |
| 2 | Nail in Pavement | 585119.0352' | 1658774.6143' |
| 3 | Mark in Headwall | 585312.4075' | 1658681.0191' |
| 4 | Nail in Pole | 585325.0713' | 1658817.8600' |

- Legend**
- Survey Control Point
 - Major Contour
 - Minor Contour
 - Parcel Boundaries
 - Edge of Road
 - Guard Rail
 - Overhead Utility
 - Vegetation Line
 - Tree
 - River Top of Bank (OHV)
 - Existing Wetland (See Note 6)
 - Thalweg Spot Elevations
 - Utility Pole
 - Manhole
 - Sanitary Manhole or Septic Cover
 - Well
 - Vent
 - Hydrant
 - Water Valve
 - Stormwater Pipe
 - Stormwater Swale
 - Sediment Probing Location
 - Sediment Sampling Location
 - Floodplain Boring Location
 - Archaeological Sensitive Areas
 - Proposed Limits of Disturbance

- Survey Notes:**
- The horizontal datum refers to Vermont State Plane Grid NAD83. The vertical datum is arbitrary. Contour interval = 1 foot.
 - Contours were created using two sources of data: 1) a topographic survey of the channel bed, banks, floodplains and structural features collected by Stone Environmental (see Note 3 below), and 2) LIDAR data of upland features, obtained from the Vermont Center for Geographic Information.
 - Site survey was performed on August 11 and 12, 2020 by Gabe Bolin, PE, of Stone Environmental, Inc. using a Stonex S900 GPS base and rover.
 - Survey data provided in these plans do not represent a boundary survey.
 - Utility locations shown on this plan should be considered approximate. Contractor is required to verify utility locations prior to work.
 - Wetland boundaries shown on this plan were delineated by Karina Dailey of the Vermont Natural Resources Council (VNRC) on October 8, 2020. The wetland delineation was performed in accordance with the U.S. Army Corps of Engineers Wetland Delineation Manual, Technical Report Y-87-1, January 1987, Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northcentral and Northeast Region (Version 2.0), January 2012, and Section 3.2 of the Vermont Wetland Rules.
 - Archaeological sensitive areas identified by the University of Vermont Consulting Archaeology Program, October, 2020.

30% DESIGN PLANS, NOT FOR PERMITTING OR CONSTRUCTION




- ## **Legend**
- | | |
|--|----------------------------------|
|  | Survey Control Point |
| — 1280 — | Major Contour |
| — 1275 — | Minor Contour |
| ===== | Parcel Boundaries |
| ————— | Edge of Road |
| ————— ————— | Guard Rail |
| — OHW — | Overhead Utility |
| ~~~~~ | Vegetation Line |
|  | Tree |
| ~~~~~ <small>OHW is a minimum of 2' from edge of road</small> | River Top of Bank (OHW) |
|  | Existing Wetland |
|  | Thalweg Spot Elevations |
| ① | Utility Pole |
| ● | Manhole |
| ● | Sanitary Manhole or Septic Cover |
| ● | Well |
|  | Vent |
| ⚓ | Hydrant |
|  | Water Valve |
|  | Stormwater Pipe |
|  | Stormwater Swale |
|  | Sediment Probing Location |
|  | Sediment Sampling Location |
|  | Floodplain Boring Location |
|  | Archaeological Sensitive Areas |
| ■■■■■■■■■■ | Proposed Limits of Disturbance |
|  | Proposed Site Access Route |
|  | Proposed Timber Mats |

Site Access & Material Removal Notes:

1. *Utility locations shown on this plan should be considered approximate. Contractor is required to verify utility locations prior to work.*
2. *The suggested site access shown on this sheet is an example and for the purposes of project bidding.*
3. *The Contractor shall submit an Access and Material Removal Plan for approval by the Engineer prior to mobilization. The plan can follow the suggested route, or vary based on revised project sequencing. Overall, the Plan will be the Contractor's plan that meets all permit requirements and is subject to approval by the Engineer. See specifications.*

30% DESIGN PLANS, NOT FOR PERMITTING OR CONSTRUCTION

| | | | | | | | | |
|-----------------|--------------------|-----------|---|------|------|-------|-------|-------------|
| DRAWING CREDITS | DRAWN ON: 9/4/2020 | REVISIONS | # | DATE | DRWN | CHK'D | APP'D | DESCRIPTION |
| | DRAWN BY: GMB | | | | | | | |
| | CHECKED ON: | | | | | | | |
| | CHECKED BY: | | | | | | | |
| | PROJECT NO: 20-007 | | | | | | | |




STONE ENVIRONMENTAL

535 Stone Cutters Way / Montpelier / VT / 05602 / USA
 802.229.4541 / info@stone-env.com / www.stone-env.com

HANDS MILL DAM REMOVAL
AT JAIL BRANCH
SITE ACCESS & MATERIAL REMOVAL PLAN

WASHINGTON VERMONT

:37E-



- Legend**
- Survey Control Point
 - Major Contour
 - Minor Contour
 - Parcel Boundaries
 - Edge of Road
 - Guard Rail
 - Overhead Utility
 - Vegetation Line
 - Tree (Brown Color Indicates to be Removed)
 - River Top of Bank (OHW)
 - Existing Wetland (See Note 6)
 - Thalweg Spot Elevations
 - Utility Pole
 - Manhole
 - Sanitary Manhole or Septic Cover
 - Well
 - Vent
 - Hydrant
 - Water Valve
 - Stormwater Pipe
 - Stormwater Swale
 - Archaeological Sensitive Areas
 - Proposed Limits of Disturbance
 - Extents of Ground Disturbance
 - Proposed Contours
 - Dam Removal Line

- Channel Restoration Plan Notes:**
- Contractor to clear and grub as necessary to provide access, remove dam and construct bank stabilizations (Item 201.10).
 - Contractor to install topsoil and seed along disturbed floodplains and other areas of disturbance per the direction of the Engineer.
 - See the 'Typical Channel Cross Section' on Sheet 6 for a depiction of the pilot channel cross section to be constructed per the extents shown on this sheet.
 - Final channel and floodplain grading associated with the limits of pilot channel construction and bank stabilizations shown on this plan may be further revised in 100% design plans.

30% DESIGN PLANS, NOT FOR PERMITTING OR CONSTRUCTION


FILE:

| # | DATE | DRWN | CHK'D | APP'D | DESCRIPTION |
|---|------|------|-------|-------|-------------|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

DRAWING CREDITS

| | |
|-------------|----------|
| DRAWN ON: | 9/4/2020 |
| DRAWN BY: | GMB |
| CHECKED ON: | |
| CHECKED BY: | |
| PROJECT NO: | 20-007 |

DRAWING SCALE



 **STONE ENVIRONMENTAL**

535 Stone Cutters Way / Montpelier / VT / 05602 / USA
802.229.4541 / info@stone-env.com / www.stone-env.com

HANDS MILL DAM REMOVAL
AT JAIL BRANCH
CHANNEL RESTORATION PLAN

WASHINGTON VERMONT

7

Attachment 5: Geotechnical Memo

November 16, 2020

To: Gianna Petito, District Manager, Winooski
Natural Resources Conservation District

From: Matt Schley, Gabe Bolin, PE, Meghan Arpino,
Stone Environmental, Inc.

Stone Project No. 20-007
Subject: Hands Mill Dam Removal – Geotechnical Report

MEMO


Stone Environmental, Inc. (Stone) has completed desktop, field, and laboratory geotechnical investigations at the Hands Mill Dam as part of the overall 30% design effort. This memo provides a summary of these investigations including field and laboratory methods, data logs, and the implications of the data for site design and construction processes.

1. Desktop Evaluation

A preliminary desktop evaluation was performed to determine the potential extents of sampling. Aerial imagery of the Hands Mill Dam location (44.10569, -72.43000) from Google Earth shows aggradation of sediment, likely coarse grained, for approximately 750 linear feet upstream of the Hands Mill Dam (See Figure 1 on the following page for approximate project extents). This area was further investigated in the field to confirm sampling locations. The number of channel samples to be collected (six in total) was predetermined and was to include a combination of pebble counts and laboratory grain size analyses (methodologies defined below). The number of floodplain samples to be collected (three in total) was also predetermined to represent the spatial extent of the left-bank floodplain.

2. Field and Laboratory Investigations

An initial site evaluation was utilized to confirm the extents of sampling. Though Google Earth aerial imagery showed aggraded sediments for approximately 750 linear feet upstream of Hands Mill Dam, visible changes in bed slope and material indicated that the direct impact of the dam on sediment impoundment was likely limited to approximately 600 linear feet upstream. Channel sediment sampling was therefore focused within this extent. Exact sampling locations were selected to maximize the range of outcomes of the grain size analyses in order to assess the variability of grain size distribution throughout the channel. One sample, HM-S6, was excluded from further analysis and was sent to archive due to extensive similarity to sample HM-S4. Floodplain samples were spaced at equidistant intervals (approximately 150 - 200 feet apart) throughout the left bank floodplain.



LEGEND

- Bed Sediment Sampling Locations
- Floodplain Soil Borings
- Approximate Limits of Disturbance




Figure 1: Site Map

Hands Mill Geotechnical Memo

West Corinth Road
Washington, Vermont



STONE ENVIRONMENTAL

Source: Esri World Imagery, VCGI - Parcel Boundary
Path: O:\PROJ-20\WRM\20-007 Hands Mill
Dam\GIS\MapDocuments\PpresentationsAndReports\Hands Mill Site Map\Hands Mill Site Map.aprx

Grain size analyses were performed using one (or more) of three methods at each channel sampling location: modified Wolman pebble count, laboratory sieve analysis, and/or laboratory hydrometer analysis. The modified Wolman pebble counts were performed using the methodology of Leopold (1970) where individual grains are selected using heel-to-toe spacing along cross-sectional transects. For laboratory testing, bulk sediment samples were collected to a depth of approximately 6-10 inches below the surface using a hand shovel. The samples were sent to the University of Vermont (UVM) Agricultural & Environmental Testing Laboratory (Lab) given the Lab's ability to perform a specific phosphorus content test. Laboratory sieve analyses were performed on the coarse fraction of bulk sediment samples, and laboratory hydrometer analyses were performed on the fine fraction of bulk sediment samples. Bulk sediment samples were also sent to the UVM laboratory for phosphorus content analysis via microwave digestion and inductively coupled plasma (ICP) analysis. Results of the laboratory analysis are included as Attachment 1.

Floodplain soil/sediment samples were collected to a depth of approximately three (3) feet using a hand auger. Soil characteristics, including color, moisture, consistency, and field-assessed USCS classifications were recorded on a soil boring log for each of the three samples (see Attachment 2). Field-assessed USCS classifications were determined in accordance with ASTM standards D-2487 and D-2488.

3. Results

The results of the channel and floodplain investigations are shown in Tables 1 through 3. Pebble count data were aligned with the size classes tested via hydrometer and sieve analyses at the UVM Lab for direct comparison. Figure 2 shows the cumulative grain size distribution at each of the channel sampling sites (note that the curves for HM-S4 and HM-S5 were generated from pebble count data).

| Table 1 – Grain Size Distribution of Channel Samples | | | | | | | | | | |
|--|--------------------------|--------------------------------------|-----------|-----------|-----------|----------|-----------|------|------|-------------------|
| Sampling Site | Sample Type ¹ | Cumulative Percent Retained (%) | | | | | | | | |
| | | Larger than 3/4 Sieve ² | 3/4 Sieve | 1/2 Sieve | 1/4 Sieve | #5 Sieve | #10 Sieve | Sand | Silt | Clay |
| HM-S1 | B/L | - | 100.0 | 100.0 | 100.0 | 99.9 | 99.7 | 5.9 | 2.0 | 0.1 |
| HM-S2 | B/L | - | 100.0 | 85.0 | 73.3 | 60.8 | 55.2 | 46.6 | 4.7 | 1.2 |
| HM-S3 | B/L | - | 100.0 | 99.9 | 99.9 | 99.3 | 98.6 | 95.8 | 3.4 | 1.6 |
| HM-S4 | B/L | - | 100.0 | 99.4 | 90.2 | 77.3 | 69.8 | 52.4 | 3.4 | 1.0 |
| | | Cumulative Percent by Size Class (%) | | | | | | | | |
| | | Larger than 3/4 Sieve | 3/4 Sieve | 1/2 Sieve | 1/4 Sieve | #5 Sieve | #10 Sieve | Sand | Silt | Clay ² |
| HM-S4 | PC | 100.0 | 88.0 | 70.0 | 48.0 | 38.0 | 36.0 | 4.0 | 0.1 | - |
| HM-S5 | PC | 100.0 | 66.7 | 56.6 | 49.5 | 42.4 | | 9.1 | 0.1 | - |

¹B/L are bulk samples sent to the UVM lab for analysis; PC are pebble count samples.

²Results not recorded for this combination of methodology and size class.

| Table 2 – Phosphorus Content of Channel Samples | | |
|---|-------------------------|-------------------|
| Sampling Site | Test Description | P-Content (mg/kg) |
| HM-S1 | Phosphorus (P) from ICP | 267.9 |
| HM-S2 | Phosphorus (P) from ICP | 343.3 |
| HM-S3 | Phosphorus (P) from ICP | 206.1 |
| HM-S4 | Phosphorus (P) from ICP | 426.5 |




Figure 2 – Cumulative grain size distribution curves for channel samples HM-S1 through HM-S5. HM-S4 and HM-S5 curves were generated using pebble count data.

| Table 3 – Soil Characteristics of Floodplain Samples ³ | | | |
|---|----------------------------------|----------------------|---------------------------------|
| Sampling Site | Composite Relative Soil Moisture | Composite Soil Color | Predominant USCS Classification |
| HM-FP1 | Moist to Wet | Dark Brown | SM (Silty Sand) |
| HM-FP2 | Moist to Wet | Brown | SM (Silty Sand) |
| HM-FP3 | Moist to Wet | Brown/Grey Brown | SM/ML (Silt with Fine Sand) |

³See individual soil boring logs for more detailed information at respective soil layers.

4. Discussion

As is common with pebble counts, the sampling data show that the pebble count samples tended towards the coarser fraction of the impounded bed sediment material than the Lab tested bulk samples. However, both the Lab samples and pebble counts indicate that the median grain size (d_{50}) of the channel material is less than 10 mm (1 cm) in diameter. Particles of this size are highly mobile via both rolling and entrainment during common storm events. Both sample types also indicate that approximately 75% or more of the impounded bed sediment is finer than 25 mm (approximately 1 inch) in diameter. Coarse gravel in this size class is still likely to mobilize during storm flow events based on a simple incipient motion approximation using the critical Shields Number.

The average phosphorus (P) content of the impounded channel sediment is approximately 311 mg P/kg sediment. The total amount of phosphorus removed can be estimated based on 1) the extent of the impoundment, 2) an assumption that the majority of the phosphorus is contained within the active sediment layer (top 10 cm), and 3) an assumption that approximately 30% of the phosphorus is biologically available (value provided by the VANR workgroup). Review of publicly available LiDAR and aerial photography, and confirmation with field-run survey yields a total area of approximately 15,000 ft² of sediment impoundment. Based on the above assumptions and an average P loading of 311 mg/kg, the total bioavailable phosphorus to be removed associated with the proposed dam removal is 21 kg (or 46 lbs.). This estimate is limited to the sediment impounded within the confines of the channel. Floodplain sediments were not tested for P content, however utilizing the same assumptions as above, the same loading rate of 311 mg/kg, and the surface area of the proposed floodplain bench excavation (approximately 18,000 ft²) an additional 25 kg (55 lbs.) of phosphorus would be removed. If the entire impounded depth was assumed to contain phosphorus-laden sediments, the total P removals from channel and floodplain sediments would increase to 317 kg (699 lbs.) and 381 kg (840 lbs.), respectively. See Attachment 3 for supporting calculations.

Field evaluation of floodplain soils revealed that the floodplain soils are predominantly silty sands, or USCS classification SM. Based on this characterization, the soils are likely limited to a maximum grade of 2H:1V outside of the channel limits. The internal friction angle of SM soils is approximately 30 to 35 degrees, depending upon the fractions of silt and sand, therefore precluding the ability to permanently grade these soils to a slope exceeding 2H:1V. Sandy soils do not generally achieve high levels of compaction in comparison to silty or clayey soils, and silty soils are subject to the highest relative amounts of post-construction settlement, particularly in regions with highly active freeze-thaw. Caution should therefore be taken to limit steep grading to the maximum extent practicable.

5. References

Leopold, L.B. 1970. An improved method for size distribution of stream-bed gravel. *Water Resources Research*. 6(5):1357-1366.

Town of Washington and Central Valley Regional Planning Commission, 2013. Local Hazard Mitigation Plan. Created August, 2013 – Adopted April, 2014.

Attachment 1: UVM Laboratory Analyses

Laboratory Analysis Report

Agricultural & Environmental Testing Laboratory
and UVM Extension

Prepared For:**Order #: 10372**

Meghan Arpino
Stone Env. Inc.
5353 Stone Cutters Way
Montpelier, VT 05602

marpino@stone-env.com
845 323-3436

Received: 9/9/2020
Reported: 10/7/2020
VT County: Washington

Particle Size Analysis (Hydrometer)

Bouyoucos Hydrometer

| <i>Lab #</i> | <i>Sample Name</i> | <i>Description</i> | <i>Value</i> | <i>Unit of Measure</i> |
|--------------|--------------------|-------------------------|--------------|------------------------|
| 70001 | HM-S1 | Sand (0.05 - 2 mm) | 94.1 | % (dry wt) |
| | | Silt (0.002 - 0.05 mm) | 3.9 | % (dry wt) |
| | | Clay (< 0.002 mm) | 2.0 | % (dry wt) |
| | | Texture class | Sand | |
| 70002 | HM-S2 | Sand (0.05 - 2 mm) | 90.0 | % (dry wt) |
| | | Silt (0.002 - 0.05 mm) | 7.5 | % (dry wt) |
| | | Clay (< 0.002 mm) | 2.5 | % (dry wt) |
| | | Texture class | Sand | |

UVM Agricultural Environmental Testing Laboratory

262 Jeffords Hall, 63 Carrigan Dr Burlington, VT 05405-1737

agtesting@uvm.edu 802-656-3030 www.uvm.edu/pss/ag_testing

Laboratory Analysis Report

Agricultural & Environmental Testing Laboratory
and UVM Extension

70003 HM-S3

| | | |
|-------------------------|------|------------|
| Sand (0.05 - 2 mm) | 96.4 | % (dry wt) |
| Silt (0.002 - 0.05 mm) | 1.8 | % (dry wt) |
| Clay (< 0.002 mm) | 1.7 | % (dry wt) |
| Texture class | Sand | |

70004 HM-S4

| | | |
|-------------------------|------|------------|
| Sand (0.05 - 2 mm) | 93.5 | % (dry wt) |
| Silt (0.002 - 0.05 mm) | 4.5 | % (dry wt) |
| Clay (< 0.002 mm) | 2.0 | % (dry wt) |
| Texture class | Sand | |

If you have questions about these results, contact the lab at agtesting@uvm.edu.

UVM Agricultural Environmental Testing Laboratory

262 Jeffords Hall, 63 Carrigan Dr Burlington, VT 05405-1737

agtesting@uvm.edu 802-656-3030 www.uvm.edu/pss/ag_testing

Laboratory Analysis Report

Agricultural & Environmental Testing Laboratory
and UVM Extension

Prepared For:

Meghan Arpino
Stone Env. Inc.
5353 Stone Cutters Way
Montpelier, VT 05602

marpino@stone-env.com
845 323-3436

Order #: 10372

Received: 9/9/2020
Reported: 10/7/2020
VT County: Washington

Particle Size Analysis (Large Sieve)

Large Sieve

| Lab # | Sample Name | Description | Value | Unit of Measure |
|-------|-------------|-----------------------|-------|-----------------|
| 70005 | HM-S1 | | | |
| | | Retained by 3/4 Sieve | < 0.1 | % (dry wt) |
| | | Retained by 1/2 Sieve | < 0.1 | % (dry wt) |
| | | Retained by 1/4 Sieve | < 0.1 | % (dry wt) |
| | | Retained by #5 Sieve | 0.1 | % (dry wt) |
| | | Retained by #10 Sieve | 0.4 | % (dry wt) |
| 70006 | HM-S2 | | | |
| | | Retained by 3/4 Sieve | 15.0 | % (dry wt) |
| | | Retained by 1/2 Sieve | 11.7 | % (dry wt) |
| | | Retained by 1/4 Sieve | 12.5 | % (dry wt) |
| | | Retained by #5 Sieve | 5.6 | % (dry wt) |
| | | Retained by #10 Sieve | 8.6 | % (dry wt) |

UVM Agricultural Environmental Testing Laboratory

262 Jeffords Hall, 63 Carrigan Dr Burlington, VT 05405-1737

agtesting@uvm.edu 802-656-3030 www.uvm.edu/pss/ag_testing

Laboratory Analysis Report

Agricultural & Environmental Testing Laboratory
and UVM Extension

70007 HM-S3

| | | |
|-----------------------|-------|------------|
| Retained by 3/4 Sieve | < 0.1 | % (dry wt) |
| Retained by 1/2 Sieve | < 0.1 | % (dry wt) |
| Retained by 1/4 Sieve | 0.6 | % (dry wt) |
| Retained by #5 Sieve | 0.7 | % (dry wt) |
| Retained by #10 Sieve | 2.8 | % (dry wt) |

70008 HM-S4

| | | |
|-----------------------|------|------------|
| Retained by 3/4 Sieve | 0.6 | % (dry wt) |
| Retained by 1/2 Sieve | 9.2 | % (dry wt) |
| Retained by 1/4 Sieve | 12.9 | % (dry wt) |
| Retained by #5 Sieve | 7.5 | % (dry wt) |
| Retained by #10 Sieve | 17.4 | % (dry wt) |

If you have questions about these results, contact the lab at agtesting@uvm.edu.

UVM Agricultural Environmental Testing Laboratory

262 Jeffords Hall, 63 Carrigan Dr Burlington, VT 05405-1737

agtesting@uvm.edu 802-656-3030 www.uvm.edu/pss/ag_testing

Order #: 10372

4 of 4

234

Laboratory Analysis Report

Agricultural & Environmental Testing Laboratory
and UVM Extension

Prepared For:

Meghan Arpino
Stone Env. Inc.
5353 Stone Cutters Way
Montpelier, VT 05602

marpino@stone-env.com
845 323-3436

Order #: 10372

Received: 9/9/2020
Reported: 10/7/2020
VT County: Washington

Lab - Microwave digest + ICP analysis

| <i>Lab #</i> | <i>Sample Name</i> | <i>Description</i> | <i>Value</i> | <i>Unit of Measure</i> |
|--------------|--------------------|-------------------------|--------------|------------------------|
| 70009 | HM-S1 | Phosphorus (P) from ICP | 267.9 | mg/kg |
| 70010 | HM-S2 | Phosphorus (P) from ICP | 343.3 | mg/kg |
| 70011 | HM-S3 | Phosphorus (P) from ICP | 206.1 | mg/kg |
| 70012 | HM-S4 | Phosphorus (P) from ICP | 426.5 | mg/kg |

If you have questions about these results, contact the lab at agtesting@uvm.edu.


Attachment 2: Floodplain Soil Boring Logs

Boring Log Form

Hands Mill Dam Removal in Washington, Vermont

Sponsor Study Number:

Stone Study Number: 20-007


| Described By : Matt Schley | | | | Date: 11/5/2020 | | | |
|--|------------|---------|-----------------------|--|--|-----------------------|--|
| Recorded By: Matt Schley | | | | Location: Washington, Vermont | | | |
| Vegetation: Dense, Wet-Tolerant | | | | Topographic Setting: Floodplain | | | |
| Slope: Very Low (Floodplain) | | | | Land use: Scrub/Shrub | | | |
| Comments: ~65 degrees F and sunny at time of sample; recent snowmelt increased soil moisture conditions | | | | | | | |
| Boring # HM-FP1 (Most Downstream) | | | | | | | |
| Depth (ft) | Color | Mottles | USCS Classification | Moisture | Consistence | Boundary Distinctness | Comments |
| 0 – 1' | Dark Brown | F/1/F | SM (Silty Sand) | D/M | VFR | G | Some organic material throughout |
| 1 – 2' | Dark Brown | F/1/F | SM (Silty Sand) | M/W | FR | G | Silt fraction declines with depth |
| 2 – 2.5' | Dark Brown | F/1/F | SM (Silty Sand) | W | FR | G | GW Encountered @ 26" BGS  |
| 2.5 – 3' | Brown | C/2/P | SW (Well-Graded Sand) | W | L | A | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Key: Color: MunsellSoil Color Chart (1994) codes refer to Hue, Value & Chroma Mottles: Expressed as abundance/size/contrast Abundance: f=few;m=many;c=common Size: 1=fine;2=medium;3=coarse Contrast: f=faint; d=distict; p=prominent | | | | | Moisture: m=moist, w=wet, d=dry Consistence: l=loose, fr=friable, fi=firm, vfr=very friable, vfi=very firm, xfi=extremely firm Boundary: Distinctness (D) g=gradual, a=abrupt ESHGW= estimated seasonal high groundwater table BGS= below ground surface | | |

Boring Log Form

Hands Mill Dam Removal in Washington, Vermont

Sponsor Study Number:

Stone Study Number: 20-007

| Described By : Matt Schley | | | | Date: 11/5/2020 | | | |
|--|------------|---------|-------------------------|--|--|-----------------------|--|
| Recorded By: Matt Schley | | | | Location: Washington, Vermont | | | |
| Vegetation: Dense, Wet-Tolerant | | | | Topographic Setting: Floodplain | | | |
| Slope: Very Low (Floodplain) | | | | Land use: Scrub/Shrub | | | |
| Comments: ~65 degrees F and sunny at time of sample; recent snowmelt increased soil moisture conditions | | | | | | | |
| Boring # HM-FP2 | | | | | | | |
| Depth (ft) | Color | Mottles | USCS Classification | Moisture | Consistence | Boundary Distinctness | Comments |
| 0 – 0.5' | Dark Brown | F/1/F | SM (Silty Sand) | D/M | VFR | G | Some organic material throughout |
| 0.5 – 1.5' | Brown | F/1/F | SM (Silty Sand) | M | FR | G | Silt fraction declines with depth |
| 1.5 – 2.5' | Brown | F/1/F | SM (Silty Sand) | M/W | FR | G | |
| 2.5 – 3' | Grey Brown | M/1/F | SP (Poorly-Graded Sand) | W | FR | G | GW Encountered @ 32" BGS  |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Key: Color: MunsellSoil Color Chart (1994) codes refer to Hue, Value & Chroma Mottles: Expressed as abundance/size/contrast Abundance: f=few;m=many;c=common Size: 1=fine;2=medium;3=coarse Contrast: f=faint; d=distict; p=prominent | | | | | Moisture: m=moist, w=wet, d=dry Consistence: l=loose, fr=friable, fi=firm, vfr=very friable, vfi=very firm, xfi=extremely firm Boundary: Distinctness (D) g=gradual, a=abrupt ESHGW= estimated seasonal high groundwater table BGS= below ground surface | | |

Boring Log Form

Hands Mill Dam Removal in Washington, Vermont

Sponsor Study Number:

Stone Study Number: 20-007

| Described By : Matt Schley | | | | Date: 11/5/2020 | | | |
|--|------------|---------|--------------------------|--|--|-----------------------|--|
| Recorded By: Matt Schley | | | | Location: Washington, Vermont | | | |
| Vegetation: Dense, Wet-Tolerant | | | | Topographic Setting: Floodplain | | | |
| Slope: Very Low (Floodplain) | | | | Land use: Scrub/Shrub | | | |
| Comments: ~65 degrees F and sunny at time of sample; recent snowmelt increased soil moisture conditions | | | | | | | |
| Boring # HM-FP3 (Most Upstream) | | | | | | | |
| Depth (ft) | Color | Mottles | USCS Classification | Moisture | Consistence | Boundary Distinctness | Comments |
| 0 – 0.5' | Dark Brown | F/1/F | ML (Silt with Fine Sand) | D/M | VFR | G | High organic material content throughout |
| 0.5 – 1.5' | Brown | F/1/F | SM (Silty Sand) | M | VFR | G | |
| 1.5 – 2.5' | Grey Brown | F/1/F | SM (Silty Sand) | M/W | FR | G | |
| 2.5 – 3' | Grey Brown | F/1/F | ML (Silt with Fine Sand) | W | FI | G | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Key: Color: MunsellSoil Color Chart (1994) codes refer to Hue, Value & Chroma Mottles: Expressed as abundance/size/contrast Abundance: f=few;m=many;c=common Size: 1=fine;2=medium;3=coarse Contrast: f=faint; d=distict; p=prominent | | | | | Moisture: m=moist, w=wet, d=dry Consistence: l=loose, fr=friable, fi=firm, vfr=very friable, vfi=very firm, xfi=extremely firm Boundary: Distinctness (D) g=gradual, a=abrupt ESHGW= estimated seasonal high groundwater table BGS= below ground surface | | |

Attachment 3: Phosphorus Loading Calculations

Hands Mill Dam P Removal Calculations

| | Assume full sediment depth | Assume 10-cm sediment depth (active layer) ¹ | Full sediment deph over floodplain bench | 10-cm sediment depth over floodplain bench |
|--|-------------------------------|---|--|--|
| Area of impounded sediment | 0.34 | 0.34 | 0.41 | 0.41 acres |
| Area of impounded sediment | 15000 | 15000 | 18000 | 18000 ft ² |
| Sediment depth ² | 5 | 0.328 | 5 | 0.328 ft |
| Total sediment volume | 75000 | 4921 | 90000 | 5904 ft ³ |
| Sediment density (estimated) | 100 | 100 | 100 | 100 lb./ft ³ |
| Sediment mass | 7,500,000 | 492,126 | 9,000,000 | 590,400 lb. |
| Sediment mass | 3,401,943 | 223,225 | 4,082,331 | 267,801 kg |
| Sediment TP conc. (estimated) ³ | 311 | 311 | 311 | 311 mg P/kg sediment |
| Total P mass | 1,058 | 69 | 1,270 | 83 kg |
| Bioavailable P fraction ¹ | 0.3 | 0.3 | 0.3 | 0.3 g/g |
| Total bioavailable P mass | 317 | 21 | 381 | 25 kg |

1. Constants assumed per preliminary guidance of ANR's *P Capture by Natural Resources Restoration Projects Workgroup* (November 26, 2019)

2. Average 5-ft sediment depth over area of impoundment is an assumption based on impoundment

3. Assumed representative value (total P in impounded sediment behind Levesque Dam near East Montpelier, VT) from: Chalmers, A. 1998. Distribution of Phosphorus in Bed Sediments of the Winooski River Watershed, Vermont, 1997. USGS Fact Sheet FS-108-98.

Area of Impoundment Calculations

| | | |
|-------------------------|-------|-----------------|
| Average Channel Width: | 25 | ft |
| Length of Impoundment: | 600 | ft |
| Area of Impoundment: | 15000 | ft ² |
| Floodplain Bench Width: | 30 | ft |
| Length of Bench: | 600 | ft |
| Area of Bench: | 18000 | ft ² |

Attachment 6: Opinion of Probable Cost (OPC)


Hands Mill Dam Removal
Alternative A4 - 30% Design OPC
Stone Environmental, 12/2020, V4

| ITEM # | ITEM | AMOUNT | UNIT | UNIT COST | TOTAL |
|--|--|--------|------|-------------|------------------|
| General | | | | | |
| 1 | SURVEY LAYOUT | 1 | LS | \$4,000.00 | \$4,000.00 |
| 2 | CONSTRUCT ACCESS | 1 | LS | \$10,000.00 | \$10,000.00 |
| 3 | EPSC MEASURES | 1 | LS | \$8,000.00 | \$8,000.00 |
| 4 | FLOW BYPASS AND DEWATER SITE | 1 | LS | \$10,000.00 | \$10,000.00 |
| Dam Removal | | | | | |
| 5 | DEMO DAM AND HAUL OUT STONE | 453.00 | CY | \$220.00 | \$99,660.00 |
| Channel Restoration | | | | | |
| 6 | COMMON EXCAVATION (CHANNEL AND FLOODPLAIN BENCHES) | 13940 | CY | \$7.50 | \$104,550.00 |
| 7 | SEDIMENT HAUL | 13386 | CY | \$7.50 | \$100,395.00 |
| 8 | CHANNEL REALIGNMENT | 1 | LS | \$5,000.00 | \$5,000.00 |
| 9 | INSTALL STONE STEPS, POOLS AND ROOTWADS | 1 | LS | \$15,000.00 | \$15,000.00 |
| 10 | PLACE SEED, MULCH AND FASCINES | 1 | LS | \$10,000.00 | \$10,000.00 |
| CONSTRUCTION TOTAL | | | | | \$366,605 |
| MOBILIZATION / DEMOBILIZATION (10%) | | | | | \$36,661 |
| CONSTRUCTION CONTINGENCY (20%) | | | | | \$73,321 |
| TOTAL (ROUNDED TO NEAREST \$100) | | | | | \$476,600 |


| | |
|---|-----------------|
| Design, Permitting and Construction Services | |
| FINAL DESIGN & PERMITTING (10%) | \$36,661 |
| BID AND CONSTRUCTION PHASE SERVICES (6%) | \$21,996 |

Attachment 7: Hydraulic Modeling Output


Hands Mill Dam Removal - Longitudinal Profile for Peak Flows



HandsMillDamRemoval



HandsMillDamRemoval



HandsMillDamRemoval

